



Technical Service Bulletin

Technical Service Bulletin: tsb103877

Released Date: 23-Jun-2009

Cylinder Head Procedure, Clean and Inspect for Reuse Section Revision

Cylinder Head Procedure, Clean and Inspect for Reuse Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

The purpose of the Service/Parts Topic is to introduce the changes to the Clean and Inspect for Reuse Section of Procedure 002-004 (Cylinder Head) in the Signature™, ISX, and QSX15 Service Manual, Bulletin 3666239. These changes include adding an inspection of the injector bores. Previously, **only** the combustion surface and valves were inspected.

Related Procedures

10-002-004-tr
(/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html)

Cylinder Head
(/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html)

Last Modified: 23-Jun-2009