



Technical Service Bulletin

Technical Service Bulletin: tsb103991

Released Date: 19-Nov-2009

Fuel Actuator and Timing Actuator Procedures, Install Section Revisions

Fuel Actuator and Timing Actuator Procedures, Install Section Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the fueling actuator and timing actuator mounting capscrew torque specifications in the Install sections of Procedures 019-110 (Fueling Actuator) and 019-111 (Timing Actuator).

Related Procedures

16-019-110 (/qs3/pubsys2/xml/en/procedures/16/16-019-110.html)	Fueling Actuator (/qs3/pubsys2/xml/en/procedures/16/16-019-110.html)
70-019-110 (/qs3/pubsys2/xml/en/procedures/70/70-019-110.html)	Fueling Actuator (/qs3/pubsys2/xml/en/procedures/70/70-019-110.html)
72-019-110 (/qs3/pubsys2/xml/en/procedures/72/72-019-110.html)	Fueling Actuator (/qs3/pubsys2/xml/en/procedures/72/72-019-110.html)
16-019-111 (/qs3/pubsys2/xml/en/procedures/16/16-019-111.html)	Timing Actuator (/qs3/pubsys2/xml/en/procedures/16/16-019-111.html)
70-019-111 (/qs3/pubsys2/xml/en/procedures/70/70-019-111.html)	Timing Actuator (/qs3/pubsys2/xml/en/procedures/70/70-019-111.html)

72-019-111
(/qs3/pubsys2/xml/en/procedures/72/72-019-111.html)

Timing Actuator
(/qs3/pubsys2/xml/en/procedures/72/72-019-111.html)

Last Modified: 19-Nov-2009
