



Technical Service Bulletin

Technical Service Bulletin: tsb104000	Released Date: 18-Nov-2009
Symptom Tree t103-56 (Lubricating Oil Filter Plugged), Major Revision	

Symptom Tree t103-56 (Lubricating Oil Filter Plugged), Major Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Symptom Tree t103-56 (Lubricating Oil Filter Plugged) for the Signature™, ISX, and QSX15 Service Manual, Bulletin 3666239. Multiple Cause and Correction steps have been revised and added to this symptom tree.

Lubricating Oil Filter Plugged

Last Modified: 18-Nov-2009
