



Technical Service Bulletin

Technical Service Bulletin: tsb104171

Released Date: 25-Jun-2010

Cooling System Procedure, Major Revision

Cooling System Procedure, Major Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic introduces major revisions to Procedure 008-018 (Cooling System) in Section 8 of the Signature™, ISX, and QSX15 Service Manual, Bulletin 3666239. The revisions clarify statements regarding the proper coolant fill and deaeration process for engines equipped with EGR and add other detail regarding this process. A graphical representation of the coolant fill and deaeration procedure has also been added.

Related Procedures

10-008-018-tr
(/qs3/pubsys2/xml/en/procedures/10/10-008-018-tr.html)

Cooling System
(/qs3/pubsys2/xml/en/procedures/10/10-008-018-tr.html)

Last Modified: 25-Jun-2010