



Technical Service Bulletin

Technical Service Bulletin: TSB130067

Released Date: 22-Apr-2013

ReCon® Engine Control Module (ECM) Release for ISX CM570 and ISM CM570

ReCon® Engine Control Module (ECM) Release for ISX CM570 and ISM CM570

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces the release of ReCon® CM570 ECM Part Number 4309175RX for ISX CM570 and ISM CM570 engines. The new part obsoletes and supersedes the previous ECM, as shown in the table below.

Obsolete and New Part Number		
Obsolete Part Number	Part Description	New Part Number
3408501RX	ECM	4309175RX

Part Number 4309175RX, contains two packages with the ECM. The large package contains vibration isolators for ISX engines. The large package contains the following:

ECM Vibration Isolator Parts for ISX CM570		
Part Number	Part Description	Quantity
3009329	Washer, Plain	3
3677204	Screw, Self tapping	1
3687573	Isolator, Vibration (Grommet)	12
3900589	Nut, Hexagon Flange	3
4298993	Screw, SDD Captive Washer	3
4298994	Wire, Ground	1
4311968	Spacer, Mounting	6
5255716	Screw, Captive Washer	3

The package labeled for 'ISM engine **only**' contains the following for ISM CM570:

ISM CM570		
Part Number	Part Description	Quantity
Supplied with ECM	Washer, Grounding	1
Supplied with ECM	Washer, Plastic	5

- Note :** Instructions for installing these parts are included with the ECM.
- Note :** Follow the instructions provided with the ECM for upfit to ISX or ISM engines.

Document History

Date	Details
2013-4-5	Module Created