



Technical Service Bulletin

Technical Service Bulletin: TSB140063

Released Date: 28-May-2014

Cylinder Head Gasket Exhaust Side Coolant Orifices Misaligned with Cylinder Block Passages

Cylinder Head Gasket Exhaust Side Coolant Orifices Misaligned with Cylinder Block Passages

Core Issue

Heavy duty cylinder head gaskets with Part Number 4299098 have 12 orifices on the exhaust side of the engine that are primarily used for venting the cooling system. Some gaskets have the potential for three of these orifices to be misaligned with the coolant passages in the cylinder block.

Confirmation

With the cylinder head gasket located on the cylinder block, misaligned orifices will be identifiable near cylinders 5 and 6 (reference Figure 1).




Figure 1, New Cylinder Head Gasket on Cylinder Block

1. Regular Orifice.
2. Misaligned Orifice.

Resolution

New cylinder head gaskets identified with misaligned orifices in these locations are fit for service and should be used, **not** scrapped.

Gaskets removed from service are **not** considered failed or defective as a result of misaligned orifices observed in these locations.

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Document History

Date	Details
2014-5-21	Module Created

Last Modified: 28-May-2014
