



Technical Service Bulletin

Technical Service Bulletin: TSB160030

Released Date: 07-Nov-2016

New J-seal Compatible Exhaust Manifold Sections for All Three Piece Exhaust Manifolds

New J-seal Compatible Exhaust Manifold Sections for All Three Piece Exhaust Manifolds

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISX15 (All Versions)
- QSX15 (All Versions)

Description of Change

This document announces new J-seal compatible exhaust manifold sections for all three piece exhaust manifolds.

Reason for Change

The new exhaust manifolds have been introduced to commonize the J-seal slip joint technology for all three piece exhaust manifolds and improve robustness of the slip joint to exhaust leaks.

Service Parts Availability

Service parts are available. See Table 1.

Table 1, Service Parts

Part Description	Exhaust Manifold Section	Existing Part Number	Obsoleted	Superseded	New Part Number
Exhaust Manifold	Center	3104190	Yes	Yes	4386668
Exhaust Manifold	End	3682549	Yes	Yes	3683870
Exhaust Manifold	Center	3686601	Yes	Yes	4386724

Table 1, Service Parts					
Part Description	Exhaust Manifold Section	Existing Part Number	Obsolete	Superseded	New Part Number
Exhaust Manifold	End	3688488	No	No	3688488
Exhaust Manifold	End	3680200	Yes	Yes	4386579
Exhaust Manifold	Center	3680199	Yes	Yes	4386606
Exhaust Manifold	Center	3681490	Yes	Yes	4386649
Exhaust Manifold	Center	3100131	Yes	Yes	4386627
Exhaust Manifold	Center	3101341	Yes	Yes	4386797
Exhaust Manifold	End	3682491	Yes	Yes	4952236
Exhaust Manifold	Center	3682548	Yes	Yes	3682959
Part Compatibility - The new exhaust manifold pieces are not compatible with existing exhaust manifold pieces and can not be intermixed. - If replacement of one existing exhaust manifold section is required and a like part is not available, all exhaust manifold pieces must be replaced with the new design. Part Inventory Action Use existing part number inventory before using the new part number.					

Document History

Date	Details
2016-3-21	Module Created
2016-11-4	Updated Table 1 to include part numbers 4952236 and 3682959.