



Technical Service Bulletin

Technical Service Bulletin: TSB200148

Released Date: 30-Oct-2024

Exhaust Valve Face Surface Finish Change

Exhaust Valve Face Surface Finish Change

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- 6B5.9
- B4.5 CM2350 B129B
- B4.5 CM2350 B146C
- B4.5 CM2350 B147B
- B5.9
- B6.7 CM2350 B121B
- B6.7 CM2350 B135B
- B6.7 CM2350 B148B
- F3.8 CM2350 F120B
- F3.8 CM2350 F128C
- F3.8 CM2450 F156C
- F3.8 CM2450 F157C
- F3.8 F102
- F4.5 CM2620 F139B
- ISB (Chrysler)
- ISB CM2150
- ISB CM2150 E
- ISB/ISD4.5 CM2150 B119
- ISB/ISD4.5 CM2150 SN
- ISB4.5 CM2150
- ISB4.5 CM2150 SN
- ISB4.5 CM2350 B104
- ISB6.7 2010 DCX Chassis Cab
- ISB6.7 2010 DCX Pickup
- ISB6.7 CM2150
- ISB6.7 CM2150 E
- ISB6.7 CM2250

- ISB6.7 CM2350 B101
- ISB6.7 CM2350 B103
- ISBE4 CM850
- ISF3.8 CM2220
- ISF3.8 CM2220 AN
- ISF3.8 CM2220 F103
- ISF3.8 CM2220 F110
- ISF3.8 CM2220 F116
- ISF3.8 CM2220 IAN
- ISF3.8 CM2350 F109
- QSB (Komatsu)
- QSB4.5 CM2250 EC
- QSB4.5 CM2350 B106
- QSB4.5 CM2350 B122
- QSB4.5 CM850
- QSB4.5 CM850(CM2850)
- QSB5.9 CM2880 B115
- QSB6.7 CM2150 B109
- QSB6.7 CM2250
- QSB6.7 CM2250 B128
- QSB6.7 CM2250 EC
- QSB6.7 CM2350 B105
- QSB6.7 CM2350 B130
- QSB6.7 CM850
- QSB6.7 CM850(CM2850)
- QSB6.7 M CM2250
- QSB7 CM2880 B117
- QSB7-DM CM850
- QSF3.8 CM2350 F107
- QSF3.8 CM2350 F118
- QSF3.8 CM2350 F119
- QSF3.8 CM2880 F112

Description of Change

The exhaust valve face surface finish may be received as forged or machined.

Reason for Change

The supplier for exhaust valve Part Number 3940734 produces parts at two facilities. A change to the manufacturing process at one facility will result in a machined valve face surface finish instead of forged.

Customer Communication

The change will be transparent to the customer.

Service Parts Availability

Either the forged or machined valve face surface finish will be in inventory. The part number will **not** be changing.

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Exhaust Valve	3940734	No	No	Not Applicable

Part Compatibility

Exhaust valves with either surface finish are completely interchangeable and can be mixed in the same cylinder head.

Part Identification

The forged and machined valve face surface finishes are visually different. See Figure 1 for comparison between forged and machined valve face surface finish (from left to right).



Figure 1, Comparison of Forged and Machined Valve Face Surface Finish

Document History

Date	Details
2020-7-1	Module Created
2024-10-4	Added F156C to Product Affected.
2024-10-30	Added F157C to Product Affected.
2024-10-30	No changes made, checking product affected list.