



Technical Service Bulletin

Technical Service Bulletin: TSB210062

Released Date: 19-Mar-2021

Starter O-ring Cut or Damaged During Starter Installation

Starter O-ring Cut or Damaged During Starter Installation

Warranty Statement

The information in this document authorizes specific changes to the repair practice for failures covered under product warranty coverages.

Contents

Product Affected

- ISX15 CM2250
- ISX15 CM2250 SN
- ISX15 CM2350 X101
- QSX15 CM2250 ECF
- QSX15 CM2350 X105
- QSX15 CM2350 X106
- QSX15 CM570
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2350 X123B
- X15 CM2350 X129B
- X15 CM2350 X130C
- X15 CM2350 X131
- X15 CM2350 X140C
- X15 CM2450 X124B
- X15 CM2450 X134B

Issue

Symptom:

- Starter O-ring is cut or damaged when installing the starter into the flywheel housing.

Root Cause:

- Flywheel housings produced prior to November 2020 do **not** include a chamfer on the starter bore to accommodate starter housings that utilize an O-ring.
- Depending on the option, some flywheel housings produced after November 2020 do include a chamfer and will accommodate starters with or without an o-ring.

- Starter part numbers 5626307, 5575820, 5575214, and 5575819 made available in March of 2021 include an o-ring on the starter housing.

Verification

When starter is installed or removed the starter O-ring is found to be cut or damaged. Inspect the flywheel housing starter bore for the presence of a chamfer. If no chamfer exists proceed to the resolution.

Resolution

With the starter removed, use a curved or round file to create an 1/8 Inch(3mm) chamfer on the starter bore. Use sandpaper to clean and smooth the chamfer.

Remove the plug at the bottom of the flywheel housing.

Clean the flywheel housing, starter bore and flywheel with contact cleaner rinsing the metal filings out of the plug hole in the bottom of the flywheel housing.

Install the plug at the bottom of the flywheel housing.

If the starter O-ring is damaged, replace the starter.

Document History

Date	Details
2021-3-19	Module Created

Last Modified: 19-Mar-2021
