



Technical Service Bulletin

Technical Service Bulletin: TSB210233

Released Date: 26-Oct-2021

15N CM2380 M104B Engine Introduction

15N CM2380 M104B Engine Introduction

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This engine introduction announces the 15N CM2380 M104B engine.

Emissions and Diagnostics

See the following for emission and diagnostic information in the 15N CM2380 M104B Operation and Maintenance Manual, Bulletin 5659762. Reference Procedure 100-006 in Section E. See Additional Information section below.

Engine Features

See the following for a complete list of engine features in the Operation and Maintenance Manual, Bulletin 5659762. Reference Procedure 100-006 in Section E. See Additional Information section below.

Recommendations and Specifications

Table 1, Recommendations and Specifications				
Manual Type	Bulletin	Procedure Title	Procedure	Section
Operation and Maintenance Manual	5659762	Lubricating Oil Recommendations and Specifications	Refer to Procedure 018-003 (/qs3/pubsys2/xml/en/procedures/1016/1016-018-003.html)	V
		Fuel Recommendations and Specifications	Refer to Procedure 018-002 (/qs3/pubsys2/xml/en/procedures/1016/1016-018-002.html)	
		Coolant Recommendations and Specifications	Refer to Procedure 018-004 (/qs3/pubsys2/xml/en/procedures/1016/1016-018-004.html)	

Maintenance Schedule

Use the following procedure for maintenance intervals in the 15N CM2380 M104B Operation and Maintenance Manual, Bulletin 5659762. Reference Procedure 359-001 in Section 3. See Additional Information section below.

Service Tools

New Cummins® service tools released to support the 15N CM2380 M104B engine are:

- EGR cooler leak test, Part Number 5573379
- Valve spring compressor, Part Number 5573421
- Valve seat installer, Part Number 5573423

For a complete list of Cummins® service tools needed to support this engine, consult a local Cummins® distributor.

INSITE™ Electronic Service Tool

INSITE™ electronic service tool version 8.7.2 or later supports full production engines. Version 8.7.2 or later includes all diagnostic tests and features necessary to fully support the 15N CM2380 M104B engine. INSITE™ electronic service tool updates are available through the Cummins® update manager. Reference the following website to access Cummins® update manager.

Note : <https://www.cummins.com/support/digital-products-and-services-support>
(<https://www.cummins.com/support/digital-products-and-services-support>)

Cummins Diagnostic System (CDS)

The CDS troubleshooting tool is available to fully support troubleshooting requirements for 15N CM2380 M104B engines.

Engine Ratings

Table 2, Engine Ratings

Control Parts List (CPL)	Power Kw [hp] at Governed Speed rpm	Peak Power Kw [hp] at rpm	Peak Torque N·m [ft-lb] at rpm	Rating Type
5480	390 (523) at 1900	390 (523) at 1900	2500 (1844) at 1200	Intermittent
5480	368 (493) at 1900	368 (493) at 1900	2400 (1770) at 1100	Intermittent
5480	346 (463) at 1900	346 (463) at 1900	2300 (1696) at 1100	Intermittent
5480	316 (424) at 1900	316 (424) at 1900	2200 (1623) at 1000	Intermittent

Additional Information

Table 3, Associated Procedures				
Manual Type	Bulletin Number	Procedure Title	Procedure	Section
Operation and Maintenance Manual	5659762	Cummins® Product Technology	Refer to Procedure 100-006 (/qs3/pubsys2/xml/en/procedures/1016/1016-100-006.html)	E
		Engine Identification	Refer to Procedure 100-001 (/qs3/pubsys2/xml/en/procedures/1016/1016-100-001.html)	
		Engine Diagrams	Refer to Procedure 100-002 (/qs3/pubsys2/xml/en/procedures/1016/1016-100-002.html)	
		General Engine	Refer to Procedure 018-015 (/qs3/pubsys2/xml/en/procedures/1016/1016-018-015.html)	V
		Additional Service Literature	Refer to Procedure 205-001 (/qs3/pubsys2/xml/en/procedures/1016/1016-205-001.html)	L
		Routine Maintenance Schedule	Refer to Procedure 359-001 (/qs3/pubsys2/xml/en/procedures/1016/1016-359-001.html)	3

Document History

Date	Details
2021-10-25	Module Created

Last Modified: 26-Oct-2021
