



# Technical Service Bulletin

Technical Service Bulletin: TSB240033

Released Date: 27-Feb-2024

New Injector Kit Part Numbers

## New Injector Kit Part Numbers

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

#### Product Affected

- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2350 X123B
- X15 CM2350 X129B
- X15 CM2450 X124B
- X15 CM2450 X134B
- X15 CM2450 X142B

#### Description of Change

Fuel injector kits for the X15 engine contain the injector, Part Number 4327147. New kit part numbers are being released (see Table 1).

#### Reason for Change

Beginning in January 2024, Part Number 4327147 fuel injector(s) have improved durability for the MY21 X3/X600 duty cycle.

#### Service Parts

Table 1, Service Parts

| Part Description  | Existing Part Number | Obsolete | Superseded | New Part Number |
|-------------------|----------------------|----------|------------|-----------------|
| Fuel Injector Kit | 5579421              | No       | Yes        | 6513590         |
| Fuel Injector Kit | 5579421              | No       | Yes        | 6513589         |

#### Part Compatibility

- Reference kit part number shown in Table 2 for the engine being serviced.
- Part Number 6513589 **must** be used for X15 CM2450 X134B and X15 CM2450 X142B.
- Part Number 6513589 can be used for All Engines listed in Table 2.

- If Part Number 6513590 is **not** available, use either Part Number 5579421 or Part Number 6513589.

| Table 2, Injector Kit Part Number Compatibility |                           |
|-------------------------------------------------|---------------------------|
| Injector Part Number                            | Engine Service Model Name |
| 5579421                                         | X15 CM2350 X114B          |
| or                                              | X15 CM2350 X116B          |
| 6513590                                         | X15 CM2350 X123B          |
| or                                              | X15 CM2350 X129B          |
| 6513589                                         | X15 CM2450 X124B          |
| 6513589                                         | X15 CM2450 X134B          |
|                                                 | X15 CM2450 X142B          |

**Part Identification**

New and Recon injectors with SN S24001xxx and later have the improvement. All new X15 engines since ESN 80608247 built 24 January 2024 have this improvement.

**Document History**

| Date      | Details            |
|-----------|--------------------|
| 2024-2-14 | Module Created     |
| 2024-2-27 | Corrected Table 2. |