



Technical Service Bulletin: TSB250034

Released Date: 18-Feb-2025

A8.5 CM2670 L153B Engine Introduction

A8.5 CM2670 L153B Engine Introduction

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This engine introduction announces the A8.5 CM2670 L153B engine.

Emissions and Diagnostics

See the following for emission and diagnostic information in the A8.5 CM2670 L153B Operation and Maintenance Manual, Bulletin 6408779 or the A8.5 CM2670 L153B Service Suite. Reference the Cummins Product Technology Purpose. See Additional Information section below.

Engine Features

See the following for a complete list of engine features in the Operation and Maintenance Manual, Bulletin 6408779 or Service Suite. Reference the Cummins Product Technology Purpose. See Additional Information section below.

Recommendations and Specifications

Table 1, Recommendations and Specifications		
Output Type	Bulletin/Suite Number	Purpose Title
Operation and Maintenance Manual or Service Suite	6408779/1868	Fuel System Specifications
		Fuel Specifications
		Lubricating Oil System Specifications
		Cooling System Specifications
		Air Intake System Specifications
		Exhaust System Specifications
		Electrical Equipment Specifications
		Diesel Exhaust Fluid Recommendations and Specifications*
*For additional information on DEF. Reference Diesel Exhaust Fluid (DEF) Specifications for Cummins® Selective Catalytic Reduction (SCR) Systems, Bulletin 4021566.		

Maintenance Schedule

Use the following for maintenance intervals in the A8.5 CM2670 L153B Operation and Maintenance Manual, Bulletin 6408779 or Service Suite. Reference the Maintenance Chapter or Maintenance Schedule. See Additional Information section below.

Service Tools

New Cummins® service tools released to support the A8.5 CM2670 L153B engine are:

- Bench calibration harness, Part Number 5572656.
- Barring Tool, Part Number 4919092.

For a complete list of Cummins® service tools needed to support this engine, consult a local Cummins® distributor.

INSITE™ Electronic Service Tool

INSITE™ electronic service tool version 9.0.0 or later supports full production engines. Version 9.0.0 or later includes all diagnostic tests and features necessary to fully support the A8.5 CM2670 L153B engine. INSITE™ electronic service tool updates are available through the Cummins® update manager. Reference the following website to access Cummins® update manager.

Note : <https://www.cummins.com/support/digital-products-and-services-support>
(<https://www.cummins.com/support/digital-products-and-services-support>)

Expert Diagnostic System (EDS)

The EDS troubleshooting tool is available to fully support troubleshooting requirements for A8.5 CM2670 L153B engines.

Engine Ratings

Table 2, Engine Ratings				
Control Parts List (CPL)	Power Kw [hp] at Governed Speed rpm	Peak Power Kw [hp] at rpm	Peak Torque N·m [ft-lb] at rpm	Rating Type
6235	206 [276] at 1900	206 [276] at 1900	1300 [959] at 900	Intermittent
6235	235 [316] at 1900	235 [316] at 1900	1350 [996] at 900	Intermittent
6235	265 [355] at 1900	265 [355] at 1900	1500 [1106] at 1000	Intermittent
6235	265 [355] at 1900	265 [355] at 1900	1800 [1328] at 1100	Intermittent
6235	279 [375] at 1900	279 [375] at 1900	1800 [1328] at 1100	Intermittent
6235	235 [316] at 1900	235 [316] at 1900	1500 [1106] at 1000	Intermittent
6235	294 [394] at 1900	294 [394] at 1900	1800 [1328] at 1100	Intermittent

Document History

Date	Details
2025-2-12	Module Created