



Technical Service Bulletin: TSB170108

Released Date: 23-Oct-2017

Single Module Aftertreatment Selective Catalytic Reduction (SCR) Insulation Heat Shield Cracking

Single Module Aftertreatment Selective Catalytic Reduction (SCR) Insulation Heat Shield Cracking

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- X15 CM2350 X114B
- X15 CM2350 X116B

Issue

Cracks are found on single module aftertreatment selective catalytic reduction (SCR) insulation heat shields.



Figure 1, Aftertreatment SCR Insulation Heat Shield Cracking.



Figure 1, Aftertreatment SCR Insulation Heat Shield Cracking.

Resolution

Never replace an aftertreatment SCR for insulation heat shield cracking. Aftertreatment SCR insulation heat shield cracking does **not** impact emissions or engine operation and is an aesthetic issue **only**.

Document History

Date	Details
2017-10-9	Module Created

Last Modified: 23-Oct-2017
