



Technical Service Bulletin

Technical Service Bulletin: TSB200003

Released Date: 16-Jun-2020

Introducing XPI Injector and High-Pressure Fuel Connector Kits

Introducing XPI Injector and High-Pressure Fuel Connector Kits

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISC CM2150
- ISL CM2150
- ISC8.3 CM2250
- ISL9 CM2250
- ISL9 CM2350 L101
- ISL9 CM2350 L111
- L9 CM2350 L116B
- L9 CM2350 L119B
- QSL9 CM850 (CM2850)
- QSL9 M CM2250 L106
- ISX15 CM2250 SN
- ISX15 CM2250
- ISX15 CM2350 X101
- X15 CM2350 X114B
- X15 CM2350 X116B
- QSX15 CM2350 X105

Description of Change

Starting January 2020, XPI injectors for the aforementioned engines will be offered in kits that include the required high-pressure fuel connector. This means each injector kit will contain (1) injector and (1) high-pressure fuel connector as shown in Table 1 below.

High-pressure fuel connectors will still be offered for sale individually, however, the aforementioned injectors will only be sold in the corresponding kits.

Reason for Change

This is a product offering enhancement that is driven by customer feedback related to ease of repair. These kits will ensure that each injector replacement event now gets the required high-pressure fuel connector without the repair location having to identify the part number and place a separate order.

Service Instructions

This TSB does not affect any service procedures.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Injector Kit Content Summary

Kit Part Number	Injector Part Number	High-Pressure Fuel Connector Part Number
557940100	287207600	287228800
557940100PX	287207600PX	
557940300	287212700	287228800
557940300PX	287212700PX	
557940500	287276500	287228800
557940500PX	287276500PX	
557940700	287206800	287228800
557940700PX	287206800PX	
557940900	287233100	287228800
557940900PX	287233100PX	
557941100PX	287262100NX	287228800
557941300	430704500	287228800
557941300PX	430704500PX	
557941500	289492000	289482900
557941500PX	289492000PX	
557941700	287240500	289482900
557941700PX	287240500PX	
557941900	289732000	289482900
557941900PX	289732000PX	
557942100	432714700	289482900
557942100PX	432714700PX	

Document History

Date	Details
2020-1-8	Module Created

Date	Details
2020-6-16	Removing part numbers: 557941100, 287262100, 557942300, 430721700, 557942300PX, and 430721700PX.

Last Modified: 16-Jun-2020
