



Technical Service Bulletin

Technical Service Bulletin: TSB230202

Released Date: 23-Oct-2023

New Prestolite™ Starting Motor Interference with Aftertreatment Intake NOx Sensor Bracket: Engine Will Not Crank or Cranks Slowly

New Prestolite™ Starting Motor Interference with Aftertreatment Intake NOx Sensor Bracket: Engine Will Not Crank or Cranks Slowly

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISX15 CM2350 X101
- QSX15 CM2350 X105
- QSX15 CM2350 X106
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2450 X124B
- X15 CM2450 X134B

Issue Summary

Symptom:

- Interference between new Prestolite™ M128 starting motor and aftertreatment intake NOx sensor bracket

Root Cause:

- Flywheel housing options FH11089, FH11099, FH11106, or FH11121 are **not** compatible with the Prestolite™ Starter M128, Part Number 5575820, and the aftertreatment intake NOx sensor bracket, Part Number 3687330.

Verification

- Verify the engine is equipped with flywheel housing options FH11089, FH11099, FH11106, or FH11121
- Prestolite™ M128 Starter, Part Number 5575820

- If replacing a Prestolite™ M125 starting motor, Part Number 3690809, with superseding Prestolite™ M128 starting motor, Part Number 5575820, and one of the above FH options is present, there will be a hard interference with the aftertreatment NOx sensor bracket, Part Number 3687330. In this instance aftertreatment NOx sensor bracket, Part Number 3687330, will need to be replaced with aftertreatment NOx sensor bracket, Part Number 5725892.

Resolution

Order and install new aftertreatment intake NOx sensor bracket in Table 1 below.

See corresponding Service Manual. Reference Procedure 011-079 in Section 11.

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
SUPPORT, MODULE	3687330	No	No	5725892

Document History

Date	Details
2023-10-17	Module Created