



Technical Service Bulletin

Technical Service Bulletin: TSB250097

Released Date: 24-Feb-2026

New Fuel Pump Part Numbers

New Fuel Pump Part Numbers

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISX12 CM2350 X102
- ISX12/ISX11.9 CM2250
- ISX15 CM2250
- ISX15 CM2250 SN
- ISX15 CM2350 X101
- QSX15 CM2250 ECF
- QSX15 CM2350 X105
- QSX15 CM2350 X106
- QSX15 CM2350 X118
- X15 CM2350 X114B
- X15 CM2350 X125M
- X15 CM2350 X130C
- X15 CM2350 X131
- X15 CM2350 X132
- X15 CM2350 X139C
- X15 CM2350 X140C
- X15 CM2450 X124B

Description of Change

- New fuel pumps are offered as optional service parts because of future obsolescence of certain fuel pump part numbers shown in Table 1.
- No change in fuel pump form, fit, and function.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Fuel Pump	4359487	Yes	No	5491785
		Yes	No	4359487PX
	4359489	Yes	No	5491784
		Yes	No	4359489PX
	4359490	Yes	No	5491786
		Yes	No	4359490PX
	4359548	Yes	No	5594376
		Yes	No	4359548PX
	4307482	Yes	No	5491782
		Yes	No	4307482RX

Service Instructions

If the existing part number is replaced with a new part number in Table 1, see Technical Service Bulletin, Low Pressure Gear Pump and Lines, TSB200140.

Part Inventory Action

Use existing part number inventory before using the new part number.

Document History

Date	Details
2025-5-6	Module Created
2026-2-24	Added models to Product Affected