



Technical Service Bulletin: TSB260094

Released Date: 30-Jun-2026

Intake Air throttle/ Air Shut-off Valve Intermediate gear

Intake Air throttle/ Air Shut-off Valve Intermediate gear

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- ISX12 CM2350 X102
- ISX15 CM2350 X101
- X12 CM2350 X119B
- X12 CM2450 X137B
- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2350 X123B
- X15 CM2350 X129B
- X15 CM2350 X129B
- X15 CM2350 X131
- X15 CM2350 X132C
- X15 CM2450 X124B
- X15 CM2450 X134B
- X15 CM2450 X142B
- X15 CM2450 X153B
- X15 CM2450 X154B
- X15 CM2450 X155B

Description of Change

Intake air throttle/air shut-off valve intermediate gear and pin material are being changed to meet duty cycle and durability needs.

Reason for Change

Supplier material change for increased durability.

Service Instructions

Use updated part numbers for replacement.

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Intake Air Throttle (IAT)	3691162	No	No	6577810
Air Shut-off Valve (ASO)	3691218	No	No	6582349

Document History

Date	Details
2026-6-29	Module Created