

Manual Change History (5411184) X15 CM2350 X114B Fault Code Troubleshooting Manual Change History

Date	09-Aug-2026
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001335
Solution Title	Lubricating oil cooler is leaking
Update Reason	Solution Removed
Date	31-Jul-2026
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00012704
Solution Title	Air compressor air pressure relief valve is not operating correctly
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012642
Solution Title	Air intake system inspection
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012642
Solution Title	Air intake system inspection
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000984
Solution Title	Aftertreatment diesel particulate filter differential/outlet pressure sensor open circuit check
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011453
Solution Title	Aftertreatment diesel particulate filter differential/outlet pressure sensor circuit pin to pin short
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011452
Solution Title	Aftertreatment diesel particulate filter differential/outlet pressure sensor open circuit check
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011453
Solution Title	Aftertreatment diesel particulate filter differential/outlet pressure sensor circuit pin to pin short
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011249
Solution Title	Aftertreatment intake NOx sensor open circuit check
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011251
Solution Title	Aftertreatment intake NOx sensor circuit pin to ground short
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011284
Solution Title	Aftertreatment outlet NOx sensor open circuit
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011285
Solution Title	Aftertreatment outlet NOx sensor circuit pin to ground short
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012642
Solution Title	Air intake system inspection
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001555
Solution Title	Aftertreatment diesel particulate filter differential/outlet pressure sensor open circuit check
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001585
Solution Title	Aftertreatment diesel particulate filter outlet pressure sensor pin shorted to another pin
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001555
Solution Title	Aftertreatment diesel particulate filter differential/outlet pressure sensor open circuit check
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00002790
Solution Title	Aftertreatment diesel particulate filter differential/outlet pressure sensor circuit pin to ground short
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010356
Solution Title	EGR cooler plugged or restricted
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment Intake Gas Sensor Heater - Current Below Normal or Open Circuit
Solution Number	S00011249
Solution Title	Aftertreatment intake NOx sensor open circuit check
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment Intake Gas Sensor Heater - Current Below Normal or Open Circuit
Solution Number	S00011251
Solution Title	Aftertreatment intake NOx sensor circuit pin to ground short
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Rate of Change
Solution Number	S00011284
Solution Title	Aftertreatment outlet NOx sensor open circuit
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Rate of Change
Solution Number	S00011285
Solution Title	Aftertreatment outlet NOx sensor circuit pin to ground short
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00011249
Solution Title	Aftertreatment intake NOx sensor open circuit check
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00011251
Solution Title	Aftertreatment intake NOx sensor circuit pin to ground short
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Rate of Change
Solution Number	S00011249
Solution Title	Aftertreatment intake NOx sensor open circuit check
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Rate of Change
Solution Number	S00011251
Solution Title	Aftertreatment intake NOx sensor circuit pin to ground short
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00011249
Solution Title	Aftertreatment intake NOx sensor open circuit check
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00011251
Solution Title	Aftertreatment intake NOx sensor circuit pin to ground short
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00011452
Solution Title	Aftertreatment diesel particulate filter differential/outlet pressure sensor open circuit check
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00011453
Solution Title	Aftertreatment diesel particulate filter differential/outlet pressure sensor circuit pin to pin short
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00011452
Solution Title	Aftertreatment diesel particulate filter differential/outlet pressure sensor open circuit check
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00002790
Solution Title	Aftertreatment diesel particulate filter differential/outlet pressure sensor circuit pin to ground short
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00011453
Solution Title	Aftertreatment diesel particulate filter differential/outlet pressure sensor circuit pin to pin short
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Self- Diagnosis - Abnormal Rate of Change
Solution Number	S00011284
Solution Title	Aftertreatment outlet NOx sensor open circuit
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Self- Diagnosis - Abnormal Rate of Change
Solution Number	S00011285
Solution Title	Aftertreatment outlet NOx sensor circuit pin to ground short
Update Reason	Solution Added
Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00011249
Solution Title	Aftertreatment intake NOx sensor open circuit check
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00011251
Solution Title	Aftertreatment intake NOx sensor circuit pin to ground short
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Intake NOx - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011249
Solution Title	Aftertreatment intake NOx sensor open circuit check
Update Reason	Solution Added

Date	31-Jul-2026
Fault Code / Symptom	Aftertreatment 1 Intake NOx - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011251
Solution Title	Aftertreatment intake NOx sensor circuit pin to ground short
Update Reason	Solution Added

Date	12-Jul-2026
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00012793
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added

Date	12-Jul-2026
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00012793
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added

Date	12-Jul-2026
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00012793
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added
Date	12-Jul-2026
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00012793
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added
Date	12-Jul-2026
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00012793
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added
Date	12-Jul-2026
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00012793
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added
Date	04-Jul-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	04-Jul-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012646
Solution Title	Service Bulletin is available
Update Reason	Solution Added
Date	04-Jul-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012788
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	04-Jul-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012643
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added
Date	04-Jul-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012789
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Added
Date	04-Jul-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012790
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Added

Date	04-Jul-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012791
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	20-Jun-2026
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006422
Solution Title	Ice buildup in the air system components
Update Reason	Solution Reordered
Date	20-Jun-2026
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006422
Solution Title	Ice buildup in the air system components
Update Reason	Solution Modified
Date	20-Jun-2026
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006422
Solution Title	Ice buildup in the air system components
Update Reason	Solution Reordered
Date	20-Jun-2026
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006422
Solution Title	Ice buildup in the air system components
Update Reason	Solution Modified
Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder 1 - Condition Exists
Solution Number	S00012775
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added

Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder 1 - Condition Exists
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed
Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder 2 - Condition Exists
Solution Number	S00012775
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added
Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder 2 - Condition Exists
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed
Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder 3 - Condition Exists
Solution Number	S00012775
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added
Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder 3 - Condition Exists
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed
Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder 4 - Condition Exists
Solution Number	S00012775
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added

Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder 4 - Condition Exists
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed
Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder 5 - Condition Exists
Solution Number	S00012775
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added
Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder 5 - Condition Exists
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed
Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder 6 - Condition Exists
Solution Number	S00012775
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added
Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder 6 - Condition Exists
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed
Date	31-May-2026
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Condition Exists
Solution Number	S00012775
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added

Date	31-May-2026
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Condition Exists
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed

Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00012774
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added

Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed

Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00012774
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added

Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed

Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00012774
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added

Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed

Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00012774
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added

Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed

Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00012774
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added

Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed
Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00012774
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added
Date	31-May-2026
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed
Date	31-May-2026
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00012775
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added
Date	31-May-2026
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed
Date	17-May-2026
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00012248
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Reordered

Date	17-May-2026
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00012248
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Modified
Date	01-May-2026
Fault Code / Symptom	Engine Brake Slow Activation
Solution Number	S00011398
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered
Date	01-May-2026
Fault Code / Symptom	Engine Brake Slow Activation
Solution Number	S00011398
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified
Date	01-May-2026
Fault Code / Symptom	Engine Brake Weak
Solution Number	S00011398
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered
Date	01-May-2026
Fault Code / Symptom	Engine Brake Weak
Solution Number	S00011398
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified
Date	01-May-2026
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00011398
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered

Date	01-May-2026
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00011398
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified
Date	01-May-2026
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00011398
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered
Date	01-May-2026
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00011398
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified
Date	22-Mar-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000787
Solution Title	Aftertreatment diesel particulate filter temperature sensor interface module circuit pin to ground short
Update Reason	Solution Removed
Date	08-Mar-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008993
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered

Date	08-Mar-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008993
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified
Date	08-Mar-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00008993
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered
Date	08-Mar-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00008993
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified
Date	08-Mar-2026
Fault Code / Symptom	Maintain ECU Power Lamp Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001000
Solution Title	Voltage check at the engine control unit power lamp to block ground
Update Reason	Solution Removed
Date	08-Mar-2026
Fault Code / Symptom	Maintain ECU Power Lamp Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001000
Solution Title	Voltage check at the engine control unit power lamp to block ground
Update Reason	Solution Removed

Date	22-Feb-2026
Fault Code / Symptom	Engine Brake Does Not Activate
Solution Number	S00001316
Solution Title	Engine brake assembly leaking oil
Update Reason	Solution Removed
Date	22-Feb-2026
Fault Code / Symptom	Engine Brake Slow Activation
Solution Number	S00001316
Solution Title	Engine brake assembly leaking oil
Update Reason	Solution Removed
Date	22-Feb-2026
Fault Code / Symptom	Engine Brake Stuck On
Solution Number	S00001316
Solution Title	Engine brake assembly leaking oil
Update Reason	Solution Removed
Date	22-Feb-2026
Fault Code / Symptom	Engine Brake Weak
Solution Number	S00001316
Solution Title	Engine brake assembly leaking oil
Update Reason	Solution Removed
Date	08-Feb-2026
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Will Not Complete
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	08-Feb-2026
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Will Not Complete
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	08-Feb-2026
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	08-Feb-2026
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	01-Feb-2026
Fault Code / Symptom	Fuel Injector Performance Test Will Not Start
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	01-Feb-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Reordered

Date	01-Feb-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Modified

Date	01-Feb-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Reordered

Date	01-Feb-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Modified

Date	01-Feb-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Reordered

Date	01-Feb-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Modified
Date	01-Feb-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Reordered
Date	01-Feb-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Modified
Date	01-Feb-2026
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	01-Feb-2026
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	01-Feb-2026
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Reordered
Date	01-Feb-2026
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Modified
Date	01-Feb-2026
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Reordered
Date	01-Feb-2026
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Modified
Date	01-Feb-2026
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	01-Feb-2026
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	01-Feb-2026
Fault Code / Symptom	Engine Crankshaft Speed/Position - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000443
Solution Title	Engine control module calibration revision history check
Update Reason	Solution Added
Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	01-Feb-2026
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	01-Feb-2026
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	01-Feb-2026
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	01-Feb-2026
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	01-Feb-2026
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	01-Feb-2026
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	01-Feb-2026
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	01-Feb-2026
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Reordered

Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Modified

Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Reordered

Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Modified

Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009929
Solution Title	EGR leaks
Update Reason	Solution Reordered

Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009929
Solution Title	EGR leaks
Update Reason	Solution Modified

Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	01-Feb-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	01-Feb-2026
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	01-Feb-2026
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	26-Jan-2026
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012663
Solution Title	Lubricating oil pressure sensor stuck in-range
Update Reason	Solution Added
Date	26-Jan-2026
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000342
Solution Title	Lubricating oil pressure sensor stuck in-range
Update Reason	Solution Removed

Date	26-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	26-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	26-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012661
Solution Title	Fault Code 1921 requires that ALL solutions be performed
Update Reason	Solution Added
Date	26-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012662
Solution Title	Fault Code 2639 requires that ALL solutions be performed
Update Reason	Solution Added
Date	26-Jan-2026
Fault Code / Symptom	Aftertreatment Intake Gas Sensor Heater - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	26-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	26-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	26-Jan-2026
Fault Code / Symptom	Aftertreatment SCR Operator Inducement - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	26-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000603
Solution Title	Fault Code 1922 requires that ALL solutions be performed
Update Reason	Solution Added
Date	18-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000645
Solution Title	Fault Code 1981 requires that ALL solutions be performed
Update Reason	Solution Added

Date	18-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jan-2026
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000792
Solution Title	Fault Code 3375 requires that ALL solutions be performed
Update Reason	Solution Added
Date	18-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00003165
Solution Title	Fault Code 3376 requires that ALL solutions be performed
Update Reason	Solution Added

Date	18-Jan-2026
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Tank Empty - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jan-2026
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Jan-2026
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction System Test Did Not Pass
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	11-Jan-2026
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction System Test Will Not Complete
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	11-Jan-2026
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction System Test Will Not Start
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	11-Jan-2026
Fault Code / Symptom	Stationary Regeneration Will Not Start
Solution Number	S00012657
Solution Title	Transmission is in gear or a command on the data link is preventing the regeneration
Update Reason	Solution Added
Date	11-Jan-2026
Fault Code / Symptom	Stationary Regeneration Will Not Start
Solution Number	S00001277
Solution Title	Transmission is not in Park or Neutral which is preventing the Aftertreatment Diesel Particulate Filter Regeneration Test from starting
Update Reason	Solution Removed
Date	11-Jan-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Reordered
Date	11-Jan-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Modified
Date	11-Jan-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Reordered

Date	11-Jan-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Modified
Date	11-Jan-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Reordered
Date	11-Jan-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Modified
Date	11-Jan-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Reordered
Date	11-Jan-2026
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Modified

Date	11-Jan-2026
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Reordered

Date	11-Jan-2026
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Modified

Date	11-Jan-2026
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Reordered

Date	11-Jan-2026
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Modified

Date	11-Jan-2026
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Added

Date	11-Jan-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Reordered
Date	11-Jan-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Modified
Date	11-Jan-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Reordered
Date	11-Jan-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Modified
Date	14-Dec-2025
Fault Code / Symptom	Engine Crankshaft Speed/Position - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	14-Dec-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000787
Solution Title	Aftertreatment diesel particulate filter temperature sensor interface module circuit pin to ground short
Update Reason	Solution Reordered

Date	14-Dec-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000787
Solution Title	Aftertreatment diesel particulate filter temperature sensor interface module circuit pin to ground short
Update Reason	Solution Modified

Date	14-Dec-2025
Fault Code / Symptom	VGT Actuator Controller - Special Instructions
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Did Not Pass
Solution Number	
Solution Title	
Update Reason	Solution Set Removed

Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	
Solution Title	
Update Reason	Solution Set Removed

Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	07-Dec-2025
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012646
Solution Title	Service Bulletin is available
Update Reason	Solution Added
Date	07-Dec-2025
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012643
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added
Date	07-Dec-2025
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012313
Solution Title	Service Bulletin is available
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012646
Solution Title	Service Bulletin is available
Update Reason	Solution Added

Date	07-Dec-2025
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012643
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added
Date	07-Dec-2025
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012313
Solution Title	Service Bulletin is available
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00012645
Solution Title	Aftertreatment diesel exhaust fluid dosing unit circuit check (with chassis ground)
Update Reason	Solution Added
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012641
Solution Title	Aftertreatment Selective Catalytic Reduction System Test
Update Reason	Solution Added
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000541
Solution Title	Aftertreatment Selective Catalytic Reduction System Test
Update Reason	Solution Removed

Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000552
Solution Title	Aftertreatment diesel exhaust fluid dosing system test failed
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000867
Solution Title	Aftertreatment intake NOx sensor failed
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000567
Solution Title	Aftertreatment outlet NOx sensor - Inspection
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000566
Solution Title	Inspect both aftertreatment NOx sensors
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000565
Solution Title	Aftertreatment Selective Catalytic Reduction Catalyst Test failed
Update Reason	Solution Removed

Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00012641
Solution Title	Aftertreatment Selective Catalytic Reduction System Test
Update Reason	Solution Added
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00000541
Solution Title	Aftertreatment Selective Catalytic Reduction System Test
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00000552
Solution Title	Aftertreatment diesel exhaust fluid dosing system test failed
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00000867
Solution Title	Aftertreatment intake NOx sensor failed
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00000567
Solution Title	Aftertreatment outlet NOx sensor - Inspection
Update Reason	Solution Removed

Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00000566
Solution Title	Inspect both aftertreatment NOx sensors
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00000565
Solution Title	Aftertreatment Selective Catalytic Reduction Catalyst Test failed
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012645
Solution Title	Aftertreatment diesel exhaust fluid dosing unit circuit check (with chassis ground)
Update Reason	Solution Added
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012645
Solution Title	Aftertreatment diesel exhaust fluid dosing unit circuit check (with chassis ground)
Update Reason	Solution Added
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00012645
Solution Title	Aftertreatment diesel exhaust fluid dosing unit circuit check (with chassis ground)
Update Reason	Solution Added

Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00012641
Solution Title	Aftertreatment Selective Catalytic Reduction System Test
Update Reason	Solution Added
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00000541
Solution Title	Aftertreatment Selective Catalytic Reduction System Test
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00000552
Solution Title	Aftertreatment diesel exhaust fluid dosing system test failed
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00000867
Solution Title	Aftertreatment intake NOx sensor failed
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00000567
Solution Title	Aftertreatment outlet NOx sensor - Inspection
Update Reason	Solution Removed

Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00000566
Solution Title	Inspect both aftertreatment NOx sensors
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00000565
Solution Title	Aftertreatment Selective Catalytic Reduction Catalyst Test failed
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00012641
Solution Title	Aftertreatment Selective Catalytic Reduction System Test
Update Reason	Solution Added
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000541
Solution Title	Aftertreatment Selective Catalytic Reduction System Test
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000552
Solution Title	Aftertreatment diesel exhaust fluid dosing system test failed
Update Reason	Solution Removed

Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000867
Solution Title	Aftertreatment intake NOx sensor failed
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000567
Solution Title	Aftertreatment outlet NOx sensor - Inspection
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000566
Solution Title	Inspect both aftertreatment NOx sensors
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000565
Solution Title	Aftertreatment Selective Catalytic Reduction Catalyst Test failed
Update Reason	Solution Removed
Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012645
Solution Title	Aftertreatment diesel exhaust fluid dosing unit circuit check (with chassis ground)
Update Reason	Solution Added

Date	07-Dec-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012645
Solution Title	Aftertreatment diesel exhaust fluid dosing unit circuit check (with chassis ground)
Update Reason	Solution Added
Date	11-Nov-2025
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	02-Nov-2025
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-Nov-2025
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-Nov-2025
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Start
Solution Number	
Solution Title	
Update Reason	Solution Set Removed

Date	29-Oct-2025
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00000553
Solution Title	Verify performance complaint
Update Reason	Solution Removed
Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Did Not Pass
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00012570
Solution Title	The status of one or both of the NOx sensors is continuously invalid
Update Reason	Solution Added
Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00012571
Solution Title	Aftertreatment Intake NOx Sensor Test
Update Reason	Solution Added
Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00012572
Solution Title	Aftertreatment Outlet NOx Sensor Test
Update Reason	Solution Added

Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00012565
Solution Title	The test has stopped because engine speed is out of the desired range
Update Reason	Solution Added

Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00009032
Solution Title	Active fault codes preventing test from starting or completing
Update Reason	Solution Added

Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00012566
Solution Title	The test has stopped because the DPF outlet temperature is out of the desired range
Update Reason	Solution Added

Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00012567
Solution Title	The test has stopped or could not start because an engine brake disable request was received on the data link
Update Reason	Solution Added

Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00012568
Solution Title	The test has stopped or could not start because the vehicle is moving or a vehicle speed sensor fault code is active
Update Reason	Solution Added

Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00012569
Solution Title	The test has stopped or could not start because another feature is controlling the engine speed
Update Reason	Solution Added
Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00012567
Solution Title	The test has stopped or could not start because an engine brake disable request was received on the data link
Update Reason	Solution Added
Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00012568
Solution Title	The test has stopped or could not start because the vehicle is moving or a vehicle speed sensor fault code is active
Update Reason	Solution Added
Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00012569
Solution Title	The test has stopped or could not start because another feature is controlling the engine speed
Update Reason	Solution Added

Date	29-Oct-2025
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00005613
Solution Title	Aftertreatment diesel particulate filter differential/outlet pressure sensor stuck in-range
Update Reason	Solution Reordered
Date	29-Oct-2025
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00005613
Solution Title	Aftertreatment diesel particulate filter differential/outlet pressure sensor stuck in-range
Update Reason	Solution Modified
Date	29-Oct-2025
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 2 Circuit Frequency - Abnormal Frequency or Pulse Width or Period
Solution Number	S00000721
Solution Title	Accelerator pedal position sensor circuit pin to pin short
Update Reason	Solution Removed
Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012452
Solution Title	Aftertreatment Diesel Particulate Filter High Idle Test
Update Reason	Solution Added

Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012452
Solution Title	Aftertreatment Diesel Particulate Filter High Idle Test
Update Reason	Solution Added
Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012452
Solution Title	Aftertreatment Diesel Particulate Filter High Idle Test
Update Reason	Solution Added
Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012452
Solution Title	Aftertreatment Diesel Particulate Filter High Idle Test
Update Reason	Solution Added
Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00012452
Solution Title	Aftertreatment Diesel Particulate Filter High Idle Test
Update Reason	Solution Added

Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00012452
Solution Title	Aftertreatment Diesel Particulate Filter High Idle Test
Update Reason	Solution Added
Date	29-Oct-2025
Fault Code / Symptom	Fuel Injector Performance Test Will Not Activate
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00012468
Solution Title	Engine protection is active
Update Reason	Solution Added
Date	29-Oct-2025
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00012468
Solution Title	Engine protection is active
Update Reason	Solution Added
Date	29-Oct-2025
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00012556
Solution Title	Variable geometry turbocharger actuator is malfunctioning
Update Reason	Solution Added

Date	29-Oct-2025
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00001120
Solution Title	Variable geometry turbocharger actuator is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Did Not Pass
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Start
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Activate
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	03-Aug-2025
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00012542
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001299
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00012542
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001299
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012463
Solution Title	Only select solution titles with corresponding status messages displayed in Engine Compression and Air Handling System Test
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012468
Solution Title	Engine protection is active
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012495
Solution Title	The test could not be completed because the cranking speed is too high
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012496
Solution Title	The test could not be completed because the cranking speed is too low
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012467
Solution Title	The test was stopped or could not start because the data link connection was lost
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012479
Solution Title	The test was stopped or could not start because the EGR valve was unable to reach the commanded position
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012480
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012481
Solution Title	The test was stopped or could not start because the engine braking is active
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012505
Solution Title	Engine Brake Switch in the on position
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012504
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012482
Solution Title	The test was stopped or could not start because there is a problem with the engine position sensor or camshaft position sensor
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012483
Solution Title	Crankshaft position sensor is malfunctioning
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012484
Solution Title	Camshaft position sensor is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012485
Solution Title	The test was stopped or could not start because the intake air throttle valve was unable to reach the commanded position
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012486
Solution Title	Engine intake throttle actuator is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012487
Solution Title	The test was stopped or could not start because the parking brake is not engaged
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012497
Solution Title	The test was stopped or could not start because the PTO is engaged
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012502
Solution Title	PTO Switch in the on position
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012503
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012469
Solution Title	The test was stopped or could not start because the transmission is in gear
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012488
Solution Title	The test was stopped or could not start because the VGT actuator was unable to reach the commanded position
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	S00012489
Solution Title	Variable geometry turbocharger actuator is malfunctioning
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Knock
Solution Number	S00012514
Solution Title	Overhead component damaged
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Knock
Solution Number	S00005336
Solution Title	Overhead component damaged
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Noise
Solution Number	S00012514
Solution Title	Overhead component damaged
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Noise
Solution Number	S00005336
Solution Title	Overhead component damaged
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00012514
Solution Title	Overhead component damaged
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00005336
Solution Title	Overhead component damaged
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00012514
Solution Title	Overhead component damaged
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00005336
Solution Title	Overhead component damaged
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Overhead Noise
Solution Number	S00012431
Solution Title	Camshaft inspection
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Overhead Noise
Solution Number	S00012514
Solution Title	Overhead component damaged
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Overhead Noise
Solution Number	S00001193
Solution Title	Camshaft inspection
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Overhead Noise
Solution Number	S00005336
Solution Title	Overhead component damaged
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00012470
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00001193
Solution Title	Camshaft inspection
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00005336
Solution Title	Overhead component damaged
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00009701
Solution Title	Overhead valve lash out of adjustment
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	White Smoke
Solution Number	S00012514
Solution Title	Overhead component damaged
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	White Smoke
Solution Number	S00005336
Solution Title	Overhead component damaged
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012508
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012507
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012511
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012507
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012511
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012507
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012511
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder 1 - Condition Exists
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder 1 - Condition Exists
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder 2 - Condition Exists
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder 2 - Condition Exists
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder 3 - Condition Exists
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder 3 - Condition Exists
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder 4 - Condition Exists
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder 4 - Condition Exists
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder 5 - Condition Exists
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder 5 - Condition Exists
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder 6 - Condition Exists
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder 6 - Condition Exists
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Missing - Condition Exists
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Missing - Condition Exists
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Condition Exists
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Condition Exists
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004187
Solution Title	Aftertreatment diesel particulate filter partially obstructed or plugged
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001113
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012421
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000603
Solution Title	Fault Code 1922 requires that ALL solutions be performed
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010364
Solution Title	EGR valve is leaking internally
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00004545
Solution Title	Aftertreatment diesel particulate filter is malfunctioning
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000645
Solution Title	Fault Code 1981 requires that ALL solutions be performed
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00004545
Solution Title	Aftertreatment diesel particulate filter is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001113
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012507
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012511
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012512
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011387
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000733
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001370
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011102
Solution Title	Exhaust gas pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001113
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012421
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012512
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012447
Solution Title	Aftertreatment diesel particulate filter partially obstructed or plugged
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011387
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004187
Solution Title	Aftertreatment diesel particulate filter partially obstructed or plugged
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012517
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012508
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012507
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012511
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012510
Solution Title	Intake manifold pressure/temperature sensor is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009946
Solution Title	Intake manifold pressure/temperature sensor is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Cooling System Monitor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012515
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Cooling System Monitor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Cooling System Monitor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012508
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00012507
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00012511
Solution Title	Intake manifold pressure sensor stuck in- range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in- range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000792
Solution Title	Fault Code 3375 requires that ALL solutions be performed
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00004187
Solution Title	Aftertreatment diesel particulate filter partially obstructed or plugged
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00003165
Solution Title	Fault Code 3376 requires that ALL solutions be performed
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00004187
Solution Title	Aftertreatment diesel particulate filter partially obstructed or plugged
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter 1 Conditions Not Met for Active Regeneration - Condition Exists
Solution Number	S00012445
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter 1 Conditions Not Met for Active Regeneration - Condition Exists
Solution Number	S00001113
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012454
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00012445
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00001113
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012512
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011387
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00009946
Solution Title	Intake manifold pressure/temperature sensor is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00011387
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00001370
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor is malfunctioning
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00009946
Solution Title	Intake manifold pressure/temperature sensor is malfunctioning
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Predictive Cruise Control State - Abnormal Update Rate
Solution Number	S00006503
Solution Title	Navigation control module check
Update Reason	Solution Reordered
Date	03-Aug-2025
Fault Code / Symptom	Predictive Cruise Control State - Abnormal Update Rate
Solution Number	S00006503
Solution Title	Navigation control module check
Update Reason	Solution Modified
Date	03-Aug-2025
Fault Code / Symptom	Navigation Control Module - Abnormal Update Rate
Solution Number	S00006503
Solution Title	Navigation control module check
Update Reason	Solution Reordered

Date	03-Aug-2025
Fault Code / Symptom	Navigation Control Module - Abnormal Update Rate
Solution Number	S00006503
Solution Title	Navigation control module check
Update Reason	Solution Modified
Date	03-Aug-2025
Fault Code / Symptom	Navigation Control Module - Abnormal Update Rate
Solution Number	S00007719
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Reordered
Date	03-Aug-2025
Fault Code / Symptom	Navigation Control Module - Abnormal Update Rate
Solution Number	S00007719
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Modified
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00012453
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00012499
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012430
Solution Title	Engine Compression and Air Handling System Test
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Activate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Compression and Air Handling System Test Will Not Complete
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012490
Solution Title	Turbocharger speed sensor voltage check
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012491
Solution Title	Turbocharger speed sensor open circuit check
Update Reason	Solution Added

Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012493
Solution Title	Turbocharger speed sensor circuit pin to ground short
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012492
Solution Title	Turbocharger speed sensor circuit pin to pin short
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000654
Solution Title	Turbocharger speed sensor voltage check
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000653
Solution Title	Turbocharger speed sensor open circuit check
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000673
Solution Title	Turbocharger speed sensor circuit pin to ground short
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000652
Solution Title	Turbocharger speed sensor circuit pin to pin short
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000654
Solution Title	Turbocharger speed sensor voltage check
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000660
Solution Title	Turbocharger speed sensor voltage check at the engine control module
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000653
Solution Title	Turbocharger speed sensor open circuit check
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000673
Solution Title	Turbocharger speed sensor circuit pin to ground short
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000652
Solution Title	Turbocharger speed sensor circuit pin to pin short
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011162
Solution Title	Crankcase breather restriction check (external)
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011163
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000767
Solution Title	EGR differential pressure sensor voltage supply check
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000366
Solution Title	EGR differential pressure sensor circuit response
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000767
Solution Title	EGR differential pressure sensor voltage supply check
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001121
Solution Title	EGR differential pressure sensor circuit response
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012490
Solution Title	Turbocharger speed sensor voltage check
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012491
Solution Title	Turbocharger speed sensor open circuit check
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012493
Solution Title	Turbocharger speed sensor circuit pin to ground short
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012492
Solution Title	Turbocharger speed sensor circuit pin to pin short
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000654
Solution Title	Turbocharger speed sensor voltage check
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000653
Solution Title	Turbocharger speed sensor open circuit check
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000673
Solution Title	Turbocharger speed sensor circuit pin to ground short
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000652
Solution Title	Turbocharger speed sensor circuit pin to pin short
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	03-Aug-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00012252
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012252
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00012252
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Turbocharger 1 Speed - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00012491
Solution Title	Turbocharger speed sensor open circuit check
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Turbocharger 1 Speed - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00012493
Solution Title	Turbocharger speed sensor circuit pin to ground short
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Engine Turbocharger 1 Speed - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000653
Solution Title	Turbocharger speed sensor open circuit check
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Turbocharger 1 Speed - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000673
Solution Title	Turbocharger speed sensor circuit pin to ground short
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Pass
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Pass
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00012456
Solution Title	Only select solution titles with corresponding status messages displayed in Aftertreatment Intake NOx Sensor Test
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00010611
Solution Title	Active fault codes preventing test from activating or completing
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00010464
Solution Title	The test has stopped due to a failure detected with the NOx sensor's signal
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00010669
Solution Title	Low battery voltage
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00010613
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00010303
Solution Title	Aftertreatment power relay voltage check
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00010305
Solution Title	Aftertreatment power relay resistance check
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00010514
Solution Title	Aftertreatment intake NOx sensor circuit check
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00010368
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00011196
Solution Title	Circuit Load Test
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00010618
Solution Title	Aftertreatment intake NOx sensor has carbon buildup
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00012458
Solution Title	Only select solution titles with corresponding status messages displayed in Aftertreatment Outlet NOx Sensor Test
Update Reason	Solution Added
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00010611
Solution Title	Active fault codes preventing test from activating or completing
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00010463
Solution Title	The test has stopped due to a failure detected with the NOx sensor's signal
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00010669
Solution Title	Low battery voltage
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00010616
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00010303
Solution Title	Aftertreatment power relay voltage check
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00010305
Solution Title	Aftertreatment power relay resistance check
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00010333
Solution Title	Aftertreatment outlet NOx sensor circuit check
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00010368
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00011196
Solution Title	Circuit Load Test
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00010610
Solution Title	Aftertreatment outlet NOx sensor has carbon buildup
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00011715
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00011715
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00011715
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00011715
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00011715
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00011715
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed

Date	03-Aug-2025
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00011715
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed
Date	21-Jul-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00012324
Solution Title	The test cannot start or has stopped because engine speed has been detected.
Update Reason	Solution Added
Date	21-Jul-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00012325
Solution Title	The test has aborted due to datalink loss of communication
Update Reason	Solution Added
Date	21-Jul-2025
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00012450
Solution Title	Aftertreatment Intake NOx Sensor test inhibited due to active fault codes
Update Reason	Solution Added
Date	21-Jul-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00012369
Solution Title	The test has aborted due to datalink loss of communication
Update Reason	Solution Added

Date	21-Jul-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00012451
Solution Title	Aftertreatment Outlet NOx Sensor test inhibited due to active fault codes
Update Reason	Solution Added

Date	21-Jul-2025
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00012332
Solution Title	The test cannot start or has stopped because engine speed has been detected.
Update Reason	Solution Added

Date	21-Jul-2025
Fault Code / Symptom	External Lubricating Oil Leak
Solution Number	S00012455
Solution Title	Fluorescent Dye Tracer Test (lubricating oil)
Update Reason	Solution Added

Date	21-Jul-2025
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00012455
Solution Title	Fluorescent Dye Tracer Test (lubricating oil)
Update Reason	Solution Added

Date	21-Jul-2025
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00012455
Solution Title	Fluorescent Dye Tracer Test (lubricating oil)
Update Reason	Solution Added

Date	21-Jul-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Jul-2025
Fault Code / Symptom	Air Handling Performance Test Will Not Complete
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	13-Jul-2025
Fault Code / Symptom	Air Handling Performance Test Will Not Start
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	06-Jul-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011006
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	06-Jul-2025
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	06-Jul-2025
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	06-Jul-2025
Fault Code / Symptom	EGR Valve Control Circuit - Current Below Normal or Open Circuit
Solution Number	S00011273
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	06-Jul-2025
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	06-Jul-2025
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	06-Jul-2025
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	08-Jun-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Voltage Above Normal or Shorted to High Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	08-Jun-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012421
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	08-Jun-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012421
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	08-Jun-2025
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00012420
Solution Title	Aftertreatment Intake NOx Sensor Test
Update Reason	Solution Added

Date	08-Jun-2025
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000622
Solution Title	Fault Code 3232 triggered by a malfunction in the J1939 data link with multiple OEM fault codes
Update Reason	Solution Removed
Date	08-Jun-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	08-Jun-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	08-Jun-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	08-Jun-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed

Date	08-Jun-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Above Normal or Shorted to High Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	08-Jun-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	08-Jun-2025
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Line Heater Relay - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	01-Jun-2025
Fault Code / Symptom	Air Handling Performance Test did not complete
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	01-Jun-2025
Fault Code / Symptom	Air Handling Performance Test did not start
Solution Number	
Solution Title	
Update Reason	Solution Set Removed

Date	01-Jun-2025
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00012390
Solution Title	EGR differential pressure sensor circuit response
Update Reason	Solution Added
Date	01-Jun-2025
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00012389
Solution Title	EGR differential pressure sensor voltage supply check
Update Reason	Solution Added
Date	01-Jun-2025
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012405
Solution Title	EGR differential pressure sensor circuit response
Update Reason	Solution Added
Date	01-Jun-2025
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012389
Solution Title	EGR differential pressure sensor voltage supply check
Update Reason	Solution Added

Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000411
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Reordered
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000411
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Modified
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00012387
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Added
Date	26-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the engine control module
Update Reason	Solution Added

Date	18-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000352
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Added
Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Reordered
Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Modified
Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Reordered
Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Modified

Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000400
Solution Title	Exhaust gas pressure sensor circuit response
Update Reason	Solution Added
Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Reordered
Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Modified
Date	04-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012382
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	Engine Intake Manifold 1 Temperature - Voltage Above Normal or Shorted to High Source
Solution Number	S00012382
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	04-May-2025
Fault Code / Symptom	Turbocharger 1 Compressor Intake Temperature Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00012382
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012382
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Voltage Above Normal or Shorted to High Source
Solution Number	S00012395
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012382
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00012382
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	04-May-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00012395
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012395
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012395
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00012382
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	04-May-2025
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012382
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00012382
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-May-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012395
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012382
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	04-May-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Above Normal or Shorted to High Source
Solution Number	S00012395
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012395
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Line Heater Relay - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012395
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00012382
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	04-May-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-May-2025
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012382
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	04-May-2025
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00012382
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed

Date	27-Apr-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	27-Apr-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed
Date	27-Apr-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	27-Apr-2025
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000352
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Removed

Date	27-Apr-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed
Date	27-Apr-2025
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	27-Apr-2025
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000400
Solution Title	Exhaust gas pressure sensor circuit response
Update Reason	Solution Removed
Date	27-Apr-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	14-Apr-2025
Fault Code / Symptom	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	06-Apr-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	06-Apr-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	06-Apr-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	06-Apr-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	06-Apr-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	06-Apr-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	06-Apr-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	06-Apr-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	06-Apr-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	06-Apr-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	30-Mar-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	24-Mar-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001906
Solution Title	Aftertreatment diesel exhaust fluid pressure sensor open circuit check
Update Reason	Solution Removed
Date	24-Mar-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001906
Solution Title	Aftertreatment diesel exhaust fluid pressure sensor open circuit check
Update Reason	Solution Removed
Date	24-Mar-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001935
Solution Title	Aftertreatment diesel exhaust fluid pressure sensor circuit pin to ground short
Update Reason	Solution Removed
Date	16-Mar-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00012343
Solution Title	Aftertreatment diesel exhaust fluid pressure sensor open circuit check
Update Reason	Solution Added

Date	16-Mar-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012343
Solution Title	Aftertreatment diesel exhaust fluid pressure sensor open circuit check
Update Reason	Solution Added
Date	16-Mar-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012361
Solution Title	Aftertreatment diesel exhaust fluid pressure sensor circuit pin to ground short
Update Reason	Solution Added
Date	16-Mar-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000852
Solution Title	Incorrect aftertreatment diesel exhaust fluid dosing valve installed
Update Reason	Solution Removed
Date	03-Mar-2025
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000690
Solution Title	Intermittent ground connection
Update Reason	Solution Added

Date	24-Feb-2025
Fault Code / Symptom	Injector Solenoid Driver Cylinder 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005157
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added

Date	24-Feb-2025
Fault Code / Symptom	Injector Solenoid Driver Cylinder 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Removed

Date	24-Feb-2025
Fault Code / Symptom	Injector Solenoid Driver Cylinder 2 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005157
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added

Date	24-Feb-2025
Fault Code / Symptom	Injector Solenoid Driver Cylinder 2 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Removed

Date	24-Feb-2025
Fault Code / Symptom	Injector Solenoid Driver Cylinder 3 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005157
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added

Date	24-Feb-2025
Fault Code / Symptom	Injector Solenoid Driver Cylinder 3 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Removed

Date	24-Feb-2025
Fault Code / Symptom	Injector Solenoid Driver Cylinder 4 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005157
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added

Date	24-Feb-2025
Fault Code / Symptom	Injector Solenoid Driver Cylinder 4 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Removed

Date	24-Feb-2025
Fault Code / Symptom	Injector Solenoid Driver Cylinder 5 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005157
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added

Date	24-Feb-2025
Fault Code / Symptom	Injector Solenoid Driver Cylinder 5 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Removed

Date	24-Feb-2025
Fault Code / Symptom	Injector Solenoid Driver Cylinder 6 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005157
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added
Date	24-Feb-2025
Fault Code / Symptom	Injector Solenoid Driver Cylinder 6 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Removed
Date	24-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000984
Solution Title	Aftertreatment DPF differential pressure sensor open circuit check
Update Reason	Solution Removed
Date	24-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011453
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed

Date	24-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011452
Solution Title	Aftertreatment DPF differential pressure sensor open circuit check
Update Reason	Solution Removed
Date	24-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011453
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	24-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001555
Solution Title	Aftertreatment DPF outlet pressure sensor open circuit check
Update Reason	Solution Removed
Date	24-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001585
Solution Title	Aftertreatment diesel particulate filter outlet pressure sensor pin shorted to another pin
Update Reason	Solution Removed

Date	24-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001555
Solution Title	Aftertreatment DPF outlet pressure sensor open circuit check
Update Reason	Solution Removed
Date	24-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00002790
Solution Title	Aftertreatment DPF outlet pressure circuit pin to ground short
Update Reason	Solution Removed
Date	24-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00011452
Solution Title	Aftertreatment DPF differential pressure sensor open circuit check
Update Reason	Solution Removed
Date	24-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00011453
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed

Date	24-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00011452
Solution Title	Aftertreatment DPF differential pressure sensor open circuit check
Update Reason	Solution Removed
Date	24-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00002790
Solution Title	Aftertreatment DPF outlet pressure circuit pin to ground short
Update Reason	Solution Removed
Date	24-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00011453
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	16-Feb-2025
Fault Code / Symptom	Sensor Supply 4 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000488
Solution Title	Sensor supply 4 voltage error due to ECM
Update Reason	Solution Removed
Date	16-Feb-2025
Fault Code / Symptom	Sensor Supply 4 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000488
Solution Title	Sensor supply 4 voltage error due to ECM
Update Reason	Solution Removed

Date	16-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	09-Feb-2025
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012313
Solution Title	Service Bulletin is available
Update Reason	Solution Added
Date	09-Feb-2025
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012313
Solution Title	Service Bulletin is available
Update Reason	Solution Added
Date	02-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	02-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	02-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Ash Load Percent - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005270
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Removed
Date	02-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	02-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00011572
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay voltage check
Update Reason	Solution Reordered
Date	02-Feb-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00011572
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay voltage check
Update Reason	Solution Modified

Date	27-Jan-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012307
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	27-Jan-2025
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002018
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	19-Jan-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	19-Jan-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	19-Jan-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed

Date	19-Jan-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	13-Jan-2025
Fault Code / Symptom	Fuel Injector Performance Test Will Not Complete
Solution Number	S00012302
Solution Title	Evaluate Fuel Injector Performance Test results
Update Reason	Solution Added
Date	13-Jan-2025
Fault Code / Symptom	Fuel Injector Performance Test Will Not Complete
Solution Number	S00003369
Solution Title	Fuel Injector Performance Test stops after a short period of time
Update Reason	Solution Removed
Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Reordered
Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Modified

Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Reordered
Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Modified
Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Reordered
Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Modified
Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Reordered

Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Modified

Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Reordered

Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Modified

Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Reordered

Date	13-Jan-2025
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Internal actuator wiring harness check
Update Reason	Solution Modified

Date	05-Jan-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00012282
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	05-Jan-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012282
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	05-Jan-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012282
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	05-Jan-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000435
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	05-Jan-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000434
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	05-Jan-2025
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012282
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	08-Dec-2024
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Out of Calibration
Solution Number	S00001147
Solution Title	Variable geometry turbocharger actuator calibration incorrect
Update Reason	Solution Reordered
Date	08-Dec-2024
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Out of Calibration
Solution Number	S00001147
Solution Title	Variable geometry turbocharger actuator calibration incorrect
Update Reason	Solution Modified
Date	03-Nov-2024
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	03-Nov-2024
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	27-Oct-2024
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000484
Solution Title	Radiator shutters malfunctioning (if equipped)
Update Reason	Solution Removed

Date	27-Oct-2024
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000484
Solution Title	Radiator shutters malfunctioning (if equipped)
Update Reason	Solution Removed

Date	27-Oct-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000144
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	27-Oct-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000145
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	27-Oct-2024
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000484
Solution Title	Radiator shutters malfunctioning (if equipped)
Update Reason	Solution Removed

Date	21-Oct-2024
Fault Code / Symptom	Coolant in the Lubricating Oil
Solution Number	S00012259
Solution Title	EGR cooler pressure test
Update Reason	Solution Added
Date	21-Oct-2024
Fault Code / Symptom	Internal Coolant Leak
Solution Number	S00012259
Solution Title	EGR cooler pressure test
Update Reason	Solution Added
Date	21-Oct-2024
Fault Code / Symptom	Lubricating Oil Level High
Solution Number	S00012259
Solution Title	EGR cooler pressure test
Update Reason	Solution Added
Date	21-Oct-2024
Fault Code / Symptom	White Smoke
Solution Number	S00012259
Solution Title	EGR cooler pressure test
Update Reason	Solution Added
Date	06-Oct-2024
Fault Code / Symptom	Engine Knock
Solution Number	S00005035
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	06-Oct-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00005035
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed

Date	06-Oct-2024
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00011059
Solution Title	Service Bulletin is available
Update Reason	Solution Added
Date	06-Oct-2024
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00000897
Solution Title	Oil consumption related to high blowby
Update Reason	Solution Removed
Date	06-Oct-2024
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00005035
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	06-Oct-2024
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00011059
Solution Title	Service Bulletin is available
Update Reason	Solution Added
Date	06-Oct-2024
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00001296
Solution Title	Blowby check for power cylinder components
Update Reason	Solution Removed
Date	06-Oct-2024
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00005035
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed

Date	30-Sep-2024
Fault Code / Symptom	Air Handling Performance Test did not pass
Solution Number	S00012253
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	30-Sep-2024
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00012248
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Added
Date	30-Sep-2024
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00001983
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	30-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00012252
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	30-Sep-2024
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012252
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	30-Sep-2024
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00012252
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00012238
Solution Title	Aftertreatment diesel exhaust fluid connections are reversed
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00012187
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00012188
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line check
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00012189
Solution Title	Aftertreatment diesel exhaust fluid dosing unit inlet connector screen check
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00000664
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012238
Solution Title	Aftertreatment diesel exhaust fluid connections are reversed
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012187
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012188
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line check
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012189
Solution Title	Aftertreatment diesel exhaust fluid dosing unit inlet connector screen check
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000664
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Removed

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012238
Solution Title	Aftertreatment diesel exhaust fluid connections are reversed
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012187
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012188
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line check
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012189
Solution Title	Aftertreatment diesel exhaust fluid dosing unit inlet connector screen check
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000664
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Removed

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012238
Solution Title	Aftertreatment diesel exhaust fluid connections are reversed
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012187
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012188
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line check
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012189
Solution Title	Aftertreatment diesel exhaust fluid dosing unit inlet connector screen check
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000664
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012238
Solution Title	Aftertreatment diesel exhaust fluid connections are reversed
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012187
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012188
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line check
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012189
Solution Title	Aftertreatment diesel exhaust fluid dosing unit inlet connector screen check
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000664
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012238
Solution Title	Aftertreatment diesel exhaust fluid connections are reversed
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012187
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012188
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line check
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012189
Solution Title	Aftertreatment diesel exhaust fluid dosing unit inlet connector screen check
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000664
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Removed

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012238
Solution Title	Aftertreatment diesel exhaust fluid connections are reversed
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012187
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012188
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line check
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012189
Solution Title	Aftertreatment diesel exhaust fluid dosing unit inlet connector screen check
Update Reason	Solution Added

Date	23-Sep-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000664
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Removed

Date	09-Sep-2024
Fault Code / Symptom	Air Handling Performance Test did not pass
Solution Number	S00008934
Solution Title	The EGR differential pressure reading is lower than expected
Update Reason	Solution Removed

Date	09-Sep-2024
Fault Code / Symptom	Air Handling Performance Test did not pass
Solution Number	S00008944
Solution Title	EGR differential pressure sensor flow port check
Update Reason	Solution Removed

Date	09-Sep-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000217
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	09-Sep-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000216
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	26-Aug-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	26-Aug-2024
Fault Code / Symptom	Engine Decelerates Slowly
Solution Number	S00003094
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	26-Aug-2024
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00000672
Solution Title	Aftertreatment diesel exhaust fluid dosing unit suction test
Update Reason	Solution Added
Date	26-Aug-2024
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00000858
Solution Title	Aftertreatment diesel exhaust fluid dosing unit return circuit check
Update Reason	Solution Added
Date	26-Aug-2024
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00002910
Solution Title	Aftertreatment diesel exhaust fluid dosing system cleaning
Update Reason	Solution Added

Date	26-Aug-2024
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00000732
Solution Title	Aftertreatment diesel exhaust fluid dosing unit intake restriction
Update Reason	Solution Added
Date	19-Aug-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00012091
Solution Title	Fuel level check
Update Reason	Solution Added
Date	11-Aug-2024
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Aug-2024
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Aug-2024
Fault Code / Symptom	Air Handling Performance Test did not pass
Solution Number	S00012110
Solution Title	The EGR differential pressure reading is lower than expected
Update Reason	Solution Added

Date	04-Aug-2024
Fault Code / Symptom	Air Handling Performance Test did not pass
Solution Number	S00012109
Solution Title	EGR differential pressure sensor flow port check
Update Reason	Solution Added
Date	29-Jul-2024
Fault Code / Symptom	Turbocharger 1 Compressor Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012098
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Added
Date	22-Jul-2024
Fault Code / Symptom	Engine Speed Surges
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	22-Jul-2024
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000689
Solution Title	Incorrect base engine timing
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000689
Solution Title	Incorrect base engine timing
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	22-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	22-Jul-2024
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	22-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	22-Jul-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Added

Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Added

Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	22-Jul-2024
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00000689
Solution Title	Incorrect base engine timing
Update Reason	Solution Added
Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	22-Jul-2024
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009950
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	14-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	14-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	14-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	14-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	14-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	14-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	14-Jul-2024
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	14-Jul-2024
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009929
Solution Title	EGR leaks
Update Reason	Solution Removed
Date	14-Jul-2024
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009948
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	14-Jul-2024
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	14-Jul-2024
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed

Date	14-Jul-2024
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	14-Jul-2024
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009932
Solution Title	Variable Geometry Turbocharger Hysteresis Test
Update Reason	Solution Removed
Date	14-Jul-2024
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009946
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00012089
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Added
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00011101
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Removed

Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00012087
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Added
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00010492
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Removed
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012090
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Added
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011101
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Removed
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012088
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Added

Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010492
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Removed
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00012082
Solution Title	Aftertreatment diesel exhaust fluid quality sensor voltage check
Update Reason	Solution Added
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00010298
Solution Title	Aftertreatment diesel exhaust fluid quality sensor voltage check
Update Reason	Solution Removed
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00012085
Solution Title	Aftertreatment DPF temperature sensor module voltage check
Update Reason	Solution Added
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00010338
Solution Title	Aftertreatment DPF temperature sensor module voltage check
Update Reason	Solution Removed

Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00012078
Solution Title	Aftertreatment SCR temperature sensor module voltage check
Update Reason	Solution Added
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000919
Solution Title	Aftertreatment SCR temperature sensor module voltage check
Update Reason	Solution Removed
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010338
Solution Title	Aftertreatment DPF temperature sensor module voltage check
Update Reason	Solution Removed
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010303
Solution Title	Aftertreatment power relay voltage check
Update Reason	Solution Removed

Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010305
Solution Title	Aftertreatment power relay resistance check
Update Reason	Solution Removed
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010339
Solution Title	Aftertreatment DPF temperature sensor module circuit check
Update Reason	Solution Removed
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010368
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Removed
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00012079
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor voltage check
Update Reason	Solution Added
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00000969
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor voltage check
Update Reason	Solution Removed

Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00012080
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor voltage check
Update Reason	Solution Added
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00000988
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor voltage check
Update Reason	Solution Removed
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00012075
Solution Title	Aftertreatment particulate matter sensor voltage check
Update Reason	Solution Added
Date	07-Jul-2024
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00000717
Solution Title	Aftertreatment particulate matter sensor voltage check
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Blue Smoke
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered

Date	24-Jun-2024
Fault Code / Symptom	Blue Smoke
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	24-Jun-2024
Fault Code / Symptom	Blue Smoke
Solution Number	S00007501
Solution Title	Crankcase Blowby Check
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Blue Smoke
Solution Number	S00006713
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Blue Smoke
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Blue Smoke
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Blue Smoke
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed

Date	24-Jun-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	24-Jun-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	24-Jun-2024
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	24-Jun-2024
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	24-Jun-2024
Fault Code / Symptom	High Blowby
Solution Number	S00011733
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Reordered
Date	24-Jun-2024
Fault Code / Symptom	High Blowby
Solution Number	S00011733
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Modified

Date	24-Jun-2024
Fault Code / Symptom	High Blowby
Solution Number	S00011734
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Reordered
Date	24-Jun-2024
Fault Code / Symptom	High Blowby
Solution Number	S00011734
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Modified
Date	24-Jun-2024
Fault Code / Symptom	High Blowby
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	High Blowby
Solution Number	S00007501
Solution Title	Crankcase Blowby Check
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	High Blowby
Solution Number	S00006713
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	High Blowby
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed

Date	24-Jun-2024
Fault Code / Symptom	High Blowby
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	High Blowby
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Reordered
Date	24-Jun-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Modified
Date	24-Jun-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Reordered

Date	24-Jun-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Modified
Date	24-Jun-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009948
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Reordered
Date	24-Jun-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Modified
Date	24-Jun-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Reordered

Date	24-Jun-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Modified
Date	24-Jun-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009948
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00012062
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00012064
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00012066
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Added

Date	24-Jun-2024
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012065
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Removed

Date	24-Jun-2024
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009948
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00012063
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00012065
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Added

Date	24-Jun-2024
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00012067
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Added

Date	24-Jun-2024
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed

Date	24-Jun-2024
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Removed

Date	24-Jun-2024
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Removed

Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00012062
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00012066
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00012062
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00012066
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Added

Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00012063
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012063
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012063
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00012062
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00012066
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Added

Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00012062
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00012066
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed

Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00012062
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00012066
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed

Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00012062
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00012066
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Removed

Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00012062
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00012066
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011387
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Added

Date	24-Jun-2024
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001370
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor is malfunctioning
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009948
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	24-Jun-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009948
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	24-Jun-2024
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00012063
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	24-Jun-2024
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00012065
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012063
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed

Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00012062
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00012066
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Added
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Removed
Date	24-Jun-2024
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009948
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered

Date	24-Jun-2024
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009948
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	02-Jun-2024
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	02-Jun-2024
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001254
Solution Title	Incorrect air compressor discharge line routing
Update Reason	Solution Removed
Date	02-Jun-2024
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001255
Solution Title	Air compressor discharge line plugged or restricted with ice
Update Reason	Solution Removed
Date	02-Jun-2024
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed

Date	02-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Missing - Condition Exists
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	02-Jun-2024
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	02-Jun-2024
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	02-Jun-2024
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	02-Jun-2024
Fault Code / Symptom	Brake Switch and Accelerator Pedal Position Incompatible - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	02-Jun-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	02-Jun-2024
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001254
Solution Title	Incorrect air compressor discharge line routing
Update Reason	Solution Removed
Date	02-Jun-2024
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001255
Solution Title	Air compressor discharge line plugged or restricted with ice
Update Reason	Solution Removed
Date	02-Jun-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	02-Jun-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed

Date	02-Jun-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	02-Jun-2024
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	26-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000595
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor circuit response
Update Reason	Solution Removed
Date	26-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00005739
Solution Title	Fault Code 4572 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Reordered
Date	26-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00005739
Solution Title	Fault Code 4572 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Modified

Date	26-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00005690
Solution Title	Fault Code 4677 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Reordered
Date	26-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00005690
Solution Title	Fault Code 4677 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Modified
Date	26-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000041
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	26-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000053
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	26-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000041
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	26-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000052
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	26-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000041
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	26-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000042
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	19-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00000397
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor circuit response (Hardwired)
Update Reason	Solution Removed
Date	19-May-2024
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed
Date	19-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00004534
Solution Title	J1939 data link harness open circuit check
Update Reason	Solution Added
Date	19-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00005705
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor voltage check
Update Reason	Solution Removed
Date	19-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00005705
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor voltage check
Update Reason	Solution Removed

Date	12-May-2024
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007920
Solution Title	Coolant level sensor open circuit check
Update Reason	Solution Removed
Date	12-May-2024
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007921
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Removed
Date	12-May-2024
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007922
Solution Title	Coolant level sensor circuit pin to pin short
Update Reason	Solution Removed
Date	12-May-2024
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Added
Date	05-May-2024
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00012002
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Reordered

Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Modified
Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Reordered
Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Modified
Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Temperature High
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Reordered
Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Temperature High
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Modified
Date	05-May-2024
Fault Code / Symptom	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000590
Solution Title	Water in fuel sensor circuit pin to pin short
Update Reason	Solution Added

Date	05-May-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001183
Solution Title	Aftertreatment DPF differential pressure sensor tubes plugged
Update Reason	Solution Removed
Date	30-Apr-2024
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor check
Update Reason	Solution Removed
Date	30-Apr-2024
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000623
Solution Title	Crankcase pressure sensor stuck in-range
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00003076
Solution Title	Gear train backlash is out of adjustment
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Reordered

Date	14-Apr-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Fuel Knock
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Reordered
Date	14-Apr-2024
Fault Code / Symptom	Fuel Knock
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Reordered
Date	14-Apr-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Reordered

Date	14-Apr-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Sensor Supply 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00005785
Solution Title	ECM sensor supply 1 voltage below normal
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Sensor Supply 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000535
Solution Title	ECM sensor supply 1 voltage below normal
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00004545
Solution Title	Aftertreatment diesel particulate filter is malfunctioning
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00004187
Solution Title	Aftertreatment diesel particulate filter partially obstructed or plugged
Update Reason	Solution Removed

Date	14-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000349
Solution Title	Aftertreatment DPF outlet pressure sensor circuit response
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001072
Solution Title	Fuel pump actuator resistance check
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001073
Solution Title	Fuel pump actuator short to ground
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Removed

Date	14-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	14-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	07-Apr-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00003075
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Reordered
Date	07-Apr-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00003075
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Modified
Date	07-Apr-2024
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011989
Solution Title	Fuel pump actuator is malfunctioning
Update Reason	Solution Added

Date	07-Apr-2024
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000980
Solution Title	Fuel pump actuator is malfunctioning
Update Reason	Solution Removed
Date	07-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	07-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	07-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	07-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	07-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	07-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Regeneration Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	07-Apr-2024
Fault Code / Symptom	Electric Lift Pump for Engine Fuel Supply - Voltage Above Normal or Shorted to High Source
Solution Number	S00011981
Solution Title	Electric fuel lift pump circuit response
Update Reason	Solution Added
Date	07-Apr-2024
Fault Code / Symptom	Electric Lift Pump for Engine Fuel Supply - Voltage Above Normal or Shorted to High Source
Solution Number	S00011982
Solution Title	Electric fuel lift pump circuit response at the ECM
Update Reason	Solution Added
Date	07-Apr-2024
Fault Code / Symptom	Electric Lift Pump for Engine Fuel Supply - Voltage Above Normal or Shorted to High Source
Solution Number	S00001649
Solution Title	Electric fuel lift pump resistance check
Update Reason	Solution Removed

Date	07-Apr-2024
Fault Code / Symptom	Electric Lift Pump for Engine Fuel Supply - Voltage Above Normal or Shorted to High Source
Solution Number	S00000321
Solution Title	Electric fuel lift pump circuit pin to pin short
Update Reason	Solution Removed
Date	07-Apr-2024
Fault Code / Symptom	Electric Lift Pump for Engine Fuel Supply - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001055
Solution Title	Electric fuel lift pump circuit pin to ground short
Update Reason	Solution Removed
Date	07-Apr-2024
Fault Code / Symptom	Electric Lift Pump for Engine Fuel Supply - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000321
Solution Title	Electric fuel lift pump circuit pin to pin short
Update Reason	Solution Removed
Date	07-Apr-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	31-Mar-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010096
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Removed

Date	31-Mar-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011387
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	31-Mar-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001370
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	31-Mar-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	31-Mar-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	31-Mar-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed

Date	31-Mar-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000780
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	31-Mar-2024
Fault Code / Symptom	Aftertreatment System Assembly - Special Instructions
Solution Number	S00011969
Solution Title	Fault code is for information only
Update Reason	Solution Added
Date	31-Mar-2024
Fault Code / Symptom	Aftertreatment System Assembly - Special Instructions
Solution Number	S00001141
Solution Title	Aftertreatment DPF system incorrect for this engine application
Update Reason	Solution Removed
Date	24-Mar-2024
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	24-Mar-2024
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00001267
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	24-Mar-2024
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	24-Mar-2024
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00001267
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	24-Mar-2024
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009956
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	24-Mar-2024
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000775
Solution Title	Exhaust gas pressure sensor circuit pin to pin short
Update Reason	Solution Removed
Date	24-Mar-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00011897
Solution Title	High exhaust restriction
Update Reason	Solution Added
Date	17-Mar-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000626
Solution Title	Plugged crankcase breather component (external)
Update Reason	Solution Reordered

Date	17-Mar-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000626
Solution Title	Plugged crankcase breather component (external)
Update Reason	Solution Modified
Date	17-Mar-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000626
Solution Title	Plugged crankcase breather component (external)
Update Reason	Solution Reordered
Date	17-Mar-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000626
Solution Title	Plugged crankcase breather component (external)
Update Reason	Solution Modified
Date	17-Mar-2024
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000626
Solution Title	Plugged crankcase breather component (external)
Update Reason	Solution Reordered

Date	17-Mar-2024
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000626
Solution Title	Plugged crankcase breather component (external)
Update Reason	Solution Modified
Date	17-Mar-2024
Fault Code / Symptom	Engine Misfire Cylinder 1 - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Mar-2024
Fault Code / Symptom	Engine Misfire Cylinder 2 - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Mar-2024
Fault Code / Symptom	Engine Misfire Cylinder 3 - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Mar-2024
Fault Code / Symptom	Engine Misfire Cylinder 4 - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Mar-2024
Fault Code / Symptom	Engine Misfire Cylinder 5 - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	17-Mar-2024
Fault Code / Symptom	Engine Misfire Cylinder 6 - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Mar-2024
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Mar-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000626
Solution Title	Plugged crankcase breather component (external)
Update Reason	Solution Reordered
Date	17-Mar-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000626
Solution Title	Plugged crankcase breather component (external)
Update Reason	Solution Modified
Date	17-Mar-2024
Fault Code / Symptom	Aftertreatment SCR Operator Inducement - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00003080
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	17-Mar-2024
Fault Code / Symptom	Engine Protection Torque Derate - Condition Exists
Solution Number	S00003080
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	17-Mar-2024
Fault Code / Symptom	Aftertreatment SCR Operator Inducement Severity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00003080
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	17-Mar-2024
Fault Code / Symptom	Engine Protection Torque Derate - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00003080
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	03-Mar-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001906
Solution Title	Aftertreatment diesel exhaust fluid pressure sensor open circuit check
Update Reason	Solution Added
Date	03-Mar-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001906
Solution Title	Aftertreatment diesel exhaust fluid pressure sensor open circuit check
Update Reason	Solution Added

Date	03-Mar-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001935
Solution Title	Aftertreatment diesel exhaust fluid pressure sensor circuit pin to ground short
Update Reason	Solution Added
Date	03-Mar-2024
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	03-Mar-2024
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	25-Feb-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011413
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Added

Date	25-Feb-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010942
Solution Title	Aftertreatment DPF differential pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	25-Feb-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00011413
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	25-Feb-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00010099
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Removed
Date	25-Feb-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00010942
Solution Title	Aftertreatment DPF differential pressure sensor is malfunctioning
Update Reason	Solution Removed

Date	11-Feb-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Feb-2024
Fault Code / Symptom	Fuel Injector Performance Test Will Not Complete
Solution Number	S00011776
Solution Title	High fuel drain line restriction
Update Reason	Solution Added
Date	04-Feb-2024
Fault Code / Symptom	Lubricating Oil in the Coolant
Solution Number	S00001324
Solution Title	Transmission lubricating oil cooler is malfunctioning
Update Reason	Solution Removed
Date	04-Feb-2024
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011099
Solution Title	Circuit Load Test
Update Reason	Solution Removed
Date	04-Feb-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011099
Solution Title	Circuit Load Test
Update Reason	Solution Removed

Date	04-Feb-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011099
Solution Title	Circuit Load Test
Update Reason	Solution Removed
Date	04-Feb-2024
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011099
Solution Title	Circuit Load Test
Update Reason	Solution Removed
Date	04-Feb-2024
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000494
Solution Title	Engine intake throttle actuator motor open circuit check
Update Reason	Solution Removed
Date	04-Feb-2024
Fault Code / Symptom	Electronic Throttle Control Actuator - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000494
Solution Title	Engine intake throttle actuator motor open circuit check
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	High Blowby
Solution Number	S00011733
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	High Blowby
Solution Number	S00011734
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000574
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor is malfunctioning
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000818
Solution Title	Engine intake throttle actuator voltage check
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008140
Solution Title	Engine intake throttle actuator voltage check at the ECM
Update Reason	Solution Removed

Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00011759
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00011759
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00011759
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00011759
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00011759
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00011759
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00011759
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	07-Jan-2024
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Leak
Solution Number	S00011721
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	07-Jan-2024
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00002840
Solution Title	Leaks in the aftertreatment diesel exhaust fluid dosing system
Update Reason	Solution Added
Date	07-Jan-2024
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00002840
Solution Title	Leaks in the aftertreatment diesel exhaust fluid dosing system
Update Reason	Solution Added

Date	07-Jan-2024
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00002840
Solution Title	Leaks in the aftertreatment diesel exhaust fluid dosing system
Update Reason	Solution Added
Date	07-Jan-2024
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00002840
Solution Title	Leaks in the aftertreatment diesel exhaust fluid dosing system
Update Reason	Solution Added
Date	24-Dec-2023
Fault Code / Symptom	Air Handling Performance Test did not pass
Solution Number	S00011666
Solution Title	Engine intake throttle actuator is malfunctioning
Update Reason	Solution Added
Date	24-Dec-2023
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000859
Solution Title	Fuel pump actuator has high resistance
Update Reason	Solution Removed
Date	24-Dec-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003985
Solution Title	Aftertreatment diesel exhaust fluid line heater is malfunctioning
Update Reason	Solution Removed

Date	24-Dec-2023
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00011715
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	24-Dec-2023
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed

Date	24-Dec-2023
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00011715
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	24-Dec-2023
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed

Date	24-Dec-2023
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00011715
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	24-Dec-2023
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed

Date	24-Dec-2023
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00011715
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	24-Dec-2023
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed

Date	24-Dec-2023
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00011715
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	24-Dec-2023
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed

Date	24-Dec-2023
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00011715
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	24-Dec-2023
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed
Date	24-Dec-2023
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00011715
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	24-Dec-2023
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed
Date	17-Dec-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00011675
Solution Title	Aftertreatment diesel exhaust fluid dosing valve resistance check
Update Reason	Solution Added

Date	17-Dec-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000849
Solution Title	Aftertreatment diesel exhaust fluid dosing valve resistance check
Update Reason	Solution Removed
Date	12-Dec-2023
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00000562
Solution Title	Leaks in the aftertreatment diesel exhaust fluid dosing system
Update Reason	Solution Removed
Date	12-Dec-2023
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00000562
Solution Title	Leaks in the aftertreatment diesel exhaust fluid dosing system
Update Reason	Solution Removed
Date	12-Dec-2023
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000562
Solution Title	Leaks in the aftertreatment diesel exhaust fluid dosing system
Update Reason	Solution Removed
Date	03-Dec-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Missing - Condition Exists
Solution Number	S00007849
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Reordered

Date	03-Dec-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Missing - Condition Exists
Solution Number	S00007849
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Modified
Date	03-Dec-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007849
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Reordered
Date	03-Dec-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007849
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Modified
Date	03-Dec-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Removed

Date	03-Dec-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	03-Dec-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Removed
Date	03-Dec-2023
Fault Code / Symptom	Engine Turbocharger 1 Speed - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000652
Solution Title	Turbocharger speed sensor circuit pin to pin short
Update Reason	Solution Removed
Date	03-Dec-2023
Fault Code / Symptom	Fan Control Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004897
Solution Title	Fan control solenoid circuit pin to pin short
Update Reason	Solution Removed
Date	03-Dec-2023
Fault Code / Symptom	Fan Control Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004897
Solution Title	Fan control solenoid circuit pin to pin short
Update Reason	Solution Removed

Date	26-Nov-2023
Fault Code / Symptom	EGR Valve Control Circuit - Current Below Normal or Open Circuit
Solution Number	S00000773
Solution Title	EGR valve motor resistance check
Update Reason	Solution Removed
Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011605
Solution Title	Aftertreatment diesel exhaust fluid line heater is malfunctioning
Update Reason	Solution Added
Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00002879
Solution Title	Aftertreatment diesel exhaust fluid line heater is malfunctioning
Update Reason	Solution Removed
Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001125
Solution Title	Aftertreatment diesel exhaust fluid line heater open circuit check
Update Reason	Solution Removed

Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000783
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Removed
Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000783
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Removed
Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011605
Solution Title	Aftertreatment diesel exhaust fluid line heater is malfunctioning
Update Reason	Solution Added
Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00002879
Solution Title	Aftertreatment diesel exhaust fluid line heater is malfunctioning
Update Reason	Solution Removed

Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001125
Solution Title	Aftertreatment diesel exhaust fluid line heater open circuit check
Update Reason	Solution Removed
Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000783
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Removed
Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000783
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Removed
Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011605
Solution Title	Aftertreatment diesel exhaust fluid line heater is malfunctioning
Update Reason	Solution Added

Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00002879
Solution Title	Aftertreatment diesel exhaust fluid line heater is malfunctioning
Update Reason	Solution Removed
Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001125
Solution Title	Aftertreatment diesel exhaust fluid line heater open circuit check
Update Reason	Solution Removed
Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000783
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Removed
Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000783
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Removed

Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing System Frozen - Condition Exists
Solution Number	S00011605
Solution Title	Aftertreatment diesel exhaust fluid line heater is malfunctioning
Update Reason	Solution Added
Date	26-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing System Frozen - Condition Exists
Solution Number	S00002879
Solution Title	Aftertreatment diesel exhaust fluid line heater is malfunctioning
Update Reason	Solution Removed
Date	26-Nov-2023
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed
Date	26-Nov-2023
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	19-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00001026
Solution Title	Aftertreatment DPF Permit Switch Status is in the OFF position
Update Reason	Solution Removed

Date	19-Nov-2023
Fault Code / Symptom	Aftertreatment Regeneration Inhibited Due to Inhibit Switch - Condition Exists
Solution Number	S00001026
Solution Title	Aftertreatment DPF Permit Switch Status is in the OFF position
Update Reason	Solution Reordered
Date	19-Nov-2023
Fault Code / Symptom	Aftertreatment Regeneration Inhibited Due to Inhibit Switch - Condition Exists
Solution Number	S00001026
Solution Title	Aftertreatment DPF Permit Switch Status is in the OFF position
Update Reason	Solution Modified
Date	19-Nov-2023
Fault Code / Symptom	Aftertreatment Regeneration Inhibit Switch - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001026
Solution Title	Aftertreatment DPF Permit Switch Status is in the OFF position
Update Reason	Solution Added
Date	19-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011461
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay voltage check
Update Reason	Solution Added
Date	19-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001015
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay voltage check
Update Reason	Solution Removed

Date	19-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00011572
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay voltage check
Update Reason	Solution Added
Date	19-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001015
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay voltage check
Update Reason	Solution Removed
Date	19-Nov-2023
Fault Code / Symptom	Aftertreatment Regeneration Inhibited Due to Inhibit Switch - Condition Exists
Solution Number	S00001026
Solution Title	Aftertreatment DPF Permit Switch Status is in the OFF position
Update Reason	Solution Reordered
Date	19-Nov-2023
Fault Code / Symptom	Aftertreatment Regeneration Inhibited Due to Inhibit Switch - Condition Exists
Solution Number	S00001026
Solution Title	Aftertreatment DPF Permit Switch Status is in the OFF position
Update Reason	Solution Modified
Date	12-Nov-2023
Fault Code / Symptom	Engine Noise
Solution Number	S00001350
Solution Title	Air intake or exhaust system leaks
Update Reason	Solution Removed

Date	12-Nov-2023
Fault Code / Symptom	Exhaust Noise
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	12-Nov-2023
Fault Code / Symptom	Exhaust Noise
Solution Number	S00001350
Solution Title	Air intake or exhaust system leaks
Update Reason	Solution Removed
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	12-Nov-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00011555
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Nov-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00011555
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment Regeneration Inhibited Due to Inhibit Switch - Condition Exists
Solution Number	S00002026
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00011555
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000852
Solution Title	Incorrect aftertreatment diesel exhaust fluid dosing valve installed
Update Reason	Solution Removed
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00011555
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00011555
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00011555
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment Regeneration Inhibit Switch - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002026
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Rate of Change
Solution Number	S00011555
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Rate of Change
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00011555
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00011555
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	12-Nov-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00011555
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Nov-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment Regeneration Inhibited Due to Inhibit Switch - Condition Exists
Solution Number	S00002026
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00011555
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Nov-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	08-Nov-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001046
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	08-Nov-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00001046
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	08-Nov-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00001046
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	03-Dec-2023
Fault Code / Symptom	Air Handling Performance Test did not pass
Solution Number	S00008935
Solution Title	The intake connection flow signature is abnormal
Update Reason	Solution Removed
Date	03-Dec-2023
Fault Code / Symptom	Air Handling Performance Test did not pass
Solution Number	S00008939
Solution Title	Air intake connection restricted
Update Reason	Solution Removed

Date	03-Dec-2023
Fault Code / Symptom	Air Handling Performance Test did not pass
Solution Number	S00008920
Solution Title	The VGT is causing low exhaust pressure
Update Reason	Solution Removed
Date	03-Dec-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Reordered
Date	03-Dec-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Modified
Date	03-Dec-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Reordered
Date	03-Dec-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000462
Solution Title	Contaminated lubricating oil
Update Reason	Solution Modified

Date	03-Dec-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	03-Dec-2023
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004996
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	22-Oct-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	22-Oct-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	08-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010492
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Removed

Date	08-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010303
Solution Title	Aftertreatment power relay voltage check
Update Reason	Solution Removed
Date	08-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010305
Solution Title	Aftertreatment power relay resistance check
Update Reason	Solution Removed
Date	08-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010514
Solution Title	Aftertreatment intake NOx sensor circuit check
Update Reason	Solution Removed
Date	08-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010368
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Removed
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00008451
Solution Title	Aftertreatment DPF outlet temperature is out of desired range
Update Reason	Solution Added

Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00008286
Solution Title	Aftertreatment DPF outlet temperature is out of desired range
Update Reason	Solution Removed

Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00008453
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed

Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011470
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay open circuit check
Update Reason	Solution Added

Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Above Normal or Shorted to High Source
Solution Number	S00010966
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay open circuit check
Update Reason	Solution Removed

Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011470
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay open circuit check
Update Reason	Solution Added
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010966
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay open circuit check
Update Reason	Solution Removed
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011472
Solution Title	Aftertreatment diesel exhaust fluid dosing valve open circuit check
Update Reason	Solution Added
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011473
Solution Title	Aftertreatment diesel exhaust fluid dosing valve circuit pin to ground short
Update Reason	Solution Added

Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000845
Solution Title	Aftertreatment diesel exhaust fluid dosing valve open circuit check
Update Reason	Solution Removed
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000846
Solution Title	Aftertreatment diesel exhaust fluid dosing valve circuit pin to ground short
Update Reason	Solution Removed
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00011472
Solution Title	Aftertreatment diesel exhaust fluid dosing valve open circuit check
Update Reason	Solution Added
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00011473
Solution Title	Aftertreatment diesel exhaust fluid dosing valve circuit pin to ground short
Update Reason	Solution Added

Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000845
Solution Title	Aftertreatment diesel exhaust fluid dosing valve open circuit check
Update Reason	Solution Removed
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00000846
Solution Title	Aftertreatment diesel exhaust fluid dosing valve circuit pin to ground short
Update Reason	Solution Removed
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011474
Solution Title	Aftertreatment diesel exhaust fluid dosing valve voltage check
Update Reason	Solution Added
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011475
Solution Title	Aftertreatment diesel exhaust fluid dosing valve resistance check
Update Reason	Solution Added

Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011471
Solution Title	Aftertreatment diesel exhaust fluid pressure sensor OEM wiring harness pin to pin short
Update Reason	Solution Added
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001171
Solution Title	Aftertreatment diesel exhaust fluid dosing valve voltage check
Update Reason	Solution Removed
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001172
Solution Title	Aftertreatment diesel exhaust fluid dosing valve resistance check
Update Reason	Solution Removed
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000853
Solution Title	Aftertreatment diesel exhaust fluid pressure sensor OEM wiring harness pin to pin short
Update Reason	Solution Removed

Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011474
Solution Title	Aftertreatment diesel exhaust fluid dosing valve voltage check
Update Reason	Solution Added
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011475
Solution Title	Aftertreatment diesel exhaust fluid dosing valve resistance check
Update Reason	Solution Added
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011471
Solution Title	Aftertreatment diesel exhaust fluid pressure sensor OEM wiring harness pin to pin short
Update Reason	Solution Added
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001171
Solution Title	Aftertreatment diesel exhaust fluid dosing valve voltage check
Update Reason	Solution Removed

Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001172
Solution Title	Aftertreatment diesel exhaust fluid dosing valve resistance check
Update Reason	Solution Removed
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000853
Solution Title	Aftertreatment diesel exhaust fluid pressure sensor OEM wiring harness pin to pin short
Update Reason	Solution Removed
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001014
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor circuit pin to pin short
Update Reason	Solution Removed
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001014
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor circuit pin to pin short
Update Reason	Solution Removed

Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Above Normal or Shorted to High Source
Solution Number	S00011470
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay open circuit check
Update Reason	Solution Added
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Above Normal or Shorted to High Source
Solution Number	S00010966
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay open circuit check
Update Reason	Solution Removed
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011470
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay open circuit check
Update Reason	Solution Added
Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010966
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay open circuit check
Update Reason	Solution Removed

Date	01-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001014
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor circuit pin to pin short
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00011412
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Air Handling Performance Test did not complete
Solution Number	S00011460
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00011412
Solution Title	Aftertreatment diesel oxidation catalyst is malfunctioning
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00006220
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Reordered

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00006220
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Modified
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00000873
Solution Title	Aftertreatment diesel exhaust fluid dosing valve return restriction check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000984
Solution Title	Aftertreatment DPF differential pressure sensor open circuit check
Update Reason	Solution Reordered
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000984
Solution Title	Aftertreatment DPF differential pressure sensor open circuit check
Update Reason	Solution Modified

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011413
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011453
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001246
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001247
Solution Title	Aftertreatment DPF differential pressure sensor circuit check
Update Reason	Solution Removed

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000582
Solution Title	Aftertreatment DPF differential pressure sensor circuit response
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007506
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011413
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011452
Solution Title	Aftertreatment DPF differential pressure sensor open circuit check
Update Reason	Solution Added

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011453
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001246
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001247
Solution Title	Aftertreatment DPF differential pressure sensor circuit check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000580
Solution Title	Aftertreatment DPF differential pressure sensor circuit response
Update Reason	Solution Removed

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000996
Solution Title	Aftertreatment DPF differential pressure sensor open circuit check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001539
Solution Title	Aftertreatment DPF differential pressure sensor circuit pin to ground short
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007506
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011413
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Reordered

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011413
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	24-Sep-2023
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00003677
Solution Title	Air leaks at the hood air plenum
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001555
Solution Title	Aftertreatment DPF outlet pressure sensor open circuit check
Update Reason	Solution Reordered
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001555
Solution Title	Aftertreatment DPF outlet pressure sensor open circuit check
Update Reason	Solution Modified

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001585
Solution Title	Aftertreatment diesel particulate filter outlet pressure sensor pin shorted to another pin
Update Reason	Solution Reordered
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001585
Solution Title	Aftertreatment diesel particulate filter outlet pressure sensor pin shorted to another pin
Update Reason	Solution Modified
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011413
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00010902
Solution Title	Aftertreatment DPF outlet pressure sensor voltage check
Update Reason	Solution Removed

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00010903
Solution Title	Aftertreatment DPF outlet pressure sensor circuit check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001555
Solution Title	Aftertreatment DPF outlet pressure sensor open circuit check
Update Reason	Solution Reordered
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001555
Solution Title	Aftertreatment DPF outlet pressure sensor open circuit check
Update Reason	Solution Modified
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00002790
Solution Title	Aftertreatment DPF outlet pressure circuit pin to ground short
Update Reason	Solution Reordered

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00002790
Solution Title	Aftertreatment DPF outlet pressure circuit pin to ground short
Update Reason	Solution Modified
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011413
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010902
Solution Title	Aftertreatment DPF outlet pressure sensor voltage check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010903
Solution Title	Aftertreatment DPF outlet pressure sensor circuit check
Update Reason	Solution Removed

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000347
Solution Title	Aftertreatment DPF outlet pressure sensor circuit response
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000793
Solution Title	Aftertreatment DPF differential pressure sensor stuck in-range
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001154
Solution Title	Aftertreatment diesel exhaust fluid dosing valve circuit pin to pin short
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00001154
Solution Title	Aftertreatment diesel exhaust fluid dosing valve circuit pin to pin short
Update Reason	Solution Removed

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00001154
Solution Title	Aftertreatment diesel exhaust fluid dosing valve circuit pin to pin short
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006220
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Reordered
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006220
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Modified
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000873
Solution Title	Aftertreatment diesel exhaust fluid dosing valve return restriction check
Update Reason	Solution Removed

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00011413
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00011452
Solution Title	Aftertreatment DPF differential pressure sensor open circuit check
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00011453
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00001246
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00001247
Solution Title	Aftertreatment DPF differential pressure sensor circuit check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00000793
Solution Title	Aftertreatment DPF differential pressure sensor stuck in-range
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00000996
Solution Title	Aftertreatment DPF differential pressure sensor open circuit check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00001539
Solution Title	Aftertreatment DPF differential pressure sensor circuit pin to ground short
Update Reason	Solution Removed

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00007506
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00002710
Solution Title	Aftertreatment DPF differential pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00002790
Solution Title	Aftertreatment DPF outlet pressure circuit pin to ground short
Update Reason	Solution Reordered
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00002790
Solution Title	Aftertreatment DPF outlet pressure circuit pin to ground short
Update Reason	Solution Modified
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00011413
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Added

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00011452
Solution Title	Aftertreatment DPF differential pressure sensor open circuit check
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00011453
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00010099
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00010902
Solution Title	Aftertreatment DPF outlet pressure sensor voltage check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00010903
Solution Title	Aftertreatment DPF outlet pressure sensor circuit check
Update Reason	Solution Removed

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00000793
Solution Title	Aftertreatment DPF differential pressure sensor stuck in-range
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00000996
Solution Title	Aftertreatment DPF differential pressure sensor open circuit check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00007506
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011464
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor open circuit check
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011468
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor circuit pin to pin short
Update Reason	Solution Added

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001013
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor open circuit check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011464
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor open circuit check
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011466
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor circuit pin to ground short
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011468
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor circuit pin to pin short
Update Reason	Solution Added

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001013
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor open circuit check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001016
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor circuit pin to ground short
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Above Normal or Shorted to High Source
Solution Number	S00011462
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay circuit pin to pin short
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Above Normal or Shorted to High Source
Solution Number	S00001025
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay circuit pin to pin short
Update Reason	Solution Removed

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011461
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay voltage check
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011463
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay circuit pin to ground short
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011462
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay circuit pin to pin short
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001022
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay voltage check
Update Reason	Solution Removed

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010905
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor open circuit check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001023
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay circuit pin to ground short
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001025
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay circuit pin to pin short
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00011465
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor open circuit check
Update Reason	Solution Added

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00011467
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor circuit pin to ground short
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00011469
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor circuit pin to pin short
Update Reason	Solution Added
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001013
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor open circuit check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001016
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor circuit pin to ground short
Update Reason	Solution Removed

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006220
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Reordered
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006220
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Modified
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000873
Solution Title	Aftertreatment diesel exhaust fluid dosing valve return restriction check
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00000793
Solution Title	Aftertreatment DPF differential pressure sensor stuck in-range
Update Reason	Solution Removed

Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00009950
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	24-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00001105
Solution Title	Aftertreatment DPF Outlet Pressure Sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Coolant Level Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000727
Solution Title	Coolant level sensor voltage check
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Coolant Level Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000815
Solution Title	Coolant level sensor circuit check
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00008348
Solution Title	Aftertreatment diesel exhaust fluid dosing valve inlet filter
Update Reason	Solution Removed

Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00003284
Solution Title	Aftertreatment diesel exhaust fluid pressure line restricted
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00003230
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011413
Solution Title	Aftertreatment diesel particulate filter differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed

Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010906
Solution Title	Aftertreatment DPF differential pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed

Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed

Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed

Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010902
Solution Title	Aftertreatment DPF outlet pressure sensor voltage check
Update Reason	Solution Removed

Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010903
Solution Title	Aftertreatment DPF outlet pressure sensor circuit check
Update Reason	Solution Removed

Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00003179
Solution Title	Aftertreatment DPF outlet pressure sensor open circuit check
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002790
Solution Title	Aftertreatment DPF outlet pressure circuit pin to ground short
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000564
Solution Title	Deposits in the SCR decomposition tube
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000735
Solution Title	Leaks in the aftertreatment diesel exhaust fluid dosing system
Update Reason	Solution Removed

Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002649
Solution Title	High exhaust restriction
Update Reason	Solution Removed

Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011449
Solution Title	Aftertreatment diesel exhaust fluid dosing valve circuit pin to pin short
Update Reason	Solution Added

Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00011449
Solution Title	Aftertreatment diesel exhaust fluid dosing valve circuit pin to pin short
Update Reason	Solution Added

Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00011449
Solution Title	Aftertreatment diesel exhaust fluid dosing valve circuit pin to pin short
Update Reason	Solution Added

Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008348
Solution Title	Aftertreatment diesel exhaust fluid dosing valve inlet filter
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003284
Solution Title	Aftertreatment diesel exhaust fluid pressure line restricted
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003230
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	17-Sep-2023
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00009929
Solution Title	EGR leaks
Update Reason	Solution Removed

Date	17-Sep-2023
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00009950
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	17-Sep-2023
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009929
Solution Title	EGR leaks
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009950
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed

Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011448
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor open circuit check
Update Reason	Solution Added
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008348
Solution Title	Aftertreatment diesel exhaust fluid dosing valve inlet filter
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed

Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00003179
Solution Title	Aftertreatment DPF outlet pressure sensor open circuit check
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00002790
Solution Title	Aftertreatment DPF outlet pressure circuit pin to ground short
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00000564
Solution Title	Deposits in the SCR decomposition tube
Update Reason	Solution Removed
Date	17-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00000735
Solution Title	Leaks in the aftertreatment diesel exhaust fluid dosing system
Update Reason	Solution Removed
Date	03-Sep-2023
Fault Code / Symptom	Engine Brake Slow Activation
Solution Number	S00011398
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	03-Sep-2023
Fault Code / Symptom	Engine Brake Slow Activation
Solution Number	S00011176
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	03-Sep-2023
Fault Code / Symptom	Engine Brake Weak
Solution Number	S00011398
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	03-Sep-2023
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00011398
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	03-Sep-2023
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00011176
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	03-Sep-2023
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00011398
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	03-Sep-2023
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00011176
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed

Date	03-Sep-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00011167
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	03-Sep-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00011370
Solution Title	Air intake system restricted
Update Reason	Solution Removed
Date	03-Sep-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	03-Sep-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00011184
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	03-Sep-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	03-Sep-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00011176
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed

Date	03-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00005738
Solution Title	Fault Code 3868 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Added
Date	03-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00009851
Solution Title	Fault Code 3868 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Removed
Date	03-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00005739
Solution Title	Fault Code 4572 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Added
Date	03-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00005705
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor voltage check
Update Reason	Solution Added

Date	03-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00009857
Solution Title	Fault Code 4572 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Removed
Date	03-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00005690
Solution Title	Fault Code 4677 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Added
Date	03-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00005705
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor voltage check
Update Reason	Solution Added
Date	03-Sep-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00009856
Solution Title	Fault Code 4677 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Removed

Date	03-Sep-2023
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00007691
Solution Title	Fault Code 5655 requires that ALL solutions be performed
Update Reason	Solution Removed
Date	27-Aug-2023
Fault Code / Symptom	Engine Noise
Solution Number	S00011388
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	27-Aug-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00011167
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	27-Aug-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00011370
Solution Title	Air intake system restricted
Update Reason	Solution Removed
Date	27-Aug-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	27-Aug-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00011185
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed

Date	27-Aug-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00011184
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	27-Aug-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	27-Aug-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00011176
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	27-Aug-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00011353
Solution Title	Air in the aftertreatment diesel exhaust fluid
Update Reason	Solution Added
Date	27-Aug-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	27-Aug-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	27-Aug-2023
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	27-Aug-2023
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	27-Aug-2023
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	27-Aug-2023
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	27-Aug-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011353
Solution Title	Air in the aftertreatment diesel exhaust fluid
Update Reason	Solution Added

Date	27-Aug-2023
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	27-Aug-2023
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	27-Aug-2023
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	27-Aug-2023
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	27-Aug-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	20-Aug-2023
Fault Code / Symptom	Engine Noise
Solution Number	S00010685
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	20-Aug-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	13-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Added
Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Added
Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Removed
Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011008
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed

Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Removed

Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed

Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011374
Solution Title	Leaks in the intake air system (Engine)
Update Reason	Solution Added

Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011375
Solution Title	Leaks in the intake air system (OEM)
Update Reason	Solution Added

Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Removed
Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011008
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Removed
Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed

Date	13-Aug-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000140
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	13-Aug-2023
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Removed

Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00011008
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Removed
Date	13-Aug-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	13-Aug-2023
Fault Code / Symptom	VGT Actuator Driver Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	13-Aug-2023
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	VGT Actuator Driver Circuit (Motor) - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011387
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Added
Date	13-Aug-2023
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor is malfunctioning
Update Reason	Solution Added

Date	13-Aug-2023
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000733
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	13-Aug-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011387
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Added
Date	13-Aug-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor is malfunctioning
Update Reason	Solution Added

Date	13-Aug-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000733
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	13-Aug-2023
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011387
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Added

Date	13-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor is malfunctioning
Update Reason	Solution Added
Date	13-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000733
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	13-Aug-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	13-Aug-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	13-Aug-2023
Fault Code / Symptom	Engine Turbocharger 1 Speed - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00011387
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Added
Date	13-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor is malfunctioning
Update Reason	Solution Added
Date	13-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000733
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	13-Aug-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	13-Aug-2023
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Aug-2023
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	06-Aug-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00011167
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered
Date	06-Aug-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00011167
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified
Date	06-Aug-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00011185
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	06-Aug-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011167
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	06-Aug-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011370
Solution Title	Air intake system restricted
Update Reason	Solution Removed
Date	06-Aug-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	06-Aug-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011185
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	06-Aug-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011182
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	06-Aug-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011184
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	06-Aug-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed

Date	06-Aug-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011176
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	06-Aug-2023
Fault Code / Symptom	Low Power
Solution Number	S00011167
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered
Date	06-Aug-2023
Fault Code / Symptom	Low Power
Solution Number	S00011167
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified
Date	06-Aug-2023
Fault Code / Symptom	EGR Valve Control Circuit - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	06-Aug-2023
Fault Code / Symptom	EGR Valve Control Circuit - Current Above Normal or Grounded Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	06-Aug-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	06-Aug-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	06-Aug-2023
Fault Code / Symptom	Route Parameter Manager Module GPS Antenna - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	30-Jul-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00011167
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00011184
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed

Date	30-Jul-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00011176
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Crank No Start
Solution Number	S00011370
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011370
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Removed

Date	30-Jul-2023
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00011370
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00011370
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00011370
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Removed

Date	30-Jul-2023
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00011370
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00011370
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00011370
Solution Title	Air intake system restricted
Update Reason	Solution Added

Date	30-Jul-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00011370
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00011370
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00011370
Solution Title	Air intake system restricted
Update Reason	Solution Added

Date	30-Jul-2023
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	30-Jul-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	30-Jul-2023
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	30-Jul-2023
Fault Code / Symptom	VGT Actuator Driver Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	30-Jul-2023
Fault Code / Symptom	Brake Switch and Accelerator Pedal Position Incompatible - Condition Exists
Solution Number	S00004426
Solution Title	Fault code is for information only
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	30-Jul-2023
Fault Code / Symptom	Engine Cooling System Monitor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	30-Jul-2023
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	30-Jul-2023
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008863
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	30-Jul-2023
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000494
Solution Title	Engine intake throttle actuator motor open circuit check
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	16-Jul-2023
Fault Code / Symptom	Engine Oil Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Engine Oil Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Engine Oil Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	16-Jul-2023
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Condition Exists
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	16-Jul-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Power Supply - Voltage Above Normal or Shorted to High Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Power Supply - Voltage Above Normal or Shorted to High Source
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed

Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Power Supply - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Power Supply - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Power Supply - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Power Supply - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed

Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Detection Status - Abnormal Rate of Change
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Detection Status - Abnormal Rate of Change
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed

Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater High Side Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater High Side Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater Low Side Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater Low Side Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed

Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Data Not Rational - Drifted Low
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Data Not Rational - Drifted Low
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Sensor Module Voltage Converter - Bad Intelligent Device or Component
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Sensor Module Voltage Converter - Bad Intelligent Device or Component
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed
Date	16-Jul-2023
Fault Code / Symptom	Engine Crankshaft Speed/Position - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	16-Jul-2023
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	VGT Actuator Driver Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000640
Solution Title	Low pressure fuel system component is malfunctioning
Update Reason	Solution Removed

Date	16-Jul-2023
Fault Code / Symptom	VGT Actuator Driver Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001205
Solution Title	Air in fuel check
Update Reason	Solution Removed

Date	16-Jul-2023
Fault Code / Symptom	VGT Actuator Driver Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001206
Solution Title	Fuel Inlet Restriction check
Update Reason	Solution Removed

Date	16-Jul-2023
Fault Code / Symptom	VGT Actuator Driver Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001207
Solution Title	Fuel lift pump check
Update Reason	Solution Removed

Date	16-Jul-2023
Fault Code / Symptom	VGT Actuator Driver Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000756
Solution Title	OEM fuel system component check
Update Reason	Solution Removed

Date	16-Jul-2023
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	16-Jul-2023
Fault Code / Symptom	EGR Valve Control Circuit - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Engine Turbocharger 1 Speed - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	09-Jul-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000654
Solution Title	Turbocharger speed sensor voltage check
Update Reason	Solution Reordered

Date	09-Jul-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000654
Solution Title	Turbocharger speed sensor voltage check
Update Reason	Solution Modified

Date	09-Jul-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000654
Solution Title	Turbocharger speed sensor voltage check
Update Reason	Solution Reordered

Date	09-Jul-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000654
Solution Title	Turbocharger speed sensor voltage check
Update Reason	Solution Modified

Date	09-Jul-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000654
Solution Title	Turbocharger speed sensor voltage check
Update Reason	Solution Reordered

Date	09-Jul-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000654
Solution Title	Turbocharger speed sensor voltage check
Update Reason	Solution Modified
Date	09-Jul-2023
Fault Code / Symptom	Source Address of Active or Pending Transmission Requested Gear - Abnormal Update Rate
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	02-Jul-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	02-Jul-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Does Not Activate
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Reordered

Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Does Not Activate
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Modified
Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Slow Activation
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Reordered
Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Slow Activation
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Modified
Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Stuck On
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Reordered
Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Stuck On
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Modified
Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Weak
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Reordered

Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Weak
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Modified
Date	25-Jun-2023
Fault Code / Symptom	Engine Decelerates Slowly
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Reordered
Date	25-Jun-2023
Fault Code / Symptom	Engine Decelerates Slowly
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Modified
Date	25-Jun-2023
Fault Code / Symptom	Vibration
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Reordered
Date	25-Jun-2023
Fault Code / Symptom	Vibration
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Modified
Date	18-Jun-2023
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Reordered

Date	18-Jun-2023
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Modified
Date	18-Jun-2023
Fault Code / Symptom	Turbocharger 1 Compressor Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000343
Solution Title	Compressor intake temperature sensor stuck in-range
Update Reason	Solution Added
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater High Side Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater Low Side Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Regeneration Status - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Power Supply - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Power Supply - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Power Supply - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Detection Status - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Regeneration Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Temperature Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Sensor Module Voltage Converter - Bad Intelligent Device or Component
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Jun-2023
Fault Code / Symptom	External Coolant Leak
Solution Number	S00011189
Solution Title	Combustion gases entering the cooling system
Update Reason	Solution Removed

Date	11-Jun-2023
Fault Code / Symptom	External Coolant Leak
Solution Number	S00001269
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Removed
Date	11-Jun-2023
Fault Code / Symptom	External Coolant Leak
Solution Number	S00011192
Solution Title	Fuel injector o-rings or fuel injector sleeves are damaged
Update Reason	Solution Removed
Date	11-Jun-2023
Fault Code / Symptom	External Coolant Leak
Solution Number	S00001270
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Removed
Date	11-Jun-2023
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified
Date	11-Jun-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment Intake Gas Sensor Heater - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	11-Jun-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation 1 Valve 1 Control 1 - Condition Exists
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Self- Diagnosis - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Temperature Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Temperature Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is malfunctioning
Update Reason	Solution Removed

Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered
Date	11-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered

Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified

Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered

Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified

Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered

Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified

Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered

Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified

Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified
Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered

Date	04-Jun-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified
Date	28-May-2023
Fault Code / Symptom	External Lubricating Oil Leak
Solution Number	S00011321
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	28-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00004545
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Reordered
Date	28-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00004545
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Modified
Date	21-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered

Date	21-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified

Date	21-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered

Date	21-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified

Date	21-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered

Date	21-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified

Date	21-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered
Date	21-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified
Date	21-May-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Root Cause Not Known
Solution Number	S00011309
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	21-May-2023
Fault Code / Symptom	VGT Actuator Driver Circuit (Motor) - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered
Date	21-May-2023
Fault Code / Symptom	VGT Actuator Driver Circuit (Motor) - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified

Date	21-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered

Date	21-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified

Date	21-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered

Date	21-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified

Date	21-May-2023
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered

Date	21-May-2023
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified

Date	21-May-2023
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered

Date	21-May-2023
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified

Date	21-May-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered

Date	21-May-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified

Date	21-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered

Date	21-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified

Date	21-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered

Date	21-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified

Date	21-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered

Date	21-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified
Date	21-May-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered
Date	21-May-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified
Date	21-May-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered
Date	21-May-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified

Date	21-May-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered
Date	21-May-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified
Date	21-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered
Date	21-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified
Date	21-May-2023
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	21-May-2023
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	21-May-2023
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	21-May-2023
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	21-May-2023
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	21-May-2023
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	21-May-2023
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	21-May-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Reordered
Date	21-May-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Modified
Date	14-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	14-May-2023
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Voltage Above Normal or Shorted to High Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	14-May-2023
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	14-May-2023
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed

Date	14-May-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Line Heater Relay - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Modified

Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	14-May-2023
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	14-May-2023
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	14-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011304
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011039
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	14-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Reordered

Date	14-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	14-May-2023
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	14-May-2023
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	07-May-2023
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	07-May-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	07-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	07-May-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	07-May-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation 1 Valve 1 Control 1 - Condition Exists
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	30-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000907
Solution Title	OEM terminating resistor ohms check for the J1939 data link
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000907
Solution Title	OEM terminating resistor ohms check for the J1939 data link
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00000907
Solution Title	OEM terminating resistor ohms check for the J1939 data link
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000907
Solution Title	OEM terminating resistor ohms check for the J1939 data link
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00000907
Solution Title	OEM terminating resistor ohms check for the J1939 data link
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000907
Solution Title	OEM terminating resistor ohms check for the J1939 data link
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000907
Solution Title	OEM terminating resistor ohms check for the J1939 data link
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00000907
Solution Title	OEM terminating resistor ohms check for the J1939 data link
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00000907
Solution Title	OEM terminating resistor ohms check for the J1939 data link
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed

Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00000907
Solution Title	OEM terminating resistor ohms check for the J1939 data link
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed
Date	30-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed

Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Barometric Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004225
Solution Title	Barometric pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Barometric Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004225
Solution Title	Barometric pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Turbocharger 1 Compressor Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004923
Solution Title	Compressor intake temperature sensor stuck in-range
Update Reason	Solution Removed

Date	23-Apr-2023
Fault Code / Symptom	Injector Solenoid Driver Cylinder 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Injector Solenoid Driver Cylinder 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Injector Solenoid Driver Cylinder 2 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Injector Solenoid Driver Cylinder 2 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Injector Solenoid Driver Cylinder 3 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Injector Solenoid Driver Cylinder 3 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Injector Solenoid Driver Cylinder 4 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Injector Solenoid Driver Cylinder 4 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Injector Solenoid Driver Cylinder 5 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Injector Solenoid Driver Cylinder 5 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Injector Solenoid Driver Cylinder 6 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Injector Solenoid Driver Cylinder 6 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000137
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000047
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Out of Calibration
Solution Number	S00008137
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Out of Calibration
Solution Number	S00008137
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00001983
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00001983
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	VGT Actuator Controller - Bad Intelligent Device or Component
Solution Number	S00000600
Solution Title	Variable geometry turbocharger actuator is malfunctioning
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	VGT Actuator Controller - Bad Intelligent Device or Component
Solution Number	S00000600
Solution Title	Variable geometry turbocharger actuator is malfunctioning
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Root Cause Not Known
Solution Number	S00001062
Solution Title	Variable geometry turbocharger actuator is malfunctioning
Update Reason	Solution Removed
Date	23-Apr-2023
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001028
Solution Title	Engine brake solenoid circuit pin to pin short
Update Reason	Solution Removed
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Rate of Change
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Rate of Change
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Calibration Memory - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Calibration Memory - Bad Intelligent Device or Component
Solution Number	S00008078
Solution Title	Internal ECM Error
Update Reason	Solution Removed
Date	23-Apr-2023
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00008682
Solution Title	Fuel pressure relief valve is malfunctioning
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00008682
Solution Title	Fuel pressure relief valve is malfunctioning
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater High Side Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater High Side Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater Low Side Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater Low Side Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Bad Intelligent Device or Component
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Bad Intelligent Device or Component
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Bad Intelligent Device or Component
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Bad Intelligent Device or Component
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Regeneration Status - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Regeneration Status - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Regeneration Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Regeneration Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Self-Diagnosis - Abnormal Rate of Change
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Self-Diagnosis - Abnormal Rate of Change
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001027
Solution Title	Engine brake solenoid circuit pin to pin short
Update Reason	Solution Added
Date	23-Apr-2023
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001028
Solution Title	Engine brake solenoid circuit pin to pin short
Update Reason	Solution Removed
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Reordered

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011290
Solution Title	Aftertreatment particulate matter sensor has incorrect mounting or debris
Update Reason	Solution Added

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000713
Solution Title	Aftertreatment particulate matter sensor has incorrect mounting or debris
Update Reason	Solution Removed

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011290
Solution Title	Aftertreatment particulate matter sensor has incorrect mounting or debris
Update Reason	Solution Added

Date	23-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000713
Solution Title	Aftertreatment particulate matter sensor has incorrect mounting or debris
Update Reason	Solution Removed

Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Reordered

Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Modified
Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Reordered
Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Modified
Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment SCR Operator Inducement - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010289
Solution Title	Fault code is for information only
Update Reason	Solution Added
Date	16-Apr-2023
Fault Code / Symptom	Engine Protection Torque Derate - Condition Exists
Solution Number	S00010289
Solution Title	Fault code is for information only
Update Reason	Solution Added

Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00011169
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00011169
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Reordered
Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Modified
Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Reordered

Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Modified
Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment SCR Operator Inducement Severity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010289
Solution Title	Fault code is for information only
Update Reason	Solution Added
Date	16-Apr-2023
Fault Code / Symptom	Engine Protection Torque Derate - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002715
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	16-Apr-2023
Fault Code / Symptom	Engine Protection Torque Derate - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010289
Solution Title	Fault code is for information only
Update Reason	Solution Added
Date	16-Apr-2023
Fault Code / Symptom	Engine Protection Torque Derate - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002776
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00011169
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Reordered
Date	16-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Modified
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Consumption Excessive
Solution Number	S00000346
Solution Title	Incorrect aftertreatment diesel exhaust fluid dosing valve installed
Update Reason	Solution Reordered
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Consumption Excessive
Solution Number	S00000346
Solution Title	Incorrect aftertreatment diesel exhaust fluid dosing valve installed
Update Reason	Solution Modified

Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Reordered
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Modified
Date	09-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment Intake Gas Sensor Heater - Current Below Normal or Open Circuit
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Reordered
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment Intake Gas Sensor Heater - Current Below Normal or Open Circuit
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Modified
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Reordered
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Modified
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Rate of Change
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Reordered

Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Rate of Change
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Modified
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Reordered
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Modified
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Rate of Change
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	09-Apr-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Reordered
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Modified
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Reordered
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Modified
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00010945
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	02-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Reordered
Date	02-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Modified
Date	02-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00010717
Solution Title	Fault Code 1894 triggered by a malfunction in the J1939 data link with multiple OEM fault codes
Update Reason	Solution Reordered
Date	02-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00010717
Solution Title	Fault Code 1894 triggered by a malfunction in the J1939 data link with multiple OEM fault codes
Update Reason	Solution Modified
Date	02-Apr-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00011273
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	02-Apr-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00001983
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Added
Date	02-Apr-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	02-Apr-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	02-Apr-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00004051
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	02-Apr-2023
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000536
Solution Title	Low battery voltage
Update Reason	Solution Reordered
Date	02-Apr-2023
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000536
Solution Title	Low battery voltage
Update Reason	Solution Modified

Date	02-Apr-2023
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Reordered
Date	02-Apr-2023
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Modified
Date	02-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Reordered
Date	02-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Modified

Date	02-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003143
Solution Title	Fault Code 2636 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Reordered
Date	02-Apr-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003143
Solution Title	Fault Code 2636 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Modified
Date	02-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	02-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	02-Apr-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Reordered

Date	02-Apr-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Modified

Date	02-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater High Side Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000536
Solution Title	Low battery voltage
Update Reason	Solution Reordered

Date	02-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater High Side Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000536
Solution Title	Low battery voltage
Update Reason	Solution Modified

Date	02-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	02-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	02-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	26-Mar-2023
Fault Code / Symptom	Blue Smoke
Solution Number	S00005035
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	26-Mar-2023
Fault Code / Symptom	Engine Knock
Solution Number	S00001332
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Reordered
Date	26-Mar-2023
Fault Code / Symptom	Engine Knock
Solution Number	S00001332
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Modified
Date	26-Mar-2023
Fault Code / Symptom	Exhaust Noise
Solution Number	S00001332
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Reordered

Date	26-Mar-2023
Fault Code / Symptom	Exhaust Noise
Solution Number	S00001332
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Modified
Date	26-Mar-2023
Fault Code / Symptom	High Blowby
Solution Number	S00011059
Solution Title	Service Bulletin is available
Update Reason	Solution Added
Date	26-Mar-2023
Fault Code / Symptom	High Blowby
Solution Number	S00005035
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	26-Mar-2023
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00011256
Solution Title	Unswitched battery open circuit check
Update Reason	Solution Added
Date	26-Mar-2023
Fault Code / Symptom	Vibration
Solution Number	S00011259
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	26-Mar-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	26-Mar-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	19-Mar-2023
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011246
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011217
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009929
Solution Title	EGR leaks
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	05-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009948
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Removed
Date	05-Mar-2023
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011099
Solution Title	Wiring harness load test
Update Reason	Solution Added

Date	05-Mar-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00011099
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011099
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	EGR Valve Position Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011099
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00011099
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011005
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed

Date	05-Mar-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011099
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011099
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011099
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	05-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009929
Solution Title	EGR leaks
Update Reason	Solution Removed

Date	05-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	05-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	05-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009931
Solution Title	Charge Air Cooler Leak Test
Update Reason	Solution Removed
Date	05-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009948
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Consumption Excessive
Solution Number	S00011184
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Consumption Excessive
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	S00011196
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	S00011196
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00011184
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	26-Feb-2023
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00011185
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00011184
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00011176
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00004138
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Black Smoke
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Blue Smoke
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Blue Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Coolant Overflow
Solution Number	S00011189
Solution Title	Combustion gases entering the cooling system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Coolant Overflow
Solution Number	S00011192
Solution Title	Fuel injector o-rings or fuel injector sleeves are damaged
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Coolant Overflow
Solution Number	S00001212
Solution Title	Combustion gases entering the cooling system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Coolant Overflow
Solution Number	S00001271
Solution Title	Fuel injector o-rings or fuel injector sleeves are damaged
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00011189
Solution Title	Combustion gases entering the cooling system
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00011192
Solution Title	Fuel injector o-rings or fuel injector sleeves are damaged
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001212
Solution Title	Combustion gases entering the cooling system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001271
Solution Title	Fuel injector o-rings or fuel injector sleeves are damaged
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Brake Slow Activation
Solution Number	S00011176
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Engine Brake Slow Activation
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Noise
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Engine Noise
Solution Number	S00011184
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Engine Noise
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Engine Noise
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Noise
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011185
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011182
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011184
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00011176
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	26-Feb-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00004138
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000559
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00011176
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Exhaust Leak
Solution Number	S00011184
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Exhaust Leak
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Exhaust Noise
Solution Number	S00011184
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Exhaust Noise
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	External Coolant Leak
Solution Number	S00011189
Solution Title	Combustion gases entering the cooling system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	External Coolant Leak
Solution Number	S00011192
Solution Title	Fuel injector o-rings or fuel injector sleeves are damaged
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	External Coolant Leak
Solution Number	S00001212
Solution Title	Combustion gases entering the cooling system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	External Coolant Leak
Solution Number	S00001271
Solution Title	Fuel injector o-rings or fuel injector sleeves are damaged
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00011184
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Low Power
Solution Number	S00011167
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Low Power
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Low Power
Solution Number	S00004138
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed

Date	26-Feb-2023
Fault Code / Symptom	Low Power
Solution Number	S00000559
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Low Power
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Low Power
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Low Power
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00011185
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00011184
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00011176
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00004138
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed

Date	26-Feb-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00011176
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00011183
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00011184
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00011181
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00011176
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed

Date	26-Feb-2023
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000362
Solution Title	Lubricating oil temperature sensor resistance check
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000362
Solution Title	Lubricating oil temperature sensor resistance check
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Root Cause Not Known
Solution Number	S00005092
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	EGR Valve Position Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00011101
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed

Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00010306
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001034
Solution Title	Engine intake throttle actuator not responding or out of adjustment
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Removed

Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010321
Solution Title	Aftertreatment Outlet NOx Sensor Test
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010306
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Removed

Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010303
Solution Title	Aftertreatment power relay voltage check
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010305
Solution Title	Aftertreatment power relay resistance check
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010333
Solution Title	Aftertreatment outlet NOx sensor circuit check
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010368
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Removed

Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000872
Solution Title	Aftertreatment outlet NOx sensor open circuit
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011101
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010306
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Quality - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005092
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Rate of Change
Solution Number	S00005092
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005092
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00011171
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005092
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005092
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Condition Exists
Solution Number	S00005092
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	20-Feb-2023
Fault Code / Symptom	Crank No Start
Solution Number	S00011015
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	20-Feb-2023
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00010936
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	External Fuel Leak
Solution Number	S00010936
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011162
Solution Title	Crankcase breather restriction check (external)
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011163
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000635
Solution Title	Crankcase breather restriction check
Update Reason	Solution Removed

Date	20-Feb-2023
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000636
Solution Title	Crankcase pressure sensor or breather element check
Update Reason	Solution Removed
Date	20-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00011169
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00011169
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00011190
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	20-Feb-2023
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00001035
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	20-Feb-2023
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00011190
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	20-Feb-2023
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00001036
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	20-Feb-2023
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00011190
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	20-Feb-2023
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00001037
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	20-Feb-2023
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00011190
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	20-Feb-2023
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00001038
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	20-Feb-2023
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00011190
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	20-Feb-2023
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00001039
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	20-Feb-2023
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00011190
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	20-Feb-2023
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00001040
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	20-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00011169
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Reordered
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Modified
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Reordered
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Modified

Date	12-Feb-2023
Fault Code / Symptom	VGT Actuator Controller - Out of Calibration
Solution Number	S00011154
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Reordered
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Modified
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Reordered
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Modified

Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Reordered
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Modified
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011147
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Reordered
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Modified
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Reordered
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Modified

Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Reordered
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Modified
Date	12-Feb-2023
Fault Code / Symptom	VGT Actuator Controller - Special Instructions
Solution Number	S00011154
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Reordered
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Modified

Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Reordered
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Modified
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Reordered
Date	12-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Modified

Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001131
Solution Title	OEM wiring harness has a short to battery
Update Reason	Solution Reordered

Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001131
Solution Title	OEM wiring harness has a short to battery
Update Reason	Solution Modified
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00002879
Solution Title	Aftertreatment diesel exhaust fluid line heater is malfunctioning
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001158
Solution Title	Aftertreatment diesel exhaust fluid line heater circuit is malfunctioning
Update Reason	Solution Removed
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001159
Solution Title	Aftertreatment diesel exhaust fluid line heater open circuit check
Update Reason	Solution Removed

Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001131
Solution Title	OEM wiring harness has a short to battery
Update Reason	Solution Reordered
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001131
Solution Title	OEM wiring harness has a short to battery
Update Reason	Solution Modified
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00002879
Solution Title	Aftertreatment diesel exhaust fluid line heater is malfunctioning
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001158
Solution Title	Aftertreatment diesel exhaust fluid line heater circuit is malfunctioning
Update Reason	Solution Removed

Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001159
Solution Title	Aftertreatment diesel exhaust fluid line heater open circuit check
Update Reason	Solution Removed
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001131
Solution Title	OEM wiring harness has a short to battery
Update Reason	Solution Reordered
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001131
Solution Title	OEM wiring harness has a short to battery
Update Reason	Solution Modified
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00002879
Solution Title	Aftertreatment diesel exhaust fluid line heater is malfunctioning
Update Reason	Solution Added

Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001373
Solution Title	Aftertreatment diesel exhaust fluid line heater 3 short circuit
Update Reason	Solution Removed
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001158
Solution Title	Aftertreatment diesel exhaust fluid line heater circuit is malfunctioning
Update Reason	Solution Removed
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001159
Solution Title	Aftertreatment diesel exhaust fluid line heater open circuit check
Update Reason	Solution Removed
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000832
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay pin to pin short check
Update Reason	Solution Reordered

Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000832
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay pin to pin short check
Update Reason	Solution Modified
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000832
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay pin to pin short check
Update Reason	Solution Reordered
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000832
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay pin to pin short check
Update Reason	Solution Modified
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000835
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay open circuit check
Update Reason	Solution Removed

Date	05-Feb-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00001244
Solution Title	Variable geometry turbocharger actuator voltage check at the ECM
Update Reason	Solution Added

Date	05-Feb-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00001120
Solution Title	Variable geometry turbocharger actuator is not communicating
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00007914
Solution Title	Variable geometry turbocharger actuator is not communicating
Update Reason	Solution Removed
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing System Frozen - Condition Exists
Solution Number	S00002879
Solution Title	Aftertreatment diesel exhaust fluid line heater is malfunctioning
Update Reason	Solution Added
Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	05-Feb-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	29-Jan-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Jan-2023
Fault Code / Symptom	VGT Actuator Driver Circuit (Motor) - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Jan-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011102
Solution Title	Exhaust gas pressure sensor is malfunctioning
Update Reason	Solution Added
Date	29-Jan-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00003039
Solution Title	Exhaust gas pressure sensor is malfunctioning
Update Reason	Solution Removed

Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010942
Solution Title	Aftertreatment DPF differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002710
Solution Title	Aftertreatment DPF differential pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000796
Solution Title	Aftertreatment diesel exhaust fluid line heater relay is malfunctioning
Update Reason	Solution Reordered
Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000796
Solution Title	Aftertreatment diesel exhaust fluid line heater relay is malfunctioning
Update Reason	Solution Modified

Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000796
Solution Title	Aftertreatment diesel exhaust fluid line heater relay is malfunctioning
Update Reason	Solution Reordered
Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000796
Solution Title	Aftertreatment diesel exhaust fluid line heater relay is malfunctioning
Update Reason	Solution Modified
Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000796
Solution Title	Aftertreatment diesel exhaust fluid line heater relay is malfunctioning
Update Reason	Solution Reordered
Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000796
Solution Title	Aftertreatment diesel exhaust fluid line heater relay is malfunctioning
Update Reason	Solution Modified
Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Line Heater Relay - Voltage Above Normal or Shorted to High Source
Solution Number	S00000796
Solution Title	Aftertreatment diesel exhaust fluid line heater relay is malfunctioning
Update Reason	Solution Reordered
Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Line Heater Relay - Voltage Above Normal or Shorted to High Source
Solution Number	S00000796
Solution Title	Aftertreatment diesel exhaust fluid line heater relay is malfunctioning
Update Reason	Solution Modified

Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	22-Jan-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor check
Update Reason	Solution Reordered

Date	22-Jan-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor check
Update Reason	Solution Modified
Date	22-Jan-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor check
Update Reason	Solution Reordered
Date	22-Jan-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor check
Update Reason	Solution Modified
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Missing - Condition Exists
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Missing - Condition Exists
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	22-Jan-2023
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	22-Jan-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor check
Update Reason	Solution Reordered
Date	22-Jan-2023
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor check
Update Reason	Solution Modified
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	22-Jan-2023
Fault Code / Symptom	Brake Pedal Position - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	22-Jan-2023
Fault Code / Symptom	Brake Pedal Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011091
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00002831
Solution Title	Turbocharger speed sensor check
Update Reason	Solution Reordered
Date	22-Jan-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00002831
Solution Title	Turbocharger speed sensor check
Update Reason	Solution Modified
Date	22-Jan-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00002831
Solution Title	Turbocharger speed sensor check
Update Reason	Solution Reordered
Date	22-Jan-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00002831
Solution Title	Turbocharger speed sensor check
Update Reason	Solution Modified

Date	22-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	15-Jan-2023
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00001200
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Removed
Date	15-Jan-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed
Date	15-Jan-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed
Date	15-Jan-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed

Date	15-Jan-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Reordered
Date	15-Jan-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Modified
Date	15-Jan-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Reordered
Date	15-Jan-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Modified
Date	15-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	15-Jan-2023
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Added
Date	15-Jan-2023
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001244
Solution Title	Variable geometry turbocharger actuator voltage check at the ECM
Update Reason	Solution Added
Date	15-Jan-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Reordered
Date	15-Jan-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Modified
Date	15-Jan-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed

Date	15-Jan-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed
Date	15-Jan-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed
Date	15-Jan-2023
Fault Code / Symptom	Engine Cooling System Monitor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed
Date	15-Jan-2023
Fault Code / Symptom	Engine Charge Air Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed

Date	15-Jan-2023
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011079
Solution Title	Verify coolant loss complaint
Update Reason	Solution Added
Date	15-Jan-2023
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003142
Solution Title	Coolant level check
Update Reason	Solution Removed
Date	15-Jan-2023
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	15-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	15-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00011076
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	15-Jan-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010905
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor open circuit check
Update Reason	Solution Reordered
Date	15-Jan-2023
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010905
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor open circuit check
Update Reason	Solution Modified
Date	15-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006220
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Added
Date	15-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008348
Solution Title	Aftertreatment diesel exhaust fluid dosing valve inlet filter
Update Reason	Solution Added

Date	15-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000862
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Removed
Date	08-Jan-2023
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	08-Jan-2023
Fault Code / Symptom	Air Handling Performance Test did not pass
Solution Number	S00011075
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	08-Jan-2023
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010935
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	08-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000564
Solution Title	Deposits in the SCR decomposition tube
Update Reason	Solution Reordered

Date	08-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000564
Solution Title	Deposits in the SCR decomposition tube
Update Reason	Solution Modified
Date	08-Jan-2023
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011078
Solution Title	EGR differential pressure sensor open circuit check
Update Reason	Solution Added
Date	08-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000564
Solution Title	Deposits in the SCR decomposition tube
Update Reason	Solution Reordered
Date	08-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000564
Solution Title	Deposits in the SCR decomposition tube
Update Reason	Solution Modified
Date	08-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00000564
Solution Title	Deposits in the SCR decomposition tube
Update Reason	Solution Reordered

Date	08-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00000564
Solution Title	Deposits in the SCR decomposition tube
Update Reason	Solution Modified
Date	08-Jan-2023
Fault Code / Symptom	Engine Injector Metering Rail 1 Cranking Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010935
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	08-Jan-2023
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	08-Jan-2023
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	08-Jan-2023
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	08-Jan-2023
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	08-Jan-2023
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	08-Jan-2023
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	08-Jan-2023
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	08-Jan-2023
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added

Date	08-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00000564
Solution Title	Deposits in the SCR decomposition tube
Update Reason	Solution Reordered
Date	08-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00000564
Solution Title	Deposits in the SCR decomposition tube
Update Reason	Solution Modified
Date	08-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00000564
Solution Title	Deposits in the SCR decomposition tube
Update Reason	Solution Reordered
Date	08-Jan-2023
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00000564
Solution Title	Deposits in the SCR decomposition tube
Update Reason	Solution Modified
Date	01-Jan-2023
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added

Date	01-Jan-2023
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Fan Not Running/Erratic Running
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Fan Runs Continuously/Excessive Operation
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Removed
Date	01-Jan-2023
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Removed
Date	11-Dec-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00003137
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Reordered

Date	11-Dec-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00003137
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Modified
Date	11-Dec-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Dec-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Dec-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Dec-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	11-Dec-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003137
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	11-Dec-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003137
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Modified
Date	11-Dec-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Dec-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Dec-2022
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	11-Dec-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Dec-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Dec-2022
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	04-Dec-2022
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00007906
Solution Title	Verify oil consumption complaint
Update Reason	Solution Removed
Date	04-Dec-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	27-Nov-2022
Fault Code / Symptom	Black Smoke
Solution Number	S00001202
Solution Title	Fuel injector is leaking
Update Reason	Solution Removed

Date	27-Nov-2022
Fault Code / Symptom	Black Smoke
Solution Number	S00001280
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed
Date	27-Nov-2022
Fault Code / Symptom	Low Power
Solution Number	S00001202
Solution Title	Fuel injector is leaking
Update Reason	Solution Removed
Date	27-Nov-2022
Fault Code / Symptom	Low Power
Solution Number	S00001280
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed
Date	27-Nov-2022
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000452
Solution Title	Remote accelerator pedal position sensor SIGNAL wire shorted to high source
Update Reason	Solution Removed
Date	27-Nov-2022
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000452
Solution Title	Remote accelerator pedal position sensor SIGNAL wire shorted to high source
Update Reason	Solution Removed

Date	27-Nov-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	20-Nov-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	20-Nov-2022
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011048
Solution Title	EGR valve circuit check
Update Reason	Solution Added
Date	20-Nov-2022
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	20-Nov-2022
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000720
Solution Title	EGR valve position sensor voltage check at the ECM
Update Reason	Solution Removed

Date	20-Nov-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	20-Nov-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	20-Nov-2022
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	20-Nov-2022
Fault Code / Symptom	EGR Valve Position Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011048
Solution Title	EGR valve circuit check
Update Reason	Solution Added
Date	20-Nov-2022
Fault Code / Symptom	EGR Valve Position Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added

Date	20-Nov-2022
Fault Code / Symptom	EGR Valve Position Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000720
Solution Title	EGR valve position sensor voltage check at the ECM
Update Reason	Solution Removed
Date	20-Nov-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	20-Nov-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added

Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added

Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed

Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added

Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	20-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00011047
Solution Title	Air intake system restricted
Update Reason	Solution Added

Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00011047
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00011047
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed

Date	13-Nov-2022
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000240
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	13-Nov-2022
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000257
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	06-Nov-2022
Fault Code / Symptom	Engine Brake Weak
Solution Number	S00001333
Solution Title	Worn exhaust brake rocker shaft detent pocket wear
Update Reason	Solution Reordered
Date	06-Nov-2022
Fault Code / Symptom	Engine Brake Weak
Solution Number	S00001333
Solution Title	Worn exhaust brake rocker shaft detent pocket wear
Update Reason	Solution Modified

Date	06-Nov-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00001333
Solution Title	Worn exhaust brake rocker shaft detent pocket wear
Update Reason	Solution Reordered

Date	06-Nov-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00001333
Solution Title	Worn exhaust brake rocker shaft detent pocket wear
Update Reason	Solution Modified

Date	06-Nov-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Removed

Date	06-Nov-2022
Fault Code / Symptom	Overhead Noise
Solution Number	S00001193
Solution Title	Camshaft inspection
Update Reason	Solution Reordered

Date	06-Nov-2022
Fault Code / Symptom	Overhead Noise
Solution Number	S00001193
Solution Title	Camshaft inspection
Update Reason	Solution Modified

Date	06-Nov-2022
Fault Code / Symptom	Overhead Noise
Solution Number	S00001333
Solution Title	Worn exhaust brake rocker shaft detent pocket wear
Update Reason	Solution Reordered

Date	06-Nov-2022
Fault Code / Symptom	Overhead Noise
Solution Number	S00001333
Solution Title	Worn exhaust brake rocker shaft detent pocket wear
Update Reason	Solution Modified
Date	06-Nov-2022
Fault Code / Symptom	Overhead Noise
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Removed
Date	06-Nov-2022
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00001193
Solution Title	Camshaft inspection
Update Reason	Solution Reordered
Date	06-Nov-2022
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00001193
Solution Title	Camshaft inspection
Update Reason	Solution Modified
Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000258
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000259
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000854
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000855
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000885
Solution Title	Incorrect aftertreatment intake NOx sensor installed
Update Reason	Solution Reordered

Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000885
Solution Title	Incorrect aftertreatment intake NOx sensor installed
Update Reason	Solution Modified
Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx - Out of Calibration
Solution Number	S00000885
Solution Title	Incorrect aftertreatment intake NOx sensor installed
Update Reason	Solution Reordered
Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx - Out of Calibration
Solution Number	S00000885
Solution Title	Incorrect aftertreatment intake NOx sensor installed
Update Reason	Solution Modified
Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor - Root Cause Not Known
Solution Number	S00000983
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor is malfunctioning
Update Reason	Solution Removed
Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011039
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00005075
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	06-Nov-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011021
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Crank No Start
Solution Number	S00010936
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	30-Oct-2022
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00010936
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed

Date	30-Oct-2022
Fault Code / Symptom	External Fuel Leak
Solution Number	S00010936
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	30-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007820
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed
Date	30-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Added

Date	30-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000352
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00002392
Solution Title	Intake manifold pressure sensor circuit response at the ECM
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007822
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	30-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Added

Date	30-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00007820
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed
Date	30-Oct-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Missing - Condition Exists
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	30-Oct-2022
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	30-Oct-2022
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	30-Oct-2022
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	30-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	30-Oct-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	30-Oct-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	30-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00011013
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	30-Oct-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Added

Date	30-Oct-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00007820
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed
Date	24-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011006
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	24-Oct-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011009
Solution Title	Fault Code 2692 requires that ALL solutions be performed
Update Reason	Solution Added
Date	24-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011005
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	24-Oct-2022
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000215
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	24-Oct-2022
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000214
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	24-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00011005
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Overhead Noise
Solution Number	S00010685
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	16-Oct-2022
Fault Code / Symptom	Coolant Level Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00010985
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Coolant Level Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010985
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	16-Oct-2022
Fault Code / Symptom	Coolant Level Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007921
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Coolant Level Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000499
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Removed
Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Reordered
Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Modified
Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011008
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Reordered
Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Modified

Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011008
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00008348
Solution Title	Aftertreatment diesel exhaust fluid dosing valve inlet filter
Update Reason	Solution Added

Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Reordered
Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Modified
Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00011008
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Added

Date	16-Oct-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000237
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	16-Oct-2022
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000238
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	16-Oct-2022
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000239
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	16-Oct-2022
Fault Code / Symptom	Wheel-Based Vehicle Speed - Abnormal Update Rate
Solution Number	S00010915
Solution Title	Vehicle speed sensor is malfunctioning
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008260
Solution Title	Aftertreatment diesel exhaust fluid pressure check
Update Reason	Solution Removed
Date	16-Oct-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000292
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	16-Oct-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000290
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	16-Oct-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added

Date	16-Oct-2022
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00000237
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	16-Oct-2022
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00000237
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	09-Oct-2022
Fault Code / Symptom	No Communication ECM to Component
Solution Number	S00010993
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication ECM to Component
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication ECM to Component
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00010993
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	09-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010992
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	02-Oct-2022
Fault Code / Symptom	Coolant Overflow
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Coolant Overflow
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered

Date	02-Oct-2022
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Fan Runs Continuously/Excessive Operation
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered

Date	02-Oct-2022
Fault Code / Symptom	Fan Runs Continuously/Excessive Operation
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00000898
Solution Title	Starter magnetic switch is malfunctioning
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00000898
Solution Title	Starter magnetic switch is malfunctioning
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Above Normal or Shorted to High Source
Solution Number	S00010966
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay open circuit check
Update Reason	Solution Added

Date	02-Oct-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010966
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay open circuit check
Update Reason	Solution Added
Date	02-Oct-2022
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Above Normal or Shorted to High Source
Solution Number	S00010966
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay open circuit check
Update Reason	Solution Added
Date	02-Oct-2022
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010966
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay open circuit check
Update Reason	Solution Added
Date	25-Sep-2022
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00010968
Solution Title	High fuel drain line restriction
Update Reason	Solution Added
Date	25-Sep-2022
Fault Code / Symptom	Lubricating Oil Level High
Solution Number	S00010968
Solution Title	High fuel drain line restriction
Update Reason	Solution Added

Date	25-Sep-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000616
Solution Title	Fuel rail pressure sensor voltage check
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000617
Solution Title	Fuel rail pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005779
Solution Title	Fuel rail pressure sensor circuit pin to ground short
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005780
Solution Title	Fuel rail pressure sensor circuit pin to pin short
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Missing - Condition Exists
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	25-Sep-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	25-Sep-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	25-Sep-2022
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00010982
Solution Title	Engine intake throttle actuator not responding or out of adjustment
Update Reason	Solution Added
Date	25-Sep-2022
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008863
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed

Date	25-Sep-2022
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000804
Solution Title	Open circuit in the engine intake throttle actuator motor
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000805
Solution Title	Engine intake throttle actuator motor resistance check
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000494
Solution Title	Engine intake throttle actuator motor open circuit check
Update Reason	Solution Removed
Date	25-Sep-2022
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000800
Solution Title	Intake throttle control actuator motor circuit pin to pin short
Update Reason	Solution Removed

Date	25-Sep-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	18-Sep-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000265
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	11-Sep-2022
Fault Code / Symptom	Crank No Start
Solution Number	S00010943
Solution Title	High-Pressure Fuel Pump Supply Flow Test
Update Reason	Solution Added
Date	11-Sep-2022
Fault Code / Symptom	Crank No Start
Solution Number	S00002777
Solution Title	High-Pressure Fuel Pump Performance Test
Update Reason	Solution Removed
Date	11-Sep-2022
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00010943
Solution Title	High-Pressure Fuel Pump Supply Flow Test
Update Reason	Solution Added
Date	11-Sep-2022
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00002777
Solution Title	High-Pressure Fuel Pump Performance Test
Update Reason	Solution Removed

Date	11-Sep-2022
Fault Code / Symptom	Low Power
Solution Number	S00010943
Solution Title	High-Pressure Fuel Pump Supply Flow Test
Update Reason	Solution Added
Date	11-Sep-2022
Fault Code / Symptom	Low Power
Solution Number	S00002777
Solution Title	High-Pressure Fuel Pump Performance Test
Update Reason	Solution Removed
Date	11-Sep-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010950
Solution Title	High-Pressure Fuel Pump Supply Flow Test
Update Reason	Solution Added
Date	11-Sep-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002146
Solution Title	High-Pressure Fuel Pump Performance Test
Update Reason	Solution Removed
Date	11-Sep-2022
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001031
Solution Title	Engine brake solenoid valve resistance check
Update Reason	Solution Removed

Date	11-Sep-2022
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000539
Solution Title	Engine brake solenoid valve resistance check
Update Reason	Solution Added
Date	11-Sep-2022
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001031
Solution Title	Engine brake solenoid valve resistance check
Update Reason	Solution Removed
Date	11-Sep-2022
Fault Code / Symptom	Engine Idle Fuel Quantity - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	11-Sep-2022
Fault Code / Symptom	Engine Injector Metering Rail 1 Cranking Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010950
Solution Title	High-Pressure Fuel Pump Supply Flow Test
Update Reason	Solution Added
Date	11-Sep-2022
Fault Code / Symptom	Engine Injector Metering Rail 1 Cranking Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002146
Solution Title	High-Pressure Fuel Pump Performance Test
Update Reason	Solution Removed

Date	11-Sep-2022
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000539
Solution Title	Engine brake solenoid valve resistance check
Update Reason	Solution Added
Date	11-Sep-2022
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001031
Solution Title	Engine brake solenoid valve resistance check
Update Reason	Solution Removed
Date	11-Sep-2022
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001031
Solution Title	Engine brake solenoid valve resistance check
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	Crank No Start
Solution Number	S00010936
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	30-Aug-2022
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00010936
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	30-Aug-2022
Fault Code / Symptom	External Fuel Leak
Solution Number	S00010936
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	30-Aug-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	30-Aug-2022
Fault Code / Symptom	J1939 Network #1 - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010935
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	30-Aug-2022
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010940
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Added

Date	30-Aug-2022
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000651
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	30-Aug-2022
Fault Code / Symptom	Accelerator Pedal Position 1 - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	Transmission Output Shaft Speed - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	Anti-Lock Braking (ABS) Controller - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	30-Aug-2022
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	Engine Injector Metering Rail 1 Cranking Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010935
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	30-Aug-2022
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	30-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00010942
Solution Title	Aftertreatment DPF differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	30-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00002710
Solution Title	Aftertreatment DPF differential pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	21-Aug-2022
Fault Code / Symptom	Engine Knock
Solution Number	S00009701
Solution Title	Overhead valve lash out of adjustment
Update Reason	Solution Added
Date	21-Aug-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00009701
Solution Title	Overhead valve lash out of adjustment
Update Reason	Solution Added

Date	21-Aug-2022
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00009701
Solution Title	Overhead valve lash out of adjustment
Update Reason	Solution Added
Date	21-Aug-2022
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00009701
Solution Title	Overhead valve lash out of adjustment
Update Reason	Solution Added
Date	21-Aug-2022
Fault Code / Symptom	Overhead Noise
Solution Number	S00009701
Solution Title	Overhead valve lash out of adjustment
Update Reason	Solution Added
Date	21-Aug-2022
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00009701
Solution Title	Overhead valve lash out of adjustment
Update Reason	Solution Added
Date	21-Aug-2022
Fault Code / Symptom	White Smoke
Solution Number	S00009701
Solution Title	Overhead valve lash out of adjustment
Update Reason	Solution Added
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010906
Solution Title	Aftertreatment DPF differential pressure sensor is malfunctioning
Update Reason	Solution Added

Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010099
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Removed
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001246
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001247
Solution Title	Aftertreatment DPF differential pressure sensor circuit check
Update Reason	Solution Removed
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000793
Solution Title	Aftertreatment DPF differential pressure sensor stuck in-range
Update Reason	Solution Removed

Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000996
Solution Title	Aftertreatment DPF differential pressure sensor open circuit check
Update Reason	Solution Removed
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001539
Solution Title	Aftertreatment DPF differential pressure sensor circuit pin to ground short
Update Reason	Solution Removed
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007506
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002710
Solution Title	Aftertreatment DPF differential pressure sensor is malfunctioning
Update Reason	Solution Removed

Date	21-Aug-2022
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000775
Solution Title	Exhaust gas pressure sensor circuit pin to pin short
Update Reason	Solution Removed
Date	21-Aug-2022
Fault Code / Symptom	Wheel-Based Vehicle Speed - Abnormal Update Rate
Solution Number	S00010912
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	21-Aug-2022
Fault Code / Symptom	Wheel-Based Vehicle Speed - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	21-Aug-2022
Fault Code / Symptom	Wheel-Based Vehicle Speed - Abnormal Update Rate
Solution Number	S00000902
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Removed
Date	21-Aug-2022
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added

Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Ash Load Percent - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010905
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor open circuit check
Update Reason	Solution Added
Date	14-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	14-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	14-Aug-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	07-Aug-2022
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008863
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	07-Aug-2022
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008863
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	07-Aug-2022
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00008863
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	07-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00010902
Solution Title	Aftertreatment DPF outlet pressure sensor voltage check
Update Reason	Solution Added
Date	07-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00010903
Solution Title	Aftertreatment DPF outlet pressure sensor circuit check
Update Reason	Solution Added

Date	07-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010902
Solution Title	Aftertreatment DPF outlet pressure sensor voltage check
Update Reason	Solution Added
Date	07-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010903
Solution Title	Aftertreatment DPF outlet pressure sensor circuit check
Update Reason	Solution Added
Date	07-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010902
Solution Title	Aftertreatment DPF outlet pressure sensor voltage check
Update Reason	Solution Added
Date	07-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010903
Solution Title	Aftertreatment DPF outlet pressure sensor circuit check
Update Reason	Solution Added

Date	07-Aug-2022
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000184
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	07-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00010902
Solution Title	Aftertreatment DPF outlet pressure sensor voltage check
Update Reason	Solution Added
Date	07-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00010903
Solution Title	Aftertreatment DPF outlet pressure sensor circuit check
Update Reason	Solution Added
Date	07-Aug-2022
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008863
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered
Date	07-Aug-2022
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008863
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified

Date	07-Aug-2022
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008863
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Reordered
Date	07-Aug-2022
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008863
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Modified
Date	31-Jul-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed

Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed

Date	31-Jul-2022
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed

Date	31-Jul-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed

Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001104
Solution Title	Aftertreatment DPF outlet pressure sensor voltage check
Update Reason	Solution Removed

Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001103
Solution Title	Aftertreatment DPF outlet pressure sensor circuit check
Update Reason	Solution Removed

Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001104
Solution Title	Aftertreatment DPF outlet pressure sensor voltage check
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001103
Solution Title	Aftertreatment DPF outlet pressure sensor circuit check
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001104
Solution Title	Aftertreatment DPF outlet pressure sensor voltage check
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001103
Solution Title	Aftertreatment DPF outlet pressure sensor circuit check
Update Reason	Solution Removed

Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00005916
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00001852
Solution Title	Fuse check
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00005940
Solution Title	Aftertreatment power relay is malfunctioning
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00005931
Solution Title	Aftertreatment intake NOx sensor open circuit check
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed

Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed

Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000184
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00001104
Solution Title	Aftertreatment DPF outlet pressure sensor voltage check
Update Reason	Solution Removed

Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00001103
Solution Title	Aftertreatment DPF outlet pressure sensor circuit check
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed

Date	31-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed
Date	24-Jul-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Reordered
Date	24-Jul-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Modified
Date	24-Jul-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Reordered

Date	24-Jul-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Modified
Date	24-Jul-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Reordered
Date	24-Jul-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Modified
Date	24-Jul-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006090
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added

Date	24-Jul-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	24-Jul-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	24-Jul-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Reordered
Date	24-Jul-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Modified

Date	24-Jul-2022
Fault Code / Symptom	Engine Cooling System Monitor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	24-Jul-2022
Fault Code / Symptom	Engine Charge Air Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	17-Jul-2022
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00002802
Solution Title	Fuel injector solenoid shorted by debris
Update Reason	Solution Removed
Date	17-Jul-2022
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00002802
Solution Title	Fuel injector solenoid shorted by debris
Update Reason	Solution Removed
Date	17-Jul-2022
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00002802
Solution Title	Fuel injector solenoid shorted by debris
Update Reason	Solution Removed

Date	17-Jul-2022
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00002802
Solution Title	Fuel injector solenoid shorted by debris
Update Reason	Solution Removed
Date	17-Jul-2022
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00002802
Solution Title	Fuel injector solenoid shorted by debris
Update Reason	Solution Removed
Date	17-Jul-2022
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00002802
Solution Title	Fuel injector solenoid shorted by debris
Update Reason	Solution Removed
Date	17-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001080
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	17-Jul-2022
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000138
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008569
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Root Cause Not Known
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Quality - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00008468
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Temperature 2 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Temperature 2 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Rate of Change
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00008468
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00008468
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor - Root Cause Not Known
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Ash Load Percent - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010777
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00010320
Solution Title	Aftertreatment Intake NOx Sensor Test
Update Reason	Solution Reordered

Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00010320
Solution Title	Aftertreatment Intake NOx Sensor Test
Update Reason	Solution Modified
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00010878
Solution Title	Aftertreatment Outlet NOx Sensor Test
Update Reason	Solution Added
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed

Date	17-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Removed
Date	10-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001079
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	10-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010851
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Added
Date	10-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000994
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Removed
Date	10-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00010851
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Added

Date	10-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00000994
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Removed
Date	10-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00000994
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Removed
Date	10-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted High
Solution Number	S00010851
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Added
Date	10-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted High
Solution Number	S00000994
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Removed
Date	10-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	S00010851
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Added

Date	10-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	S00000994
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Removed
Date	10-Jul-2022
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00010321
Solution Title	Aftertreatment Outlet NOx Sensor Test
Update Reason	Solution Removed
Date	10-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Root Cause Not Known
Solution Number	S00010851
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Added
Date	10-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Root Cause Not Known
Solution Number	S00000994
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Removed
Date	10-Jul-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00000994
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Removed

Date	04-Jul-2022
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000464
Solution Title	Loose or broken lubricating oil suction tube
Update Reason	Solution Reordered
Date	04-Jul-2022
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000464
Solution Title	Loose or broken lubricating oil suction tube
Update Reason	Solution Modified
Date	04-Jul-2022
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000464
Solution Title	Loose or broken lubricating oil suction tube
Update Reason	Solution Reordered
Date	04-Jul-2022
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000464
Solution Title	Loose or broken lubricating oil suction tube
Update Reason	Solution Modified
Date	04-Jul-2022
Fault Code / Symptom	J1939 Network #1 - Abnormal Update Rate
Solution Number	S00003428
Solution Title	ECM data link malfunction
Update Reason	Solution Removed

Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Added
Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00007559
Solution Title	Crankcase Blowby Check
Update Reason	Solution Removed
Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006713
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed
Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Removed

Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Added
Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00007559
Solution Title	Crankcase Blowby Check
Update Reason	Solution Removed
Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006713
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed
Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed

Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Removed
Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010850
Solution Title	Crankcase Blowby Check
Update Reason	Solution Added
Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00007559
Solution Title	Crankcase Blowby Check
Update Reason	Solution Removed
Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006713
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed

Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Removed
Date	04-Jul-2022
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	28-Jun-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000318
Solution Title	Reversed engine position sensors
Update Reason	Solution Reordered
Date	28-Jun-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000318
Solution Title	Reversed engine position sensors
Update Reason	Solution Modified

Date	28-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Missing - Condition Exists
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	28-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	28-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	28-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	28-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added

Date	28-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	28-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	28-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	28-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	28-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added

Date	28-Jun-2022
Fault Code / Symptom	Engine Protection Torque Derate - Condition Exists
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Removed
Date	28-Jun-2022
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	28-Jun-2022
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	28-Jun-2022
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010798
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	28-Jun-2022
Fault Code / Symptom	Engine Speed - Root Cause Not Known
Solution Number	S00000318
Solution Title	Reversed engine position sensors
Update Reason	Solution Reordered

Date	28-Jun-2022
Fault Code / Symptom	Engine Speed - Root Cause Not Known
Solution Number	S00000318
Solution Title	Reversed engine position sensors
Update Reason	Solution Modified
Date	12-Jun-2022
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00001151
Solution Title	High pressure pump head is leaking
Update Reason	Solution Removed
Date	12-Jun-2022
Fault Code / Symptom	J1939 Network #1 - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000334
Solution Title	Intake manifold temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	12-Jun-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000334
Solution Title	Intake manifold temperature sensor stuck in-range
Update Reason	Solution Modified

Date	12-Jun-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000334
Solution Title	Intake manifold temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	12-Jun-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000334
Solution Title	Intake manifold temperature sensor stuck in-range
Update Reason	Solution Modified
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Root Cause Not Known
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Ambient Air Density - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00010759
Solution Title	Fault code is for information only
Update Reason	Solution Added

Date	12-Jun-2022
Fault Code / Symptom	Ambient Air Density - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000172
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	12-Jun-2022
Fault Code / Symptom	Ambient Air Density - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000340
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Removed
Date	12-Jun-2022
Fault Code / Symptom	Ambient Air Density - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Removed
Date	12-Jun-2022
Fault Code / Symptom	Ambient Air Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000334
Solution Title	Intake manifold temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	12-Jun-2022
Fault Code / Symptom	Ambient Air Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000334
Solution Title	Intake manifold temperature sensor stuck in-range
Update Reason	Solution Modified

Date	12-Jun-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000334
Solution Title	Intake manifold temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	12-Jun-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000334
Solution Title	Intake manifold temperature sensor stuck in-range
Update Reason	Solution Modified
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	12-Jun-2022
Fault Code / Symptom	Accelerator Pedal Position 1 - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Transmission Output Shaft Speed - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Engine Charge Air Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000334
Solution Title	Intake manifold temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	12-Jun-2022
Fault Code / Symptom	Engine Charge Air Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000334
Solution Title	Intake manifold temperature sensor stuck in-range
Update Reason	Solution Modified

Date	12-Jun-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000334
Solution Title	Intake manifold temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	12-Jun-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000334
Solution Title	Intake manifold temperature sensor stuck in-range
Update Reason	Solution Modified
Date	12-Jun-2022
Fault Code / Symptom	Anti-Lock Braking (ABS) Controller - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Wheel-Based Vehicle Speed - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000851
Solution Title	Aftertreatment diesel exhaust fluid dosing valve circuit pin to ground short
Update Reason	Solution Removed
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00010758
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00006565
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Removed

Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010758
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006565
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Removed
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010758
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006565
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Removed

Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010758
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006565
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Removed
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Quality - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Temperature 2 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Temperature 2 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Rate of Change
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor - Root Cause Not Known
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	12-Jun-2022
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	12-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009049
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	05-Jun-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Condition Exists
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	05-Jun-2022
Fault Code / Symptom	Aftertreatment Intake NOx Sensor Test Did Not Complete
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	05-Jun-2022
Fault Code / Symptom	Aftertreatment Outlet NOx Sensor Test Did Not Complete
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	05-Jun-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004548
Solution Title	Air in fuel check
Update Reason	Solution Removed
Date	05-Jun-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00004548
Solution Title	Air in fuel check
Update Reason	Solution Removed
Date	05-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000984
Solution Title	Aftertreatment DPF differential pressure sensor open circuit check
Update Reason	Solution Removed

Date	05-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007506
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	05-Jun-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00001154
Solution Title	Aftertreatment diesel exhaust fluid dosing valve circuit pin to pin short
Update Reason	Solution Added
Date	05-Jun-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010338
Solution Title	Aftertreatment DPF temperature sensor module voltage check
Update Reason	Solution Added
Date	05-Jun-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010303
Solution Title	Aftertreatment power relay voltage check
Update Reason	Solution Added

Date	05-Jun-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010305
Solution Title	Aftertreatment power relay resistance check
Update Reason	Solution Added
Date	05-Jun-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010339
Solution Title	Aftertreatment DPF temperature sensor module circuit check
Update Reason	Solution Added
Date	05-Jun-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00010368
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Added
Date	05-Jun-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000925
Solution Title	Aftertreatment DPF temperature sensor module voltage check
Update Reason	Solution Removed

Date	29-May-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00010717
Solution Title	Fault Code 1894 triggered by a malfunction in the J1939 data link with multiple OEM fault codes
Update Reason	Solution Added
Date	29-May-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001109
Solution Title	Fault Code 1894 triggered by a malfunction in the J1939 data link with multiple OEM fault codes
Update Reason	Solution Removed
Date	22-May-2022
Fault Code / Symptom	Air Handling Performance Test did not start
Solution Number	S00010668
Solution Title	Key cycle is required
Update Reason	Solution Added
Date	15-May-2022
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Consumption Excessive
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Consumption Excessive
Solution Number	S00002515
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	15-May-2022
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00002515
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Engine Knock
Solution Number	S00010685
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	15-May-2022
Fault Code / Symptom	Engine Knock
Solution Number	S00005686
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00010685
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	15-May-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00005686
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed

Date	15-May-2022
Fault Code / Symptom	Exhaust Leak
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Exhaust Leak
Solution Number	S00002515
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Fuel Knock
Solution Number	S00010685
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	15-May-2022
Fault Code / Symptom	Fuel Knock
Solution Number	S00005686
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Overhead Noise
Solution Number	S00010685
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	15-May-2022
Fault Code / Symptom	Overhead Noise
Solution Number	S00005686
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed

Date	15-May-2022
Fault Code / Symptom	Coolant Level Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000727
Solution Title	Coolant level sensor voltage check
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Coolant Level Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000815
Solution Title	Coolant level sensor circuit check
Update Reason	Solution Removed
Date	08-May-2022
Fault Code / Symptom	Coolant Level Low
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	08-May-2022
Fault Code / Symptom	Lubricating Oil in the Coolant
Solution Number	S00000975
Solution Title	Internally leaking turbocharger bearing housing
Update Reason	Solution Removed
Date	08-May-2022
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed

Date	08-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Reordered

Date	08-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Modified

Date	08-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Reordered

Date	08-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Modified

Date	08-May-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Reordered

Date	08-May-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Modified
Date	08-May-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Removed
Date	08-May-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001852
Solution Title	Fuse check
Update Reason	Solution Removed
Date	08-May-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Removed
Date	08-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Reordered

Date	08-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Modified
Date	02-May-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000684
Solution Title	Engine crankshaft speed/position sensor check
Update Reason	Solution Added
Date	02-May-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009205
Solution Title	Crankshaft position sensor is damaged
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000684
Solution Title	Engine crankshaft speed/position sensor check
Update Reason	Solution Added

Date	02-May-2022
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00009205
Solution Title	Crankshaft position sensor is damaged
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed

Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Missing - Condition Exists
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed

Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009205
Solution Title	Crankshaft position sensor is damaged
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009205
Solution Title	Crankshaft position sensor is damaged
Update Reason	Solution Removed

Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00010321
Solution Title	Aftertreatment Outlet NOx Sensor Test
Update Reason	Solution Added
Date	02-May-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor - Root Cause Not Known
Solution Number	S00000982
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor is malfunctioning
Update Reason	Solution Added
Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00010321
Solution Title	Aftertreatment Outlet NOx Sensor Test
Update Reason	Solution Added
Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00010320
Solution Title	Aftertreatment Intake NOx Sensor Test
Update Reason	Solution Added

Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00010321
Solution Title	Aftertreatment Outlet NOx Sensor Test
Update Reason	Solution Added
Date	02-May-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00001197
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Removed
Date	17-Apr-2022
Fault Code / Symptom	High Blowby
Solution Number	S00001294
Solution Title	Lubricating oil level is incorrect
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Apr-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00003142
Solution Title	Coolant level check
Update Reason	Solution Added
Date	17-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00003142
Solution Title	Coolant level check
Update Reason	Solution Reordered
Date	17-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00003142
Solution Title	Coolant level check
Update Reason	Solution Modified

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003142
Solution Title	Coolant level check
Update Reason	Solution Reordered

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003142
Solution Title	Coolant level check
Update Reason	Solution Modified

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007852
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00003142
Solution Title	Coolant level check
Update Reason	Solution Reordered

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00003142
Solution Title	Coolant level check
Update Reason	Solution Modified
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007852
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Removed
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Removed
Date	17-Apr-2022
Fault Code / Symptom	Engine Oil Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008424
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	17-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in- range
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	VGT Actuator Driver Circuit (Motor) - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00003142
Solution Title	Coolant level check
Update Reason	Solution Reordered
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00003142
Solution Title	Coolant level check
Update Reason	Solution Modified
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00007852
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Removed
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Condition Exists
Solution Number	S00010599
Solution Title	Fault code is for information only
Update Reason	Solution Added
Date	17-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Condition Exists
Solution Number	S00001240
Solution Title	Fault code is for information only
Update Reason	Solution Removed
Date	17-Apr-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Apr-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00003142
Solution Title	Coolant level check
Update Reason	Solution Reordered

Date	17-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00003142
Solution Title	Coolant level check
Update Reason	Solution Modified
Date	17-Apr-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Apr-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003142
Solution Title	Coolant level check
Update Reason	Solution Reordered
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003142
Solution Title	Coolant level check
Update Reason	Solution Modified

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007852
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Removed
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Removed
Date	17-Apr-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Apr-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	17-Apr-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	17-Apr-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000540
Solution Title	Aftertreatment outlet NOx sensor has carbon buildup
Update Reason	Solution Reordered
Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000540
Solution Title	Aftertreatment outlet NOx sensor has carbon buildup
Update Reason	Solution Modified
Date	10-Apr-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009834
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed

Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	10-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003116
Solution Title	Radiator shutters malfunctioning (if equipped)
Update Reason	Solution Reordered

Date	10-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003116
Solution Title	Radiator shutters malfunctioning (if equipped)
Update Reason	Solution Modified

Date	10-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002161
Solution Title	Excessive coolant flow through OEM plumbing and heater cores
Update Reason	Solution Reordered
Date	10-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002161
Solution Title	Excessive coolant flow through OEM plumbing and heater cores
Update Reason	Solution Modified
Date	10-Apr-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009834
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000540
Solution Title	Aftertreatment outlet NOx sensor has carbon buildup
Update Reason	Solution Reordered
Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000540
Solution Title	Aftertreatment outlet NOx sensor has carbon buildup
Update Reason	Solution Modified

Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00000540
Solution Title	Aftertreatment outlet NOx sensor has carbon buildup
Update Reason	Solution Reordered

Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00000540
Solution Title	Aftertreatment outlet NOx sensor has carbon buildup
Update Reason	Solution Modified

Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted High
Solution Number	S00000540
Solution Title	Aftertreatment outlet NOx sensor has carbon buildup
Update Reason	Solution Reordered

Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted High
Solution Number	S00000540
Solution Title	Aftertreatment outlet NOx sensor has carbon buildup
Update Reason	Solution Modified

Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	S00000540
Solution Title	Aftertreatment outlet NOx sensor has carbon buildup
Update Reason	Solution Reordered

Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	S00000540
Solution Title	Aftertreatment outlet NOx sensor has carbon buildup
Update Reason	Solution Modified
Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00000540
Solution Title	Aftertreatment outlet NOx sensor has carbon buildup
Update Reason	Solution Reordered
Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00000540
Solution Title	Aftertreatment outlet NOx sensor has carbon buildup
Update Reason	Solution Modified
Date	03-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010587
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00010587
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	03-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00010587
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00010492
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00010303
Solution Title	Aftertreatment power relay voltage check
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00010305
Solution Title	Aftertreatment power relay resistance check
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00010514
Solution Title	Aftertreatment intake NOx sensor circuit check
Update Reason	Solution Added

Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00010368
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000880
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Removed
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000881
Solution Title	Aftertreatment intake NOx sensor circuit pin to ground short
Update Reason	Solution Removed
Date	03-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010587
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010492
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Added

Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010303
Solution Title	Aftertreatment power relay voltage check
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010305
Solution Title	Aftertreatment power relay resistance check
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010514
Solution Title	Aftertreatment intake NOx sensor circuit check
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010368
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000880
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Removed

Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000881
Solution Title	Aftertreatment intake NOx sensor circuit pin to ground short
Update Reason	Solution Removed
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010492
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010303
Solution Title	Aftertreatment power relay voltage check
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010305
Solution Title	Aftertreatment power relay resistance check
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010514
Solution Title	Aftertreatment intake NOx sensor circuit check
Update Reason	Solution Added

Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010368
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000880
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Removed
Date	03-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000881
Solution Title	Aftertreatment intake NOx sensor circuit pin to ground short
Update Reason	Solution Removed
Date	27-Mar-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Injector Power Supply - Bad Intelligent Device or Component
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Injector Power Supply - Bad Intelligent Device or Component
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000859
Solution Title	Fuel pump actuator has high resistance
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000859
Solution Title	Fuel pump actuator has high resistance
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000706
Solution Title	Battery power removed by battery disconnect switch
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000706
Solution Title	Battery power removed by battery disconnect switch
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00010368
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Added

Date	27-Mar-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010368
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Added
Date	27-Mar-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010368
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Added
Date	27-Mar-2022
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation 1 Valve 1 Control 1 - Condition Exists
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation 1 Valve 1 Control 1 - Condition Exists
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000859
Solution Title	Fuel pump actuator has high resistance
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000859
Solution Title	Fuel pump actuator has high resistance
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Engine Injector Metering Rail 1 Cold Start Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Engine Injector Metering Rail 1 Cold Start Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Engine Injector Metering Rail 1 Cold Start Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000859
Solution Title	Fuel pump actuator has high resistance
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Engine Injector Metering Rail 1 Cold Start Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000859
Solution Title	Fuel pump actuator has high resistance
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Fuel Level 1 - Out of Calibration
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Fuel Level 1 - Out of Calibration
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Fuel Level 2 - Out of Calibration
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Fuel Level 2 - Out of Calibration
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Engine Speed - Root Cause Not Known
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Engine Speed - Root Cause Not Known
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Accelerator Pedal Position 1 - Out of Calibration
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Accelerator Pedal Position 1 - Out of Calibration
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	20-Mar-2022
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	20-Mar-2022
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	20-Mar-2022
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	20-Mar-2022
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	20-Mar-2022
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	20-Mar-2022
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	20-Mar-2022
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	20-Mar-2022
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	20-Mar-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000916
Solution Title	Aftertreatment DPF temperature sensor module voltage check
Update Reason	Solution Removed
Date	20-Mar-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001066
Solution Title	Aftertreatment DPF temperature sensor module voltage check
Update Reason	Solution Removed
Date	20-Mar-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Ash Load Percent - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	06-Mar-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001120
Solution Title	Variable geometry turbocharger actuator is not communicating
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001120
Solution Title	Variable geometry turbocharger actuator is not communicating
Update Reason	Solution Removed

Date	06-Mar-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00010368
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00010355
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00001216
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00001216
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010354
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010364
Solution Title	EGR valve is leaking internally
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000164
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00010338
Solution Title	Aftertreatment DPF temperature sensor module voltage check
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00010303
Solution Title	Aftertreatment power relay voltage check
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00010305
Solution Title	Aftertreatment power relay resistance check
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00010339
Solution Title	Aftertreatment DPF temperature sensor module circuit check
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00010355
Solution Title	Aftertreatment power relay circuit check
Update Reason	Solution Added
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00010306
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Added

Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00010303
Solution Title	Aftertreatment power relay voltage check
Update Reason	Solution Added
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00010305
Solution Title	Aftertreatment power relay resistance check
Update Reason	Solution Added
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00010333
Solution Title	Aftertreatment outlet NOx sensor circuit check
Update Reason	Solution Added
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00000882
Solution Title	Aftertreatment outlet NOx sensor has incorrect voltage
Update Reason	Solution Removed
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00000883
Solution Title	Aftertreatment outlet NOx sensor open circuit
Update Reason	Solution Removed

Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010306
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Added
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010303
Solution Title	Aftertreatment power relay voltage check
Update Reason	Solution Added
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010305
Solution Title	Aftertreatment power relay resistance check
Update Reason	Solution Added
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00010333
Solution Title	Aftertreatment outlet NOx sensor circuit check
Update Reason	Solution Added
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000882
Solution Title	Aftertreatment outlet NOx sensor has incorrect voltage
Update Reason	Solution Removed

Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000883
Solution Title	Aftertreatment outlet NOx sensor open circuit
Update Reason	Solution Removed
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000869
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Removed
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000870
Solution Title	Battery circuit fuse has open circuit
Update Reason	Solution Removed
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000871
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Removed
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed

Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010306
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Added
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010303
Solution Title	Aftertreatment power relay voltage check
Update Reason	Solution Added
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010305
Solution Title	Aftertreatment power relay resistance check
Update Reason	Solution Added
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010333
Solution Title	Aftertreatment outlet NOx sensor circuit check
Update Reason	Solution Added
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000882
Solution Title	Aftertreatment outlet NOx sensor has incorrect voltage
Update Reason	Solution Removed

Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000883
Solution Title	Aftertreatment outlet NOx sensor open circuit
Update Reason	Solution Removed
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000869
Solution Title	Aftertreatment outlet NOx sensor voltage check
Update Reason	Solution Removed
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000870
Solution Title	Battery circuit fuse has open circuit
Update Reason	Solution Removed
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000871
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Removed
Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed

Date	27-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	20-Feb-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	20-Feb-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	20-Feb-2022
Fault Code / Symptom	Vibration
Solution Number	S00001378
Solution Title	Engine driven accessories damaged
Update Reason	Solution Reordered
Date	20-Feb-2022
Fault Code / Symptom	Vibration
Solution Number	S00001378
Solution Title	Engine driven accessories damaged
Update Reason	Solution Modified
Date	20-Feb-2022
Fault Code / Symptom	Vibration
Solution Number	S00001949
Solution Title	Engine mounts are damaged
Update Reason	Solution Reordered

Date	20-Feb-2022
Fault Code / Symptom	Vibration
Solution Number	S00001949
Solution Title	Engine mounts are damaged
Update Reason	Solution Modified
Date	20-Feb-2022
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000723
Solution Title	Engine brake solenoid circuit pin to ground short
Update Reason	Solution Added
Date	20-Feb-2022
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001027
Solution Title	Engine brake solenoid circuit pin to pin short
Update Reason	Solution Added
Date	20-Feb-2022
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000723
Solution Title	Engine brake solenoid circuit pin to ground short
Update Reason	Solution Added
Date	20-Feb-2022
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001027
Solution Title	Engine brake solenoid circuit pin to pin short
Update Reason	Solution Added

Date	20-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00010298
Solution Title	Aftertreatment diesel exhaust fluid quality sensor voltage check
Update Reason	Solution Added
Date	20-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00010303
Solution Title	Aftertreatment power relay voltage check
Update Reason	Solution Added
Date	20-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00010305
Solution Title	Aftertreatment power relay resistance check
Update Reason	Solution Added
Date	20-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00010304
Solution Title	Aftertreatment diesel exhaust fluid quality sensor circuit check
Update Reason	Solution Added
Date	20-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00000904
Solution Title	Aftertreatment diesel exhaust fluid quality sensor voltage check
Update Reason	Solution Removed

Date	20-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00000905
Solution Title	Aftertreatment diesel exhaust fluid quality sensor circuit check
Update Reason	Solution Removed
Date	13-Feb-2022
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	06-Feb-2022
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Reordered
Date	06-Feb-2022
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Modified

Date	06-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Reordered

Date	06-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Modified

Date	06-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Reordered

Date	06-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Modified

Date	06-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Reordered
Date	06-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Modified
Date	06-Feb-2022
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Reordered
Date	06-Feb-2022
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Modified

Date	06-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Reordered
Date	06-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Modified
Date	06-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Reordered
Date	06-Feb-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Modified
Date	30-Jan-2022
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Reordered

Date	30-Jan-2022
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Modified
Date	30-Jan-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Reordered
Date	30-Jan-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Modified
Date	30-Jan-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Reordered
Date	30-Jan-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Modified
Date	09-Jan-2022
Fault Code / Symptom	Belt Fraying/Belt Wear
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Reordered

Date	09-Jan-2022
Fault Code / Symptom	Belt Fraying/Belt Wear
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Modified
Date	09-Jan-2022
Fault Code / Symptom	Belt Noise/Whining
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Reordered
Date	09-Jan-2022
Fault Code / Symptom	Belt Noise/Whining
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Modified
Date	09-Jan-2022
Fault Code / Symptom	Coolant Overflow
Solution Number	S00002071
Solution Title	Cooling system pressure cap is malfunctioning
Update Reason	Solution Reordered
Date	09-Jan-2022
Fault Code / Symptom	Coolant Overflow
Solution Number	S00002071
Solution Title	Cooling system pressure cap is malfunctioning
Update Reason	Solution Modified
Date	09-Jan-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Reordered

Date	09-Jan-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Modified
Date	09-Jan-2022
Fault Code / Symptom	Fan Not Running/Erratic Running
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Reordered
Date	09-Jan-2022
Fault Code / Symptom	Fan Not Running/Erratic Running
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Modified
Date	09-Jan-2022
Fault Code / Symptom	Vibration
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Reordered
Date	09-Jan-2022
Fault Code / Symptom	Vibration
Solution Number	S00001273
Solution Title	Front end belt driven accessories
Update Reason	Solution Modified
Date	09-Jan-2022
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00009814
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00009814
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00009814
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00009814
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00009814
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00009814
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001852
Solution Title	Fuse check
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Sensor Supply 4 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000724
Solution Title	ECM sensor supply 4 voltage above normal
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00001852
Solution Title	Fuse check
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000882
Solution Title	Aftertreatment outlet NOx sensor has incorrect voltage
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000883
Solution Title	Aftertreatment outlet NOx sensor open circuit
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001852
Solution Title	Fuse check
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00001852
Solution Title	Fuse check
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Air Shutoff Status - Special Instructions
Solution Number	S00000091
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	12-Dec-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010099
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Added
Date	12-Dec-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Missing - Condition Exists
Solution Number	S00010099
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Added

Date	12-Dec-2021
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010099
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Added
Date	12-Dec-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010096
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Added
Date	12-Dec-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00010099
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Added
Date	12-Dec-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00010099
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Added
Date	12-Dec-2021
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted High
Solution Number	S00010098
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Added

Date	12-Dec-2021
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	S00010098
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Added
Date	12-Dec-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00010099
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Added
Date	12-Dec-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00010099
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Added
Date	05-Dec-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Condition Exists
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	05-Dec-2021
Fault Code / Symptom	Air Handling Performance Test did not complete
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	05-Dec-2021
Fault Code / Symptom	Air Handling Performance Test did not pass
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	05-Dec-2021
Fault Code / Symptom	Air Handling Performance Test did not start
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	05-Dec-2021
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Consumption Excessive
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	05-Dec-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00010138
Solution Title	Maximum DPF outlet temperature in the regeneration history is above specification
Update Reason	Solution Added
Date	05-Dec-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00010155
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Added
Date	05-Dec-2021
Fault Code / Symptom	Exhaust Leak
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added

Date	05-Dec-2021
Fault Code / Symptom	Exhaust Noise
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	05-Dec-2021
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	05-Dec-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	05-Dec-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added

Date	05-Dec-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	05-Dec-2021
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	05-Dec-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	05-Dec-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00010054
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	29-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000484
Solution Title	Radiator shutters malfunctioning (if equipped)
Update Reason	Solution Added
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater High Side Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater Low Side Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Regeneration Status - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Power Supply - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Power Supply - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Power Supply - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Detection Status - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Regeneration Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater High Side Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater Low Side Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Temperature Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Sensor Module - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Sensor Module - Current Above Normal or Grounded Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Sensor Module Voltage Converter - Bad Intelligent Device or Component
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	29-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002207
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	21-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002207
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	21-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Crank No Start
Solution Number	S00004043
Solution Title	High exhaust restriction
Update Reason	Solution Removed

Date	14-Nov-2021
Fault Code / Symptom	Crank No Start
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Crank No Start
Solution Number	S00004044
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00004043
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00004044
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001246
Solution Title	Aftertreatment DPF differential pressure sensor voltage check
Update Reason	Solution Added

Date	14-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001247
Solution Title	Aftertreatment DPF differential pressure sensor circuit check
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001104
Solution Title	Aftertreatment DPF outlet pressure sensor voltage check
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001103
Solution Title	Aftertreatment DPF outlet pressure sensor open circuit check
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	14-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	14-Nov-2021
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00009929
Solution Title	EGR leaks
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00004969
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009929
Solution Title	EGR leaks
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000101
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	14-Nov-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009929
Solution Title	EGR leaks
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00001104
Solution Title	Aftertreatment DPF outlet pressure sensor voltage check
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00001103
Solution Title	Aftertreatment DPF outlet pressure sensor open circuit check
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	14-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	14-Nov-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	14-Nov-2021
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009929
Solution Title	EGR leaks
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Stationary Regeneration Will Not Start
Solution Number	S00002863
Solution Title	Vehicle speed sensor is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Stationary Regeneration Will Not Start
Solution Number	S00002865
Solution Title	Vehicle speed sensor resistance check
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000463
Solution Title	Variable Geometry Turbocharger Hysteresis Test
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005632
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000324
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000463
Solution Title	Variable Geometry Turbocharger Hysteresis Test
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000465
Solution Title	EGR leaks
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008465
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001048
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in- range
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009952
Solution Title	EGR valve restricted
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000681
Solution Title	EGR valve restricted
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Condition Exists
Solution Number	S00009956
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Condition Exists
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009957
Solution Title	EGR differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001115
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00003480
Solution Title	EGR differential pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005090
Solution Title	EGR temperature sensor circuit pin to ground short
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005079
Solution Title	EGR temperature sensor circuit pin to pin short
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001010
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Missing - Condition Exists
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Missing - Condition Exists
Solution Number	S00001010
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Missing - Condition Exists
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Missing - Condition Exists
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009956
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	VGT Actuator Driver Circuit (Motor) - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	VGT Actuator Driver Circuit (Motor) - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009956
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009956
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009932
Solution Title	Variable Geometry Turbocharger Hysteresis Test
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000463
Solution Title	Variable Geometry Turbocharger Hysteresis Test
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001010
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009956
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000348
Solution Title	EGR valve is leaking internally
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001029
Solution Title	EGR cooler plugged or restricted
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001010
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000348
Solution Title	EGR valve is leaking internally
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001029
Solution Title	EGR cooler plugged or restricted
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009953
Solution Title	EGR cooler plugged or restricted
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001116
Solution Title	EGR cooler plugged or restricted
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009946
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005632
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001048
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001010
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001115
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001116
Solution Title	EGR cooler plugged or restricted
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000348
Solution Title	EGR valve is leaking internally
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005090
Solution Title	EGR temperature sensor circuit pin to ground short
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005079
Solution Title	EGR temperature sensor circuit pin to pin short
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in- range
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00000465
Solution Title	EGR leaks
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00001010
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00001010
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000795
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001116
Solution Title	EGR cooler plugged or restricted
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000681
Solution Title	EGR valve restricted
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003480
Solution Title	EGR differential pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000795
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000681
Solution Title	EGR valve restricted
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000324
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00003480
Solution Title	EGR differential pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00000681
Solution Title	EGR valve restricted
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00003480
Solution Title	EGR differential pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00009950
Solution Title	High exhaust restriction
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00009916
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00000324
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00000465
Solution Title	EGR leaks
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000465
Solution Title	EGR leaks
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00008465
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009950
Solution Title	High exhaust restriction
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000324
Solution Title	High exhaust restriction
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000465
Solution Title	EGR leaks
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009948
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000465
Solution Title	EGR leaks
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00008465
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted High
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00007914
Solution Title	Variable geometry turbocharger actuator is not communicating
Update Reason	Solution Reordered
Date	09-Jan-2022
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00007914
Solution Title	Variable geometry turbocharger actuator is not communicating
Update Reason	Solution Modified
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00001010
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00001010
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00009956
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00009956
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00009956
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00009956
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00009956
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00009956
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00009956
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00009950
Solution Title	High exhaust restriction
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00009946
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000324
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00001048
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00009950
Solution Title	High exhaust restriction
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00009956
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00009946
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000324
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00001048
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00009950
Solution Title	High exhaust restriction
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00001010
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00000324
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009149
Solution Title	Air Handling Performance Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000795
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000681
Solution Title	EGR valve restricted
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000324
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009944
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009931
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009950
Solution Title	High exhaust restriction
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009932
Solution Title	Variable Geometry Turbocharger Hysteresis Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009948
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009946
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in- range
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000324
Solution Title	High exhaust restriction
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000463
Solution Title	Variable Geometry Turbocharger Hysteresis Test
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000465
Solution Title	EGR leaks
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00008465
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00001048
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009924
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009926
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009932
Solution Title	Variable Geometry Turbocharger Hysteresis Test
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in- range
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000463
Solution Title	Variable Geometry Turbocharger Hysteresis Test
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed

Date	31-Oct-2021
Fault Code / Symptom	Crank No Start
Solution Number	S00009681
Solution Title	High exhaust restriction
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008180
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010083
Solution Title	EGR temperature sensor circuit pin to ground short
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010084
Solution Title	EGR temperature sensor circuit pin to pin short
Update Reason	Solution Added

Date	31-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006722
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008080
Solution Title	Aftertreatment DPF temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter 1 Conditions Not Met for Active Regeneration - Condition Exists
Solution Number	S00006722
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Removed

Date	31-Oct-2021
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00008180
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Quality - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Bad Intelligent Device or Component
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	31-Oct-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Bad Intelligent Device or Component
Solution Number	S00008080
Solution Title	Aftertreatment DPF temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00008180
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Engine Injector Metering Rail 1 Cold Start Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Added

Date	31-Oct-2021
Fault Code / Symptom	Engine Injector Metering Rail 1 Cold Start Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008180
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed
Date	24-Oct-2021
Fault Code / Symptom	Engine Oil Change Interval - Condition Exists
Solution Number	S00000671
Solution Title	Oil change interval maintenance warning
Update Reason	Solution Reordered
Date	24-Oct-2021
Fault Code / Symptom	Engine Oil Change Interval - Condition Exists
Solution Number	S00000671
Solution Title	Oil change interval maintenance warning
Update Reason	Solution Modified
Date	24-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Reordered
Date	24-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Modified

Date	24-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Rate of Change
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Reordered
Date	24-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Rate of Change
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Modified
Date	24-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Self-Diagnosis - Abnormal Rate of Change
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Reordered
Date	24-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Self-Diagnosis - Abnormal Rate of Change
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Modified
Date	24-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Self-Diagnosis - Abnormal Rate of Change
Solution Number	S00001012
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Removed

Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001432
Solution Title	Aftertreatment DPF temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001432
Solution Title	Aftertreatment DPF temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001432
Solution Title	Aftertreatment DPF temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001432
Solution Title	Aftertreatment DPF temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001432
Solution Title	Aftertreatment DPF temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Above Normal or Shorted to High Source
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Above Normal or Shorted to High Source
Solution Number	S00001432
Solution Title	Aftertreatment DPF temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001432
Solution Title	Aftertreatment DPF temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	17-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	17-Oct-2021
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Added
Date	10-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000886
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	03-Oct-2021
Fault Code / Symptom	Fuel in the Coolant
Solution Number	S00002998
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Removed
Date	03-Oct-2021
Fault Code / Symptom	Fuel in the Coolant
Solution Number	S00002967
Solution Title	Cylinder head coolant passage damaged
Update Reason	Solution Removed

Date	03-Oct-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00001539
Solution Title	Aftertreatment DPF differential pressure sensor circuit pin to ground short
Update Reason	Solution Removed
Date	03-Oct-2021
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00000708
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Black Smoke
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Black Smoke
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Black Smoke
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	19-Sep-2021
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Low Power
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	19-Sep-2021
Fault Code / Symptom	Low Power
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Low Power
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00003330
Solution Title	Lubricating oil pressure sensor stuck in-range
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed

Date	19-Sep-2021
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00002515
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00009627
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00009631
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00009851
Solution Title	Fault Code 3868 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Added

Date	19-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00005738
Solution Title	Fault Code 3868 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00005705
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor voltage check
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00009857
Solution Title	Fault Code 4572 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Added
Date	19-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00009856
Solution Title	Fault Code 4677 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Added

Date	12-Sep-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	12-Sep-2021
Fault Code / Symptom	EGR Valve Control Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00000773
Solution Title	EGR valve motor resistance check
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	12-Sep-2021
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Sep-2021
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	12-Sep-2021
Fault Code / Symptom	Engine Control Module Calibration Memory - Bad Intelligent Device or Component
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	Engine Starter Mode Overcrank Protection - Condition Exists
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Root Cause Not Known
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	Engine/Transmission Match - Out of Calibration
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Special Instructions
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Sep-2021
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added

Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Root Cause Not Known
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Added

Date	06-Sep-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Added

Date	06-Sep-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Added

Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Added

Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Added

Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Added

Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Added

Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Temperature 2 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Temperature 2 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Condition Exists
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added

Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Rate of Change
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Added

Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Temperature 2 - Root Cause Not Known
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Root Cause Not Known
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Added

Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added
Date	06-Sep-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Condition Exists
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Root Cause Not Known
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	ECU Power Output Supply Voltage 1 - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Temperature 2 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Temperature 2 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Condition Exists
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Rate of Change
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00005739
Solution Title	Fault Code 4572 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00005705
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor voltage check
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00005690
Solution Title	Fault Code 4677 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00005705
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor voltage check
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Temperature 2 - Root Cause Not Known
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Root Cause Not Known
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00000594
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00003176
Solution Title	OEM sensor voltage check
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00003331
Solution Title	J1939 data link harness pin to ground short circuit
Update Reason	Solution Removed

Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00001002
Solution Title	Incorrect terminating resistance in the J1939 data link by a J1939 data linked component
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00001003
Solution Title	J1939 wire resistance check at the crossover connector for each component
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Removed
Date	30-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Condition Exists
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Removed

Date	25-Aug-2021
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Reordered
Date	25-Aug-2021
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Modified
Date	25-Aug-2021
Fault Code / Symptom	Lubricating Oil Filter Plugging
Solution Number	S00001886
Solution Title	Incorrect lubricating oil filter
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001886
Solution Title	Incorrect lubricating oil filter
Update Reason	Solution Reordered
Date	25-Aug-2021
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001886
Solution Title	Incorrect lubricating oil filter
Update Reason	Solution Modified
Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Voltage Above Normal or Shorted to High Source
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Special Instructions
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00009782
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	15-Aug-2021
Fault Code / Symptom	Engine Brake Weak
Solution Number	S00000568
Solution Title	EGR valve is leaking internally
Update Reason	Solution Removed
Date	15-Aug-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00004548
Solution Title	Air in fuel check
Update Reason	Solution Added
Date	08-Aug-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00003137
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Added

Date	08-Aug-2021
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000769
Solution Title	EGR temperature sensor circuit response
Update Reason	Solution Removed
Date	08-Aug-2021
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001089
Solution Title	EGR temperature sensor circuit response at the ECM
Update Reason	Solution Removed
Date	08-Aug-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Property - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001232
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor is malfunctioning
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008388
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor voltage check
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00005386
Solution Title	Aftertreatment power relay open circuit check
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00005422
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor open circuit check
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000393
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor circuit response
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000942
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor open circuit check
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000696
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor circuit pin to ground short
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000697
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor circuit pin to pin short
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001174
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001232
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor is malfunctioning
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008388
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor voltage check
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00005386
Solution Title	Aftertreatment power relay open circuit check
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00005422
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor open circuit check
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000392
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor circuit response
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000942
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor open circuit check
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000697
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor circuit pin to pin short
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000947
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor circuit response (Hardwired)
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000757
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor circuit pin to ground short
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000680
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor circuit pin shorted to another pin
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00000729
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor open circuit check
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00000680
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor circuit pin shorted to another pin
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000339
Solution Title	OEM ambient air temperature sensor stuck in-range
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000729
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor open circuit check
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000680
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor circuit pin shorted to another pin
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Ambient Air Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000339
Solution Title	OEM ambient air temperature sensor stuck in-range
Update Reason	Solution Removed

Date	25-Jul-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000339
Solution Title	OEM ambient air temperature sensor stuck in-range
Update Reason	Solution Removed

Date	12-Jul-2021
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00008282
Solution Title	Aftertreatment inhibit feature setting is incorrect
Update Reason	Solution Reordered

Date	12-Jul-2021
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00008282
Solution Title	Aftertreatment inhibit feature setting is incorrect
Update Reason	Solution Modified
Date	12-Jul-2021
Fault Code / Symptom	Engine Brake Slow Activation
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	12-Jul-2021
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	12-Jul-2021
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00005336
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	12-Jul-2021
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added

Date	12-Jul-2021
Fault Code / Symptom	Low Power
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	12-Jul-2021
Fault Code / Symptom	Low Power
Solution Number	S00005336
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	12-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater High Side Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	12-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater High Side Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Removed
Date	12-Jul-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Bad Intelligent Device or Component
Solution Number	S00008080
Solution Title	Aftertreatment DPF temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	12-Jul-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Bad Intelligent Device or Component
Solution Number	S00001432
Solution Title	Aftertreatment DPF temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	05-Jul-2021
Fault Code / Symptom	Air Compressor Pumping Coolant
Solution Number	S00009574
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (two cylinder)
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Coolant Overflow
Solution Number	S00009574
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (two cylinder)
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Coolant in the Lubricating Oil
Solution Number	S00009574
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (two cylinder)
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Crank No Start
Solution Number	S00001217
Solution Title	Cranking State malfunction
Update Reason	Solution Reordered

Date	05-Jul-2021
Fault Code / Symptom	Crank No Start
Solution Number	S00001217
Solution Title	Cranking State malfunction
Update Reason	Solution Modified
Date	05-Jul-2021
Fault Code / Symptom	Internal Coolant Leak
Solution Number	S00009574
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (two cylinder)
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002897
Solution Title	High exhaust restriction
Update Reason	Solution Reordered
Date	05-Jul-2021
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002897
Solution Title	High exhaust restriction
Update Reason	Solution Modified
Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Added

Date	27-Jun-2021
Fault Code / Symptom	Lubricating Oil Pressure High
Solution Number	S00009535
Solution Title	Lubricating oil pressure relief valve is malfunctioning
Update Reason	Solution Added
Date	27-Jun-2021
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00009535
Solution Title	Lubricating oil pressure relief valve is malfunctioning
Update Reason	Solution Added
Date	27-Jun-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Added
Date	27-Jun-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor - Abnormal Rate of Change
Solution Number	S00004330
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor is malfunctioning
Update Reason	Solution Removed
Date	21-Jun-2021
Fault Code / Symptom	Lubricating Oil Pressure High
Solution Number	S00000312
Solution Title	Lubricating oil pressure relief valve is malfunctioning
Update Reason	Solution Removed

Date	21-Jun-2021
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00000312
Solution Title	Lubricating oil pressure relief valve is malfunctioning
Update Reason	Solution Removed
Date	21-Jun-2021
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00008682
Solution Title	Fuel pressure relief valve is malfunctioning
Update Reason	Solution Added
Date	14-Jun-2021
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00001202
Solution Title	Fuel injector is leaking
Update Reason	Solution Removed
Date	14-Jun-2021
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00001280
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed
Date	14-Jun-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Removed

Date	09-Jun-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	09-Jun-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	16-May-2021
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	16-May-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000341
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Reordered

Date	16-May-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000341
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Modified
Date	16-May-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000341
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	16-May-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000341
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Modified
Date	16-May-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	16-May-2021
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	16-May-2021
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Removed
Date	09-May-2021
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009205
Solution Title	Crankshaft position sensor is damaged
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Added

Date	09-May-2021
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00009205
Solution Title	Crankshaft position sensor is damaged
Update Reason	Solution Added

Date	09-May-2021
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Added

Date	09-May-2021
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Added

Date	09-May-2021
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009205
Solution Title	Crankshaft position sensor is damaged
Update Reason	Solution Added

Date	09-May-2021
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Added

Date	09-May-2021
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009205
Solution Title	Crankshaft position sensor is damaged
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000295
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	27-Apr-2021
Fault Code / Symptom	Lubricating Oil Filter Plugging
Solution Number	S00001322
Solution Title	Cracked fuel injector body or damaged injector o-ring
Update Reason	Solution Removed
Date	27-Apr-2021
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001021
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	18-Apr-2021
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Reordered
Date	18-Apr-2021
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Modified
Date	18-Apr-2021
Fault Code / Symptom	Will Not Crank
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Reordered
Date	18-Apr-2021
Fault Code / Symptom	Will Not Crank
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Modified
Date	18-Apr-2021
Fault Code / Symptom	Ambient Air Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000833
Solution Title	Ambient air temperature sensor open circuit check
Update Reason	Solution Removed
Date	18-Apr-2021
Fault Code / Symptom	Engine Air Shutoff Status - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	11-Apr-2021
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001113
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001113
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Sensor Supply 4 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003160
Solution Title	Sensor supply 4 circuit pin to pin short
Update Reason	Solution Removed

Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001113
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter 1 Conditions Not Met for Active Regeneration - Condition Exists
Solution Number	S00001113
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00001113
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Coolant in the Fuel
Solution Number	S00001309
Solution Title	Fuel injector o-rings or fuel injector sleeves are damaged (single cam injectors)
Update Reason	Solution Removed

Date	11-Apr-2021
Fault Code / Symptom	Coolant in the Fuel
Solution Number	S00001312
Solution Title	Top fuel injector sleeve inspection (single cam injectors)
Update Reason	Solution Removed
Date	11-Apr-2021
Fault Code / Symptom	Fuel in the Coolant
Solution Number	S00001309
Solution Title	Fuel injector o-rings or fuel injector sleeves are damaged (single cam injectors)
Update Reason	Solution Removed
Date	11-Apr-2021
Fault Code / Symptom	Fuel in the Coolant
Solution Number	S00001312
Solution Title	Top fuel injector sleeve inspection (single cam injectors)
Update Reason	Solution Removed
Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009031
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	VGT Actuator Driver Circuit (Motor) - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000599
Solution Title	Incorrect variable geometry turbocharger actuator installation
Update Reason	Solution Removed

Date	11-Apr-2021
Fault Code / Symptom	VGT Actuator Driver Circuit (Motor) - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00008994
Solution Title	Variable geometry turbocharger actuator calibration incorrect
Update Reason	Solution Removed
Date	11-Apr-2021
Fault Code / Symptom	VGT Actuator Controller - Out of Calibration
Solution Number	S00009051
Solution Title	Incorrect variable geometry turbocharger actuator installation
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	VGT Actuator Controller - Out of Calibration
Solution Number	S00000599
Solution Title	Incorrect variable geometry turbocharger actuator installation
Update Reason	Solution Removed
Date	11-Apr-2021
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008140
Solution Title	Engine intake throttle actuator voltage check at the ECM
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	U10001037
Solution Title	Water pump open circuit check
Update Reason	Solution Removed

Date	11-Apr-2021
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008140
Solution Title	Engine intake throttle actuator voltage check at the ECM
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	U10001037
Solution Title	Water pump open circuit check
Update Reason	Solution Removed
Date	11-Apr-2021
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008140
Solution Title	Engine intake throttle actuator voltage check at the ECM
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	U10001037
Solution Title	Water pump open circuit check
Update Reason	Solution Removed
Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00000251
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00000114
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00000251
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00000985
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	11-Apr-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor - Out of Calibration
Solution Number	S00002684
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor is malfunctioning
Update Reason	Solution Removed
Date	11-Apr-2021
Fault Code / Symptom	VGT Actuator Controller - Special Instructions
Solution Number	S00009051
Solution Title	Incorrect variable geometry turbocharger actuator installation
Update Reason	Solution Added

Date	11-Apr-2021
Fault Code / Symptom	VGT Actuator Controller - Special Instructions
Solution Number	S00000599
Solution Title	Incorrect variable geometry turbocharger actuator installation
Update Reason	Solution Removed
Date	29-Mar-2021
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Consumption Excessive
Solution Number	S00002923
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Added
Date	29-Mar-2021
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Consumption Excessive
Solution Number	S00000337
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Removed
Date	29-Mar-2021
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Consumption Low
Solution Number	S00000337
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Removed
Date	15-Mar-2021
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008993
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	15-Mar-2021
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00008993
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	15-Mar-2021
Fault Code / Symptom	VGT Actuator Driver Circuit (Motor) - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00008994
Solution Title	Variable geometry turbocharger actuator calibration incorrect
Update Reason	Solution Added
Date	15-Mar-2021
Fault Code / Symptom	VGT Actuator Controller - Out of Calibration
Solution Number	S00008994
Solution Title	Variable geometry turbocharger actuator calibration incorrect
Update Reason	Solution Added
Date	15-Mar-2021
Fault Code / Symptom	VGT Actuator Controller - Special Instructions
Solution Number	S00008994
Solution Title	Variable geometry turbocharger actuator calibration incorrect
Update Reason	Solution Added
Date	28-Feb-2021
Fault Code / Symptom	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000545
Solution Title	Water accumulation in the fuel filter
Update Reason	Solution Reordered

Date	28-Feb-2021
Fault Code / Symptom	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000545
Solution Title	Water accumulation in the fuel filter
Update Reason	Solution Modified
Date	28-Feb-2021
Fault Code / Symptom	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000545
Solution Title	Water accumulation in the fuel filter
Update Reason	Solution Reordered
Date	28-Feb-2021
Fault Code / Symptom	Water in Fuel Indicator - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000545
Solution Title	Water accumulation in the fuel filter
Update Reason	Solution Modified
Date	28-Feb-2021
Fault Code / Symptom	Engine Start Enable Device 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	28-Feb-2021
Fault Code / Symptom	Engine Start Enable Device 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	28-Feb-2021
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000353
Solution Title	Remote accelerator pedal position sensor circuit response
Update Reason	Solution Removed
Date	21-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004548
Solution Title	Air in fuel check
Update Reason	Solution Reordered
Date	21-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004548
Solution Title	Air in fuel check
Update Reason	Solution Modified
Date	21-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000620
Solution Title	Fuel pump actuator o-ring is malfunctioning
Update Reason	Solution Reordered
Date	21-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000620
Solution Title	Fuel pump actuator o-ring is malfunctioning
Update Reason	Solution Modified

Date	21-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005307
Solution Title	Loose or damaged fuel line fittings
Update Reason	Solution Removed
Date	21-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000860
Solution Title	Measured rail pressure is greater than commanded rail pressure
Update Reason	Solution Removed
Date	21-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001205
Solution Title	Air in fuel check
Update Reason	Solution Removed
Date	21-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002037
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed
Date	21-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002842
Solution Title	Fuel pump actuator o-ring is malfunctioning
Update Reason	Solution Removed

Date	21-Feb-2021
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	21-Feb-2021
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000353
Solution Title	Remote accelerator pedal position sensor circuit response
Update Reason	Solution Added
Date	21-Feb-2021
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	21-Feb-2021
Fault Code / Symptom	Aftertreatment SCR Operator Inducement - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Removed
Date	21-Feb-2021
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00004548
Solution Title	Air in fuel check
Update Reason	Solution Reordered

Date	21-Feb-2021
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00004548
Solution Title	Air in fuel check
Update Reason	Solution Modified
Date	21-Feb-2021
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000620
Solution Title	Fuel pump actuator o-ring is malfunctioning
Update Reason	Solution Reordered
Date	21-Feb-2021
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000620
Solution Title	Fuel pump actuator o-ring is malfunctioning
Update Reason	Solution Modified
Date	21-Feb-2021
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005307
Solution Title	Loose or damaged fuel line fittings
Update Reason	Solution Removed
Date	21-Feb-2021
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000860
Solution Title	Measured rail pressure is greater than commanded rail pressure
Update Reason	Solution Removed

Date	21-Feb-2021
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001205
Solution Title	Air in fuel check
Update Reason	Solution Removed

Date	21-Feb-2021
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002037
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed

Date	21-Feb-2021
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002842
Solution Title	Fuel pump actuator o-ring is malfunctioning
Update Reason	Solution Removed

Date	21-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00004548
Solution Title	Air in fuel check
Update Reason	Solution Reordered

Date	21-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00004548
Solution Title	Air in fuel check
Update Reason	Solution Modified

Date	21-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005307
Solution Title	Loose or damaged fuel line fittings
Update Reason	Solution Removed
Date	21-Feb-2021
Fault Code / Symptom	Engine Injector Metering Rail 1 Cold Start Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000860
Solution Title	Measured rail pressure is greater than commanded rail pressure
Update Reason	Solution Removed
Date	21-Feb-2021
Fault Code / Symptom	Engine Injector Metering Rail 1 Cold Start Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001205
Solution Title	Air in fuel check
Update Reason	Solution Removed
Date	21-Feb-2021
Fault Code / Symptom	Engine Injector Metering Rail 1 Cold Start Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002037
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed
Date	21-Feb-2021
Fault Code / Symptom	Engine Injector Metering Rail 1 Cold Start Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002842
Solution Title	Fuel pump actuator o-ring is malfunctioning
Update Reason	Solution Removed

Date	21-Feb-2021
Fault Code / Symptom	Electric Lift Pump for Engine Fuel Supply - Voltage Above Normal or Shorted to High Source
Solution Number	S00001051
Solution Title	Fuel lift pump supply voltage check
Update Reason	Solution Removed
Date	21-Feb-2021
Fault Code / Symptom	Electric Lift Pump for Engine Fuel Supply - Voltage Above Normal or Shorted to High Source
Solution Number	S00001052
Solution Title	Fuel lift pump voltage check at the ECM
Update Reason	Solution Removed
Date	14-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000620
Solution Title	Fuel pump actuator o-ring is malfunctioning
Update Reason	Solution Added
Date	14-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004548
Solution Title	Air in fuel check
Update Reason	Solution Added
Date	14-Feb-2021
Fault Code / Symptom	VGT Actuator Driver Circuit - Root Cause Not Known
Solution Number	S00000746
Solution Title	ECM or J1939 data link is malfunctioning
Update Reason	Solution Removed

Date	14-Feb-2021
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00004548
Solution Title	Air in fuel check
Update Reason	Solution Added
Date	14-Feb-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00004548
Solution Title	Air in fuel check
Update Reason	Solution Added
Date	14-Feb-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Self-Diagnosis - Abnormal Rate of Change
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Added
Date	14-Feb-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Added
Date	14-Feb-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000016
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Removed

Date	14-Feb-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	14-Feb-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter 1 Soot Sensor ECU Internal Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Removed
Date	07-Feb-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	07-Feb-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00000463
Solution Title	Variable Geometry Turbocharger Hysteresis Test
Update Reason	Solution Removed
Date	17-Mar-2021
Fault Code / Symptom	Real Time Clock - Abnormal Rate of Change
Solution Number	S00008886
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Fuel in the Coolant
Solution Number	S00002937
Solution Title	Contaminated coolant supply
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00008683
Solution Title	Service Bulletin is available
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00008683
Solution Title	Service Bulletin is available
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00002761
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00001245
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002761
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001245
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00002761
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00001245
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002761
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001245
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002761
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001245
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002761
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001245
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00002761
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00001245
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00002761
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00001245
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Fan Control Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001060
Solution Title	Fan control solenoid circuit pin to ground short
Update Reason	Solution Reordered
Date	17-Jan-2021
Fault Code / Symptom	Fan Control Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001060
Solution Title	Fan control solenoid circuit pin to ground short
Update Reason	Solution Modified

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00002761
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00001245
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002761
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001245
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002761
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002764
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001245
Solution Title	Aftertreatment Diesel Exhaust Fluid Doser Pump Override test
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	External Lubricating Oil Leak
Solution Number	S00000838
Solution Title	External oil leak
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00000838
Solution Title	External oil leak
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00000838
Solution Title	External oil leak
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008863
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008863
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00008863
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008388
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor voltage check
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00005386
Solution Title	Aftertreatment power relay open circuit check
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00005422
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor open circuit check
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001177
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor voltage check
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001237
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor open circuit check
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008388
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor voltage check
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00005386
Solution Title	Aftertreatment power relay open circuit check
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00005422
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor open circuit check
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001177
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor voltage check
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001237
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor open circuit check
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Missing - Condition Exists
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002689
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002689
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002689
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002689
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000890
Solution Title	Fuel pressure relief valve is malfunctioning
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000930
Solution Title	Aftertreatment SCR temperature sensor module is above normal operating range
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00002689
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002689
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008863
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008863
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	17-Jan-2021
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00008386
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	17-Jan-2021
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	10-Jan-2021
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	10-Jan-2021
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	10-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	10-Jan-2021
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000620
Solution Title	Fuel pump actuator o-ring is malfunctioning
Update Reason	Solution Removed
Date	10-Jan-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	10-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	10-Jan-2021
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001022
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay voltage check
Update Reason	Solution Added
Date	03-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Missing - Condition Exists
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Added
Date	03-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Missing - Condition Exists
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	03-Jan-2021
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Missing - Condition Exists
Solution Number	S00000647
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	03-Jan-2021
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00008815
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	03-Jan-2021
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00000647
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	13-Dec-2020
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001116
Solution Title	EGR cooler plugged or restricted
Update Reason	Solution Added
Date	29-Nov-2020
Fault Code / Symptom	High Blowby
Solution Number	S00001256
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed
Date	29-Nov-2020
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	U10001037
Solution Title	Water pump open circuit check
Update Reason	Solution Added

Date	29-Nov-2020
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008140
Solution Title	Engine intake throttle actuator voltage check at the ECM
Update Reason	Solution Removed
Date	29-Nov-2020
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	U10001037
Solution Title	Water pump open circuit check
Update Reason	Solution Added
Date	29-Nov-2020
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008140
Solution Title	Engine intake throttle actuator voltage check at the ECM
Update Reason	Solution Removed
Date	29-Nov-2020
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	U10001037
Solution Title	Water pump open circuit check
Update Reason	Solution Added
Date	29-Nov-2020
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008140
Solution Title	Engine intake throttle actuator voltage check at the ECM
Update Reason	Solution Removed

Date	22-Nov-2020
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Added

Date	22-Nov-2020
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00003131
Solution Title	Cooling fan component inspection
Update Reason	Solution Removed

Date	22-Nov-2020
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Added

Date	22-Nov-2020
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00003131
Solution Title	Cooling fan component inspection
Update Reason	Solution Removed

Date	22-Nov-2020
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Added

Date	22-Nov-2020
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00003131
Solution Title	Cooling fan component inspection
Update Reason	Solution Removed
Date	15-Nov-2020
Fault Code / Symptom	Crank No Start
Solution Number	S00001221
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed
Date	15-Nov-2020
Fault Code / Symptom	Fuel Knock
Solution Number	S00001221
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed
Date	15-Nov-2020
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001221
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed
Date	15-Nov-2020
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000978
Solution Title	Crankcase pressure sensor voltage check at the ECM
Update Reason	Solution Reordered

Date	15-Nov-2020
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000978
Solution Title	Crankcase pressure sensor voltage check at the ECM
Update Reason	Solution Modified
Date	15-Nov-2020
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000978
Solution Title	Crankcase pressure sensor voltage check at the ECM
Update Reason	Solution Reordered
Date	15-Nov-2020
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000978
Solution Title	Crankcase pressure sensor voltage check at the ECM
Update Reason	Solution Modified
Date	08-Nov-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00008526
Solution Title	Aftertreatment Warm Up and Diesel Exhaust Fluid Dosing System Test Failed
Update Reason	Solution Added
Date	08-Nov-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00001256
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed

Date	08-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008569
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	08-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008569
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	08-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008569
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	08-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008569
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	08-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00008468
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	08-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Temperature 2 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008569
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	08-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Temperature 2 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008569
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	08-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00008468
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	08-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00008468
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added

Date	08-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor - Root Cause Not Known
Solution Number	S00008569
Solution Title	Multiple Technical Service Bulletins are available
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00001376
Solution Title	Aftertreatment DPF inhibit switch is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00001325
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001010
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Removed

Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008077
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008077
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001426
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004316
Solution Title	Aftertreatment DOC temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004316
Solution Title	Aftertreatment DOC temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001426
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Bad Intelligent Device or Component
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Bad Intelligent Device or Component
Solution Number	S00001426
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Voltage Above Normal or Shorted to High Source
Solution Number	S00001426
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001426
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008077
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001426
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001426
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Special Instructions
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Special Instructions
Solution Number	S00001426
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00004316
Solution Title	Aftertreatment DOC temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00004316
Solution Title	Aftertreatment DOC temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00004316
Solution Title	Aftertreatment DOC temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00004316
Solution Title	Aftertreatment DOC temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00001426
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00001426
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00004310
Solution Title	Aftertreatment exhaust gas temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	01-Nov-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00001426
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	18-Oct-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00008286
Solution Title	Aftertreatment DPF outlet temperature is out of desired range
Update Reason	Solution Added
Date	18-Oct-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00008453
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	18-Oct-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00008340
Solution Title	Engine out NOx levels could not be modulated
Update Reason	Solution Added
Date	18-Oct-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00008282
Solution Title	Aftertreatment inhibit feature setting is incorrect
Update Reason	Solution Added

Date	18-Oct-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00008121
Solution Title	Only select solution titles with corresponding status messages displayed in Aftertreatment SCR System Test
Update Reason	Solution Removed
Date	18-Oct-2020
Fault Code / Symptom	Black Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	18-Oct-2020
Fault Code / Symptom	Black Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	18-Oct-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	18-Oct-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	18-Oct-2020
Fault Code / Symptom	Engine Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered

Date	18-Oct-2020
Fault Code / Symptom	Engine Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	18-Oct-2020
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	18-Oct-2020
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	18-Oct-2020
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	18-Oct-2020
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	18-Oct-2020
Fault Code / Symptom	Low Power
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered

Date	18-Oct-2020
Fault Code / Symptom	Low Power
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	18-Oct-2020
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	18-Oct-2020
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	18-Oct-2020
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	18-Oct-2020
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	18-Oct-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008465
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added

Date	18-Oct-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000780
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed

Date	18-Oct-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004310
Solution Title	Aftertreatment temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	18-Oct-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008079
Solution Title	Aftertreatment DOC temperature sensor module is malfunctioning
Update Reason	Solution Removed

Date	18-Oct-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004310
Solution Title	Aftertreatment temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	18-Oct-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00008465
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added

Date	18-Oct-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000780
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed

Date	18-Oct-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00008465
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added

Date	18-Oct-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000780
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed

Date	18-Oct-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00000717
Solution Title	Aftertreatment particulate matter sensor voltage check
Update Reason	Solution Reordered

Date	18-Oct-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00000717
Solution Title	Aftertreatment particulate matter sensor voltage check
Update Reason	Solution Modified
Date	18-Oct-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00000716
Solution Title	Fault Code 6688 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Reordered
Date	18-Oct-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00000716
Solution Title	Fault Code 6688 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Modified
Date	18-Oct-2020
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00008465
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	18-Oct-2020
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000780
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed

Date	11-Oct-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00008361
Solution Title	Exhaust flow rate is out of range
Update Reason	Solution Added
Date	11-Oct-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00008362
Solution Title	Air intake or exhaust system leaks
Update Reason	Solution Added
Date	11-Oct-2020
Fault Code / Symptom	Engine Oil Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00008424
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	11-Oct-2020
Fault Code / Symptom	Turbocharger 1 Compressor Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004923
Solution Title	Compressor intake temperature sensor stuck in-range
Update Reason	Solution Added
Date	04-Oct-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00008193
Solution Title	Only select solution titles with corresponding status messages displayed in Aftertreatment SCR System Test
Update Reason	Solution Added

Date	04-Oct-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00008234
Solution Title	Ambient temperature is too low
Update Reason	Solution Added
Date	04-Oct-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00008121
Solution Title	Only select solution titles with corresponding status messages displayed in Aftertreatment SCR System Test
Update Reason	Solution Added
Date	04-Oct-2020
Fault Code / Symptom	Stationary Regeneration Will Not Start
Solution Number	S00001305
Solution Title	Soot load too low to allow DPF active regeneration
Update Reason	Solution Removed
Date	04-Oct-2020
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	04-Oct-2020
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00000446
Solution Title	Internal ECM Error
Update Reason	Solution Removed

Date	04-Oct-2020
Fault Code / Symptom	Engine Oil Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000809
Solution Title	High coolant temperature causing high oil temperature
Update Reason	Solution Removed
Date	04-Oct-2020
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00000446
Solution Title	Internal ECM Error
Update Reason	Solution Removed
Date	04-Oct-2020
Fault Code / Symptom	Engine Exhaust Gas Recirculation 1 Valve 1 Control 1 - Condition Exists
Solution Number	S00000446
Solution Title	Internal ECM Error
Update Reason	Solution Removed
Date	04-Oct-2020
Fault Code / Symptom	Electric Lift Pump for Engine Fuel Supply - Voltage Above Normal or Shorted to High Source
Solution Number	S00001649
Solution Title	Electric fuel lift pump resistance check
Update Reason	Solution Reordered
Date	04-Oct-2020
Fault Code / Symptom	Electric Lift Pump for Engine Fuel Supply - Voltage Above Normal or Shorted to High Source
Solution Number	S00001649
Solution Title	Electric fuel lift pump resistance check
Update Reason	Solution Modified

Date	27-Sep-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00001376
Solution Title	Aftertreatment DPF inhibit switch is malfunctioning
Update Reason	Solution Removed
Date	27-Sep-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00001325
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Removed
Date	27-Sep-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008260
Solution Title	Aftertreatment diesel exhaust fluid pressure check
Update Reason	Solution Added
Date	27-Sep-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008348
Solution Title	Aftertreatment diesel exhaust fluid dosing valve inlet filter
Update Reason	Solution Added
Date	20-Sep-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00001350
Solution Title	Air intake or exhaust system leaks
Update Reason	Solution Removed

Date	20-Sep-2020
Fault Code / Symptom	Belt Fraying/Belt Wear
Solution Number	S00004006
Solution Title	Loose alternator belt
Update Reason	Solution Added
Date	20-Sep-2020
Fault Code / Symptom	Belt Noise/Whining
Solution Number	S00004006
Solution Title	Loose alternator belt
Update Reason	Solution Added
Date	20-Sep-2020
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00001210
Solution Title	Aftertreatment DPF differential pressure sensor tubes plugged
Update Reason	Solution Reordered
Date	20-Sep-2020
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00001210
Solution Title	Aftertreatment DPF differential pressure sensor tubes plugged
Update Reason	Solution Modified
Date	20-Sep-2020
Fault Code / Symptom	Sensor Supply 5 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	20-Sep-2020
Fault Code / Symptom	Sensor Supply 5 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	20-Sep-2020
Fault Code / Symptom	Aftertreatment Intake Gas Sensor Heater - Current Below Normal or Open Circuit
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	20-Sep-2020
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	20-Sep-2020
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00001183
Solution Title	Aftertreatment DPF differential pressure sensor tubes plugged
Update Reason	Solution Added
Date	20-Sep-2020
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00000793
Solution Title	Aftertreatment DPF differential pressure sensor stuck in-range
Update Reason	Solution Added
Date	20-Sep-2020
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00001197
Solution Title	Perform the Snap Acceleration Test - Aftertreatment Connected
Update Reason	Solution Added

Date	20-Sep-2020
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter System - Special Instructions
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Added
Date	13-Sep-2020
Fault Code / Symptom	Sensor Supply 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	13-Sep-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	06-Sep-2020
Fault Code / Symptom	Belt Fraying/Belt Wear
Solution Number	S00004006
Solution Title	Loose alternator belt
Update Reason	Solution Removed
Date	06-Sep-2020
Fault Code / Symptom	Belt Noise/Whining
Solution Number	S00004006
Solution Title	Loose alternator belt
Update Reason	Solution Removed

Date	06-Sep-2020
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Special Instructions
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	01-Sep-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Root Cause Not Known
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Removed
Date	01-Sep-2020
Fault Code / Symptom	VGT Actuator Controller - Bad Intelligent Device or Component
Solution Number	S00000599
Solution Title	Incorrect variable geometry turbocharger actuator installation
Update Reason	Solution Removed
Date	01-Sep-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Removed
Date	01-Sep-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Rate of Change
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Removed

Date	01-Sep-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Removed
Date	01-Sep-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Removed
Date	01-Sep-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor - Abnormal Rate of Change
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Removed
Date	23-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00001350
Solution Title	Air intake or exhaust system leaks
Update Reason	Solution Added
Date	23-Aug-2020
Fault Code / Symptom	Black Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered

Date	23-Aug-2020
Fault Code / Symptom	Black Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	23-Aug-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	23-Aug-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	23-Aug-2020
Fault Code / Symptom	Engine Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	23-Aug-2020
Fault Code / Symptom	Engine Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	23-Aug-2020
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered

Date	23-Aug-2020
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	23-Aug-2020
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	23-Aug-2020
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	23-Aug-2020
Fault Code / Symptom	Low Power
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	23-Aug-2020
Fault Code / Symptom	Low Power
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	23-Aug-2020
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered

Date	23-Aug-2020
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	23-Aug-2020
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	23-Aug-2020
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	23-Aug-2020
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007820
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Added
Date	23-Aug-2020
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Added

Date	23-Aug-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00007820
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Added
Date	23-Aug-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Added
Date	23-Aug-2020
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00007820
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Added
Date	23-Aug-2020
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Added
Date	16-Aug-2020
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00001202
Solution Title	Fuel injector is leaking
Update Reason	Solution Added

Date	16-Aug-2020
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00001280
Solution Title	Fuel injector isolation test
Update Reason	Solution Added
Date	16-Aug-2020
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	16-Aug-2020
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008140
Solution Title	Engine intake throttle actuator voltage check at the ECM
Update Reason	Solution Added
Date	16-Aug-2020
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008140
Solution Title	Engine intake throttle actuator voltage check at the ECM
Update Reason	Solution Added
Date	16-Aug-2020
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008140
Solution Title	Engine intake throttle actuator voltage check at the ECM
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00005162
Solution Title	Low engine coolant temperature preventing test from completing
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00005173
Solution Title	Cooling system component is leaking
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002986
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00005174
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00001376
Solution Title	Aftertreatment DPF inhibit switch is malfunctioning
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00001274
Solution Title	Clutch switch or circuit is malfunctioning
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00001289
Solution Title	Vehicle service brake switch or circuit is malfunctioning
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00005179
Solution Title	Vehicle parking brake is malfunctioning
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00001382
Solution Title	Accelerator pedal sensor malfunctioning
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00000710
Solution Title	Accelerator pedal circuit check
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00001325
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00001356
Solution Title	Cruise control/PTO selector switch or circuit is malfunctioning
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00004515
Solution Title	Transmission is not in Park or Neutral which is preventing the Aftertreatment SCR System Test from starting
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Reordered

Date	09-Aug-2020
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Modified
Date	09-Aug-2020
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Reordered
Date	09-Aug-2020
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Modified
Date	09-Aug-2020
Fault Code / Symptom	Will Not Crank
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Reordered
Date	09-Aug-2020
Fault Code / Symptom	Will Not Crank
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Modified
Date	09-Aug-2020
Fault Code / Symptom	Will Not Crank
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Reordered

Date	09-Aug-2020
Fault Code / Symptom	Will Not Crank
Solution Number	S00001224
Solution Title	Crankshaft rotation is restricted
Update Reason	Solution Modified
Date	09-Aug-2020
Fault Code / Symptom	J1939 Network #1 - Abnormal Update Rate
Solution Number	S00000384
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	09-Aug-2020
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008180
Solution Title	High fuel drain line restriction
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed
Date	09-Aug-2020
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000384
Solution Title	ECM Malfunction
Update Reason	Solution Removed

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00008019
Solution Title	Check for multiple fuel injector fault codes
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00002037
Solution Title	High fuel drain line restriction
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 2 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00008019
Solution Title	Check for multiple fuel injector fault codes
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 2 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00002037
Solution Title	High fuel drain line restriction
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 2 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 3 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00008019
Solution Title	Check for multiple fuel injector fault codes
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 3 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00002037
Solution Title	High fuel drain line restriction
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 3 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 4 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00008019
Solution Title	Check for multiple fuel injector fault codes
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 4 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00002037
Solution Title	High fuel drain line restriction
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 4 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 5 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00008019
Solution Title	Check for multiple fuel injector fault codes
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 5 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00002037
Solution Title	High fuel drain line restriction
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 5 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 6 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00008019
Solution Title	Check for multiple fuel injector fault codes
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 6 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00002037
Solution Title	High fuel drain line restriction
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 6 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed

Date	09-Aug-2020
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00008180
Solution Title	High fuel drain line restriction
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed

Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Root Cause Not Known
Solution Number	S00000929
Solution Title	Aftertreatment SCR temperature sensor module voltage check
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Root Cause Not Known
Solution Number	S00001067
Solution Title	Aftertreatment SCR temperature sensor open circuit check
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Root Cause Not Known
Solution Number	S00000943
Solution Title	Aftertreatment SCR temperature sensor module voltage check
Update Reason	Solution Removed
Date	09-Aug-2020
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00008180
Solution Title	High fuel drain line restriction
Update Reason	Solution Added

Date	09-Aug-2020
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed
Date	09-Aug-2020
Fault Code / Symptom	Engine Injector Metering Rail 1 Cold Start Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008180
Solution Title	High fuel drain line restriction
Update Reason	Solution Added
Date	09-Aug-2020
Fault Code / Symptom	Engine Injector Metering Rail 1 Cold Start Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000537
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed
Date	26-Jul-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00005162
Solution Title	Low engine coolant temperature preventing test from completing
Update Reason	Solution Added
Date	26-Jul-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00005173
Solution Title	Cooling system component is leaking
Update Reason	Solution Added

Date	26-Jul-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00002986
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Added
Date	26-Jul-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00005174
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added
Date	26-Jul-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Added
Date	26-Jul-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00001289
Solution Title	Vehicle service brake switch or circuit is malfunctioning
Update Reason	Solution Added
Date	26-Jul-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00001382
Solution Title	Accelerator pedal sensor malfunctioning
Update Reason	Solution Added

Date	26-Jul-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00000710
Solution Title	Accelerator pedal circuit check
Update Reason	Solution Added
Date	26-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Out of Calibration
Solution Number	S00008137
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Added
Date	26-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Out of Calibration
Solution Number	S00000933
Solution Title	Aftertreatment diesel exhaust fluid quality sensor is malfunctioning
Update Reason	Solution Removed
Date	26-Jul-2020
Fault Code / Symptom	Engine Starter Mode Overcrank Protection - Condition Exists
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Removed
Date	26-Jul-2020
Fault Code / Symptom	Engine Starter Mode Overcrank Protection - Condition Exists
Solution Number	S00000896
Solution Title	Malfunctioning starter or damaged ring gear
Update Reason	Solution Removed

Date	26-Jul-2020
Fault Code / Symptom	Engine Starter Mode Overcrank Protection - Condition Exists
Solution Number	S00002861
Solution Title	Starter magnetic switch is malfunctioning
Update Reason	Solution Removed
Date	26-Jul-2020
Fault Code / Symptom	Engine Starter Mode Overcrank Protection - Condition Exists
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Removed
Date	26-Jul-2020
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00003130
Solution Title	OEM wiring harness has a short to battery
Update Reason	Solution Removed
Date	12-Jul-2020
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000681
Solution Title	EGR valve restricted
Update Reason	Solution Added
Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	12-Jul-2020
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008077
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001426
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008077
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001426
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008079
Solution Title	Aftertreatment DOC temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004316
Solution Title	Aftertreatment DOC temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008080
Solution Title	Aftertreatment DPF temperature sensor module is malfunctioning
Update Reason	Solution Added

Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001432
Solution Title	Aftertreatment DPF temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Jul-2020
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000681
Solution Title	EGR valve restricted
Update Reason	Solution Added
Date	12-Jul-2020
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001117
Solution Title	EGR valve stuck open
Update Reason	Solution Removed
Date	12-Jul-2020
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00000681
Solution Title	EGR valve restricted
Update Reason	Solution Added
Date	12-Jul-2020
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00001117
Solution Title	EGR valve stuck open
Update Reason	Solution Removed

Date	12-Jul-2020
Fault Code / Symptom	Engine Control Module Calibration Memory - Bad Intelligent Device or Component
Solution Number	S00008078
Solution Title	Internal ECM Error
Update Reason	Solution Added
Date	12-Jul-2020
Fault Code / Symptom	Engine Control Module Calibration Memory - Bad Intelligent Device or Component
Solution Number	S00000446
Solution Title	Internal ECM Error
Update Reason	Solution Removed
Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008077
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001426
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Added

Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00000016
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Removed
Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000563
Solution Title	Aftertreatment diesel exhaust fluid is contaminated
Update Reason	Solution Added
Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Added
Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000663
Solution Title	Aftertreatment diesel exhaust fluid pressure sensor open circuit check
Update Reason	Solution Added

Date	12-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Actual Dosing Quantity - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Added
Date	12-Jul-2020
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000681
Solution Title	EGR valve restricted
Update Reason	Solution Added
Date	12-Jul-2020
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001117
Solution Title	EGR valve stuck open
Update Reason	Solution Removed
Date	05-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00000016
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Removed
Date	05-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	05-Jul-2020
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Consumption Excessive
Solution Number	S00002515
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00002966
Solution Title	Aftertreatment DPF inlet temperature is above the maximum specification
Update Reason	Solution Removed
Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00002922
Solution Title	Aftertreatment fuel injector is malfunctioning
Update Reason	Solution Removed
Date	28-Jun-2020
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00002515
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	28-Jun-2020
Fault Code / Symptom	Exhaust Leak
Solution Number	S00002515
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	28-Jun-2020
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00002515
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Reordered
Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Modified
Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Reordered
Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Modified

Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Root Cause Not Known
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Added

Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Reordered

Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Modified

Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Added

Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Rate of Change
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Added

Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Added
Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Added
Date	28-Jun-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor - Abnormal Rate of Change
Solution Number	S00000547
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve malfunctioning
Update Reason	Solution Added
Date	21-Jun-2020
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001199
Solution Title	Keyswitch open circuit check
Update Reason	Solution Removed
Date	21-Jun-2020
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00001202
Solution Title	Fuel injector is leaking
Update Reason	Solution Added

Date	21-Jun-2020
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00001280
Solution Title	Fuel injector isolation test
Update Reason	Solution Added
Date	21-Jun-2020
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001199
Solution Title	Keyswitch open circuit check
Update Reason	Solution Removed
Date	21-Jun-2020
Fault Code / Symptom	Accelerator Pedal Position 1 - Received Network Data in Error
Solution Number	S00000902
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	21-Jun-2020
Fault Code / Symptom	Accelerator Pedal Position 1 - Received Network Data in Error
Solution Number	S00000516
Solution Title	Incorrect multiplexed accelerator pedal configuration
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Reordered
Date	07-Jun-2020
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Modified

Date	07-Jun-2020
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Reordered
Date	07-Jun-2020
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Modified
Date	07-Jun-2020
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00002820
Solution Title	Lubricating oil filter plugged
Update Reason	Solution Reordered
Date	07-Jun-2020
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00002820
Solution Title	Lubricating oil filter plugged
Update Reason	Solution Modified
Date	07-Jun-2020
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00003330
Solution Title	Lubricating oil pressure sensor stuck in-range
Update Reason	Solution Reordered
Date	07-Jun-2020
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00003330
Solution Title	Lubricating oil pressure sensor stuck in-range
Update Reason	Solution Modified

Date	07-Jun-2020
Fault Code / Symptom	Lubricating Oil Temperature High
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Reordered
Date	07-Jun-2020
Fault Code / Symptom	Lubricating Oil Temperature High
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Modified
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007852
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007920
Solution Title	Coolant level sensor open circuit check
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007921
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007922
Solution Title	Coolant level sensor circuit pin to pin short
Update Reason	Solution Added

Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007923
Solution Title	Coolant level sensor is malfunctioning
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000481
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000747
Solution Title	Coolant level sensor open circuit check
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000748
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000749
Solution Title	Coolant level sensor circuit pin to pin short
Update Reason	Solution Removed

Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005533
Solution Title	Coolant level sensor is malfunctioning
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007852
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007920
Solution Title	Coolant level sensor open circuit check
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007921
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007922
Solution Title	Coolant level sensor circuit pin to pin short
Update Reason	Solution Added

Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007923
Solution Title	Coolant level sensor is malfunctioning
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000481
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000747
Solution Title	Coolant level sensor open circuit check
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000748
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000749
Solution Title	Coolant level sensor circuit pin to pin short
Update Reason	Solution Removed

Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00005533
Solution Title	Coolant level sensor is malfunctioning
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	SAE J1939 Multiplexing Remote Accelerator Pedal or Lever Position Sensor System - Received Network Data in Error
Solution Number	S00000902
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	SAE J1939 Multiplexing Remote Accelerator Pedal or Lever Position Sensor System - Received Network Data in Error
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	J1939 Network #1 - Abnormal Update Rate
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Sensor Supply 5 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	07-Jun-2020
Fault Code / Symptom	Sensor Supply 5 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00007852
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00007920
Solution Title	Coolant level sensor open circuit check
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00007921
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00007922
Solution Title	Coolant level sensor circuit pin to pin short
Update Reason	Solution Added

Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00007923
Solution Title	Coolant level sensor is malfunctioning
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000481
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000747
Solution Title	Coolant level sensor open circuit check
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000748
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000749
Solution Title	Coolant level sensor circuit pin to pin short
Update Reason	Solution Removed

Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00005533
Solution Title	Coolant level sensor is malfunctioning
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004187
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Accelerator Pedal Position 1 - Abnormal Update Rate
Solution Number	S00001584
Solution Title	J1939 data link harness resistance check
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007852
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007920
Solution Title	Coolant level sensor open circuit check
Update Reason	Solution Added

Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007921
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007922
Solution Title	Coolant level sensor circuit pin to pin short
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007923
Solution Title	Coolant level sensor is malfunctioning
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000481
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000747
Solution Title	Coolant level sensor open circuit check
Update Reason	Solution Removed

Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000748
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000749
Solution Title	Coolant level sensor circuit pin to pin short
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005533
Solution Title	Coolant level sensor is malfunctioning
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00006251
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Cruise Control Disable Command - Abnormal Update Rate
Solution Number	S00000901
Solution Title	J1939 data link harness pin to pin short circuit
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Fuel Level 1 - Abnormal Update Rate
Solution Number	S00000902
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added

Date	07-Jun-2020
Fault Code / Symptom	Fuel Level 1 - Abnormal Update Rate
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Fuel Level 1 - Out of Calibration
Solution Number	S00000902
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Fuel Level 1 - Out of Calibration
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Fuel Level 2 - Abnormal Update Rate
Solution Number	S00000902
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Fuel Level 2 - Abnormal Update Rate
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Fuel Level 2 - Abnormal Update Rate
Solution Number	S00001584
Solution Title	J1939 data link harness resistance check
Update Reason	Solution Removed

Date	07-Jun-2020
Fault Code / Symptom	Fuel Level 2 - Out of Calibration
Solution Number	S00000902
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Fuel Level 2 - Out of Calibration
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	SAE J1939 Multiplexing Remote Accelerator Pedal or Lever Sensor System - Received Network Data in Error
Solution Number	S00000902
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	SAE J1939 Multiplexing Remote Accelerator Pedal or Lever Sensor System - Received Network Data in Error
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Transmission Gear Ratio Module - Abnormal Update Rate
Solution Number	S00000902
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added

Date	07-Jun-2020
Fault Code / Symptom	Transmission Gear Ratio Module - Abnormal Update Rate
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Accelerator Pedal Position 1 - Out of Calibration
Solution Number	S00000902
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Accelerator Pedal Position 1 - Out of Calibration
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	Transmission Communications Failure Idle Torque Limit - Condition Exists
Solution Number	S00000902
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	Transmission Communications Failure Idle Torque Limit - Condition Exists
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed

Date	07-Jun-2020
Fault Code / Symptom	TSC1 Control Purpose P7 Inhibit Command - Out of Calibration
Solution Number	S00000902
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	TSC1 Control Purpose P7 Inhibit Command - Out of Calibration
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed
Date	07-Jun-2020
Fault Code / Symptom	TSC1 Control Purpose P7 Inhibit Command - Abnormal Update Rate
Solution Number	S00000902
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	07-Jun-2020
Fault Code / Symptom	TSC1 Control Purpose P7 Inhibit Command - Abnormal Update Rate
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed
Date	31-May-2020
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00007906
Solution Title	Verify oil consumption complaint
Update Reason	Solution Added

Date	31-May-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added

Date	31-May-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005157
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Removed

Date	31-May-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 2 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added

Date	31-May-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 2 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005157
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Removed

Date	31-May-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 3 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added

Date	31-May-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 3 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005157
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Removed

Date	31-May-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 4 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added

Date	31-May-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 4 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005157
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Removed

Date	31-May-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 5 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added

Date	31-May-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 5 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005157
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Removed

Date	31-May-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 6 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007909
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added
Date	31-May-2020
Fault Code / Symptom	Injector Solenoid Driver Cylinder 6 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005157
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Removed
Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Added
Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000016
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Removed
Date	31-May-2020
Fault Code / Symptom	Aftertreatment Intake Gas Sensor Heater - Current Below Normal or Open Circuit
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Added

Date	31-May-2020
Fault Code / Symptom	Aftertreatment Intake Gas Sensor Heater - Current Below Normal or Open Circuit
Solution Number	S00000016
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Removed

Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Added

Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000016
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Removed

Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Rate of Change
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Added

Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Rate of Change
Solution Number	S00000016
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Removed

Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00007913
Solution Title	Aftertreatment intake NOx sensor is malfunctioning
Update Reason	Solution Added
Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Removed
Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added

Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Removed
Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater Low Side Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Heater Low Side Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Removed
Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Regeneration Status - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added

Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Regeneration Status - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Removed

Date	31-May-2020
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00007914
Solution Title	Variable geometry turbocharger actuator is not communicating
Update Reason	Solution Added

Date	31-May-2020
Fault Code / Symptom	Variable Geometry Turbocharger Actuator Software - Abnormal Update Rate
Solution Number	S00001120
Solution Title	Variable geometry turbocharger actuator is not communicating
Update Reason	Solution Removed

Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Regeneration Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added

Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Regeneration Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Removed
Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00007912
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Added
Date	31-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Soot Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00000913
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Removed
Date	24-May-2020
Fault Code / Symptom	Fan Not Running/Erratic Running
Solution Number	S00001290
Solution Title	Fan clutch actuator is malfunctioning
Update Reason	Solution Removed
Date	24-May-2020
Fault Code / Symptom	Fan Runs Continuously/Excessive Operation
Solution Number	S00001290
Solution Title	Fan clutch actuator is malfunctioning
Update Reason	Solution Removed

Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Missing - Condition Exists
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Added
Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Missing - Condition Exists
Solution Number	S00000698
Solution Title	Aftertreatment DOC is leaking exhaust gas externally
Update Reason	Solution Removed
Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Reordered
Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Modified

Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000698
Solution Title	Aftertreatment DOC is leaking exhaust gas externally
Update Reason	Solution Removed

Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Reordered

Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Modified

Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Reordered

Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Modified

Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000698
Solution Title	Aftertreatment DOC is leaking exhaust gas externally
Update Reason	Solution Removed
Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Reordered
Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 SCR Catalyst System Missing - Condition Exists
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Modified
Date	24-May-2020
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Reordered
Date	24-May-2020
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Modified

Date	24-May-2020
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00000698
Solution Title	Aftertreatment DOC is leaking exhaust gas externally
Update Reason	Solution Removed
Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Reordered
Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Modified
Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Root Cause Not Known
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Reordered
Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Root Cause Not Known
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Modified

Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Reordered

Date	24-May-2020
Fault Code / Symptom	Aftertreatment 1 SCR Feedback Control Status - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00001008
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Modified

Date	17-May-2020
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00001354
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added

Date	17-May-2020
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00001327
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed

Date	17-May-2020
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00001329
Solution Title	Fuel gear pump is leaking fuel into the oil
Update Reason	Solution Removed

Date	17-May-2020
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00001355
Solution Title	Fuel gear pump is leaking fuel into the oil
Update Reason	Solution Removed

Date	17-May-2020
Fault Code / Symptom	Lubricating Oil Filter Plugging
Solution Number	S00001354
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added
Date	17-May-2020
Fault Code / Symptom	Lubricating Oil Level High
Solution Number	S00001354
Solution Title	Fuel injector is malfunctioning
Update Reason	Solution Added
Date	17-May-2020
Fault Code / Symptom	Lubricating Oil Level High
Solution Number	S00001327
Solution Title	High fuel drain line restriction
Update Reason	Solution Removed
Date	17-May-2020
Fault Code / Symptom	Lubricating Oil Level High
Solution Number	S00001329
Solution Title	Fuel gear pump is leaking fuel into the oil
Update Reason	Solution Removed
Date	17-May-2020
Fault Code / Symptom	Lubricating Oil Level High
Solution Number	S00001355
Solution Title	Fuel gear pump is leaking fuel into the oil
Update Reason	Solution Removed
Date	10-May-2020
Fault Code / Symptom	Coolant in the Fuel
Solution Number	S00007850
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	10-May-2020
Fault Code / Symptom	Fuel in the Coolant
Solution Number	S00007850
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	10-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Missing - Condition Exists
Solution Number	S00007849
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	10-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007849
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	10-May-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor Module Battery Voltage Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	03-May-2020
Fault Code / Symptom	Fuel Knock
Solution Number	S00001221
Solution Title	Fuel injector isolation test
Update Reason	Solution Added

Date	03-May-2020
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001221
Solution Title	Fuel injector isolation test
Update Reason	Solution Added
Date	03-May-2020
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed
Date	03-May-2020
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	03-May-2020
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007822
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Added
Date	03-May-2020
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed

Date	03-May-2020
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	03-May-2020
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000352
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Removed
Date	03-May-2020
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00002392
Solution Title	Intake manifold pressure sensor circuit response at the ECM
Update Reason	Solution Removed
Date	03-May-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed

Date	03-May-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	03-May-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000623
Solution Title	Crankcase pressure sensor stuck in-range
Update Reason	Solution Reordered
Date	03-May-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000623
Solution Title	Crankcase pressure sensor stuck in-range
Update Reason	Solution Modified
Date	03-May-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000623
Solution Title	Crankcase pressure sensor stuck in-range
Update Reason	Solution Reordered
Date	03-May-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000623
Solution Title	Crankcase pressure sensor stuck in-range
Update Reason	Solution Modified

Date	03-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001026
Solution Title	Aftertreatment DPF Permit Switch Status is in the OFF position
Update Reason	Solution Removed

Date	03-May-2020
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000623
Solution Title	Crankcase pressure sensor stuck in-range
Update Reason	Solution Reordered

Date	03-May-2020
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000623
Solution Title	Crankcase pressure sensor stuck in-range
Update Reason	Solution Modified

Date	03-May-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000623
Solution Title	Crankcase pressure sensor stuck in-range
Update Reason	Solution Reordered

Date	03-May-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000623
Solution Title	Crankcase pressure sensor stuck in-range
Update Reason	Solution Modified

Date	03-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007816
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Added
Date	03-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001092
Solution Title	Aftertreatment particulate matter sensor is damaged
Update Reason	Solution Removed
Date	03-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001215
Solution Title	Aftertreatment DPF damaged or missing
Update Reason	Solution Removed
Date	03-May-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	03-May-2020
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed

Date	03-May-2020
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	26-Apr-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Voltage Above Normal or Shorted to High Source
Solution Number	S00005496
Solution Title	Aftertreatment diesel exhaust fluid tank heater control valve open circuit check
Update Reason	Solution Added
Date	12-Apr-2020
Fault Code / Symptom	External Lubricating Oil Leak
Solution Number	S00000838
Solution Title	External oil leak
Update Reason	Solution Removed
Date	12-Apr-2020
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00000838
Solution Title	External oil leak
Update Reason	Solution Removed
Date	12-Apr-2020
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00000838
Solution Title	External oil leak
Update Reason	Solution Removed

Date	12-Apr-2020
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000489
Solution Title	Engine oil temperature sensor SIGNAL voltage check
Update Reason	Solution Removed
Date	12-Apr-2020
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001163
Solution Title	Lubricating oil temperature sensor voltage check at the ECM
Update Reason	Solution Removed
Date	12-Apr-2020
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00002804
Solution Title	Lubricating oil temperature sensor open circuit check
Update Reason	Solution Removed
Date	12-Apr-2020
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00002821
Solution Title	Lubricating oil temperature sensor circuit pin to pin short
Update Reason	Solution Removed

Date	12-Apr-2020
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000489
Solution Title	Engine oil temperature sensor SIGNAL voltage check
Update Reason	Solution Removed
Date	12-Apr-2020
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001163
Solution Title	Lubricating oil temperature sensor voltage check at the ECM
Update Reason	Solution Removed
Date	12-Apr-2020
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00002890
Solution Title	Lubricating oil temperature sensor circuit pin to ground short
Update Reason	Solution Removed
Date	12-Apr-2020
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00002821
Solution Title	Lubricating oil temperature sensor circuit pin to pin short
Update Reason	Solution Removed

Date	12-Apr-2020
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003480
Solution Title	EGR differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	12-Apr-2020
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00003480
Solution Title	EGR differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	12-Apr-2020
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00003480
Solution Title	EGR differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	12-Apr-2020
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	12-Apr-2020
Fault Code / Symptom	Navigation Control Module - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	12-Apr-2020
Fault Code / Symptom	Navigation Control Module - Abnormal Update Rate
Solution Number	S00007719
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	05-Apr-2020
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00000071
Solution Title	Check for primary fault codes
Update Reason	Solution Reordered
Date	05-Apr-2020
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00000071
Solution Title	Check for primary fault codes
Update Reason	Solution Modified
Date	05-Apr-2020
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00007691
Solution Title	Fault Code 5655 requires that ALL solutions be performed
Update Reason	Solution Added
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007506
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added

Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007507
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000987
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007506
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000350
Solution Title	Aftertreatment DPF differential pressure OEM wiring harness short to ground circuit check
Update Reason	Solution Removed

Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007507
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000987
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007506
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007507
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed

Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000987
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007506
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007507
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000987
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed

Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00007506
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00000350
Solution Title	Aftertreatment DPF differential pressure OEM wiring harness short to ground circuit check
Update Reason	Solution Removed
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00000987
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00007507
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed

Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00007506
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00007507
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	29-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00000987
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Removed
Date	22-Mar-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00001257
Solution Title	Worn or damaged valves, valve guides or valve seats
Update Reason	Solution Reordered
Date	22-Mar-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00001257
Solution Title	Worn or damaged valves, valve guides or valve seats
Update Reason	Solution Modified

Date	22-Mar-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00007501
Solution Title	Crankcase Blowby Check
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00006713
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	High Blowby
Solution Number	S00007501
Solution Title	Crankcase Blowby Check
Update Reason	Solution Added

Date	22-Mar-2020
Fault Code / Symptom	High Blowby
Solution Number	S00006713
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	High Blowby
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	High Blowby
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	High Blowby
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00000897
Solution Title	Oil consumption related to high blowby
Update Reason	Solution Reordered
Date	22-Mar-2020
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00000897
Solution Title	Oil consumption related to high blowby
Update Reason	Solution Modified

Date	22-Mar-2020
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00001257
Solution Title	Worn or damaged valves, valve guides or valve seats
Update Reason	Solution Reordered
Date	22-Mar-2020
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00001257
Solution Title	Worn or damaged valves, valve guides or valve seats
Update Reason	Solution Modified
Date	22-Mar-2020
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00001257
Solution Title	Worn or damaged valves, valve guides or valve seats
Update Reason	Solution Reordered
Date	22-Mar-2020
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00001257
Solution Title	Worn or damaged valves, valve guides or valve seats
Update Reason	Solution Modified
Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00007559
Solution Title	Crankcase Blowby Check
Update Reason	Solution Added

Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006713
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00007559
Solution Title	Crankcase Blowby Check
Update Reason	Solution Added

Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006713
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00007559
Solution Title	Crankcase Blowby Check
Update Reason	Solution Added

Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006713
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006090
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added

Date	22-Mar-2020
Fault Code / Symptom	Engine Charge Air Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006090
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Added
Date	22-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	01-Mar-2020
Fault Code / Symptom	Connected Calibrations Malfunctioning
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	01-Mar-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00005141
Solution Title	Crankcase Blowby Check
Update Reason	Solution Removed

Date	01-Mar-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00001375
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	High Blowby
Solution Number	S00005141
Solution Title	Crankcase Blowby Check
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	High Blowby
Solution Number	S00001375
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed

Date	01-Mar-2020
Fault Code / Symptom	High Blowby
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	High Blowby
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	High Blowby
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is damaged
Update Reason	Solution Removed

Date	01-Mar-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is damaged
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005143
Solution Title	Crankcase Blowby Check
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Removed

Date	01-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005143
Solution Title	Crankcase Blowby Check
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed

Date	01-Mar-2020
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is damaged
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added

Date	01-Mar-2020
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is damaged
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007507
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007507
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007507
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added

Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005143
Solution Title	Crankcase Blowby Check
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001204
Solution Title	Air compressor leaking air into crankcase
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed

Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is damaged
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000733
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001370
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed

Date	01-Mar-2020
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in- range
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007507
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in- range
Update Reason	Solution Added

Date	01-Mar-2020
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is damaged
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is damaged
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00007558
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Valve 1 - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00007558
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is damaged
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment 1 SCR Conversion Efficiency - Condition Exists
Solution Number	S00000561
Solution Title	Fault Code 5655 requires that ALL solutions be performed
Update Reason	Solution Removed

Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Abnormal Rate of Change
Solution Number	S00007507
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00007507
Solution Title	Aftertreatment DPF differential pressure sensor wire pin to pin short circuit check
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001022
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay voltage check
Update Reason	Solution Removed

Date	01-Mar-2020
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in- range
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is damaged
Update Reason	Solution Removed
Date	01-Mar-2020
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002814
Solution Title	Intake manifold pressure sensor stuck in- range
Update Reason	Solution Added
Date	01-Mar-2020
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is damaged
Update Reason	Solution Removed
Date	15-Feb-2020
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006422
Solution Title	Ice buildup in the air system components
Update Reason	Solution Added

Date	15-Feb-2020
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007344
Solution Title	EGR valve plugged or restricted with ice
Update Reason	Solution Added
Date	15-Feb-2020
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001254
Solution Title	Incorrect air compressor discharge line routing
Update Reason	Solution Added
Date	15-Feb-2020
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001255
Solution Title	Air compressor discharge line plugged or restricted with ice
Update Reason	Solution Added
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Modified

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00006220
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00006220
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Reordered

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Modified

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000622
Solution Title	Fault Code 3232 triggered by a malfunction in the J1939 data link with multiple OEM fault codes
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000622
Solution Title	Fault Code 3232 triggered by a malfunction in the J1939 data link with multiple OEM fault codes
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Reordered

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003985
Solution Title	Aftertreatment diesel exhaust fluid line heater is malfunctioning
Update Reason	Solution Added
Date	15-Feb-2020
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006422
Solution Title	Ice buildup in the air system components
Update Reason	Solution Added
Date	15-Feb-2020
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007344
Solution Title	EGR valve plugged or restricted with ice
Update Reason	Solution Added
Date	15-Feb-2020
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001254
Solution Title	Incorrect air compressor discharge line routing
Update Reason	Solution Added

Date	15-Feb-2020
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001255
Solution Title	Air compressor discharge line plugged or restricted with ice
Update Reason	Solution Added
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Rate of Change
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Rate of Change
Solution Number	S00000587
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Modified

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006220
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006220
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Modified

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Reordered

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Modified

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Reordered

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Modified

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Reordered

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Modified

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000677
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000677
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000677
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000677
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Modified

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Above Normal or Shorted to High Source
Solution Number	S00000830
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay resistance check
Update Reason	Solution Added
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Above Normal or Shorted to High Source
Solution Number	S00001025
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay circuit pin to pin short
Update Reason	Solution Added
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Above Normal or Shorted to High Source
Solution Number	S00001018
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay coil resistance check
Update Reason	Solution Removed
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Above Normal or Shorted to High Source
Solution Number	S00001020
Solution Title	Aftertreatment diesel exhaust fluid pump relay FEEDBACK circuit pin to pin short
Update Reason	Solution Removed

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000830
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay resistance check
Update Reason	Solution Added
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001024
Solution Title	Aftertreatment diesel exhaust fluid dosing unit circuit pin to ground short
Update Reason	Solution Removed
Date	15-Feb-2020
Fault Code / Symptom	Engine Turbocharger 1 Speed - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	15-Feb-2020
Fault Code / Symptom	Fan Control Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	15-Feb-2020
Fault Code / Symptom	Fan Control Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed

Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pump Drive Percentage - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000662
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Reordered
Date	15-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00000593
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Modified
Date	09-Feb-2020
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Start
Solution Number	S00005179
Solution Title	Vehicle parking brake is malfunctioning
Update Reason	Solution Added

Date	09-Feb-2020
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	09-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000141
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	09-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000831
Solution Title	Aftertreatment diesel exhaust fluid dosing unit short circuit to battery
Update Reason	Solution Removed
Date	09-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	01-Feb-2020
Fault Code / Symptom	Coolant Overflow
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered

Date	01-Feb-2020
Fault Code / Symptom	Coolant Overflow
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified
Date	01-Feb-2020
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	01-Feb-2020
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified
Date	01-Feb-2020
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	01-Feb-2020
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified
Date	01-Feb-2020
Fault Code / Symptom	Fan Runs Continuously/Excessive Operation
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered

Date	01-Feb-2020
Fault Code / Symptom	Fan Runs Continuously/Excessive Operation
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified
Date	01-Feb-2020
Fault Code / Symptom	High Blowby
Solution Number	S00001295
Solution Title	Valve stem seals are malfunctioning
Update Reason	Solution Removed
Date	01-Feb-2020
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	01-Feb-2020
Fault Code / Symptom	VGT Actuator Driver Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000900
Solution Title	Fuel filter restriction
Update Reason	Solution Removed
Date	01-Feb-2020
Fault Code / Symptom	Aftertreatment Regeneration Inhibited Due to Inhibit Switch - Condition Exists
Solution Number	S00005697
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	01-Feb-2020
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000339
Solution Title	OEM ambient air temperature sensor stuck in-range
Update Reason	Solution Added
Date	01-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Not Rational - Drifted High
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	01-Feb-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Ash Load Percent - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	01-Feb-2020
Fault Code / Symptom	Estimated Engine Parasitic Losses - Percent Torque - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	25-Jan-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00005141
Solution Title	Crankcase Blowby Check
Update Reason	Solution Reordered

Date	25-Jan-2020
Fault Code / Symptom	Blue Smoke
Solution Number	S00005141
Solution Title	Crankcase Blowby Check
Update Reason	Solution Modified
Date	25-Jan-2020
Fault Code / Symptom	High Blowby
Solution Number	S00005141
Solution Title	Crankcase Blowby Check
Update Reason	Solution Reordered
Date	25-Jan-2020
Fault Code / Symptom	High Blowby
Solution Number	S00005141
Solution Title	Crankcase Blowby Check
Update Reason	Solution Modified
Date	25-Jan-2020
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000491
Solution Title	Engine intake throttle actuator motor circuit pin to ground short
Update Reason	Solution Removed
Date	25-Jan-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00004187
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Removed

Date	25-Jan-2020
Fault Code / Symptom	Electronic Throttle Control Actuator Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000491
Solution Title	Engine intake throttle actuator motor circuit pin to ground short
Update Reason	Solution Removed
Date	25-Jan-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001015
Solution Title	Aftertreatment diesel exhaust fluid dosing unit voltage check
Update Reason	Solution Added
Date	25-Jan-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001013
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor open circuit check
Update Reason	Solution Added
Date	25-Jan-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001016
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor circuit pin to ground short
Update Reason	Solution Added

Date	25-Jan-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001014
Solution Title	Aftertreatment diesel exhaust fluid dosing unit pump motor circuit pin to pin short
Update Reason	Solution Added
Date	18-Jan-2020
Fault Code / Symptom	TSC1 Control Purpose P7 Inhibit Command - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	18-Jan-2020
Fault Code / Symptom	TSC1 Control Purpose P7 Inhibit Command - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	18-Jan-2020
Fault Code / Symptom	Sensor Supply 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Removed
Date	18-Jan-2020
Fault Code / Symptom	Sensor Supply 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Removed

Date	18-Jan-2020
Fault Code / Symptom	VGT Actuator Controller - Bad Intelligent Device or Component
Solution Number	S00000599
Solution Title	Incorrect variable geometry turbocharger actuator installation
Update Reason	Solution Reordered
Date	18-Jan-2020
Fault Code / Symptom	VGT Actuator Controller - Bad Intelligent Device or Component
Solution Number	S00000599
Solution Title	Incorrect variable geometry turbocharger actuator installation
Update Reason	Solution Modified
Date	18-Jan-2020
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jan-2020
Fault Code / Symptom	VGT Actuator Driver Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001207
Solution Title	Fuel lift pump check
Update Reason	Solution Added
Date	18-Jan-2020
Fault Code / Symptom	EGR Valve Control Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00001182
Solution Title	EGR valve motor short to ground
Update Reason	Solution Removed

Date	18-Jan-2020
Fault Code / Symptom	EGR Valve Control Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	18-Jan-2020
Fault Code / Symptom	VGT Actuator Driver Circuit (Motor) - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000599
Solution Title	Incorrect variable geometry turbocharger actuator installation
Update Reason	Solution Reordered
Date	18-Jan-2020
Fault Code / Symptom	VGT Actuator Driver Circuit (Motor) - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000599
Solution Title	Incorrect variable geometry turbocharger actuator installation
Update Reason	Solution Modified
Date	18-Jan-2020
Fault Code / Symptom	VGT Actuator Controller - Out of Calibration
Solution Number	S00000599
Solution Title	Incorrect variable geometry turbocharger actuator installation
Update Reason	Solution Reordered
Date	18-Jan-2020
Fault Code / Symptom	VGT Actuator Controller - Out of Calibration
Solution Number	S00000599
Solution Title	Incorrect variable geometry turbocharger actuator installation
Update Reason	Solution Modified

Date	18-Jan-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000798
Solution Title	Aftertreatment diesel exhaust fluid level is low
Update Reason	Solution Removed
Date	18-Jan-2020
Fault Code / Symptom	VGT Actuator Controller - Special Instructions
Solution Number	S00000599
Solution Title	Incorrect variable geometry turbocharger actuator installation
Update Reason	Solution Reordered
Date	18-Jan-2020
Fault Code / Symptom	VGT Actuator Controller - Special Instructions
Solution Number	S00000599
Solution Title	Incorrect variable geometry turbocharger actuator installation
Update Reason	Solution Modified
Date	18-Jan-2020
Fault Code / Symptom	Predictive Cruise Control State - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jan-2020
Fault Code / Symptom	Route Parameter Manager Module GPS Antenna Current - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Jan-2020
Fault Code / Symptom	Navigation Control Module - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Jan-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00000338
Solution Title	Aftertreatment temperature sensor stuck in-range
Update Reason	Solution Added
Date	18-Jan-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00004316
Solution Title	Aftertreatment DOC temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	05-Jan-2020
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00001268
Solution Title	Air compressor damaged or excessively worn
Update Reason	Solution Added
Date	05-Jan-2020
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00006373
Solution Title	Variable Geometry Turbocharger Hysteresis Test
Update Reason	Solution Added

Date	05-Jan-2020
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00006373
Solution Title	Variable Geometry Turbocharger Hysteresis Test
Update Reason	Solution Added
Date	05-Jan-2020
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00001354
Solution Title	Fuel injector o-rings damaged
Update Reason	Solution Removed
Date	05-Jan-2020
Fault Code / Symptom	Lubricating Oil Filter Plugging
Solution Number	S00001354
Solution Title	Fuel injector o-rings damaged
Update Reason	Solution Removed
Date	05-Jan-2020
Fault Code / Symptom	Lubricating Oil Level High
Solution Number	S00001354
Solution Title	Fuel injector o-rings damaged
Update Reason	Solution Removed
Date	05-Jan-2020
Fault Code / Symptom	Lubricating Oil Temperature High
Solution Number	S00006690
Solution Title	Lubricating oil thermostat is malfunctioning
Update Reason	Solution Added
Date	05-Jan-2020
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000500
Solution Title	Fuel pump actuator circuit pin to pin short
Update Reason	Solution Added

Date	05-Jan-2020
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000500
Solution Title	Fuel pump actuator circuit pin to pin short
Update Reason	Solution Added
Date	05-Jan-2020
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	05-Jan-2020
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	05-Jan-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005101
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Removed
Date	05-Jan-2020
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Added

Date	05-Jan-2020
Fault Code / Symptom	EGR Valve Control Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	05-Jan-2020
Fault Code / Symptom	EGR Valve Control Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00000766
Solution Title	EGR valve position sensor circuit pin to pin short
Update Reason	Solution Removed
Date	05-Jan-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006722
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Added
Date	05-Jan-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000260
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	05-Jan-2020
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter 1 Conditions Not Met for Active Regeneration - Condition Exists
Solution Number	S00006722
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Added

Date	05-Jan-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Ash Load Percent - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005270
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Added
Date	05-Jan-2020
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Ash Load Percent - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005101
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Removed
Date	05-Jan-2020
Fault Code / Symptom	Fan Control Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	05-Jan-2020
Fault Code / Symptom	Fan Control Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	05-Jan-2020
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Added

Date	28-Dec-2019
Fault Code / Symptom	Brake Pedal Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	21-Dec-2019
Fault Code / Symptom	Brake Pedal Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Removed
Date	14-Dec-2019
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	14-Dec-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005101
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Added
Date	14-Dec-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Ash Load Percent - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005101
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Added

Date	07-Dec-2019
Fault Code / Symptom	Coolant Overflow
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Added
Date	07-Dec-2019
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000183
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	07-Dec-2019
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001375
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed
Date	07-Dec-2019
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001375
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed
Date	07-Dec-2019
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001375
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed

Date	07-Dec-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001431
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Removed
Date	07-Dec-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001431
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Removed
Date	07-Dec-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00006565
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Added
Date	07-Dec-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001431
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Removed

Date	07-Dec-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006565
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Added
Date	07-Dec-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001431
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Removed
Date	07-Dec-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006565
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Added
Date	07-Dec-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001431
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Removed

Date	07-Dec-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006565
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Added
Date	07-Dec-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001431
Solution Title	Aftertreatment diesel exhaust fluid dosing unit is malfunctioning
Update Reason	Solution Removed
Date	07-Dec-2019
Fault Code / Symptom	Engine Turbocharger 1 Speed - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000653
Solution Title	Turbocharger speed sensor open circuit check
Update Reason	Solution Added
Date	07-Dec-2019
Fault Code / Symptom	Engine Turbocharger 1 Speed - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000673
Solution Title	Turbocharger speed sensor circuit pin to ground short
Update Reason	Solution Added
Date	07-Dec-2019
Fault Code / Symptom	Engine Turbocharger 1 Speed - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000652
Solution Title	Turbocharger speed sensor circuit pin to pin short
Update Reason	Solution Added

Date	07-Dec-2019
Fault Code / Symptom	Engine Turbocharger 1 Speed - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000651
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Added
Date	07-Dec-2019
Fault Code / Symptom	Engine Turbocharger 1 Speed - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000324
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	07-Dec-2019
Fault Code / Symptom	Predictive Cruise Control State - Abnormal Update Rate
Solution Number	S00006503
Solution Title	Navigation control module check
Update Reason	Solution Added
Date	07-Dec-2019
Fault Code / Symptom	Navigation Control Module - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	07-Dec-2019
Fault Code / Symptom	Navigation Control Module - Abnormal Update Rate
Solution Number	S00006503
Solution Title	Navigation control module check
Update Reason	Solution Added
Date	30-Nov-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Reordered

Date	30-Nov-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Modified
Date	30-Nov-2019
Fault Code / Symptom	Engine Decelerates Slowly
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Reordered
Date	30-Nov-2019
Fault Code / Symptom	Engine Decelerates Slowly
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Modified
Date	30-Nov-2019
Fault Code / Symptom	Engine Knock
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Reordered
Date	30-Nov-2019
Fault Code / Symptom	Engine Knock
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Modified
Date	30-Nov-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Reordered

Date	30-Nov-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Modified

Date	30-Nov-2019
Fault Code / Symptom	Engine Run On
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Reordered

Date	30-Nov-2019
Fault Code / Symptom	Engine Run On
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Modified

Date	30-Nov-2019
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Reordered

Date	30-Nov-2019
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Modified

Date	30-Nov-2019
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Reordered

Date	30-Nov-2019
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Modified
Date	30-Nov-2019
Fault Code / Symptom	Fuel Knock
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Reordered
Date	30-Nov-2019
Fault Code / Symptom	Fuel Knock
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Modified
Date	30-Nov-2019
Fault Code / Symptom	Low Power
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Reordered
Date	30-Nov-2019
Fault Code / Symptom	Low Power
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Modified
Date	30-Nov-2019
Fault Code / Symptom	Overhead Noise
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Reordered

Date	30-Nov-2019
Fault Code / Symptom	Overhead Noise
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Modified
Date	30-Nov-2019
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Reordered
Date	30-Nov-2019
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Modified
Date	30-Nov-2019
Fault Code / Symptom	Vibration
Solution Number	S00001377
Solution Title	Vibration damper is damaged
Update Reason	Solution Reordered
Date	30-Nov-2019
Fault Code / Symptom	Vibration
Solution Number	S00001377
Solution Title	Vibration damper is damaged
Update Reason	Solution Modified
Date	30-Nov-2019
Fault Code / Symptom	White Smoke
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Reordered

Date	30-Nov-2019
Fault Code / Symptom	White Smoke
Solution Number	S00001712
Solution Title	Cylinder Cutout Test
Update Reason	Solution Modified
Date	30-Nov-2019
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00006545
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	30-Nov-2019
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	30-Nov-2019
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006545
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	30-Nov-2019
Fault Code / Symptom	Idle Shutdown Vehicle Accessories Relay Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001166
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Reordered

Date	30-Nov-2019
Fault Code / Symptom	Idle Shutdown Vehicle Accessories Relay Driver Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001166
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Modified
Date	30-Nov-2019
Fault Code / Symptom	Idle Shutdown Vehicle Accessories Relay Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001166
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Reordered
Date	30-Nov-2019
Fault Code / Symptom	Idle Shutdown Vehicle Accessories Relay Driver Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001166
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Modified
Date	30-Nov-2019
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	30-Nov-2019
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001825
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	30-Nov-2019
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder 1 - Condition Exists
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder 1 - Condition Exists
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder 2 - Condition Exists
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder 2 - Condition Exists
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed

Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder 3 - Condition Exists
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder 3 - Condition Exists
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder 4 - Condition Exists
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder 4 - Condition Exists
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder 5 - Condition Exists
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added

Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder 5 - Condition Exists
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder 6 - Condition Exists
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder 6 - Condition Exists
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	30-Nov-2019
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001219
Solution Title	Variable geometry turbocharger actuator open circuit check
Update Reason	Solution Removed
Date	30-Nov-2019
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001219
Solution Title	Variable geometry turbocharger actuator open circuit check
Update Reason	Solution Removed

Date	30-Nov-2019
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	30-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	30-Nov-2019
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000301
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	30-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Above Normal or Shorted to High Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	30-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006541
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added

Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added

Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added

Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added

Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added

Date	30-Nov-2019
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00005074
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	30-Nov-2019
Fault Code / Symptom	Fan Control Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001059
Solution Title	Fan control solenoid resistance check
Update Reason	Solution Reordered
Date	30-Nov-2019
Fault Code / Symptom	Fan Control Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001059
Solution Title	Fan control solenoid resistance check
Update Reason	Solution Modified
Date	23-Nov-2019
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00001334
Solution Title	Gear train components damaged or out of adjustment
Update Reason	Solution Added
Date	23-Nov-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00001336
Solution Title	Lubricating oil pump is malfunctioning
Update Reason	Solution Reordered
Date	23-Nov-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00001336
Solution Title	Lubricating oil pump is malfunctioning
Update Reason	Solution Modified

Date	23-Nov-2019
Fault Code / Symptom	Gear Whine Noise
Solution Number	S00001336
Solution Title	Lubricating oil pump is malfunctioning
Update Reason	Solution Reordered
Date	23-Nov-2019
Fault Code / Symptom	Gear Whine Noise
Solution Number	S00001336
Solution Title	Lubricating oil pump is malfunctioning
Update Reason	Solution Modified
Date	23-Nov-2019
Fault Code / Symptom	Lubricating Oil Pressure High
Solution Number	S00001336
Solution Title	Lubricating oil pump is malfunctioning
Update Reason	Solution Reordered
Date	23-Nov-2019
Fault Code / Symptom	Lubricating Oil Pressure High
Solution Number	S00001336
Solution Title	Lubricating oil pump is malfunctioning
Update Reason	Solution Modified
Date	23-Nov-2019
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001336
Solution Title	Lubricating oil pump is malfunctioning
Update Reason	Solution Reordered
Date	23-Nov-2019
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001336
Solution Title	Lubricating oil pump is malfunctioning
Update Reason	Solution Modified

Date	23-Nov-2019
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00000514
Solution Title	Battery circuit fuse has open circuit
Update Reason	Solution Removed
Date	23-Nov-2019
Fault Code / Symptom	Injector Power Supply - Bad Intelligent Device or Component
Solution Number	S00000514
Solution Title	Battery circuit fuse has open circuit
Update Reason	Solution Removed
Date	23-Nov-2019
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000514
Solution Title	Battery circuit fuse has open circuit
Update Reason	Solution Removed
Date	23-Nov-2019
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000514
Solution Title	Battery circuit fuse has open circuit
Update Reason	Solution Removed
Date	23-Nov-2019
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	23-Nov-2019
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001088
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	23-Nov-2019
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000191
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	23-Nov-2019
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	23-Nov-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation 1 Valve 1 Control 1 - Condition Exists
Solution Number	S00000514
Solution Title	Battery circuit fuse has open circuit
Update Reason	Solution Removed

Date	23-Nov-2019
Fault Code / Symptom	Engine Starter Mode Overcrank Protection - Condition Exists
Solution Number	S00000514
Solution Title	Battery circuit fuse has open circuit
Update Reason	Solution Removed

Date	23-Nov-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000733
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	23-Nov-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00001370
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	23-Nov-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	23-Nov-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	23-Nov-2019
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000514
Solution Title	Battery circuit fuse has open circuit
Update Reason	Solution Removed

Date	23-Nov-2019
Fault Code / Symptom	Fuel Level 1 - Out of Calibration
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Added
Date	23-Nov-2019
Fault Code / Symptom	Fuel Level 1 - Out of Calibration
Solution Number	S00000514
Solution Title	Battery circuit fuse has open circuit
Update Reason	Solution Removed
Date	23-Nov-2019
Fault Code / Symptom	Fuel Level 2 - Out of Calibration
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Added
Date	23-Nov-2019
Fault Code / Symptom	Fuel Level 2 - Out of Calibration
Solution Number	S00000514
Solution Title	Battery circuit fuse has open circuit
Update Reason	Solution Removed
Date	23-Nov-2019
Fault Code / Symptom	Accelerator Pedal Position 1 - Out of Calibration
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Added
Date	23-Nov-2019
Fault Code / Symptom	Accelerator Pedal Position 1 - Out of Calibration
Solution Number	S00000514
Solution Title	Battery circuit fuse has open circuit
Update Reason	Solution Removed

Date	16-Nov-2019
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00000446
Solution Title	Internal ECM Error
Update Reason	Solution Reordered
Date	16-Nov-2019
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00000446
Solution Title	Internal ECM Error
Update Reason	Solution Modified
Date	16-Nov-2019
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	16-Nov-2019
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000046
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	16-Nov-2019
Fault Code / Symptom	Sensor Supply 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	16-Nov-2019
Fault Code / Symptom	Sensor Supply 3 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	16-Nov-2019
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00000446
Solution Title	Internal ECM Error
Update Reason	Solution Reordered
Date	16-Nov-2019
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00000446
Solution Title	Internal ECM Error
Update Reason	Solution Modified
Date	16-Nov-2019
Fault Code / Symptom	Sensor Supply 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	16-Nov-2019
Fault Code / Symptom	Sensor Supply 6 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	16-Nov-2019
Fault Code / Symptom	Sensor Supply 6 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	16-Nov-2019
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000706
Solution Title	Battery power removed by battery disconnect switch
Update Reason	Solution Reordered
Date	16-Nov-2019
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000706
Solution Title	Battery power removed by battery disconnect switch
Update Reason	Solution Modified
Date	16-Nov-2019
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003143
Solution Title	Fault Code 2636 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Reordered
Date	16-Nov-2019
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00003143
Solution Title	Fault Code 2636 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Modified

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001183
Solution Title	Aftertreatment DPF differential pressure sensor tubes plugged
Update Reason	Solution Added
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000263
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000263
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000263
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000263
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000263
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000272
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000272
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000272
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000272
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000272
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000272
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000272
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000272
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	16-Nov-2019
Fault Code / Symptom	Engine Control Module Calibration Memory - Bad Intelligent Device or Component
Solution Number	S00000446
Solution Title	Internal ECM Error
Update Reason	Solution Reordered

Date	16-Nov-2019
Fault Code / Symptom	Engine Control Module Calibration Memory - Bad Intelligent Device or Component
Solution Number	S00000446
Solution Title	Internal ECM Error
Update Reason	Solution Modified

Date	16-Nov-2019
Fault Code / Symptom	Engine Control Module Calibration Memory - Bad Intelligent Device or Component
Solution Number	S00003077
Solution Title	Internal ECM Error
Update Reason	Solution Removed

Date	16-Nov-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation 1 Valve 1 Control 1 - Condition Exists
Solution Number	S00000446
Solution Title	Internal ECM Error
Update Reason	Solution Reordered

Date	16-Nov-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation 1 Valve 1 Control 1 - Condition Exists
Solution Number	S00000446
Solution Title	Internal ECM Error
Update Reason	Solution Modified

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00004970
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00000425
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00000425
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Outlet Gas Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00000425
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00000425
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted Low
Solution Number	S00000425
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00000280
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	16-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature Sensor - Data Not Rational - Drifted High
Solution Number	S00000421
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	11-Nov-2019
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00000897
Solution Title	Oil consumption related to high blowby
Update Reason	Solution Reordered

Date	11-Nov-2019
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00000897
Solution Title	Oil consumption related to high blowby
Update Reason	Solution Modified
Date	11-Nov-2019
Fault Code / Symptom	Ambient Air Temperature Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	11-Nov-2019
Fault Code / Symptom	Ambient Air Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	11-Nov-2019
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000624
Solution Title	Lubricating oil dipstick calibration is incorrect
Update Reason	Solution Removed
Date	11-Nov-2019
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000625
Solution Title	Lubricating oil dipstick calibration is incorrect
Update Reason	Solution Removed

Date	11-Nov-2019
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000624
Solution Title	Lubricating oil dipstick calibration is incorrect
Update Reason	Solution Removed

Date	11-Nov-2019
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000625
Solution Title	Lubricating oil dipstick calibration is incorrect
Update Reason	Solution Removed

Date	11-Nov-2019
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006414
Solution Title	Crankcase pressure sensor is malfunctioning
Update Reason	Solution Added

Date	11-Nov-2019
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000624
Solution Title	Lubricating oil dipstick calibration is incorrect
Update Reason	Solution Removed

Date	11-Nov-2019
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000625
Solution Title	Lubricating oil dipstick calibration is incorrect
Update Reason	Solution Removed

Date	11-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00000994
Solution Title	Aftertreatment outlet NOx sensor is malfunctioning
Update Reason	Solution Added
Date	11-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Above Normal or Shorted to High Source
Solution Number	S00006440
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	11-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006440
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	11-Nov-2019
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Data Not Rational - Drifted Low
Solution Number	S00000967
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Removed
Date	11-Nov-2019
Fault Code / Symptom	Transmission Gear Ratio Module - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	11-Nov-2019
Fault Code / Symptom	Navigation Control Module - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	02-Nov-2019
Fault Code / Symptom	Connected Calibrations Malfunctioning
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-Nov-2019
Fault Code / Symptom	Coolant Pressure Low
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-Nov-2019
Fault Code / Symptom	Coolant Smell
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-Nov-2019
Fault Code / Symptom	Crankcase Filter Life Reduced
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-Nov-2019
Fault Code / Symptom	Crankcase Sludge
Solution Number	
Solution Title	
Update Reason	Solution Set Removed

Date	02-Nov-2019
Fault Code / Symptom	Dynamic Engine System Analysis Will Not Activate
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-Nov-2019
Fault Code / Symptom	Electronic Dash Failure
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-Nov-2019
Fault Code / Symptom	Erratic Idle Speed
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-Nov-2019
Fault Code / Symptom	Fuel Smell
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-Nov-2019
Fault Code / Symptom	Hydrocarbon/Exhaust Smell
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-Nov-2019
Fault Code / Symptom	Lift Pump Cycling
Solution Number	
Solution Title	
Update Reason	Solution Set Removed

Date	02-Nov-2019
Fault Code / Symptom	No Communication ECM to ECM
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-Nov-2019
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000047
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	02-Nov-2019
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000045
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	02-Nov-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00006184
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	02-Nov-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006184
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	02-Nov-2019
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	02-Nov-2019
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000635
Solution Title	Crankcase pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	02-Nov-2019
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000635
Solution Title	Crankcase pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	02-Nov-2019
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00003234
Solution Title	Lubricating oil level is incorrect
Update Reason	Solution Added
Date	02-Nov-2019
Fault Code / Symptom	Fuel Level (Main Tank) Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000047
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	26-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000755
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	26-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000755
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	26-Oct-2019
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000060
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	26-Oct-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002207
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	26-Oct-2019
Fault Code / Symptom	Turbocharger 1 Compressor Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000343
Solution Title	Compressor intake temperature sensor stuck in-range
Update Reason	Solution Removed
Date	26-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00000143
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	26-Oct-2019
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000755
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	26-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00000755
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	26-Oct-2019
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000755
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed

Date	26-Oct-2019
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000755
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	19-Oct-2019
Fault Code / Symptom	Engine/Transmission Match - Received Network Data in Error
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	19-Oct-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	19-Oct-2019
Fault Code / Symptom	Crank No Start
Solution Number	S00001220
Solution Title	Fuel pressure relief valve return flow excessive
Update Reason	Solution Removed
Date	19-Oct-2019
Fault Code / Symptom	Low Power
Solution Number	S00001220
Solution Title	Fuel pressure relief valve return flow excessive
Update Reason	Solution Removed

Date	19-Oct-2019
Fault Code / Symptom	Lubricating Oil Temperature High
Solution Number	S00001357
Solution Title	Lubricating oil thermostat is malfunctioning
Update Reason	Solution Removed
Date	19-Oct-2019
Fault Code / Symptom	White Smoke
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	19-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	19-Oct-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added

Date	19-Oct-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	19-Oct-2019
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	19-Oct-2019
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	19-Oct-2019
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	19-Oct-2019
Fault Code / Symptom	Engine Cooling System Monitor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Added

Date	19-Oct-2019
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	19-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	19-Oct-2019
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000900
Solution Title	Fuel filter restriction
Update Reason	Solution Removed
Date	19-Oct-2019
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 1 Circuit Frequency - Abnormal Frequency or Pulse Width or Period
Solution Number	S00000193
Solution Title	Check for primary fault codes
Update Reason	Solution Reordered
Date	19-Oct-2019
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 1 Circuit Frequency - Abnormal Frequency or Pulse Width or Period
Solution Number	S00000193
Solution Title	Check for primary fault codes
Update Reason	Solution Modified

Date	19-Oct-2019
Fault Code / Symptom	Engine Air Shutoff - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000187
Solution Title	Check for primary fault codes
Update Reason	Solution Reordered
Date	19-Oct-2019
Fault Code / Symptom	Engine Air Shutoff - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000187
Solution Title	Check for primary fault codes
Update Reason	Solution Modified
Date	19-Oct-2019
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000121
Solution Title	Check for primary fault codes
Update Reason	Solution Reordered
Date	19-Oct-2019
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000121
Solution Title	Check for primary fault codes
Update Reason	Solution Modified
Date	19-Oct-2019
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000120
Solution Title	Check for primary fault codes
Update Reason	Solution Reordered

Date	19-Oct-2019
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000120
Solution Title	Check for primary fault codes
Update Reason	Solution Modified
Date	19-Oct-2019
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00000107
Solution Title	Check for primary fault codes
Update Reason	Solution Reordered
Date	19-Oct-2019
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00000107
Solution Title	Check for primary fault codes
Update Reason	Solution Modified
Date	19-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	19-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Temperature 2 - Root Cause Not Known
Solution Number	S00000100
Solution Title	Check for primary fault codes
Update Reason	Solution Reordered

Date	19-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Temperature 2 - Root Cause Not Known
Solution Number	S00000100
Solution Title	Check for primary fault codes
Update Reason	Solution Modified
Date	19-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted High
Solution Number	S00000099
Solution Title	Check for primary fault codes
Update Reason	Solution Reordered
Date	19-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted High
Solution Number	S00000099
Solution Title	Check for primary fault codes
Update Reason	Solution Modified
Date	19-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	S00000096
Solution Title	Check for primary fault codes
Update Reason	Solution Reordered
Date	19-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	S00000096
Solution Title	Check for primary fault codes
Update Reason	Solution Modified

Date	19-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor - Abnormal Rate of Change
Solution Number	S00000093
Solution Title	Check for primary fault codes
Update Reason	Solution Reordered
Date	19-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor - Abnormal Rate of Change
Solution Number	S00000093
Solution Title	Check for primary fault codes
Update Reason	Solution Modified
Date	19-Oct-2019
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	19-Oct-2019
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006329
Solution Title	Intake manifold pressure sensor has carbon buildup
Update Reason	Solution Added
Date	12-Oct-2019
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00001253
Solution Title	Air compressor discharge line damaged or restricted with carbon
Update Reason	Solution Reordered

Date	12-Oct-2019
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00001253
Solution Title	Air compressor discharge line damaged or restricted with carbon
Update Reason	Solution Modified
Date	12-Oct-2019
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00001253
Solution Title	Air compressor discharge line damaged or restricted with carbon
Update Reason	Solution Reordered
Date	12-Oct-2019
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00001253
Solution Title	Air compressor discharge line damaged or restricted with carbon
Update Reason	Solution Modified
Date	12-Oct-2019
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00001253
Solution Title	Air compressor discharge line damaged or restricted with carbon
Update Reason	Solution Reordered
Date	12-Oct-2019
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00001253
Solution Title	Air compressor discharge line damaged or restricted with carbon
Update Reason	Solution Modified
Date	12-Oct-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered

Date	12-Oct-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	12-Oct-2019
Fault Code / Symptom	Blue Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	12-Oct-2019
Fault Code / Symptom	Blue Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	12-Oct-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	12-Oct-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	12-Oct-2019
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered

Date	12-Oct-2019
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	12-Oct-2019
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	12-Oct-2019
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	12-Oct-2019
Fault Code / Symptom	Low Power
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	12-Oct-2019
Fault Code / Symptom	Low Power
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	12-Oct-2019
Fault Code / Symptom	Low Power
Solution Number	S00005346
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed

Date	12-Oct-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00001345
Solution Title	Aftertreatment DPF is full of ash
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Reordered
Date	12-Oct-2019
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Modified
Date	12-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004111
Solution Title	Fuel injector solenoid isolation test
Update Reason	Solution Added
Date	12-Oct-2019
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00001280
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed

Date	12-Oct-2019
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004111
Solution Title	Fuel injector solenoid isolation test
Update Reason	Solution Added
Date	12-Oct-2019
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00001280
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004111
Solution Title	Fuel injector solenoid isolation test
Update Reason	Solution Added
Date	12-Oct-2019
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00001280
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004111
Solution Title	Fuel injector solenoid isolation test
Update Reason	Solution Added

Date	12-Oct-2019
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00001280
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004111
Solution Title	Fuel injector solenoid isolation test
Update Reason	Solution Added
Date	12-Oct-2019
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00001280
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004111
Solution Title	Fuel injector solenoid isolation test
Update Reason	Solution Added
Date	12-Oct-2019
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00001280
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed

Date	12-Oct-2019
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000156
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	12-Oct-2019
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	12-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00000463
Solution Title	Variable Geometry Turbocharger Hysteresis Test
Update Reason	Solution Added
Date	12-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00000755
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Added
Date	12-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	12-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	12-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00001043
Solution Title	Aftertreatment diesel exhaust fluid dosing valve is malfunctioning
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	12-Oct-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Oct-2019
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Belt Fraying/Belt Wear
Solution Number	S00004006
Solution Title	Loose alternator belt
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Belt Fraying/Belt Wear
Solution Number	S00004006
Solution Title	Loose alternator belt
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Belt Noise/Whining
Solution Number	S00004006
Solution Title	Loose alternator belt
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Belt Noise/Whining
Solution Number	S00004006
Solution Title	Loose alternator belt
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Blue Smoke
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Removed

Date	28-Sep-2019
Fault Code / Symptom	Low Power
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000340
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000340
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Ambient Air Density - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000340
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Ambient Air Density - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000340
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added

Date	28-Sep-2019
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000340
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000340
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added

Date	28-Sep-2019
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added

Date	28-Sep-2019
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added

Date	28-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added

Date	28-Sep-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added

Date	28-Sep-2019
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Dosing Unit Relay Feedback - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000340
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000340
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000340
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000340
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Blue Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added

Date	28-Sep-2019
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Low Power
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000484
Solution Title	Radiator shutters malfunctioning (if equipped)
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000484
Solution Title	Radiator shutters malfunctioning (if equipped)
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000484
Solution Title	Radiator shutters malfunctioning (if equipped)
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000484
Solution Title	Radiator shutters malfunctioning (if equipped)
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed

Date	28-Sep-2019
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Fuel injector isolation test
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Fuel injector isolation test
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Fuel injector isolation test
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Fuel injector isolation test
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Fuel injector isolation test
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Fuel injector isolation test
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Fuel injector isolation test
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Fuel injector isolation test
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Fuel injector isolation test
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Fuel injector isolation test
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Fuel injector isolation test
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00004511
Solution Title	Fuel injector isolation test
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Exhaust Gas Recirculation Temperature Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Exhaust Gas Recirculation Temperature Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00003142
Solution Title	Cooling system component is leaking
Update Reason	Solution Added
Date	28-Sep-2019
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Modified

Date	28-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed

Date	28-Sep-2019
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Reordered

Date	28-Sep-2019
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000477
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Engine/Transmission Match - Out of Calibration
Solution Number	S00006176
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	28-Sep-2019
Fault Code / Symptom	Engine/Transmission Match - Out of Calibration
Solution Number	S00005706
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Engine/Transmission Match - Out of Calibration
Solution Number	S00001139
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	28-Sep-2019
Fault Code / Symptom	Source Address of Active or Pending Transmission Requested Gear - Abnormal Update Rate
Solution Number	S00006267
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	28-Sep-2019
Fault Code / Symptom	Source Address of Active or Pending Transmission Requested Gear - Abnormal Update Rate
Solution Number	S00004933
Solution Title	Transmission Control Module software phase check
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Source Address of Active or Pending Transmission Requested Gear - Abnormal Update Rate
Solution Number	S00004898
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Removed
Date	28-Sep-2019
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Reordered
Date	28-Sep-2019
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000385
Solution Title	Intake manifold pressure sensor is malfunctioning
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00006092
Solution Title	Aftertreatment DPF outlet temperature is high
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00002546
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00006097
Solution Title	Aftertreatment DPF inlet temperature is below the minimum specification
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00002546
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	14-Sep-2019
Fault Code / Symptom	Blue Smoke
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Blue Smoke
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	14-Sep-2019
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001304
Solution Title	Excessive coolant flow through OEM plumbing and heater cores
Update Reason	Solution Reordered
Date	14-Sep-2019
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001304
Solution Title	Excessive coolant flow through OEM plumbing and heater cores
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001211
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	14-Sep-2019
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00000312
Solution Title	Lubricating oil pressure relief valve is malfunctioning
Update Reason	Solution Removed
Date	14-Sep-2019
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001200
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered

Date	14-Sep-2019
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001200
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Electronic Dash Failure
Solution Number	S00001200
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	14-Sep-2019
Fault Code / Symptom	Electronic Dash Failure
Solution Number	S00001200
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	14-Sep-2019
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	14-Sep-2019
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00001200
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	14-Sep-2019
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00001200
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00003099
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Removed
Date	14-Sep-2019
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00001811
Solution Title	OEM power supply wiring harness voltage check
Update Reason	Solution Removed
Date	14-Sep-2019
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00001852
Solution Title	Blown or incorrect OEM fuse installation
Update Reason	Solution Removed

Date	14-Sep-2019
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	14-Sep-2019
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	14-Sep-2019
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001200
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	14-Sep-2019
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001200
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified

Date	14-Sep-2019
Fault Code / Symptom	Low Power
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Low Power
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	14-Sep-2019
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000790
Solution Title	Turbocharger wastegate is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed
Date	14-Sep-2019
Fault Code / Symptom	Will Not Crank
Solution Number	S00001200
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	14-Sep-2019
Fault Code / Symptom	Will Not Crank
Solution Number	S00001200
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified

Date	14-Sep-2019
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered

Date	14-Sep-2019
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified

Date	14-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Removed

Date	14-Sep-2019
Fault Code / Symptom	Engine Fuel Pump Pressurizing Assembly 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000507
Solution Title	Fuel pump actuator circuit pin to ground short
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	14-Sep-2019
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Injector Power Supply - Bad Intelligent Device or Component
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	14-Sep-2019
Fault Code / Symptom	Injector Power Supply - Bad Intelligent Device or Component
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	J1939 Network #1 - Abnormal Update Rate
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed

Date	14-Sep-2019
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	14-Sep-2019
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	14-Sep-2019
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005285
Solution Title	Unswitched battery open circuit check
Update Reason	Solution Reordered

Date	14-Sep-2019
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005285
Solution Title	Unswitched battery open circuit check
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	14-Sep-2019
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005285
Solution Title	Unswitched battery open circuit check
Update Reason	Solution Reordered

Date	14-Sep-2019
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005285
Solution Title	Unswitched battery open circuit check
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Missing - Condition Exists
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00006220
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00000862
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Removed

Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006220
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006140
Solution Title	Aftertreatment Diesel Exhaust Fluid Voltage Drop Test
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000862
Solution Title	Aftertreatment diesel exhaust fluid dosing valve pressure check
Update Reason	Solution Removed
Date	14-Sep-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation 1 Valve 1 Control 1 - Condition Exists
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	14-Sep-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation 1 Valve 1 Control 1 - Condition Exists
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Engine Starter Mode Overcrank Protection - Condition Exists
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered

Date	14-Sep-2019
Fault Code / Symptom	Engine Starter Mode Overcrank Protection - Condition Exists
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005082
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	14-Sep-2019
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added

Date	14-Sep-2019
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	14-Sep-2019
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	14-Sep-2019
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00005285
Solution Title	Unswitched battery open circuit check
Update Reason	Solution Reordered

Date	14-Sep-2019
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00005285
Solution Title	Unswitched battery open circuit check
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Engine Speed - Root Cause Not Known
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	14-Sep-2019
Fault Code / Symptom	Engine Speed - Root Cause Not Known
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	14-Sep-2019
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00005083
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	07-Sep-2019
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000569
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	07-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000029
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	07-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006090
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added
Date	07-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006090
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added
Date	07-Sep-2019
Fault Code / Symptom	Engine Intake Manifold 1 Temperature - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	07-Sep-2019
Fault Code / Symptom	J1939 Network #1 - Out of Calibration
Solution Number	S00000514
Solution Title	Battery circuit fuse has open circuit
Update Reason	Solution Removed
Date	07-Sep-2019
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001117
Solution Title	EGR valve stuck open
Update Reason	Solution Removed

Date	07-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006090
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added
Date	07-Sep-2019
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000789
Solution Title	Coolant level or mixture incorrect
Update Reason	Solution Removed
Date	07-Sep-2019
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000789
Solution Title	Coolant level or mixture incorrect
Update Reason	Solution Removed
Date	07-Sep-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006090
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added
Date	07-Sep-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000324
Solution Title	High exhaust restriction
Update Reason	Solution Removed

Date	07-Sep-2019
Fault Code / Symptom	Engine Cooling System Monitor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006090
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added
Date	07-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00003165
Solution Title	Fault Code 3376 requires that ALL solutions be performed
Update Reason	Solution Reordered
Date	07-Sep-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00003165
Solution Title	Fault Code 3376 requires that ALL solutions be performed
Update Reason	Solution Modified
Date	07-Sep-2019
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000302
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	07-Sep-2019
Fault Code / Symptom	Engine Control Module Calibration Memory - Bad Intelligent Device or Component
Solution Number	S00000446
Solution Title	Internal ECM Error
Update Reason	Solution Added

Date	07-Sep-2019
Fault Code / Symptom	Cruise Control Disable Command - Abnormal Update Rate
Solution Number	S00001584
Solution Title	J1939 data link harness resistance check
Update Reason	Solution Removed
Date	07-Sep-2019
Fault Code / Symptom	Engine/Transmission Match - Out of Calibration
Solution Number	S00001139
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	07-Sep-2019
Fault Code / Symptom	Engine/Transmission Match - Received Network Data in Error
Solution Number	S00001139
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	07-Sep-2019
Fault Code / Symptom	Aftertreatment Outlet Oxygen - Abnormal Rate of Change
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	31-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00005146
Solution Title	Crankcase pressure is above the maximum specification
Update Reason	Solution Added

Date	31-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00002975
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Added
Date	31-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00004429
Solution Title	Crankcase pressure is above the maximum specification
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00001381
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00005106
Solution Title	Aftertreatment DPF outlet temperature is high
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00002546
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	31-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00004839
Solution Title	Aftertreatment DPF inlet temperature is below the minimum specification
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	S00002546
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00001353
Solution Title	Flywheel or flexplate is damaged or loose
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00001201
Solution Title	OEM power supply wiring harness voltage check
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00002998
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00002967
Solution Title	Cylinder head coolant passage damaged
Update Reason	Solution Removed

Date	31-Aug-2019
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001201
Solution Title	OEM power supply wiring harness voltage check
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	White Smoke
Solution Number	S00001196
Solution Title	Cracked or leaking cylinder liner
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001235
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000153
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000153
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	31-Aug-2019
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000183
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000183
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000476
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000476
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Engine Control Module Calibration Memory Software - Bad Intelligent Device or Component
Solution Number	S00000446
Solution Title	Internal ECM Error
Update Reason	Solution Removed

Date	31-Aug-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000089
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000153
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000153
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit Input Lines - Condition Exists
Solution Number	S00001387
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	31-Aug-2019
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000153
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	31-Aug-2019
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000153
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000183
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000183
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000476
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	31-Aug-2019
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000476
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed

Date	31-Aug-2019
Fault Code / Symptom	Engine Cooling System Monitor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000476
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	25-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00005360
Solution Title	Aftertreatment fuel injector is malfunctioning
Update Reason	Solution Removed
Date	25-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00005361
Solution Title	Stuck open or leaking aftertreatment fuel shutoff valve
Update Reason	Solution Removed
Date	25-Aug-2019
Fault Code / Symptom	Engine Knock
Solution Number	S00005686
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	25-Aug-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00005686
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	25-Aug-2019
Fault Code / Symptom	Fuel Knock
Solution Number	S00005686
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	25-Aug-2019
Fault Code / Symptom	Overhead Noise
Solution Number	S00005686
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	25-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000153
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	25-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000153
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	25-Aug-2019
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000047
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	25-Aug-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000153
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	25-Aug-2019
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000153
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	25-Aug-2019
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000047
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	25-Aug-2019
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000047
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	25-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000047
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	25-Aug-2019
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000153
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	25-Aug-2019
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000151
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	25-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000047
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	25-Aug-2019
Fault Code / Symptom	Fuel Level (Main Tank) Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000047
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	25-Aug-2019
Fault Code / Symptom	EGR Valve Position Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000181
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	25-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005632
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Added

Date	25-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000793
Solution Title	Aftertreatment DPF differential pressure sensor stuck in-range
Update Reason	Solution Added
Date	25-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001197
Solution Title	Perform the Snap Acceleration Test - Aftertreatment Connected
Update Reason	Solution Added
Date	25-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000651
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Removed
Date	25-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000651
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Removed
Date	25-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000651
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Pass
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00005166
Solution Title	Active fault codes preventing test from activating or completing
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00005162
Solution Title	Low engine coolant temperature preventing test from completing
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00005173
Solution Title	Cooling system component is leaking
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00002986
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00005174
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00005359
Solution Title	Aftertreatment DOC not reaching target temperature
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00005360
Solution Title	Aftertreatment fuel injector is malfunctioning
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00005361
Solution Title	Stuck open or leaking aftertreatment fuel shutoff valve
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00005093
Solution Title	Coolant temperature is above the maximum specification
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00005170
Solution Title	Cooling fan component inspection
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00005164
Solution Title	Radiator is externally obstructed
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00001285
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00002986
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00001281
Solution Title	Fan control solenoid or circuit is malfunctioning
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Complete
Solution Number	S00002225
Solution Title	Aftertreatment DOC not reaching target temperature
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Start
Solution Number	S00005166
Solution Title	Active fault codes preventing test from activating or completing
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Did Not Start
Solution Number	S00005179
Solution Title	Vehicle parking brake is malfunctioning
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002225
Solution Title	Aftertreatment DOC not reaching target temperature
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00003098
Solution Title	Aftertreatment DOC temperature limited by ambient temperature
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002515
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002535
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002224
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002534
Solution Title	EGR valve stuck open
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002546
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002537
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00000619
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00000619
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00000570
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Dynamic Engine System Analysis Will Not Activate
Solution Number	S00005179
Solution Title	Vehicle parking brake is malfunctioning
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Engine Knock
Solution Number	S00005336
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Engine Knock
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00005336
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00005336
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Exhaust Leak
Solution Number	S00000619
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Exhaust Noise
Solution Number	S00000619
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00005336
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Fuel Knock
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00001202
Solution Title	Fuel injector is leaking
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00001280
Solution Title	Fuel injector isolation test
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00005336
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Hydrocarbon/Exhaust Smell
Solution Number	S00000619
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Low Power
Solution Number	S00005346
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Low Power
Solution Number	S00005336
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Low Power
Solution Number	S00000570
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Low Power
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Overhead Noise
Solution Number	S00005336
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Overhead Noise
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000517
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00005336
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00002225
Solution Title	Aftertreatment DOC not reaching target temperature
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00003098
Solution Title	Aftertreatment DOC temperature limited by ambient temperature
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00002515
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00002535
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00002224
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00002534
Solution Title	EGR valve stuck open
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00002546
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00002537
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00000619
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00000570
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Stationary Regeneration Will Not Start
Solution Number	S00005179
Solution Title	Vehicle parking brake is malfunctioning
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00005335
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000570
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	White Smoke
Solution Number	S00005336
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	White Smoke
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000183
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000183
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000060
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000333
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000183
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000049
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Engine Intake Manifold 1 Temperature - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Engine Intake Manifold 1 Temperature - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Engine Intake Manifold 1 Temperature - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000834
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000389
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001207
Solution Title	Fuel lift pump check
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Engine Crankshaft Speed/Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000684
Solution Title	Engine crankshaft speed/position sensor is malfunctioning
Update Reason	Solution Reordered

Date	10-Aug-2019
Fault Code / Symptom	Engine Crankshaft Speed/Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000684
Solution Title	Engine crankshaft speed/position sensor is malfunctioning
Update Reason	Solution Modified

Date	10-Aug-2019
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Missing - Condition Exists
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004187
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000602
Solution Title	Snap acceleration check for excessive black smoke
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000601
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001113
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00004545
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000602
Solution Title	Snap acceleration check for excessive black smoke
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000389
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005101
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00004187
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000602
Solution Title	Snap acceleration check for excessive black smoke
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000601
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000389
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001113
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	EGR Valve Position Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000183
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000183
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000182
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Engine Crankshaft Speed/Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000684
Solution Title	Engine crankshaft speed/position sensor is malfunctioning
Update Reason	Solution Reordered
Date	10-Aug-2019
Fault Code / Symptom	Engine Crankshaft Speed/Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000684
Solution Title	Engine crankshaft speed/position sensor is malfunctioning
Update Reason	Solution Modified

Date	10-Aug-2019
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Turbocharger Compressor Outlet Temperature (Calculated) - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000183
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000899
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000183
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	VGT Actuator Driver Circuit (Motor) - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	VGT Actuator Driver Circuit (Motor) - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005112
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Turbocharger Turbine Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00004187
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000602
Solution Title	Snap acceleration check for excessive black smoke
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000601
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001113
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000602
Solution Title	Snap acceleration check for excessive black smoke
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004187
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000602
Solution Title	Snap acceleration check for excessive black smoke
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000601
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000389
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00005916
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00005940
Solution Title	Aftertreatment power relay is malfunctioning
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00005931
Solution Title	Aftertreatment intake NOx sensor open circuit check
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000880
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000881
Solution Title	Aftertreatment intake NOx sensor SUPPLY wire shorted to ground
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000389
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation Cooler Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Abnormal Rate of Change
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00004187
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000602
Solution Title	Snap acceleration check for excessive black smoke
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000601
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000389
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00005073
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00004187
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00003823
Solution Title	Aftertreatment Diesel Particulate Filter Regeneration Analyzer Test
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000602
Solution Title	Snap acceleration check for excessive black smoke
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000601
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000389
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Abnormal Rate of Change
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter 1 Conditions Not Met for Active Regeneration - Condition Exists
Solution Number	S00001113
Solution Title	Stationary aftertreatment regeneration is needed
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000183
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000183
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00005936
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay circuit pin to ground short
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Dosing Unit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000836
Solution Title	Aftertreatment diesel exhaust fluid dosing unit relay circuit pin to ground short
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000880
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000881
Solution Title	Aftertreatment intake NOx sensor SUPPLY wire shorted to ground
Update Reason	Solution Added

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000880
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000881
Solution Title	Aftertreatment intake NOx sensor SUPPLY wire shorted to ground
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000684
Solution Title	Engine crankshaft speed/position sensor is malfunctioning
Update Reason	Solution Reordered
Date	10-Aug-2019
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000684
Solution Title	Engine crankshaft speed/position sensor is malfunctioning
Update Reason	Solution Modified

Date	10-Aug-2019
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000684
Solution Title	Engine crankshaft speed/position sensor is malfunctioning
Update Reason	Solution Reordered
Date	10-Aug-2019
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000684
Solution Title	Engine crankshaft speed/position sensor is malfunctioning
Update Reason	Solution Modified
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000761
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Engine Intake Manifold Pressure System Monitor - Condition Exists
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Engine Injector Metering Rail 1 Cranking Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001207
Solution Title	Fuel lift pump check
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Exhaust Gas Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Maintain ECU Power Lamp Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Maintain ECU Power Lamp Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Ash Load Percent - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000602
Solution Title	Snap acceleration check for excessive black smoke
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Ash Load Percent - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000601
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Ash Load Percent - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Ash Load Percent - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Ash Load Percent - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Ash Load Percent - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005101
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000601
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000601
Solution Title	Aftertreatment DPF partially obstructed or plugged
Update Reason	Solution Removed

Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Engine Intake Manifold Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000311
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	10-Aug-2019
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000684
Solution Title	Engine crankshaft speed/position sensor is malfunctioning
Update Reason	Solution Reordered

Date	10-Aug-2019
Fault Code / Symptom	Engine Speed At Idle - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000684
Solution Title	Engine crankshaft speed/position sensor is malfunctioning
Update Reason	Solution Modified
Date	03-Aug-2019
Fault Code / Symptom	Crank No Start
Solution Number	S00005778
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	03-Aug-2019
Fault Code / Symptom	Low Power
Solution Number	S00001220
Solution Title	Fuel pressure relief valve return flow excessive
Update Reason	Solution Added
Date	03-Aug-2019
Fault Code / Symptom	Low Power
Solution Number	S00002777
Solution Title	High-Pressure Fuel Pump Performance Test
Update Reason	Solution Added
Date	03-Aug-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000324
Solution Title	High exhaust restriction
Update Reason	Solution Added

Date	03-Aug-2019
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000129
Solution Title	Coolant temperature sensor SIGNAL wire shorted to ground
Update Reason	Solution Removed
Date	03-Aug-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005779
Solution Title	Fuel rail pressure sensor circuit pin to ground short
Update Reason	Solution Reordered
Date	03-Aug-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005779
Solution Title	Fuel rail pressure sensor circuit pin to ground short
Update Reason	Solution Modified
Date	03-Aug-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005870
Solution Title	Fuel rail pressure sensor is malfunctioning
Update Reason	Solution Added
Date	03-Aug-2019
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	03-Aug-2019
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	03-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000880
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Removed
Date	03-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00000881
Solution Title	Aftertreatment intake NOx sensor SUPPLY wire shorted to ground
Update Reason	Solution Removed
Date	03-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000880
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Removed
Date	03-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000881
Solution Title	Aftertreatment intake NOx sensor SUPPLY wire shorted to ground
Update Reason	Solution Removed

Date	03-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000880
Solution Title	Aftertreatment intake NOx sensor voltage check
Update Reason	Solution Removed
Date	03-Aug-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000881
Solution Title	Aftertreatment intake NOx sensor SUPPLY wire shorted to ground
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00001258
Solution Title	Turbocharger oil seal is leaking oil into air intake/exhaust system
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Brake Switch and Accelerator Pedal Position Incompatible - Condition Exists
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 SCR Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Oxidation Catalyst Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Intake Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment Diesel Oxidation Catalyst Conversion Efficiency - Condition Exists
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed

Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000657
Solution Title	Malfunctioning fuel injector - Injector Performance Test
Update Reason	Solution Removed
Date	27-Jul-2019
Fault Code / Symptom	Aftertreatment 1 SCR Intermediate Gas Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000656
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Connected Calibrations Malfunctioning
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002225
Solution Title	Aftertreatment DOC not reaching target temperature
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00003098
Solution Title	Aftertreatment DOC temperature limited by ambient temperature
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002515
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002535
Solution Title	Aftertreatment exhaust system leaks
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002224
Solution Title	Turbocharger is malfunctioning
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002534
Solution Title	EGR valve stuck open
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002546
Solution Title	Aftertreatment DOC is malfunctioning
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00002537
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00004507
Solution Title	Aftertreatment exhaust gas temperature sensor is malfunctioning
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment Selective Catalyst Reduction System Test Will Not Complete
Solution Number	S00000619
Solution Title	Exhaust leak visual check
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00000619
Solution Title	Exhaust leak visual check
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00000711
Solution Title	Air governor signal line / actuator line is restricted
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00001350
Solution Title	Air intake or exhaust system leaks
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	25-May-2019
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Modified

Date	25-May-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00005355
Solution Title	Low pressure fuel system component is malfunctioning
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00001205
Solution Title	Air in fuel check
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00001206
Solution Title	Fuel Inlet Restriction check
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Black Smoke
Solution Number	S00005034
Solution Title	Fuel filter differential and gear pump pressure check
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Coolant Overflow
Solution Number	S00001194
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Crank No Start
Solution Number	S00002777
Solution Title	High-Pressure Fuel Pump Performance Test
Update Reason	Solution Reordered

Date	25-May-2019
Fault Code / Symptom	Crank No Start
Solution Number	S00002777
Solution Title	High-Pressure Fuel Pump Performance Test
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Crank No Start
Solution Number	S00005778
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Engine Knock
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Engine Knock
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Engine Noise
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Modified

Date	25-May-2019
Fault Code / Symptom	Engine Overspeed
Solution Number	S00001258
Solution Title	Turbocharger oil seal is leaking oil into air intake/exhaust system
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Engine Speed Surges
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	25-May-2019
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Exhaust Leak
Solution Number	S00000619
Solution Title	Exhaust leak visual check
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Exhaust Noise
Solution Number	S00000619
Solution Title	Exhaust leak visual check
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	25-May-2019
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Fuel Knock
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Fuel Knock
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00001329
Solution Title	Fuel gear pump is leaking fuel into the oil
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Fuel in the Lubricating Oil
Solution Number	S00001329
Solution Title	Fuel gear pump is leaking fuel into the oil
Update Reason	Solution Modified

Date	25-May-2019
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00002777
Solution Title	High-Pressure Fuel Pump Performance Test
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00002777
Solution Title	High-Pressure Fuel Pump Performance Test
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Modified

Date	25-May-2019
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00004043
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000658
Solution Title	Variable Geometry Turbocharger actuator or sector gear damaged
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00004044
Solution Title	Aftertreatment DPF is malfunctioning
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Hydrocarbon/Exhaust Smell
Solution Number	S00000619
Solution Title	Exhaust leak visual check
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified

Date	25-May-2019
Fault Code / Symptom	Low Power
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Low Power
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00000838
Solution Title	External oil leak
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Lubricating Oil Level High
Solution Number	S00001329
Solution Title	Fuel gear pump is leaking fuel into the oil
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Lubricating Oil Level High
Solution Number	S00001329
Solution Title	Fuel gear pump is leaking fuel into the oil
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	25-May-2019
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Overhead Noise
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Overhead Noise
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Reordered

Date	25-May-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00001191
Solution Title	Fuel Injector Performance Test
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Stationary Regeneration Will Not Complete
Solution Number	S00000619
Solution Title	Exhaust leak visual check
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	25-May-2019
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	White Smoke
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Reordered

Date	25-May-2019
Fault Code / Symptom	White Smoke
Solution Number	S00004302
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	White Smoke
Solution Number	S00005355
Solution Title	Low pressure fuel system component is malfunctioning
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	White Smoke
Solution Number	S00001205
Solution Title	Air in fuel check
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	White Smoke
Solution Number	S00001206
Solution Title	Fuel Inlet Restriction check
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	White Smoke
Solution Number	S00005034
Solution Title	Fuel filter differential and gear pump pressure check
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	White Smoke
Solution Number	S00001193
Solution Title	Camshaft inspection
Update Reason	Solution Removed

Date	25-May-2019
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000342
Solution Title	Lubricating oil pressure sensor stuck in-range
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Engine Oil Rifle Pressure 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000342
Solution Title	Lubricating oil pressure sensor stuck in-range
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000296
Solution Title	Coolant temperature sensor SIGNAL or RETURN wire open circuit
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00002802
Solution Title	Fuel injector solenoid shorted by debris
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00002802
Solution Title	Fuel injector solenoid shorted by debris
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00002802
Solution Title	Fuel injector solenoid shorted by debris
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00002802
Solution Title	Fuel injector solenoid shorted by debris
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00002802
Solution Title	Fuel injector solenoid shorted by debris
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00002802
Solution Title	Fuel injector solenoid shorted by debris
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Injector Power Supply - Bad Intelligent Device or Component
Solution Number	S00002325
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Engine Fuel 1 Injector Metering Rail 1 Pressure 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000515
Solution Title	High fuel inlet restriction
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Modified

Date	25-May-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000673
Solution Title	Turbocharger speed sensor circuit pin to ground short
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000651
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Turbocharger 1 Compressor Intake Temperature Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001225
Solution Title	Turbocharger compressor intake air temperature open circuit check
Update Reason	Solution Removed

Date	25-May-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000616
Solution Title	Fuel rail pressure sensor voltage check
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000617
Solution Title	Fuel rail pressure sensor voltage check at the ECM
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005779
Solution Title	Fuel rail pressure sensor circuit pin to ground short
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00005780
Solution Title	Fuel rail pressure sensor circuit pin to pin short
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000876
Solution Title	Fuel rail pressure sensor circuit response
Update Reason	Solution Removed

Date	25-May-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000609
Solution Title	Fuel rail pressure sensor circuit response
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000612
Solution Title	Fuel rail pressure sensor circuit response at the ECM
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Injector Metering Rail 1 Pressure - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000614
Solution Title	Fuel rail pressure sensor circuit response at the ECM
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	S00004854
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor is malfunctioning
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000945
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor is malfunctioning
Update Reason	Solution Removed

Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000695
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor is malfunctioning
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00004854
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor is malfunctioning
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00000945
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor is malfunctioning
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00000695
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor is malfunctioning
Update Reason	Solution Removed

Date	25-May-2019
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001109
Solution Title	Fault Code 1894 triggered by a malfunction in the J1939 data link with multiple OEM fault codes
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00001109
Solution Title	Fault Code 1894 triggered by a malfunction in the J1939 data link with multiple OEM fault codes
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00004051
Solution Title	Stuck open or leaking EGR valve
Update Reason	Solution Reordered

Date	25-May-2019
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00004051
Solution Title	Stuck open or leaking EGR valve
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Sensor Supply 4 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001061
Solution Title	Accelerator pedal position sensor circuit response
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000651
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Engine Crankshaft Speed/Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000676
Solution Title	Crankshaft position sensor open circuit check
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003039
Solution Title	Exhaust gas pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000886
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	VGT Actuator Driver Circuit - Abnormal Update Rate
Solution Number	S00000597
Solution Title	Variable geometry turbocharger actuator voltage check
Update Reason	Solution Modified

Date	25-May-2019
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001183
Solution Title	Aftertreatment DPF differential pressure sensor tubes plugged
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor - Abnormal Update Rate
Solution Number	S00001242
Solution Title	Variable geometry turbocharger actuator has incorrect J1939 terminating resistance
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment Regeneration Inhibited Due to Inhibit Switch - Condition Exists
Solution Number	S00005697
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Modified

Date	25-May-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000651
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000703
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor - Abnormal Update Rate
Solution Number	S00001242
Solution Title	Variable geometry turbocharger actuator has incorrect J1939 terminating resistance
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003309
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003309
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Removed

Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00001396
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Heater - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00001102
Solution Title	No coolant flow through diesel exhaust fluid tank heater line
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Modified

Date	25-May-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000795
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000795
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Modified

Date	25-May-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000795
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000795
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003309
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000394
Solution Title	Engine intake throttle actuator circuit response
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Engine Intake Throttle Actuator Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001369
Solution Title	Engine intake throttle actuator circuit response
Update Reason	Solution Removed

Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000664
Solution Title	Aftertreatment diesel exhaust fluid dosing unit line or fittings are cracked, plugged or restricted
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	High Pressure Common Rail Fuel Pressure Relief Valve - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000515
Solution Title	High fuel inlet restriction
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00005738
Solution Title	Fault Code 3868 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00005705
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor voltage check
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00001242
Solution Title	Variable geometry turbocharger actuator has incorrect J1939 terminating resistance
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Quality - Abnormal Update Rate
Solution Number	S00000906
Solution Title	Fault Code 3868 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Removed

Date	25-May-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001242
Solution Title	Variable geometry turbocharger actuator has incorrect J1939 terminating resistance
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Abnormal Update Rate
Solution Number	S00001242
Solution Title	Variable geometry turbocharger actuator has incorrect J1939 terminating resistance
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Bad Intelligent Device or Component
Solution Number	S00001432
Solution Title	Aftertreatment DPF temperature sensor module is malfunctioning
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment Diesel Particulate Filter Temperature Sensor Module - Bad Intelligent Device or Component
Solution Number	S00001184
Solution Title	Aftertreatment temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Aftertreatment Selective Catalytic Reduction Temperature Sensor Module - Bad Intelligent Device or Component
Solution Number	S00000922
Solution Title	Aftertreatment SCR temperature sensor module is malfunctioning
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00005739
Solution Title	Fault Code 4572 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00005705
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor voltage check
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00001242
Solution Title	Variable geometry turbocharger actuator has incorrect J1939 terminating resistance
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Abnormal Update Rate
Solution Number	S00000968
Solution Title	Fault Code 4572 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00005690
Solution Title	Fault Code 4677 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00005705
Solution Title	Aftertreatment diesel exhaust fluid tank level/temperature/quality sensor voltage check
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00001242
Solution Title	Variable geometry turbocharger actuator has incorrect J1939 terminating resistance
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00000990
Solution Title	Fault Code 4677 triggered by a malfunction in the J1939 data link with multiple OEM fault code
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Root Cause Not Known
Solution Number	S00004854
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor is malfunctioning
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature - Root Cause Not Known
Solution Number	S00000945
Solution Title	Aftertreatment diesel exhaust fluid tank temperature sensor is malfunctioning
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted High
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted High
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Modified

Date	25-May-2019
Fault Code / Symptom	Engine/Transmission Match - Out of Calibration
Solution Number	S00005706
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Engine/Transmission Match - Out of Calibration
Solution Number	S00001139
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Engine/Transmission Match - Received Network Data in Error
Solution Number	S00005706
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Engine/Transmission Match - Received Network Data in Error
Solution Number	S00001139
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Removed
Date	25-May-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Reordered

Date	25-May-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00000651
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00000651
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Added

Date	25-May-2019
Fault Code / Symptom	Aftertreatment 1 Particulate Sensor - Abnormal Update Rate
Solution Number	S00001242
Solution Title	Variable geometry turbocharger actuator has incorrect J1939 terminating resistance
Update Reason	Solution Added
Date	25-May-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Reordered
Date	25-May-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001114
Solution Title	Leaking EGR differential pressure sensor mounting surface
Update Reason	Solution Modified
Date	25-May-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000795
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Reordered

Date	25-May-2019
Fault Code / Symptom	Engine Exhaust Gas Recirculation (EGR) System - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000795
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Modified
Date	20-Jul-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Reordered
Date	20-Jul-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Modified
Date	20-Jul-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Reordered
Date	20-Jul-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Modified

Date	20-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000584
Solution Title	Aftertreatment DPF differential pressure sensor tubes orientation is incorrect
Update Reason	Solution Removed
Date	20-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000584
Solution Title	Aftertreatment DPF differential pressure sensor tubes orientation is incorrect
Update Reason	Solution Removed
Date	20-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000584
Solution Title	Aftertreatment DPF differential pressure sensor tubes orientation is incorrect
Update Reason	Solution Removed
Date	20-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter System - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000584
Solution Title	Aftertreatment DPF differential pressure sensor tubes orientation is incorrect
Update Reason	Solution Removed

Date	20-Jul-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Reordered
Date	20-Jul-2019
Fault Code / Symptom	Turbocharger 1 Speed - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Modified
Date	20-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000584
Solution Title	Aftertreatment DPF differential pressure sensor tubes orientation is incorrect
Update Reason	Solution Removed
Date	20-Jul-2019
Fault Code / Symptom	Engine Diesel Particulate Filter Intake Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000584
Solution Title	Aftertreatment DPF differential pressure sensor tubes orientation is incorrect
Update Reason	Solution Removed
Date	20-Jul-2019
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001010
Solution Title	Damaged or missing aftertreatment DPF differential pressure sensor tubes
Update Reason	Solution Added

Date	20-Jul-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Reordered
Date	20-Jul-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Modified
Date	20-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000584
Solution Title	Aftertreatment DPF differential pressure sensor tubes orientation is incorrect
Update Reason	Solution Removed
Date	20-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Regeneration too Frequent - Condition Exists
Solution Number	S00000584
Solution Title	Aftertreatment DPF differential pressure sensor tubes orientation is incorrect
Update Reason	Solution Removed
Date	20-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Incomplete Regeneration - Condition Exists
Solution Number	S00000584
Solution Title	Aftertreatment DPF differential pressure sensor tubes orientation is incorrect
Update Reason	Solution Removed

Date	20-Jul-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Reordered
Date	20-Jul-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted High
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Modified
Date	20-Jul-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Reordered
Date	20-Jul-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Not Rational - Drifted Low
Solution Number	S00002831
Solution Title	Turbocharger speed sensor is malfunctioning
Update Reason	Solution Modified
Date	20-Jul-2019
Fault Code / Symptom	Fan Control Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00005653
Solution Title	Fan control solenoid or circuit is malfunctioning
Update Reason	Solution Added

Date	20-Jul-2019
Fault Code / Symptom	Fan Control Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001056
Solution Title	Fan control solenoid or circuit is malfunctioning
Update Reason	Solution Removed
Date	20-Jul-2019
Fault Code / Symptom	Fan Control Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00005653
Solution Title	Fan control solenoid or circuit is malfunctioning
Update Reason	Solution Added
Date	20-Jul-2019
Fault Code / Symptom	Fan Control Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001056
Solution Title	Fan control solenoid or circuit is malfunctioning
Update Reason	Solution Removed
Date	20-Jul-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00000584
Solution Title	Aftertreatment DPF differential pressure sensor tubes orientation is incorrect
Update Reason	Solution Removed
Date	12-May-2019
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Consumption Excessive
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Reordered

Date	12-May-2019
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Consumption Excessive
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Modified
Date	12-May-2019
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Reordered
Date	12-May-2019
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Modified
Date	12-May-2019
Fault Code / Symptom	Exhaust Leak
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Reordered
Date	12-May-2019
Fault Code / Symptom	Exhaust Leak
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Modified
Date	12-May-2019
Fault Code / Symptom	Fuel Smell
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Reordered

Date	12-May-2019
Fault Code / Symptom	Fuel Smell
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Modified
Date	12-May-2019
Fault Code / Symptom	Hydrocarbon/Exhaust Smell
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Reordered
Date	12-May-2019
Fault Code / Symptom	Hydrocarbon/Exhaust Smell
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Modified
Date	12-May-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Reordered
Date	12-May-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00001209
Solution Title	Exhaust leak visual check
Update Reason	Solution Modified
Date	12-May-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00005613
Solution Title	Aftertreatment DPF differential pressure sensor stuck in-range
Update Reason	Solution Added

Date	12-May-2019
Fault Code / Symptom	Regeneration Excessive
Solution Number	S00001197
Solution Title	Perform the Snap Acceleration Test - Aftertreatment Connected
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000324
Solution Title	High exhaust restriction
Update Reason	Solution Removed
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000695
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor is malfunctioning
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Temperature Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00000695
Solution Title	Aftertreatment diesel exhaust fluid tank level sensor is malfunctioning
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00005632
Solution Title	Barometric air pressure sensor stuck in-range
Update Reason	Solution Added

Date	12-May-2019
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00002790
Solution Title	Aftertreatment DPF outlet pressure circuit pin to ground short
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000583
Solution Title	Aftertreatment DPF outlet pressure circuit pin to ground short
Update Reason	Solution Removed
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003309
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Reordered

Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003309
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Modified
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003309
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Reordered
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003309
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Modified
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003309
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Reordered

Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Line Heater 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003309
Solution Title	Aftertreatment diesel exhaust fluid line heater pin shorted to another pin
Update Reason	Solution Modified
Date	12-May-2019
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Line Heater Relay - Voltage Above Normal or Shorted to High Source
Solution Number	S00000796
Solution Title	Aftertreatment diesel exhaust fluid line heater relay is malfunctioning
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment Diesel Exhaust Fluid Line Heater Relay - Voltage Above Normal or Shorted to High Source
Solution Number	S00000840
Solution Title	Aftertreatment diesel exhaust fluid line heater relay resistance check
Update Reason	Solution Removed
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added

Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Added

Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Heater - Abnormal Rate of Change
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Outlet NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added

Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Intake NOx Sensor Power Supply - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00004534
Solution Title	J1939 data link harness open circuit check
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Abnormal Update Rate
Solution Number	S00001584
Solution Title	J1939 data link harness resistance check
Update Reason	Solution Removed
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00002790
Solution Title	Aftertreatment DPF outlet pressure circuit pin to ground short
Update Reason	Solution Added
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00000347
Solution Title	Aftertreatment DPF Outlet Pressure Sensor circuit response
Update Reason	Solution Removed
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00000349
Solution Title	Aftertreatment DPF Outlet Pressure Sensor circuit response
Update Reason	Solution Removed

Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Abnormal Rate of Change
Solution Number	S00000583
Solution Title	Aftertreatment DPF outlet pressure circuit pin to ground short
Update Reason	Solution Removed
Date	12-May-2019
Fault Code / Symptom	Electric Lift Pump for Engine Fuel Supply - Voltage Above Normal or Shorted to High Source
Solution Number	S00001649
Solution Title	Electric fuel lift pump resistance check
Update Reason	Solution Reordered
Date	12-May-2019
Fault Code / Symptom	Electric Lift Pump for Engine Fuel Supply - Voltage Above Normal or Shorted to High Source
Solution Number	S00001649
Solution Title	Electric fuel lift pump resistance check
Update Reason	Solution Modified
Date	12-May-2019
Fault Code / Symptom	Engine Starter Motor Relay Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000667
Solution Title	Starter lockout relay is malfunctioning
Update Reason	Solution Removed
Date	12-May-2019
Fault Code / Symptom	Fan Control Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00001058
Solution Title	Fan control solenoid circuit pin to pin short
Update Reason	Solution Removed

Date	12-May-2019
Fault Code / Symptom	Fan Control Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001058
Solution Title	Fan control solenoid circuit pin to pin short
Update Reason	Solution Removed
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00000349
Solution Title	Aftertreatment DPF Outlet Pressure Sensor circuit response
Update Reason	Solution Removed
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00000347
Solution Title	Aftertreatment DPF Outlet Pressure Sensor circuit response
Update Reason	Solution Removed
Date	12-May-2019
Fault Code / Symptom	Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00000583
Solution Title	Aftertreatment DPF outlet pressure circuit pin to ground short
Update Reason	Solution Removed
Date	12-May-2019
Fault Code / Symptom	
Solution Number	
Solution Title	
Update Reason	X15 CM2350 X114B New manual released for use.

