

Manual Change History (3666322) ISM, ISMe, and QSM11

Service Manual

Date	Not Available
Section	Front
Procedure Number	3666322-toc (/qs3/pubsys2/xml/en/manual/3666322/3666322-toc.html)
Procedure Title	Table of Contents
Update Reason	

Date	12-Mar-2002
Section	Section i - Introduction
Procedure Number	99-204-004 (/qs3/pubsys2/xml/en/procedures/99/99-204-004.html)
Procedure Title	Symbols
Update Reason	

Date	12-Mar-2002
Section	Section i - Introduction
Procedure Number	99-204-005 (/qs3/pubsys2/xml/en/procedures/99/99-204-005.html)
Procedure Title	Illustrations
Update Reason	

Date	03-Apr-2002
Section	Section TS - Troubleshooting Symptoms
Procedure Number	99-t00-002 (/qs3/pubsys2/xml/en/procedures/99/99-t00-002.html)
Procedure Title	Troubleshooting Symptoms Charts
Update Reason	

Date	24-Jul-2002
Section	Section F - Familiarization
Procedure Number	35-000-999 (/qs3/pubsys2/xml/en/procedures/35/35-000-999.html)
Procedure Title	Complete Engine - Overview
Update Reason	
Date	26-Jul-2002
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-013 (/qs3/pubsys2/xml/en/procedures/35/35-001-013.html)
Procedure Title	Camshaft Gear (Camshaft Removed)
Update Reason	
Date	14-Aug-2002
Section	Section 9 - Drive Units - Group 09
Procedure Number	35-022-001_09 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_09.html)
Procedure Title	Service Tools
Update Reason	
Date	19-Aug-2002
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-022-001_12 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_12.html)
Procedure Title	Service Tools
Update Reason	
Date	19-Aug-2002
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	35-022-001_13 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_13.html)
Procedure Title	Service Tools
Update Reason	

Date	27-Aug-2002
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	35-022-001_16 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_16.html)
Procedure Title	Service Tools
Update Reason	
Date	27-Aug-2002
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	35-016-008 (/qs3/pubsys2/xml/en/procedures/35/35-016-008.html)
Procedure Title	Flywheel Ring Gear
Update Reason	
Date	30-Sep-2002
Section	Section F - Familiarization
Procedure Number	35-020-999 (/qs3/pubsys2/xml/en/procedures/35/35-020-999.html)
Procedure Title	Vehicle Braking - Overview
Update Reason	
Date	17-Feb-2003
Section	Section 14 - Engine Testing - Group 14
Procedure Number	101-014-008 (/qs3/pubsys2/xml/en/procedures/101/101-014-008.html)
Procedure Title	Engine Testing (In Chassis)
Update Reason	
Date	17-Feb-2003
Section	Section 14 - Engine Testing - Group 14
Procedure Number	101-014-009 (/qs3/pubsys2/xml/en/procedures/101/101-014-009.html)
Procedure Title	Engine Testing (Portable Dynamometer or Load Bank)
Update Reason	

Date	12-May-2003
Section	Section 17 - Miscellaneous - Group 17
Procedure Number	99-017-007 (/qs3/pubsys2/xml/en/procedures/99/99-017-007.html)
Procedure Title	Pipe Plug
Update Reason	
Date	26-Aug-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	99-013-007 (/qs3/pubsys2/xml/en/procedures/99/99-013-007.html)
Procedure Title	Batteries
Update Reason	
Date	26-Aug-2003
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	99-013-009 (/qs3/pubsys2/xml/en/procedures/99/99-013-009.html)
Procedure Title	Battery Cables and Connections
Update Reason	
Date	18-Dec-2003
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t004-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t004-tr.html)
Procedure Title	Air Compressor Air Pressure Rises Slowly
Update Reason	
Date	18-Dec-2003
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t005-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t005-tr.html)
Procedure Title	Air Compressor Cycles Frequently
Update Reason	

Date	18-Dec-2003
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t008-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t008-tr.html)
Procedure Title	Air Compressor Will Not Maintain Adequate Air Pressure (Not Pumping Continuously)
Update Reason	
Date	18-Dec-2003
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t014-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t014-tr.html)
Procedure Title	Alternator Overcharging
Update Reason	
Date	19-Dec-2003
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t048-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t048-tr.html)
Procedure Title	Engine Noise Excessive - Combustion Knocks
Update Reason	
Date	19-Dec-2003
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t072-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t072-tr.html)
Procedure Title	Engine Starts But Will Not Keep Running
Update Reason	
Date	22-Dec-2003
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t108-10-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t108-10-tr.html)
Procedure Title	Oil Pan Level Incorrect - Low (Centinel)
Update Reason	

Date	22-Dec-2003
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t108-11-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t108-11-tr.html)
Procedure Title	Oil Pan Level Incorrect - High (Centinel)
Update Reason	
Date	22-Dec-2003
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t109-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t109-tr.html)
Procedure Title	Operating Fuel Pressure is Low
Update Reason	
Date	05-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t081-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t081-tr.html)
Procedure Title	Engine Will Not Shut Off
Update Reason	
Date	05-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t096-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t096-tr.html)
Procedure Title	Intake Manifold Air Temperature Above Specification
Update Reason	
Date	05-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t097-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t097-tr.html)
Procedure Title	Intake Manifold Pressure (Boost) is Below Normal
Update Reason	

Date	05-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t099-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t099-tr.html)
Procedure Title	Low Idle Adjust Switch Does Not Work
Update Reason	
Date	05-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t103-2-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t103-2-tr.html)
Procedure Title	Lubricating Oil Degradation (Centinel)
Update Reason	
Date	08-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t027-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t027-tr.html)
Procedure Title	Crankcase Gases (Blowby) Excessive
Update Reason	
Date	08-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t038-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t038-tr.html)
Procedure Title	Engine Brake - One or More Cylinders Braking with Power Switch Off
Update Reason	
Date	08-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t041-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t041-tr.html)
Procedure Title	Engine Decelerates Slowly
Update Reason	

Date	16-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t006-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t006-tr.html)
Procedure Title	Air Compressor Noise is Excessive
Update Reason	
Date	16-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t007-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t007-tr.html)
Procedure Title	Air Compressor Pumping Excess Lubricating Oil into the Air System
Update Reason	
Date	16-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t009-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t009-tr.html)
Procedure Title	Air Compressor Will Not Pump Air
Update Reason	
Date	16-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t010-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t010-tr.html)
Procedure Title	Air Compressor Will Not Stop Pumping
Update Reason	
Date	16-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t023-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t023-tr.html)
Procedure Title	Coolant Temperature is Above Normal - Sudden Overheat
Update Reason	

Date	16-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t024-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t024-tr.html)
Procedure Title	Coolant Temperature Below Normal
Update Reason	
Date	16-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t052-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t052-tr.html)
Procedure Title	Engine Noise Excessive - Turbocharger
Update Reason	
Date	16-Jan-2004
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t091-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t091-tr.html)
Procedure Title	Fuel in Coolant
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-010 (/qs3/pubsys2/xml/en/procedures/99/99-018-010.html)
Procedure Title	Fraction, Decimal, Millimeter Conversions
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-011 (/qs3/pubsys2/xml/en/procedures/99/99-018-011.html)
Procedure Title	Newton-Meter to Foot-Pound Conversions
Update Reason	

Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-012 (/qs3/pubsys2/xml/en/procedures/99/99-018-012.html)
Procedure Title	Pipe Plug Torque Values
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-013 (/qs3/pubsys2/xml/en/procedures/99/99-018-013.html)
Procedure Title	Tap-Drill Chart - U.S. Customary and Metric
Update Reason	
Date	03-Mar-2004
Section	Section V - Specifications
Procedure Number	99-018-014 (/qs3/pubsys2/xml/en/procedures/99/99-018-014.html)
Procedure Title	Weights and Measures - Conversion Factors
Update Reason	
Date	01-Jul-2004
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-022-001_07 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_07.html)
Procedure Title	Service Tools
Update Reason	
Date	28-Mar-2005
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t022-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t022-tr.html)
Procedure Title	Coolant Temperature Above Normal - Gradual Overheat
Update Reason	

Date	28-Mar-2005
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t068-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t068-tr.html)
Procedure Title	Engine Speed Surges in PTO or Cruise Control
Update Reason	
Date	28-Mar-2005
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t103-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t103-tr.html)
Procedure Title	Lubricating Oil Contaminated
Update Reason	
Date	28-Mar-2005
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t104-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t104-tr.html)
Procedure Title	Lubricating Oil Pressure High
Update Reason	
Date	28-Mar-2005
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t106-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t106-tr.html)
Procedure Title	Lubricating Oil Sludge in the Crankcase Excessive
Update Reason	
Date	20-Jul-2005
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	35-022-001_02 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_02.html)
Procedure Title	Service Tools
Update Reason	

Date	20-Jul-2005
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	35-022-001_03 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_03.html)
Procedure Title	Service Tools
Update Reason	
Date	20-Jul-2005
Section	Section 4 - Cam Followers/Tappets - Group 04
Procedure Number	35-022-001_04 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_04.html)
Procedure Title	Service Tools
Update Reason	
Date	20-Jul-2005
Section	Section 5 - Fuel System - Group 05
Procedure Number	35-022-001_05 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_05.html)
Procedure Title	Service Tools
Update Reason	
Date	20-Jul-2005
Section	Section 5 - Fuel System - Group 05
Procedure Number	35-005-026 (/qs3/pubsys2/xml/en/procedures/35/35-005-026.html)
Procedure Title	Fuel Pump Gear Pump Check Valve
Update Reason	
Date	01-Sep-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-028-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-028-tr.html)
Procedure Title	Lubricating Oil Pressure Gauge
Update Reason	

Date	01-Sep-2005
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-078-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-078-tr.html)
Procedure Title	Centinel™ Oil Control Valve
Update Reason	
Date	22-Sep-2005
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-006-018-shopds (/qs3/pubsys2/xml/en/procedures/35/35-006-018-shopds.html)
Procedure Title	Fuel Filter Head Bracket
Update Reason	
Date	22-Sep-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-006-018-shopas (/qs3/pubsys2/xml/en/procedures/35/35-006-018-shopas.html)
Procedure Title	Fuel Filter Head Bracket
Update Reason	
Date	11-Oct-2005
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-013-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-013-shopds.html)
Procedure Title	Camshaft Gear (Camshaft Removed)
Update Reason	
Date	11-Oct-2005
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-012-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-012-shopds.html)
Procedure Title	Camshaft Gear (Camshaft Installed)
Update Reason	

Date	11-Oct-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-012-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-012-shopas.html)
Procedure Title	Camshaft Gear (Camshaft Installed)
Update Reason	
Date	11-Oct-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-013-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-013-shopas.html)
Procedure Title	Camshaft Gear (Camshaft Removed)
Update Reason	
Date	12-Oct-2005
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-008-035-shopds (/qs3/pubsys2/xml/en/procedures/35/35-008-035-shopds.html)
Procedure Title	Fan Hub Bracket
Update Reason	
Date	12-Oct-2005
Section	Section DS - Engine Disassembly Group 00
Procedure Number	101-001-054-shopds (/qs3/pubsys2/xml/en/procedures/101/101-001-054-shopds.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	
Date	12-Oct-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	101-001-054-shopas (/qs3/pubsys2/xml/en/procedures/101/101-001-054-shopas.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	

Date	12-Oct-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-008-035-shopas (/qs3/pubsys2/xml/en/procedures/35/35-008-035-shopas.html)
Procedure Title	Fan Hub Bracket
Update Reason	
Date	12-Oct-2005
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	101-001-054-tr (/qs3/pubsys2/xml/en/procedures/101/101-001-054-tr.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	
Date	12-Oct-2005
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-061-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-061-tr.html)
Procedure Title	Water Manifold
Update Reason	
Date	13-Oct-2005
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t049-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t049-tr.html)
Procedure Title	Engine Noise Excessive - Connecting Rod
Update Reason	
Date	13-Oct-2005
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t050-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t050-tr.html)
Procedure Title	Engine Noise Excessive - Main Bearing
Update Reason	

Date	13-Oct-2005
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t051-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t051-tr.html)
Procedure Title	Engine Noise Excessive - Piston
Update Reason	
Date	13-Oct-2005
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-011-030-shopds (/qs3/pubsys2/xml/en/procedures/35/35-011-030-shopds.html)
Procedure Title	EGR Valve Coolant Lines
Update Reason	
Date	13-Oct-2005
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-011-032-shopds (/qs3/pubsys2/xml/en/procedures/35/35-011-032-shopds.html)
Procedure Title	Heat Shield
Update Reason	
Date	13-Oct-2005
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-010-118-shopds (/qs3/pubsys2/xml/en/procedures/35/35-010-118-shopds.html)
Procedure Title	Turbocharger Actuator Air Line
Update Reason	
Date	13-Oct-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-010-118-shopas (/qs3/pubsys2/xml/en/procedures/35/35-010-118-shopas.html)
Procedure Title	Turbocharger Actuator Air Line
Update Reason	

Date	13-Oct-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-011-032-shopas (/qs3/pubsys2/xml/en/procedures/35/35-011-032-shopas.html)
Procedure Title	Heat Shield
Update Reason	
Date	13-Oct-2005
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-011-030-shopas (/qs3/pubsys2/xml/en/procedures/35/35-011-030-shopas.html)
Procedure Title	EGR Valve Coolant Lines
Update Reason	
Date	13-Oct-2005
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-116-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-116-tr.html)
Procedure Title	Turbocharger Control Shutoff Valve Filter Head Mounting Bracket
Update Reason	
Date	13-Oct-2005
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-117-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-117-tr.html)
Procedure Title	Turbocharger Control Valve Mounting Bracket
Update Reason	
Date	13-Oct-2005
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-118-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-118-tr.html)
Procedure Title	Turbocharger Actuator Air Line
Update Reason	

Date	13-Oct-2005
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-030-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-030-tr.html)
Procedure Title	EGR Valve Coolant Lines
Update Reason	
Date	13-Oct-2005
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-032-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-032-tr.html)
Procedure Title	Heat Shield
Update Reason	
Date	21-Oct-2005
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t013-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t013-tr.html)
Procedure Title	Alternator Not Charging or Insufficient Charging
Update Reason	
Date	02-Nov-2005
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t087-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t087-tr.html)
Procedure Title	Fuel Consumption Excessive
Update Reason	
Date	08-Nov-2005
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-088-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-088-tr.html)
Procedure Title	Turbocharger Control Valve
Update Reason	

Date	03-Jan-2006
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	00-016-025 (/qs3/pubsys2/xml/en/procedures/00/00-016-025.html)
Procedure Title	Propeller Shaft
Update Reason	
Date	02-Feb-2006
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	00-016-026 (/qs3/pubsys2/xml/en/procedures/00/00-016-026.html)
Procedure Title	Marine Vibration Isolator
Update Reason	
Date	02-May-2006
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-000-001-shopds (/qs3/pubsys2/xml/en/procedures/35/35-000-001-shopds.html)
Procedure Title	Engine Removal
Update Reason	
Date	22-May-2006
Section	Front
Procedure Number	shopds-frwd (/qs3/pubsys2/xml/en/manual/preface/shopds-frwd.html)
Procedure Title	Foreword
Update Reason	
Date	22-May-2006
Section	Section 6- Injectors and Fuel Lines - Group 06
Procedure Number	35-022-001_06 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_06.html)
Procedure Title	Service Tools
Update Reason	

Date	08-Jun-2006
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-011-031-shopds (/qs3/pubsys2/xml/en/procedures/35/35-011-031-shopds.html)
Procedure Title	EGR Cooler Coolant Lines
Update Reason	
Date	08-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-011-031-shopas (/qs3/pubsys2/xml/en/procedures/35/35-011-031-shopas.html)
Procedure Title	EGR Cooler Coolant Lines
Update Reason	
Date	08-Jun-2006
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-031-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-031-tr.html)
Procedure Title	EGR Cooler Coolant Lines
Update Reason	
Date	08-Jun-2006
Section	Back
Procedure Number	3666322-backcover (/qs3/pubsys2/xml/en/manual/3666322/3666322-backcover.html)
Procedure Title	Backcover
Update Reason	
Date	21-Jun-2006
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-011-028-shopds (/qs3/pubsys2/xml/en/procedures/35/35-011-028-shopds.html)
Procedure Title	EGR Differential Pressure Sensor Adapter
Update Reason	

Date	21-Jun-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-011-028-shopas (/qs3/pubsys2/xml/en/procedures/35/35-011-028-shopas.html)
Procedure Title	EGR Differential Pressure Sensor Adapter
Update Reason	
Date	21-Jun-2006
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-028-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-028-tr.html)
Procedure Title	EGR Differential Pressure Sensor Adapter
Update Reason	
Date	27-Jun-2006
Section	Section L - Service Literature
Procedure Number	99-205-002 (/qs3/pubsys2/xml/en/procedures/99/99-205-002.html)
Procedure Title	Service Literature Ordering Location
Update Reason	
Date	17-Jul-2006
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-011-021-shopds (/qs3/pubsys2/xml/en/procedures/35/35-011-021-shopds.html)
Procedure Title	EGR Mixer
Update Reason	
Date	17-Jul-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-011-021-shopas (/qs3/pubsys2/xml/en/procedures/35/35-011-021-shopas.html)
Procedure Title	EGR Mixer
Update Reason	

Date	20-Jul-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t020-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t020-tr.html)
Procedure Title	Coolant Loss - External
Update Reason	
Date	25-Jul-2006
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-021-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-021-tr.html)
Procedure Title	EGR Mixer
Update Reason	
Date	25-Jul-2006
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-027-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-027-tr.html)
Procedure Title	Exhaust Gas Pressure Sensor Tube
Update Reason	
Date	31-Jul-2006
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-010-041-shopds (/qs3/pubsys2/xml/en/procedures/35/35-010-041-shopds.html)
Procedure Title	Turbocharger Coolant Hoses
Update Reason	
Date	31-Jul-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-010-041-shopas (/qs3/pubsys2/xml/en/procedures/35/35-010-041-shopas.html)
Procedure Title	Turbocharger Coolant Hoses
Update Reason	

Date	31-Jul-2006
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-041-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-041-tr.html)
Procedure Title	Turbocharger Coolant Hoses
Update Reason	
Date	08-Aug-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t012-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t012-tr.html)
Procedure Title	Aftertreatment Diesel Particulate Filter - Excessive Ash Cleaning
Update Reason	
Date	14-Aug-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t011-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t011-tr.html)
Procedure Title	Aftertreatment Diesel Particulate Filter - Excessive Soot Loading
Update Reason	
Date	14-Aug-2006
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t028-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t028-tr.html)
Procedure Title	Crankcase Coalescing Filter - Frequent Replacement
Update Reason	

Date	19-Sep-2006
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-010-114-shopds (/qs3/pubsys2/xml/en/procedures/35/35-010-114-shopds.html)
Procedure Title	Turbocharger Air Shutoff Valve Filter
Update Reason	
Date	19-Sep-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-010-114-shopas (/qs3/pubsys2/xml/en/procedures/35/35-010-114-shopas.html)
Procedure Title	Turbocharger Air Shutoff Valve Filter
Update Reason	
Date	19-Sep-2006
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-114-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-114-tr.html)
Procedure Title	Turbocharger Air Shutoff Valve Filter
Update Reason	
Date	20-Sep-2006
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-010-115-shopds (/qs3/pubsys2/xml/en/procedures/35/35-010-115-shopds.html)
Procedure Title	Turbocharger Control Shutoff Valve Filter Head
Update Reason	
Date	20-Sep-2006
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-010-115-shopas (/qs3/pubsys2/xml/en/procedures/35/35-010-115-shopas.html)
Procedure Title	Turbocharger Control Shutoff Valve Filter Head
Update Reason	

Date	20-Sep-2006
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-115-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-115-tr.html)
Procedure Title	Turbocharger Control Shutoff Valve Filter Head
Update Reason	
Date	12-Feb-2007
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	99-013-047 (/qs3/pubsys2/xml/en/procedures/99/99-013-047.html)
Procedure Title	ECM Unswitched Power Terminal Blocks
Update Reason	
Date	26-Apr-2007
Section	Section 14 - Engine Testing - Group 14
Procedure Number	35-022-001_14 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_14.html)
Procedure Title	Service Tools
Update Reason	
Date	24-May-2007
Section	Front
Procedure Number	3666322-titlepage (/qs3/pubsys2/xml/en/manual/3666322/3666322-titlepage.html)
Procedure Title	Titlepage
Update Reason	
Date	25-May-2007
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t146-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t146-tr.html)
Procedure Title	Stationary Regeneration - Will Not Activate
Update Reason	

Date	24-Jul-2007
Section	Section i - Introduction
Procedure Number	99-204-008 (/qs3/pubsys2/xml/en/procedures/99/99-204-008.html)
Procedure Title	General Cleaning Instructions
Update Reason	
Date	01-Nov-2007
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	101-007-018 (/qs3/pubsys2/xml/en/procedures/101/101-007-018.html)
Procedure Title	Lubricating Oil Filter Head Adapter
Update Reason	
Date	12-Dec-2007
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t036-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t036-tr.html)
Procedure Title	Engine Brake Does Not Operate
Update Reason	
Date	08-Jan-2008
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-022-001_08 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_08.html)
Procedure Title	Service Tools
Update Reason	
Date	08-May-2008
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t148-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t148-tr.html)
Procedure Title	Valve Cover - Frequent Replacement
Update Reason	

Date	08-May-2008
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-008-053-shopds (/qs3/pubsys2/xml/en/procedures/35/35-008-053-shopds.html)
Procedure Title	Heat Exchanger
Update Reason	
Date	08-May-2008
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-008-053-shopas (/qs3/pubsys2/xml/en/procedures/35/35-008-053-shopas.html)
Procedure Title	Heat Exchanger
Update Reason	
Date	08-May-2008
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-053-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-053-tr.html)
Procedure Title	Heat Exchanger
Update Reason	
Date	28-May-2008
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-056 (/qs3/pubsys2/xml/en/procedures/35/35-011-056.html)
Procedure Title	Exhaust System Diagnostics
Update Reason	
Date	24-Sep-2008
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t092-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t092-tr.html)
Procedure Title	Fuel in the Lubricating Oil
Update Reason	

Date	13-Nov-2008
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	00-016-010 (/qs3/pubsys2/xml/en/procedures/00/00-016-010.html)
Procedure Title	Engine Mounts
Update Reason	
Date	17-Nov-2008
Section	Section F - Familiarization
Procedure Number	35-006-999-tr (/qs3/pubsys2/xml/en/procedures/35/35-006-999-tr.html)
Procedure Title	Injectors and Fuel Lines - Overview
Update Reason	
Date	18-Nov-2008
Section	Section F - Familiarization
Procedure Number	35-012-999-tr (/qs3/pubsys2/xml/en/procedures/35/35-012-999-tr.html)
Procedure Title	Compressed Air System - Overview
Update Reason	
Date	01-Dec-2008
Section	Section F - Familiarization
Procedure Number	35-013-999-tr (/qs3/pubsys2/xml/en/procedures/35/35-013-999-tr.html)
Procedure Title	Electrical Equipment - Overview
Update Reason	
Date	05-Jan-2009
Section	Section F - Familiarization
Procedure Number	35-005-999 (/qs3/pubsys2/xml/en/procedures/35/35-005-999.html)
Procedure Title	Fuel System - Overview
Update Reason	

Date	05-Jan-2009
Section	Section F - Familiarization
Procedure Number	35-200-006-tr (/qs3/pubsys2/xml/en/procedures/35/35-200-006-tr.html)
Procedure Title	Flow Diagram, Compressed Air System
Update Reason	
Date	05-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-001-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-001-shopds.html)
Procedure Title	Alternator Drive Seal
Update Reason	
Date	05-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-005-016-shopds (/qs3/pubsys2/xml/en/procedures/35/35-005-016-shopds.html)
Procedure Title	Fuel Pump
Update Reason	
Date	05-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-003-011-shopds (/qs3/pubsys2/xml/en/procedures/35/35-003-011-shopds.html)
Procedure Title	Rocker Lever Cover
Update Reason	
Date	05-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-004-014-shopds (/qs3/pubsys2/xml/en/procedures/35/35-004-014-shopds.html)
Procedure Title	Push Rods or Tubes
Update Reason	

Date	05-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-003-013-shopds (/qs3/pubsys2/xml/en/procedures/35/35-003-013-shopds.html)
Procedure Title	Rocker Lever Housing
Update Reason	
Date	05-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-036-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-036-shopds.html)
Procedure Title	Idler Gear, Camshaft
Update Reason	
Date	05-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-046-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-046-shopds.html)
Procedure Title	Piston Cooling Nozzle
Update Reason	
Date	05-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-007-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-007-shopds.html)
Procedure Title	Bearings, Thrust
Update Reason	
Date	05-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-007-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-007-shopas.html)
Procedure Title	Bearings, Thrust
Update Reason	

Date	05-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-046-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-046-shopas.html)
Procedure Title	Piston Cooling Nozzle
Update Reason	
Date	05-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-036-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-036-shopas.html)
Procedure Title	Idler Gear, Camshaft
Update Reason	
Date	05-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-003-013-shopas (/qs3/pubsys2/xml/en/procedures/35/35-003-013-shopas.html)
Procedure Title	Rocker Lever Housing
Update Reason	
Date	05-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-004-014-shopas (/qs3/pubsys2/xml/en/procedures/35/35-004-014-shopas.html)
Procedure Title	Push Rods or Tubes
Update Reason	
Date	05-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-003-011-shopas (/qs3/pubsys2/xml/en/procedures/35/35-003-011-shopas.html)
Procedure Title	Rocker Lever Cover
Update Reason	

Date	05-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-005-016-shopas (/qs3/pubsys2/xml/en/procedures/35/35-005-016-shopas.html)
Procedure Title	Fuel Pump
Update Reason	
Date	05-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-001-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-001-shopas.html)
Procedure Title	Alternator Drive Seal
Update Reason	
Date	05-Jan-2009
Section	Section 0 - Complete Engine - Group 00
Procedure Number	35-022-001_00 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_00.html)
Procedure Title	Service Tools
Update Reason	
Date	05-Jan-2009
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	35-003-011-tr (/qs3/pubsys2/xml/en/procedures/35/35-003-011-tr.html)
Procedure Title	Rocker Lever Cover
Update Reason	
Date	05-Jan-2009
Section	Section 5 - Fuel System - Group 05
Procedure Number	35-005-010-tr (/qs3/pubsys2/xml/en/procedures/35/35-005-010-tr.html)
Procedure Title	Fuel Consumption
Update Reason	

Date	05-Jan-2009
Section	Section 5 - Fuel System - Group 05
Procedure Number	35-005-016-tr (/qs3/pubsys2/xml/en/procedures/35/35-005-016-tr.html)
Procedure Title	Fuel Pump
Update Reason	
Date	14-Jan-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t147-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t147-tr.html)
Procedure Title	Aftertreatment Diesel Particulate Filter - Excessive Automatic and/or Stationary Regeneration
Update Reason	
Date	14-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	101-001-026-tr (/qs3/pubsys2/xml/en/procedures/101/101-001-026-tr.html)
Procedure Title	Cylinder Block
Update Reason	
Date	21-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-040-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-040-shopds.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	
Date	21-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-040-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-040-shopas.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	

Date	21-Jan-2009
Section	Section 0 - Complete Engine - Group 00
Procedure Number	35-000-006-tr (/qs3/pubsys2/xml/en/procedures/35/35-000-006-tr.html)
Procedure Title	Engine Storage - Short Term
Update Reason	
Date	21-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-001-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-001-tr.html)
Procedure Title	Alternator Drive Seal
Update Reason	
Date	21-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-007-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-007-tr.html)
Procedure Title	Bearings, Thrust
Update Reason	
Date	21-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-012-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-012-tr.html)
Procedure Title	Camshaft Gear (Camshaft Installed)
Update Reason	
Date	21-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-014-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-014-tr.html)
Procedure Title	Connecting Rod
Update Reason	

Date	21-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-018-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-018-tr.html)
Procedure Title	Crankshaft Gear, Front (Crankshaft Installed)
Update Reason	
Date	21-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-022-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-022-tr.html)
Procedure Title	Crankshaft Pulley
Update Reason	
Date	21-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-036-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-036-tr.html)
Procedure Title	Idler Gear, Camshaft
Update Reason	
Date	21-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-040-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-040-tr.html)
Procedure Title	Idler Gear, Water Pump
Update Reason	
Date	21-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-046-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-046-tr.html)
Procedure Title	Piston Cooling Nozzle
Update Reason	

Date	21-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-047-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-047-tr.html)
Procedure Title	Piston Rings
Update Reason	
Date	21-Jan-2009
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	35-003-013-tr (/qs3/pubsys2/xml/en/procedures/35/35-003-013-tr.html)
Procedure Title	Rocker Lever Housing
Update Reason	
Date	21-Jan-2009
Section	Section 4 - Cam Followers/Tappets - Group 04
Procedure Number	35-004-014-tr (/qs3/pubsys2/xml/en/procedures/35/35-004-014-tr.html)
Procedure Title	Push Rods or Tubes
Update Reason	
Date	22-Jan-2009
Section	Section F - Familiarization
Procedure Number	35-014-999-tr (/qs3/pubsys2/xml/en/procedures/35/35-014-999-tr.html)
Procedure Title	Engine Testing - Overview
Update Reason	
Date	22-Jan-2009
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	35-013-005-tr (/qs3/pubsys2/xml/en/procedures/35/35-013-005-tr.html)
Procedure Title	Drive Belt, Alternator
Update Reason	

Date	23-Jan-2009
Section	Section F - Familiarization
Procedure Number	35-200-001-tr (/qs3/pubsys2/xml/en/procedures/35/35-200-001-tr.html)
Procedure Title	Flow Diagram, Fuel System
Update Reason	
Date	23-Jan-2009
Section	Section F - Familiarization
Procedure Number	35-200-002-tr (/qs3/pubsys2/xml/en/procedures/35/35-200-002-tr.html)
Procedure Title	Flow Diagram, Lubricating Oil System
Update Reason	
Date	23-Jan-2009
Section	Section F - Familiarization
Procedure Number	35-200-003-tr (/qs3/pubsys2/xml/en/procedures/35/35-200-003-tr.html)
Procedure Title	Flow Diagram, Cooling System
Update Reason	
Date	23-Jan-2009
Section	Section F - Familiarization
Procedure Number	35-200-004-tr (/qs3/pubsys2/xml/en/procedures/35/35-200-004-tr.html)
Procedure Title	Flow Diagram, Air Intake System
Update Reason	
Date	23-Jan-2009
Section	Section F - Familiarization
Procedure Number	35-200-005-tr (/qs3/pubsys2/xml/en/procedures/35/35-200-005-tr.html)
Procedure Title	Flow Diagram, Exhaust System
Update Reason	

Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-013-020-shopds (/qs3/pubsys2/xml/en/procedures/35/35-013-020-shopds.html)
Procedure Title	Starting Motor
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-007-013-shopds (/qs3/pubsys2/xml/en/procedures/35/35-007-013-shopds.html)
Procedure Title	Lubricating Oil Filter (Spin-On)
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-003-021-shopds (/qs3/pubsys2/xml/en/procedures/35/35-003-021-shopds.html)
Procedure Title	Crankcase Ventilation Filter
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-013-001-shopds (/qs3/pubsys2/xml/en/procedures/35/35-013-001-shopds.html)
Procedure Title	Alternator
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-010-119-shopds (/qs3/pubsys2/xml/en/procedures/35/35-010-119-shopds.html)
Procedure Title	Turbocharger Control Valve Air Line
Update Reason	

Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-010-045-shopds (/qs3/pubsys2/xml/en/procedures/35/35-010-045-shopds.html)
Procedure Title	Turbocharger Oil Drain Line
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-007-010-shopds (/qs3/pubsys2/xml/en/procedures/35/35-007-010-shopds.html)
Procedure Title	Lubricating Oil Dipstick Housing
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-007-003-shopds (/qs3/pubsys2/xml/en/procedures/35/35-007-003-shopds.html)
Procedure Title	Lubricating Oil Cooler
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-007-015-shopds (/qs3/pubsys2/xml/en/procedures/35/35-007-015-shopds.html)
Procedure Title	Lubricating Oil Filter Head
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-009-010-shopds (/qs3/pubsys2/xml/en/procedures/35/35-009-010-shopds.html)
Procedure Title	Alternator Drive Pulley
Update Reason	

Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-008-062-shopds (/qs3/pubsys2/xml/en/procedures/35/35-008-062-shopds.html)
Procedure Title	Water Pump
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-008-007-shopds (/qs3/pubsys2/xml/en/procedures/35/35-008-007-shopds.html)
Procedure Title	Coolant Filter Head
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-008-012-shopds (/qs3/pubsys2/xml/en/procedures/35/35-008-012-shopds.html)
Procedure Title	Coolant Heater Housing
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-016-001-shopds (/qs3/pubsys2/xml/en/procedures/35/35-016-001-shopds.html)
Procedure Title	Engine Lifting Brackets
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-008-026-shopds (/qs3/pubsys2/xml/en/procedures/35/35-008-026-shopds.html)
Procedure Title	Fan Clutch, Electric
Update Reason	

Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-012-004-shopds (/qs3/pubsys2/xml/en/procedures/35/35-012-004-shopds.html)
Procedure Title	Air Compressor Coolant Coolant Lines
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-006-006-shopds (/qs3/pubsys2/xml/en/procedures/35/35-006-006-shopds.html)
Procedure Title	ECM Cooling Plate, Fuel Cooled
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-012-014-shopds (/qs3/pubsys2/xml/en/procedures/35/35-012-014-shopds.html)
Procedure Title	Air Compressor
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-003-002-shopds (/qs3/pubsys2/xml/en/procedures/35/35-003-002-shopds.html)
Procedure Title	Crankcase Breather (Internal)
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-003-009-shopds (/qs3/pubsys2/xml/en/procedures/35/35-003-009-shopds.html)
Procedure Title	Rocker Lever Assembly
Update Reason	

Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-006-026-shopds (/qs3/pubsys2/xml/en/procedures/35/35-006-026-shopds.html)
Procedure Title	Injector
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-003-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-003-shopds.html)
Procedure Title	Accessory Drive Seal
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-052-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-052-shopds.html)
Procedure Title	Vibration Damper, Viscous
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-004-001-shopds (/qs3/pubsys2/xml/en/procedures/35/35-004-001-shopds.html)
Procedure Title	Cam Follower Assembly
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-039-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-039-shopds.html)
Procedure Title	Idler Gear, Hydraulic Pump
Update Reason	

Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-009-001-shopds (/qs3/pubsys2/xml/en/procedures/35/35-009-001-shopds.html)
Procedure Title	Accessory Drive
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	101-009-016-shopds (/qs3/pubsys2/xml/en/procedures/101/101-009-016-shopds.html)
Procedure Title	Hydraulic Pump Drive
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-007-031-shopds (/qs3/pubsys2/xml/en/procedures/35/35-007-031-shopds.html)
Procedure Title	Lubricating Oil Pump
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	101-007-025-shopds (/qs3/pubsys2/xml/en/procedures/101/101-007-025-shopds.html)
Procedure Title	Lubricating Oil Pan
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	101-001-089-shopds (/qs3/pubsys2/xml/en/procedures/101/101-001-089-shopds.html)
Procedure Title	Block Stiffener Plate
Update Reason	

Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-007-029-shopds (/qs3/pubsys2/xml/en/procedures/35/35-007-029-shopds.html)
Procedure Title	Lubricating Oil Pressure Regulator (Main Rifle)
Update Reason	
Date	23-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-007-021-shopds (/qs3/pubsys2/xml/en/procedures/35/35-007-021-shopds.html)
Procedure Title	Lubricating Oil High Pressure Relief Valve
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-007-021-shopas (/qs3/pubsys2/xml/en/procedures/35/35-007-021-shopas.html)
Procedure Title	Lubricating Oil High Pressure Relief Valve
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-007-029-shopas (/qs3/pubsys2/xml/en/procedures/35/35-007-029-shopas.html)
Procedure Title	Lubricating Oil Pressure Regulator (Main Rifle)
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	101-001-089-shopas (/qs3/pubsys2/xml/en/procedures/101/101-001-089-shopas.html)
Procedure Title	Block Stiffener Plate
Update Reason	

Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	101-007-025-shopas (/qs3/pubsys2/xml/en/procedures/101/101-007-025-shopas.html)
Procedure Title	Lubricating Oil Pan
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-007-031-shopas (/qs3/pubsys2/xml/en/procedures/35/35-007-031-shopas.html)
Procedure Title	Lubricating Oil Pump
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	101-009-016-shopas (/qs3/pubsys2/xml/en/procedures/101/101-009-016-shopas.html)
Procedure Title	Hydraulic Pump Drive
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-009-001-shopas (/qs3/pubsys2/xml/en/procedures/35/35-009-001-shopas.html)
Procedure Title	Accessory Drive
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-039-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-039-shopas.html)
Procedure Title	Idler Gear, Hydraulic Pump
Update Reason	

Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-004-001-shopas (/qs3/pubsys2/xml/en/procedures/35/35-004-001-shopas.html)
Procedure Title	Cam Follower Assembly
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-052-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-052-shopas.html)
Procedure Title	Vibration Damper, Viscous
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-003-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-003-shopas.html)
Procedure Title	Accessory Drive Seal
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-006-026-shopas (/qs3/pubsys2/xml/en/procedures/35/35-006-026-shopas.html)
Procedure Title	Injector
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-003-009-shopas (/qs3/pubsys2/xml/en/procedures/35/35-003-009-shopas.html)
Procedure Title	Rocker Lever Assembly
Update Reason	

Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-003-002-shopas (/qs3/pubsys2/xml/en/procedures/35/35-003-002-shopas.html)
Procedure Title	Crankcase Breather (Internal)
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-012-014-shopas (/qs3/pubsys2/xml/en/procedures/35/35-012-014-shopas.html)
Procedure Title	Air Compressor
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-006-006-shopas (/qs3/pubsys2/xml/en/procedures/35/35-006-006-shopas.html)
Procedure Title	ECM Cooling Plate, Fuel Cooled
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-012-004-shopas (/qs3/pubsys2/xml/en/procedures/35/35-012-004-shopas.html)
Procedure Title	Air Compressor Coolant Lines
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-008-026-shopas (/qs3/pubsys2/xml/en/procedures/35/35-008-026-shopas.html)
Procedure Title	Fan Clutch, Electric
Update Reason	

Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-016-001-shopas (/qs3/pubsys2/xml/en/procedures/35/35-016-001-shopas.html)
Procedure Title	Engine Lifting Brackets
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-008-012-shopas (/qs3/pubsys2/xml/en/procedures/35/35-008-012-shopas.html)
Procedure Title	Coolant Heater Housing
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-008-007-shopas (/qs3/pubsys2/xml/en/procedures/35/35-008-007-shopas.html)
Procedure Title	Coolant Filter Head
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-008-015-shopas (/qs3/pubsys2/xml/en/procedures/35/35-008-015-shopas.html)
Procedure Title	Coolant Thermostat Housing Support
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-008-062-shopas (/qs3/pubsys2/xml/en/procedures/35/35-008-062-shopas.html)
Procedure Title	Water Pump
Update Reason	

Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-009-010-shopas (/qs3/pubsys2/xml/en/procedures/35/35-009-010-shopas.html)
Procedure Title	Alternator Drive Pulley
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-007-015-shopas (/qs3/pubsys2/xml/en/procedures/35/35-007-015-shopas.html)
Procedure Title	Lubricating Oil Filter Head
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-007-003-shopas (/qs3/pubsys2/xml/en/procedures/35/35-007-003-shopas.html)
Procedure Title	Lubricating Oil Cooler
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-007-010-shopas (/qs3/pubsys2/xml/en/procedures/35/35-007-010-shopas.html)
Procedure Title	Lubricating Oil Dipstick Housing
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-010-045-shopas (/qs3/pubsys2/xml/en/procedures/35/35-010-045-shopas.html)
Procedure Title	Turbocharger Oil Drain Line
Update Reason	

Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-010-119-shopas (/qs3/pubsys2/xml/en/procedures/35/35-010-119-shopas.html)
Procedure Title	Turbocharger Control Valve Air Line
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-013-001-shopas (/qs3/pubsys2/xml/en/procedures/35/35-013-001-shopas.html)
Procedure Title	Alternator
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-003-021-shopas (/qs3/pubsys2/xml/en/procedures/35/35-003-021-shopas.html)
Procedure Title	Crankcase Ventilation Filter
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-007-013-shopas (/qs3/pubsys2/xml/en/procedures/35/35-007-013-shopas.html)
Procedure Title	Lubricating Oil Filter (Spin-On)
Update Reason	
Date	23-Jan-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-013-020-shopas (/qs3/pubsys2/xml/en/procedures/35/35-013-020-shopas.html)
Procedure Title	Starting Motor
Update Reason	

Date	23-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-022-001_01 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_01.html)
Procedure Title	Service Tools
Update Reason	
Date	23-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-003-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-003-tr.html)
Procedure Title	Accessory Drive Seal
Update Reason	
Date	23-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-039-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-039-tr.html)
Procedure Title	Idler Gear, Hydraulic Pump
Update Reason	
Date	23-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-052-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-052-tr.html)
Procedure Title	Vibration Damper, Viscous
Update Reason	
Date	23-Jan-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	101-001-089-tr (/qs3/pubsys2/xml/en/procedures/101/101-001-089-tr.html)
Procedure Title	Block Stiffener Plate
Update Reason	

Date	23-Jan-2009
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	35-003-002-tr (/qs3/pubsys2/xml/en/procedures/35/35-003-002-tr.html)
Procedure Title	Crankcase Breather (Internal)
Update Reason	
Date	23-Jan-2009
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	35-003-004-tr (/qs3/pubsys2/xml/en/procedures/35/35-003-004-tr.html)
Procedure Title	Overhead Set
Update Reason	
Date	23-Jan-2009
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	35-003-021-tr (/qs3/pubsys2/xml/en/procedures/35/35-003-021-tr.html)
Procedure Title	Crankcase Ventilation Filter
Update Reason	
Date	23-Jan-2009
Section	Section 4 - Cam Followers/Tappets - Group 04
Procedure Number	35-004-001-tr (/qs3/pubsys2/xml/en/procedures/35/35-004-001-tr.html)
Procedure Title	Cam Follower Assembly
Update Reason	
Date	23-Jan-2009
Section	Section 5 - Fuel System - Group 05
Procedure Number	35-005-031-tr (/qs3/pubsys2/xml/en/procedures/35/35-005-031-tr.html)
Procedure Title	Fuel Pump Pulsation Damper
Update Reason	

Date	23-Jan-2009
Section	Section 5 - Fuel System - Group 05
Procedure Number	35-005-043-tr (/qs3/pubsys2/xml/en/procedures/35/35-005-043-tr.html)
Procedure Title	Fuel Shutoff Valve
Update Reason	
Date	23-Jan-2009
Section	Section 5 - Fuel System - Group 05
Procedure Number	35-005-054-tr (/qs3/pubsys2/xml/en/procedures/35/35-005-054-tr.html)
Procedure Title	Stall Speed Test
Update Reason	
Date	23-Jan-2009
Section	Section 5 - Fuel System - Group 05
Procedure Number	35-005-060-tr (/qs3/pubsys2/xml/en/procedures/35/35-005-060-tr.html)
Procedure Title	Fuel Pump Pressure Regulator
Update Reason	
Date	23-Jan-2009
Section	Section 6- Injectors and Fuel Lines - Group 06
Procedure Number	35-006-003-tr (/qs3/pubsys2/xml/en/procedures/35/35-006-003-tr.html)
Procedure Title	Air in Fuel
Update Reason	
Date	23-Jan-2009
Section	Section 6- Injectors and Fuel Lines - Group 06
Procedure Number	35-006-005-tr (/qs3/pubsys2/xml/en/procedures/35/35-006-005-tr.html)
Procedure Title	Cylinder Misfires or Smokes
Update Reason	

Date	23-Jan-2009
Section	Section 6- Injectors and Fuel Lines - Group 06
Procedure Number	35-006-006-tr (/qs3/pubsys2/xml/en/procedures/35/35-006-006-tr.html)
Procedure Title	ECM Cooling Plate, Fuel Cooled
Update Reason	

Date	23-Jan-2009
Section	Section 6- Injectors and Fuel Lines - Group 06
Procedure Number	35-006-012-tr (/qs3/pubsys2/xml/en/procedures/35/35-006-012-tr.html)
Procedure Title	Fuel Drain Line Restriction
Update Reason	

Date	23-Jan-2009
Section	Section 6- Injectors and Fuel Lines - Group 06
Procedure Number	35-006-020-tr (/qs3/pubsys2/xml/en/procedures/35/35-006-020-tr.html)
Procedure Title	Fuel Inlet Restriction
Update Reason	

Date	23-Jan-2009
Section	Section 6- Injectors and Fuel Lines - Group 06
Procedure Number	35-006-024-tr (/qs3/pubsys2/xml/en/procedures/35/35-006-024-tr.html)
Procedure Title	Fuel Supply Lines
Update Reason	

Date	23-Jan-2009
Section	Section 6- Injectors and Fuel Lines - Group 06
Procedure Number	35-006-025-tr (/qs3/pubsys2/xml/en/procedures/35/35-006-025-tr.html)
Procedure Title	Static Injection Timing
Update Reason	

Date	23-Jan-2009
Section	Section 6- Injectors and Fuel Lines - Group 06
Procedure Number	35-006-026-tr (/qs3/pubsys2/xml/en/procedures/35/35-006-026-tr.html)
Procedure Title	Injector
Update Reason	
Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-003-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-003-tr.html)
Procedure Title	Lubricating Oil Cooler
Update Reason	
Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-009-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-009-tr.html)
Procedure Title	Lubricating Oil Dipstick
Update Reason	
Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-010-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-010-tr.html)
Procedure Title	Lubricating Oil Dipstick Housing
Update Reason	
Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-012-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-012-tr.html)
Procedure Title	Lubricating Oil Filter (Canister-Type)
Update Reason	

Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-013-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-013-tr.html)
Procedure Title	Lubricating Oil Filter (Spin-On)
Update Reason	
Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-021-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-021-tr.html)
Procedure Title	Lubricating Oil High Pressure Relief Valve
Update Reason	
Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-024-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-024-tr.html)
Procedure Title	Lubricating Oil Leaks
Update Reason	
Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	101-007-025-tr (/qs3/pubsys2/xml/en/procedures/101/101-007-025-tr.html)
Procedure Title	Lubricating Oil Pan
Update Reason	
Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-029-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-029-tr.html)
Procedure Title	Lubricating Oil Pressure Regulator (Main Rifle)
Update Reason	

Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-031-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-031-tr.html)
Procedure Title	Lubricating Oil Pump
Update Reason	
Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-037-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-037-tr.html)
Procedure Title	Lubricating Oil System
Update Reason	
Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-038-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-038-tr.html)
Procedure Title	Lubricating Oil Temperature Gauge
Update Reason	
Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-039-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-039-tr.html)
Procedure Title	Lubricating Oil Thermostat
Update Reason	
Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-041-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-041-tr.html)
Procedure Title	Lubricating Oil Viscosity Sensor
Update Reason	

Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-044-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-044-tr.html)
Procedure Title	Lubricating Oil Contamination
Update Reason	
Date	23-Jan-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-083-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-083-tr.html)
Procedure Title	Lubricating Oil and Filter Analysis
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-004-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-004-tr.html)
Procedure Title	Coolant Temperature Gauge
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-007-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-007-tr.html)
Procedure Title	Coolant Filter Head
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-012-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-012-tr.html)
Procedure Title	Coolant Heater Housing
Update Reason	

Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-013-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-013-tr.html)
Procedure Title	Coolant Thermostat
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-016-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-016-tr.html)
Procedure Title	Coolant Thermostat Seal
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-017-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-017-tr.html)
Procedure Title	Coolant Vent Lines
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-018-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-018-tr.html)
Procedure Title	Cooling System
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-020-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-020-tr.html)
Procedure Title	Cooling System Diagnostics
Update Reason	

Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-021-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-021-tr.html)
Procedure Title	Cooling System Precharge
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-024-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-024-tr.html)
Procedure Title	Fan Clutch, Air-Disengaged
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-025-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-025-tr.html)
Procedure Title	Fan Clutch, Air-Engaged
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-026-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-026-tr.html)
Procedure Title	Fan Clutch, Electric
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-027-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-027-tr.html)
Procedure Title	Fan Clutch, On-Off
Update Reason	

Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-028-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-028-tr.html)
Procedure Title	Fan Clutch, Viscous
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-038-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-038-tr.html)
Procedure Title	Fan Shroud Assembly
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-040-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-040-tr.html)
Procedure Title	Fan, Cooling
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-042-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-042-tr.html)
Procedure Title	Radiator
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-047-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-047-tr.html)
Procedure Title	Radiator Pressure Cap
Update Reason	

Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-049-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-049-tr.html)
Procedure Title	Radiator Shutter Assembly
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-065-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-065-tr.html)
Procedure Title	Torque Converter Cooler
Update Reason	
Date	23-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-069-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-069-tr.html)
Procedure Title	Wiring Harness, Cummins Electric Fan Clutch
Update Reason	
Date	23-Jan-2009
Section	Section 9 - Drive Units - Group 09
Procedure Number	35-009-001-tr (/qs3/pubsys2/xml/en/procedures/35/35-009-001-tr.html)
Procedure Title	Accessory Drive
Update Reason	
Date	23-Jan-2009
Section	Section 9 - Drive Units - Group 09
Procedure Number	35-009-010-tr (/qs3/pubsys2/xml/en/procedures/35/35-009-010-tr.html)
Procedure Title	Alternator Drive Pulley
Update Reason	

Date	23-Jan-2009
Section	Section 9 - Drive Units - Group 09
Procedure Number	101-009-016-tr (/qs3/pubsys2/xml/en/procedures/101/101-009-016-tr.html)
Procedure Title	Hydraulic Pump Drive
Update Reason	
Date	23-Jan-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-031-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-031-tr.html)
Procedure Title	Air Intake Restriction
Update Reason	
Date	23-Jan-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-045-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-045-tr.html)
Procedure Title	Turbocharger Oil Drain Line
Update Reason	
Date	23-Jan-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-046-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-046-tr.html)
Procedure Title	Turbocharger Oil Supply Line
Update Reason	
Date	23-Jan-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-050-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-050-tr.html)
Procedure Title	Turbocharger Wastegate Actuator
Update Reason	

Date	23-Jan-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-055-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-055-tr.html)
Procedure Title	Turbocharger Wastegate Valve Body
Update Reason	
Date	23-Jan-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-109-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-109-tr.html)
Procedure Title	Turbocharger Wastegate Controller
Update Reason	
Date	23-Jan-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-119-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-119-tr.html)
Procedure Title	Turbocharger Control Valve Air Line
Update Reason	
Date	23-Jan-2009
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-010-tr (/qs3/pubsys2/xml/en/procedures/35/35-012-010-tr.html)
Procedure Title	Air Compressor Pin Bore Wear
Update Reason	
Date	23-Jan-2009
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-013-tr (/qs3/pubsys2/xml/en/procedures/35/35-012-013-tr.html)
Procedure Title	Air Compressor Unloader and Valve Assembly
Update Reason	

Date	23-Jan-2009
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-014-tr (/qs3/pubsys2/xml/en/procedures/35/35-012-014-tr.html)
Procedure Title	Air Compressor
Update Reason	
Date	23-Jan-2009
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-017-tr (/qs3/pubsys2/xml/en/procedures/35/35-012-017-tr.html)
Procedure Title	Air Governor (Air Compressor Will Not Pump)
Update Reason	
Date	23-Jan-2009
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-018-tr (/qs3/pubsys2/xml/en/procedures/35/35-012-018-tr.html)
Procedure Title	Air Governor (Air Compressor Pumps Continuously)
Update Reason	
Date	23-Jan-2009
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-019-tr (/qs3/pubsys2/xml/en/procedures/35/35-012-019-tr.html)
Procedure Title	Air Leaks, Compressed Air System
Update Reason	

Date	23-Jan-2009
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	35-013-001-tr (/qs3/pubsys2/xml/en/procedures/35/35-013-001-tr.html)
Procedure Title	Alternator
Update Reason	
Date	23-Jan-2009
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	35-013-003-tr (/qs3/pubsys2/xml/en/procedures/35/35-013-003-tr.html)
Procedure Title	Alternator Bracket
Update Reason	
Date	23-Jan-2009
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	35-013-017 (/qs3/pubsys2/xml/en/procedures/35/35-013-017.html)
Procedure Title	Starter Magnetic Switch
Update Reason	
Date	23-Jan-2009
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	35-013-018-tr (/qs3/pubsys2/xml/en/procedures/35/35-013-018-tr.html)
Procedure Title	Starter Switch
Update Reason	
Date	23-Jan-2009
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	35-013-019-tr (/qs3/pubsys2/xml/en/procedures/35/35-013-019-tr.html)
Procedure Title	Starter Solenoid
Update Reason	

Date	23-Jan-2009
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	35-013-020-tr (/qs3/pubsys2/xml/en/procedures/35/35-013-020-tr.html)
Procedure Title	Starting Motor
Update Reason	
Date	23-Jan-2009
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	35-016-001-tr (/qs3/pubsys2/xml/en/procedures/35/35-016-001-tr.html)
Procedure Title	Engine Lifting Brackets
Update Reason	
Date	26-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-019-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-019-tr.html)
Procedure Title	Cooling System - Air or Combustion Gas Test
Update Reason	
Date	27-Jan-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-008-015-shopds (/qs3/pubsys2/xml/en/procedures/35/35-008-015-shopds.html)
Procedure Title	Coolant Thermostat Housing Support
Update Reason	
Date	27-Jan-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-015-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-015-tr.html)
Procedure Title	Coolant Thermostat Housing Support
Update Reason	

Date	06-Feb-2009
Section	Section E - Engine and System Identification
Procedure Number	35-100-002-tr (/qs3/pubsys2/xml/en/procedures/35/35-100-002-tr.html)
Procedure Title	Engine Diagrams
Update Reason	
Date	06-Feb-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-008-006-shopds (/qs3/pubsys2/xml/en/procedures/35/35-008-006-shopds.html)
Procedure Title	Coolant Filter
Update Reason	
Date	06-Feb-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-008-006-shopas (/qs3/pubsys2/xml/en/procedures/35/35-008-006-shopas.html)
Procedure Title	Coolant Filter
Update Reason	
Date	06-Feb-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-006-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-006-tr.html)
Procedure Title	Coolant Filter
Update Reason	
Date	06-Feb-2009
Section	Section V - Specifications
Procedure Number	35-018-016-tr (/qs3/pubsys2/xml/en/procedures/35/35-018-016-tr.html)
Procedure Title	Fuel System
Update Reason	

Date	06-Feb-2009
Section	Section V - Specifications
Procedure Number	35-018-017-tr (/qs3/pubsys2/xml/en/procedures/35/35-018-017-tr.html)
Procedure Title	Lubricating Oil System
Update Reason	
Date	06-Feb-2009
Section	Section V - Specifications
Procedure Number	35-018-020-tr (/qs3/pubsys2/xml/en/procedures/35/35-018-020-tr.html)
Procedure Title	Exhaust System
Update Reason	
Date	06-Feb-2009
Section	Section V - Specifications
Procedure Number	35-018-021-tr (/qs3/pubsys2/xml/en/procedures/35/35-018-021-tr.html)
Procedure Title	Electrical System
Update Reason	
Date	06-Feb-2009
Section	Section V - Specifications
Procedure Number	35-018-022-tr (/qs3/pubsys2/xml/en/procedures/35/35-018-022-tr.html)
Procedure Title	Compressed Air System
Update Reason	
Date	06-Feb-2009
Section	Section V - Specifications
Procedure Number	35-018-023 (/qs3/pubsys2/xml/en/procedures/35/35-018-023.html)
Procedure Title	Engine Testing
Update Reason	

Date	09-Feb-2009
Section	Section 0 - Complete Engine - Group 00
Procedure Number	35-000-007-tr (/qs3/pubsys2/xml/en/procedures/35/35-000-007-tr.html)
Procedure Title	Engine Painting
Update Reason	
Date	11-Feb-2009
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	35-003-009-tr (/qs3/pubsys2/xml/en/procedures/35/35-003-009-tr.html)
Procedure Title	Rocker Lever Assembly
Update Reason	
Date	12-Feb-2009
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	105-t02-1005 (/qs3/pubsys2/xml/en/procedures/105/105-t02-1005.html)
Procedure Title	Vibration Excessive
Update Reason	
Date	12-Feb-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-008-036-shopds (/qs3/pubsys2/xml/en/procedures/35/35-008-036-shopds.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	
Date	12-Feb-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-008-036-shopas (/qs3/pubsys2/xml/en/procedures/35/35-008-036-shopas.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	

Date	12-Feb-2009
Section	Section 5 - Fuel System - Group 05
Procedure Number	35-005-011-tr (/qs3/pubsys2/xml/en/procedures/35/35-005-011-tr.html)
Procedure Title	Fuel Flow
Update Reason	
Date	12-Feb-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-036-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-036-tr.html)
Procedure Title	Fan Hub, Belt Driven
Update Reason	
Date	13-Feb-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-012-109-shopds (/qs3/pubsys2/xml/en/procedures/35/35-012-109-shopds.html)
Procedure Title	Air Compressor Inlet Tube
Update Reason	
Date	13-Feb-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-012-109-shopas (/qs3/pubsys2/xml/en/procedures/35/35-012-109-shopas.html)
Procedure Title	Air Compressor Inlet Tube
Update Reason	
Date	13-Feb-2009
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-015-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-015-tr.html)
Procedure Title	Lubricating Oil Filter Head
Update Reason	

Date	13-Feb-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-062-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-062-tr.html)
Procedure Title	Water Pump
Update Reason	
Date	13-Feb-2009
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-109-tr (/qs3/pubsys2/xml/en/procedures/35/35-012-109-tr.html)
Procedure Title	Air Compressor Inlet Tube
Update Reason	
Date	17-Feb-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-006-015-shopds (/qs3/pubsys2/xml/en/procedures/35/35-006-015-shopds.html)
Procedure Title	Fuel Filter (Spin-On Type)
Update Reason	
Date	17-Feb-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-008-002-shopds (/qs3/pubsys2/xml/en/procedures/35/35-008-002-shopds.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	
Date	17-Feb-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-008-030-shopds (/qs3/pubsys2/xml/en/procedures/35/35-008-030-shopds.html)
Procedure Title	Fan Drive Idler Pulley Assembly
Update Reason	

Date	17-Feb-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-008-030-shopas (/qs3/pubsys2/xml/en/procedures/35/35-008-030-shopas.html)
Procedure Title	Fan Drive Idler Pulley Assembly
Update Reason	
Date	17-Feb-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-008-002-shopas (/qs3/pubsys2/xml/en/procedures/35/35-008-002-shopas.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	
Date	17-Feb-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-006-015-shopas (/qs3/pubsys2/xml/en/procedures/35/35-006-015-shopas.html)
Procedure Title	Fuel Filter (Spin-On Type)
Update Reason	
Date	17-Feb-2009
Section	Section 6- Injectors and Fuel Lines - Group 06
Procedure Number	35-006-015-tr (/qs3/pubsys2/xml/en/procedures/35/35-006-015-tr.html)
Procedure Title	Fuel Filter (Spin-On Type)
Update Reason	
Date	17-Feb-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-002-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-002-tr.html)
Procedure Title	Drive Belt, Cooling Fan
Update Reason	

Date	17-Feb-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-030-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-030-tr.html)
Procedure Title	Fan Drive Idler Pulley Assembly
Update Reason	
Date	18-Feb-2009
Section	Section F - Familiarization
Procedure Number	35-001-999 (/qs3/pubsys2/xml/en/procedures/35/35-001-999.html)
Procedure Title	Cylinder Block - Overview
Update Reason	
Date	18-Feb-2009
Section	Section V - Specifications
Procedure Number	35-018-018-tr (/qs3/pubsys2/xml/en/procedures/35/35-018-018-tr.html)
Procedure Title	Cooling System
Update Reason	
Date	20-Feb-2009
Section	Section V - Specifications
Procedure Number	35-018-015-tr (/qs3/pubsys2/xml/en/procedures/35/35-018-015-tr.html)
Procedure Title	General Engine
Update Reason	
Date	26-Feb-2009
Section	Section F - Familiarization
Procedure Number	35-007-999-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-999-tr.html)
Procedure Title	Lubricating Oil System - Overview
Update Reason	

Date	26-Feb-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-020-024-shopds (/qs3/pubsys2/xml/en/procedures/35/35-020-024-shopds.html)
Procedure Title	Engine Brake
Update Reason	
Date	26-Feb-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-009-004-shopds (/qs3/pubsys2/xml/en/procedures/35/35-009-004-shopds.html)
Procedure Title	Accessory Drive Pulley
Update Reason	
Date	26-Feb-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-009-004-shopas (/qs3/pubsys2/xml/en/procedures/35/35-009-004-shopas.html)
Procedure Title	Accessory Drive Pulley
Update Reason	
Date	26-Feb-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-020-024-shopas (/qs3/pubsys2/xml/en/procedures/35/35-020-024-shopas.html)
Procedure Title	Engine Brake
Update Reason	
Date	26-Feb-2009
Section	Section 9 - Drive Units - Group 09
Procedure Number	35-009-004-tr (/qs3/pubsys2/xml/en/procedures/35/35-009-004-tr.html)
Procedure Title	Accessory Drive Pulley
Update Reason	

Date	26-Feb-2009
Section	Section 17 - Miscellaneous - Group 17
Procedure Number	35-017-002-tr (/qs3/pubsys2/xml/en/procedures/35/35-017-002-tr.html)
Procedure Title	Cup Plug
Update Reason	
Date	02-Mar-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-053-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-053-shopds.html)
Procedure Title	Water Header Plate, Cylinder Block
Update Reason	
Date	02-Mar-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-053-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-053-shopas.html)
Procedure Title	Water Header Plate, Cylinder Block
Update Reason	
Date	02-Mar-2009
Section	Section 0 - Complete Engine - Group 00
Procedure Number	35-000-001-tr (/qs3/pubsys2/xml/en/procedures/35/35-000-001-tr.html)
Procedure Title	Engine Removal
Update Reason	
Date	02-Mar-2009
Section	Section 0 - Complete Engine - Group 00
Procedure Number	35-000-002-tr (/qs3/pubsys2/xml/en/procedures/35/35-000-002-tr.html)
Procedure Title	Engine Installation
Update Reason	

Date	05-Mar-2009
Section	Section F - Familiarization
Procedure Number	35-010-999-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-999-tr.html)
Procedure Title	Air Intake System - Overview
Update Reason	
Date	05-Mar-2009
Section	Section F - Familiarization
Procedure Number	35-011-999-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-999-tr.html)
Procedure Title	Exhaust System - Overview
Update Reason	
Date	05-Mar-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-023-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-023-shopds.html)
Procedure Title	Crankshaft Seal, Front
Update Reason	
Date	05-Mar-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-013-021-shopds (/qs3/pubsys2/xml/en/procedures/35/35-013-021-shopds.html)
Procedure Title	Belt Tensioner, Automatic (Alternator)
Update Reason	
Date	05-Mar-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-008-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-008-shopds.html)
Procedure Title	Camshaft
Update Reason	

Date	05-Mar-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-005-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-005-shopds.html)
Procedure Title	Bearings, Connecting Rod
Update Reason	
Date	05-Mar-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-005-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-005-shopas.html)
Procedure Title	Bearings, Connecting Rod
Update Reason	
Date	05-Mar-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-008-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-008-shopas.html)
Procedure Title	Camshaft
Update Reason	
Date	05-Mar-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-013-021-shopas (/qs3/pubsys2/xml/en/procedures/35/35-013-021-shopas.html)
Procedure Title	Belt Tensioner, Automatic (Alternator)
Update Reason	
Date	05-Mar-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-023-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-023-shopas.html)
Procedure Title	Crankshaft Seal, Front
Update Reason	

Date	05-Mar-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-005-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-005-tr.html)
Procedure Title	Bearings, Connecting Rod
Update Reason	
Date	05-Mar-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-008-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-008-tr.html)
Procedure Title	Camshaft
Update Reason	
Date	05-Mar-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-010-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-010-tr.html)
Procedure Title	Camshaft Bushings
Update Reason	
Date	05-Mar-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-023-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-023-tr.html)
Procedure Title	Crankshaft Seal, Front
Update Reason	
Date	05-Mar-2009
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	35-013-021-tr (/qs3/pubsys2/xml/en/procedures/35/35-013-021-tr.html)
Procedure Title	Belt Tensioner, Automatic (Alternator)
Update Reason	

Date	06-Mar-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-033-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-033-shopds.html)
Procedure Title	Gear Housing, Front
Update Reason	
Date	06-Mar-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-028-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-028-shopds.html)
Procedure Title	Cylinder Liner
Update Reason	
Date	06-Mar-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-028-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-028-shopas.html)
Procedure Title	Cylinder Liner
Update Reason	
Date	06-Mar-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-033-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-033-shopas.html)
Procedure Title	Gear Housing, Front
Update Reason	
Date	06-Mar-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-027-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-027-tr.html)
Procedure Title	Cylinder Block and Liner Seats
Update Reason	

Date	06-Mar-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-028-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	
Date	06-Mar-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-033-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-033-tr.html)
Procedure Title	Gear Housing, Front
Update Reason	
Date	06-Mar-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-043-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-043-tr.html)
Procedure Title	Piston
Update Reason	
Date	09-Mar-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-053-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-053-tr.html)
Procedure Title	Water Header Plate, Cylinder Block
Update Reason	
Date	09-Mar-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-065-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-065-tr.html)
Procedure Title	Camshaft End Clearance
Update Reason	

Date	13-Mar-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-024-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-024-tr.html)
Procedure Title	Air Leaks, Air Intake and Exhaust Systems
Update Reason	
Date	13-Mar-2009
Section	Section 17 - Miscellaneous - Group 17
Procedure Number	35-017-011-tr (/qs3/pubsys2/xml/en/procedures/35/35-017-011-tr.html)
Procedure Title	Straight Thread Plug
Update Reason	
Date	26-Mar-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	101-001-006-shopds (/qs3/pubsys2/xml/en/procedures/101/101-001-006-shopds.html)
Procedure Title	Bearings, Main
Update Reason	
Date	26-Mar-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	101-001-006-shopas (/qs3/pubsys2/xml/en/procedures/101/101-001-006-shopas.html)
Procedure Title	Bearings, Main
Update Reason	
Date	26-Mar-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	101-001-006-tr (/qs3/pubsys2/xml/en/procedures/101/101-001-006-tr.html)
Procedure Title	Bearings, Main
Update Reason	

Date	31-Mar-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-010-023-shopas (/qs3/pubsys2/xml/en/procedures/35/35-010-023-shopas.html)
Procedure Title	Air Intake Manifold
Update Reason	
Date	01-Apr-2009
Section	Section 20 - Vehicle Braking - Group 20
Procedure Number	35-020-024-tr (/qs3/pubsys2/xml/en/procedures/35/35-020-024-tr.html)
Procedure Title	Engine Brake
Update Reason	
Date	03-Apr-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	101-001-024-shopds (/qs3/pubsys2/xml/en/procedures/101/101-001-024-shopds.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	
Date	03-Apr-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	101-001-024-shopas (/qs3/pubsys2/xml/en/procedures/101/101-001-024-shopas.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	
Date	03-Apr-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	101-001-024-tr (/qs3/pubsys2/xml/en/procedures/101/101-001-024-tr.html)
Procedure Title	Crankshaft Seal, Rear
Update Reason	

Date	08-Apr-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-031-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-031-shopds.html)
Procedure Title	Gear Cover, Front
Update Reason	
Date	08-Apr-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-031-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-031-shopas.html)
Procedure Title	Gear Cover, Front
Update Reason	
Date	08-Apr-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-031-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-031-tr.html)
Procedure Title	Gear Cover, Front
Update Reason	
Date	09-Apr-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-134 (/qs3/pubsys2/xml/en/procedures/35/35-010-134.html)
Procedure Title	Variable Geometry Turbocharger Actuator, Electric
Update Reason	
Date	13-Apr-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t021-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t021-tr.html)
Procedure Title	Coolant Loss - Internal
Update Reason	

Date	13-Apr-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t025-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t025-tr.html)
Procedure Title	Coolant in the Lubricating Oil
Update Reason	
Date	16-Apr-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-010-023-shopds (/qs3/pubsys2/xml/en/procedures/35/35-010-023-shopds.html)
Procedure Title	Air Intake Manifold
Update Reason	
Date	16-Apr-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-023-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-023-tr.html)
Procedure Title	Air Intake Manifold
Update Reason	
Date	16-Apr-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-027-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-027-tr.html)
Procedure Title	Charge-Air Cooler
Update Reason	
Date	16-Apr-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-080-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-080-tr.html)
Procedure Title	Air Intake Connection
Update Reason	

Date	22-Apr-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-011-026-shopds (/qs3/pubsys2/xml/en/procedures/35/35-011-026-shopds.html)
Procedure Title	EGR Differential Pressure Sensor Tubes
Update Reason	
Date	29-Apr-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-011-025-shopds (/qs3/pubsys2/xml/en/procedures/35/35-011-025-shopds.html)
Procedure Title	EGR Connection Tubes
Update Reason	
Date	29-Apr-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-011-007-shopds (/qs3/pubsys2/xml/en/procedures/35/35-011-007-shopds.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	
Date	29-Apr-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-011-007-shopas (/qs3/pubsys2/xml/en/procedures/35/35-011-007-shopas.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	
Date	29-Apr-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-011-019-shopas (/qs3/pubsys2/xml/en/procedures/35/35-011-019-shopas.html)
Procedure Title	EGR Cooler
Update Reason	

Date	29-Apr-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-011-025-shopas (/qs3/pubsys2/xml/en/procedures/35/35-011-025-shopas.html)
Procedure Title	EGR Connection Tubes
Update Reason	
Date	29-Apr-2009
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-007-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-007-tr.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	
Date	29-Apr-2009
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-022-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-022-tr.html)
Procedure Title	EGR Valve
Update Reason	
Date	29-Apr-2009
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-025-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-025-tr.html)
Procedure Title	EGR Connection Tubes
Update Reason	
Date	29-Apr-2009
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-048-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-048-tr.html)
Procedure Title	Aftertreatment Inlet and Outlet
Update Reason	

Date	05-May-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-022-001_10 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_10.html)
Procedure Title	Service Tools
Update Reason	
Date	07-May-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-016-005-shopds (/qs3/pubsys2/xml/en/procedures/35/35-016-005-shopds.html)
Procedure Title	Flywheel
Update Reason	
Date	07-May-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-016-006-shopds (/qs3/pubsys2/xml/en/procedures/35/35-016-006-shopds.html)
Procedure Title	Flywheel Housing
Update Reason	
Date	07-May-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-016-006-shopas (/qs3/pubsys2/xml/en/procedures/35/35-016-006-shopas.html)
Procedure Title	Flywheel Housing
Update Reason	
Date	07-May-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-016-005-shopas (/qs3/pubsys2/xml/en/procedures/35/35-016-005-shopas.html)
Procedure Title	Flywheel
Update Reason	

Date	07-May-2009
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	35-016-005-tr (/qs3/pubsys2/xml/en/procedures/35/35-016-005-tr.html)
Procedure Title	Flywheel
Update Reason	
Date	07-May-2009
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	35-016-006-tr (/qs3/pubsys2/xml/en/procedures/35/35-016-006-tr.html)
Procedure Title	Flywheel Housing
Update Reason	
Date	07-May-2009
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	35-016-007-tr (/qs3/pubsys2/xml/en/procedures/35/35-016-007-tr.html)
Procedure Title	Flywheel Housing, REPTO
Update Reason	
Date	13-May-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-002-004-shopas (/qs3/pubsys2/xml/en/procedures/35/35-002-004-shopas.html)
Procedure Title	Cylinder Head
Update Reason	
Date	13-May-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-011-026-shopas (/qs3/pubsys2/xml/en/procedures/35/35-011-026-shopas.html)
Procedure Title	EGR Differential Pressure Sensor Tubes
Update Reason	

Date	13-May-2009
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-026-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-026-tr.html)
Procedure Title	EGR Differential Pressure Sensor Tubes
Update Reason	
Date	18-Jun-2009
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-022-001_11-tr (/qs3/pubsys2/xml/en/procedures/35/35-022-001_11-tr.html)
Procedure Title	Service Tools
Update Reason	
Date	25-Jun-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	99-t00-001-tr (/qs3/pubsys2/xml/en/procedures/99/99-t00-001-tr.html)
Procedure Title	Troubleshooting Procedures and Techniques
Update Reason	
Date	02-Jul-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-011-019-shopds (/qs3/pubsys2/xml/en/procedures/35/35-011-019-shopds.html)
Procedure Title	EGR Cooler
Update Reason	
Date	02-Jul-2009
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-019-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-019-tr.html)
Procedure Title	EGR Cooler
Update Reason	

Date	02-Jul-2009
Section	Section 14 - Engine Testing - Group 14
Procedure Number	101-014-013 (/qs3/pubsys2/xml/en/procedures/101/101-014-013.html)
Procedure Title	Aftertreatment Testing
Update Reason	
Date	22-Jul-2009
Section	Section L - Service Literature
Procedure Number	99-205-004 (/qs3/pubsys2/xml/en/procedures/99/99-205-004.html)
Procedure Title	Cummins Customized Parts Catalog
Update Reason	
Date	28-Jul-2009
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-016-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-016-tr.html)
Procedure Title	Crankshaft
Update Reason	
Date	05-Aug-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-002-004-shopds (/qs3/pubsys2/xml/en/procedures/35/35-002-004-shopds.html)
Procedure Title	Cylinder Head
Update Reason	
Date	07-Aug-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t108-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t108-tr.html)
Procedure Title	Lubricating or Transmission Oil in the Coolant
Update Reason	

Date	07-Aug-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-016-002-shopds (/qs3/pubsys2/xml/en/procedures/35/35-016-002-shopds.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	
Date	07-Aug-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-016-002-shopas (/qs3/pubsys2/xml/en/procedures/35/35-016-002-shopas.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	
Date	07-Aug-2009
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	35-016-002-tr (/qs3/pubsys2/xml/en/procedures/35/35-016-002-tr.html)
Procedure Title	Engine Support Bracket, Front
Update Reason	
Date	14-Aug-2009
Section	Section 14 - Engine Testing - Group 14
Procedure Number	101-014-005-tr (/qs3/pubsys2/xml/en/procedures/101/101-014-005-tr.html)
Procedure Title	Engine Testing (Engine Dynamometer)
Update Reason	
Date	20-Aug-2009
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	105-t02-1001 (/qs3/pubsys2/xml/en/procedures/105/105-t02-1001.html)
Procedure Title	Engine Performance Troubleshooting Tree
Update Reason	

Date	25-Aug-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	35-t00-004 (/qs3/pubsys2/xml/en/procedures/35/35-t00-004.html)
Procedure Title	Troubleshooting Overview
Update Reason	
Date	10-Sep-2009
Section	Section i - Introduction
Procedure Number	99-204-002-shopds (/qs3/pubsys2/xml/en/procedures/99/99-204-002-shopds.html)
Procedure Title	About the Manual
Update Reason	
Date	10-Sep-2009
Section	Section i - Introduction
Procedure Number	99-204-003-shopds (/qs3/pubsys2/xml/en/procedures/99/99-204-003-shopds.html)
Procedure Title	How to Use the Manual
Update Reason	
Date	24-Sep-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t077-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t077-tr.html)
Procedure Title	Engine Will Not Crank or Cranks Slowly (Air Starter)
Update Reason	
Date	26-Sep-2009
Section	Section 14 - Engine Testing - Group 14
Procedure Number	101-014-006-tr (/qs3/pubsys2/xml/en/procedures/101/101-014-006-tr.html)
Procedure Title	Engine Run-in (Engine Dynamometer)
Update Reason	

Date	07-Oct-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t078-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t078-tr.html)
Procedure Title	Engine Will Not Crank or Cranks Slowly (Electric Starter)
Update Reason	
Date	08-Oct-2009
Section	Section i - Introduction
Procedure Number	99-204-007-tr (/qs3/pubsys2/xml/en/procedures/99/99-204-007-tr.html)
Procedure Title	General Repair Instructions
Update Reason	
Date	09-Oct-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t107-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t107-tr.html)
Procedure Title	Lubricating Oil Temperature Above Specification
Update Reason	
Date	09-Oct-2009
Section	Section 0 - Complete Engine - Group 00
Procedure Number	99-000-005-tr (/qs3/pubsys2/xml/en/procedures/99/99-000-005-tr.html)
Procedure Title	Engine Storage - Long Term
Update Reason	
Date	15-Oct-2009
Section	Section 8 - Cooling System - Group 08
Procedure Number	99-008-045 (/qs3/pubsys2/xml/en/procedures/99/99-008-045.html)
Procedure Title	Radiator Hoses
Update Reason	

Date	27-Oct-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-010-033-shopds (/qs3/pubsys2/xml/en/procedures/35/35-010-033-shopds.html)
Procedure Title	Turbocharger
Update Reason	
Date	30-Oct-2009
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t047-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t047-tr.html)
Procedure Title	Engine Noise Excessive
Update Reason	
Date	16-Nov-2009
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-010-113-shopds (/qs3/pubsys2/xml/en/procedures/35/35-010-113-shopds.html)
Procedure Title	Turbocharger, Variable Geometry Actuator
Update Reason	
Date	16-Nov-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-010-033-shopas (/qs3/pubsys2/xml/en/procedures/35/35-010-033-shopas.html)
Procedure Title	Turbocharger
Update Reason	
Date	16-Nov-2009
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-010-113-shopas (/qs3/pubsys2/xml/en/procedures/35/35-010-113-shopas.html)
Procedure Title	Variable Geometry Turbocharger Actuator
Update Reason	

Date	16-Nov-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-033-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	
Date	16-Nov-2009
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-113-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-113-tr.html)
Procedure Title	Variable Geometry Turbocharger Actuator, Pneumatic
Update Reason	
Date	04-Dec-2009
Section	Section L - Service Literature
Procedure Number	35-205-001-tr (/qs3/pubsys2/xml/en/procedures/35/35-205-001-tr.html)
Procedure Title	Additional Service Literature
Update Reason	
Date	11-Jan-2010
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t122-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t122-tr.html)
Procedure Title	Turbocharger Leaks Engine Oil or Fuel
Update Reason	
Date	20-Jan-2010
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t102-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t102-tr.html)
Procedure Title	Lubricating Oil Consumption Excessive
Update Reason	

Date	22-Jan-2010
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t105-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t105-tr.html)
Procedure Title	Lubricating Oil Pressure Low
Update Reason	
Date	25-Jan-2010
Section	Section i - Introduction
Procedure Number	99-204-006-tr (/qs3/pubsys2/xml/en/procedures/99/99-204-006-tr.html)
Procedure Title	General Safety Instructions
Update Reason	
Date	25-Jan-2010
Section	Section V - Specifications
Procedure Number	99-018-005 (/qs3/pubsys2/xml/en/procedures/99/99-018-005.html)
Procedure Title	Drive Belt Tension
Update Reason	
Date	25-Jan-2010
Section	Section V - Specifications
Procedure Number	99-018-009 (/qs3/pubsys2/xml/en/procedures/99/99-018-009.html)
Procedure Title	Capscrew Markings and Torque Values
Update Reason	
Date	26-Jan-2010
Section	Section 14 - Engine Testing - Group 14
Procedure Number	101-014-004 (/qs3/pubsys2/xml/en/procedures/101/101-014-004.html)
Procedure Title	Engine Run-in (Without Dynamometer)
Update Reason	

Date	03-Feb-2010
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	35-002-004-tr (/qs3/pubsys2/xml/en/procedures/35/35-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	
Date	10-Feb-2010
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-035-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-035-shopds.html)
Procedure Title	Hand Hole Cover
Update Reason	
Date	10-Feb-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	35-001-035-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-035-shopas.html)
Procedure Title	Hand Hole Cover
Update Reason	
Date	11-Feb-2010
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t037-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t037-tr.html)
Procedure Title	Engine Brake - Low Retarding Power or Slow to Activate
Update Reason	
Date	18-Feb-2010
Section	Section 14 - Engine Testing - Group 14
Procedure Number	101-014-010-tr (/qs3/pubsys2/xml/en/procedures/101/101-014-010-tr.html)
Procedure Title	Crankcase Blowby, Measure
Update Reason	

Date	19-Feb-2010
Section	Section V - Specifications
Procedure Number	35-018-019-tr (/qs3/pubsys2/xml/en/procedures/35/35-018-019-tr.html)
Procedure Title	Air Intake System
Update Reason	
Date	01-Mar-2010
Section	Section F - Familiarization
Procedure Number	35-008-999-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-999-tr.html)
Procedure Title	Cooling System - Overview
Update Reason	
Date	24-Mar-2010
Section	Section i - Introduction
Procedure Number	99-204-009 (/qs3/pubsys2/xml/en/procedures/99/99-204-009.html)
Procedure Title	Acronyms and Abbreviations
Update Reason	
Date	25-Mar-2010
Section	Section 20 - Vehicle Braking - Group 20
Procedure Number	35-020-007 (/qs3/pubsys2/xml/en/procedures/35/35-020-007.html)
Procedure Title	Engine Brake Housing Spacer
Update Reason	
Date	30-Mar-2010
Section	Section TS - Troubleshooting Symptoms
Procedure Number	3666322-t149-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t149-tr.html)
Procedure Title	Stationary Regeneration - Will Not Complete
Update Reason	

Date	07-Apr-2010
Section	Section TT - Troubleshooting Symptoms (New Format)
Procedure Number	16-t02-1001b (/qs3/pubsys2/xml/en/procedures/16/16-t02-1001b.html)
Procedure Title	Engine Performance Troubleshooting Tree - ISM with CM876
Update Reason	
Date	27-Apr-2010
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	101-012-003-tr (/qs3/pubsys2/xml/en/procedures/101/101-012-003-tr.html)
Procedure Title	Air Compressor Carbon Buildup
Update Reason	
Date	27-Apr-2010
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	101-012-007-tr (/qs3/pubsys2/xml/en/procedures/101/101-012-007-tr.html)
Procedure Title	Air Compressor Cylinder Head, Single Cylinder
Update Reason	
Date	27-Apr-2010
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	101-012-024-tr (/qs3/pubsys2/xml/en/procedures/101/101-012-024-tr.html)
Procedure Title	Air Pressure Relief Valve
Update Reason	

Date	26-May-2010
Section	Section E - Engine and System Identification
Procedure Number	35-100-001-tr (/qs3/pubsys2/xml/en/procedures/35/35-100-001-tr.html)
Procedure Title	Engine Identification
Update Reason	
Date	09-Jun-2010
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-041-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-041-tr.html)
Procedure Title	Aftertreatment Diesel Particulate Filter
Update Reason	
Date	09-Jun-2010
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-046-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-046-tr.html)
Procedure Title	Aftertreatment Diesel Particulate Filter Differential Pressure Sensor Mounting Bracket
Update Reason	
Date	09-Jun-2010
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-047-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-047-tr.html)
Procedure Title	Aftertreatment Diesel Particulate Filter Differential Pressure Sensor Tubes
Update Reason	
Date	09-Jun-2010
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-049-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-049-tr.html)
Procedure Title	Aftertreatment Diesel Oxidation Catalyst
Update Reason	

Date	09-Jun-2010
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-061-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-061-tr.html)
Procedure Title	Aftertreatment Fuel Injector Coolant Test
Update Reason	
Date	09-Jun-2010
Section	Section 14 - Engine Testing - Group 14
Procedure Number	101-014-001-tr (/qs3/pubsys2/xml/en/procedures/101/101-014-001-tr.html)
Procedure Title	Dynamometer Worksheet
Update Reason	
Date	09-Jun-2010
Section	Section 14 - Engine Testing - Group 14
Procedure Number	101-014-002-tr (/qs3/pubsys2/xml/en/procedures/101/101-014-002-tr.html)
Procedure Title	Engine Testing (Chassis Dynamometer)
Update Reason	
Date	09-Jun-2010
Section	Section 14 - Engine Testing - Group 14
Procedure Number	101-014-003-tr (/qs3/pubsys2/xml/en/procedures/101/101-014-003-tr.html)
Procedure Title	Engine Run-in (Chassis Dynamometer)
Update Reason	
Date	11-Jun-2010
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	101-007-040-tr (/qs3/pubsys2/xml/en/procedures/101/101-007-040-tr.html)
Procedure Title	Lubricating Oil Transfer Tube
Update Reason	

Date	23-Jun-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	101-011-042-shopds (/qs3/pubsys2/xml/en/procedures/101/101-011-042-shopds.html)
Procedure Title	Aftertreatment Fuel Injector
Update Reason	
Date	23-Jun-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	101-011-042-shopas (/qs3/pubsys2/xml/en/procedures/101/101-011-042-shopas.html)
Procedure Title	Aftertreatment Fuel Injector
Update Reason	
Date	23-Jun-2010
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	101-003-019-tr (/qs3/pubsys2/xml/en/procedures/101/101-003-019-tr.html)
Procedure Title	Crankcase Breather Element
Update Reason	
Date	23-Jun-2010
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-042-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-042-tr.html)
Procedure Title	Aftertreatment Fuel Injector
Update Reason	
Date	28-Jun-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	101-011-051-shopds (/qs3/pubsys2/xml/en/procedures/101/101-011-051-shopds.html)
Procedure Title	Aftertreatment Injector Lines
Update Reason	

Date	28-Jun-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	101-011-043-shopds (/qs3/pubsys2/xml/en/procedures/101/101-011-043-shopds.html)
Procedure Title	Aftertreatment Adapter Pipe
Update Reason	
Date	28-Jun-2010
Section	Section DS - Engine Disassembly - Group 00
Procedure Number	101-011-052-shopds (/qs3/pubsys2/xml/en/procedures/101/101-011-052-shopds.html)
Procedure Title	Aftertreatment Fuel Shutoff Manifold
Update Reason	
Date	28-Jun-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	101-011-052-shopas (/qs3/pubsys2/xml/en/procedures/101/101-011-052-shopas.html)
Procedure Title	Aftertreatment Fuel Shutoff Manifold
Update Reason	
Date	28-Jun-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	101-011-043-shopas (/qs3/pubsys2/xml/en/procedures/101/101-011-043-shopas.html)
Procedure Title	Aftertreatment Adapter Pipe
Update Reason	
Date	28-Jun-2010
Section	Section AS - Engine Assembly - Group 00
Procedure Number	101-011-051-shopas (/qs3/pubsys2/xml/en/procedures/101/101-011-051-shopas.html)
Procedure Title	Aftertreatment Injector Lines
Update Reason	

Date	28-Jun-2010
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-009-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-009-tr.html)
Procedure Title	Exhaust Restriction
Update Reason	
Date	28-Jun-2010
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-043-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-043-tr.html)
Procedure Title	Aftertreatment Adapter Pipe
Update Reason	
Date	28-Jun-2010
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-050-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-050-tr.html)
Procedure Title	Aftertreatment System
Update Reason	
Date	28-Jun-2010
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-051-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-051-tr.html)
Procedure Title	Aftertreatment Injector Lines
Update Reason	
Date	28-Jun-2010
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-052-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-052-tr.html)
Procedure Title	Aftertreatment Fuel Shutoff Manifold
Update Reason	

Date	28-Jun-2010
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-054-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-054-tr.html)
Procedure Title	Aftertreatment Fuel Injector Flow
Update Reason	
Date	28-Jun-2010
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-054-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-054-tr.html)
Procedure Title	Aftertreatment Fuel Injector Flow
Update Reason	Initial Check section revised.
Date	11-Oct-2010
Section	Section 16 - Mounting Adaptations - Group 11
Procedure Number	35-016-027 (/qs3/pubsys2/xml/en/procedures/35/35-016-027.html)
Procedure Title	Engine Drive Shaft
Update Reason	Changed installation service tool part number and added the number of capscrews used to install the drive shaft.
Date	11-Oct-2010
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t027-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t027-tr.html)
Procedure Title	Crankcase Gases (Blowby) Excessive
Update Reason	Revision to troubleshooting node - Turbocharger Oil Seal is Leaking.

Date	19-Nov-2010
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	101-012-020 (/qs3/pubsys2/xml/en/procedures/101/101-012-020.html)
Procedure Title	Air Compressor (Oil Carryover)
Update Reason	Released this new procedure.
Date	17-Jan-2011
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t105-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t105-tr.html)
Procedure Title	Lubricating Oil Pressure Low
Update Reason	Changed the order of some of the troubleshooting steps.
Date	31-Jan-2011
Section	Section F - Familiarization - Section F
Procedure Number	35-001-999 (/qs3/pubsys2/xml/en/procedures/35/35-001-999.html)
Procedure Title	Cylinder Block - Overview
Update Reason	Updated Theory of Operation section with new main bearing clearance specifications.
Date	10-Feb-2011
Section	Section 3 -Rocker Levers -Group 3
Procedure Number	35-003-004-tr (/qs3/pubsys2/xml/en/procedures/35/35-003-004-tr.html)
Procedure Title	Overhead Set
Update Reason	Removed engine brake lash specification in the Adjust section.

Date	21-Feb-2011
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t078-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t078-tr.html)
Procedure Title	Engine Will Not Crank or Cranks Slowly (Electric Starter)
Update Reason	Tree t078 removed and replaced by t074-005 and t074-010.

Date	21-Feb-2011
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t074-005-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t074-005-tr.html)
Procedure Title	Engine Will Not Crank (Electric Starter)
Update Reason	Replaces t078.

Date	21-Feb-2011
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t074-010-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t074-010-tr.html)
Procedure Title	Engine Cranks Slowly (Electric Starter)
Update Reason	Replaces t078.

Date	17-Mar-2011
Section	Section TT - Troubleshooting Symptoms (New Format) - Group TT
Procedure Number	105-t02-1001 (/qs3/pubsys2/xml/en/procedures/105/105-t02-1001.html)
Procedure Title	Engine Performance Troubleshooting Tree
Update Reason	Added Step 4D

Date	17-Mar-2011
Section	Section TT - Troubleshooting Symptoms (New Format) - Group TT
Procedure Number	16-t02-1001b (/qs3/pubsys2/xml/en/procedures/16/16-t02-1001b.html)
Procedure Title	Engine Performance Troubleshooting Tree
Update Reason	Added Step 4D
Date	21-Mar-2011
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	101-001-026-tr (/qs3/pubsys2/xml/en/procedures/101/101-001-026-tr.html)
Procedure Title	Cylinder Block
Update Reason	Updated main bearing clearance specification in Inspect for Reuse section.
Date	21-Mar-2011
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t108-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t108-tr.html)
Procedure Title	Lubricating or Transmission Oil in the Coolant
Update Reason	Revised order of steps in tree.
Date	05-Apr-2011
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t020-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t020-tr.html)
Procedure Title	Coolant Loss - External
Update Reason	Revised order and technical content of steps in tree.

Date	05-Apr-2011
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t021-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t021-tr.html)
Procedure Title	Coolant Loss - Internal
Update Reason	Revised order and technical content of steps in tree.

Date	05-Apr-2011
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t025-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t025-tr.html)
Procedure Title	Coolant in the Lubricating Oil
Update Reason	Revised order and technical content of steps in tree.

Date	01-Jun-2011
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	35-002-004-tr (/qs3/pubsys2/xml/en/procedures/35/35-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Added replacing the crankcase breather element for cylinder head injector sleeves to the Finishing Steps.

Date	06-Jun-2011
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-047-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-047-tr.html)
Procedure Title	Radiator Pressure Cap
Update Reason	Revised graphic of radiator pressure cap.

Date	08-Jun-2011
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-003-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-003-tr.html)
Procedure Title	Lubricating Oil Cooler
Update Reason	Added note concerning progressive damage replacement in the event of debris contamination of the lubricating oil.

Date	11-Jul-2011
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-042-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-042-tr.html)
Procedure Title	Aftertreatment Fuel Injector
Update Reason	Updated procedure to advise replacing bolts instead of using bolts again, and revised torque specification.

Date	11-Jul-2011
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	35-003-001-tr (/qs3/pubsys2/xml/en/procedures/35/35-003-001-tr.html)
Procedure Title	Crankcase Breather (External)
Update Reason	Added procedure to manual.

Date	12-Jul-2011
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	35-002-004-tr (/qs3/pubsys2/xml/en/procedures/35/35-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Changed task titles to read: With EGR and Without EGR.

Date	25-Jul-2011
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-019-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-019-tr.html)
Procedure Title	EGR Cooler
Update Reason	Added detail regarding component inspection and crankcase element replacement due to EGR issue.

Date	8-Sep-2011
Section	Section TT - Troubleshooting Symptoms (New Format) - Group TT
Procedure Number	16-t02-1001b (/qs3/pubsys2/xml/en/procedures/16/16-t02-1001b.html)
Procedure Title	Engine Performance Troubleshooting Tree - ISM with CM876
Update Reason	Added Steps 6B, 6C, and change 6B to 6D.

Date	15-Sep-2011
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t149-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t149-tr.html)
Procedure Title	Stationary Regeneration - Will Not Complete
Update Reason	Updated tree to monitor closing of EGR valve and inspection of EGR differential pressure sensor.

Date	22-Sep-2011
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-033-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Updated procedure to include leak test.

Date	05-Oct-2011
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-113-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-113-tr.html)
Procedure Title	Turbocharger, Variable Geometry Actuator
Update Reason	Remove the electric VG actuator references from the procedure.

Date	07-Oct-2011
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-021-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-021-tr.html)
Procedure Title	EGR Mixer
Update Reason	Updated procedure with information related to the EGR hoses from replacing to inspecting the hoses.

Date	07-Oct-2011
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-022-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-022-tr.html)
Procedure Title	EGR Valve
Update Reason	Updated procedure with information related to the EGR hoses from replacing to inspecting the hoses.

Date	07-Oct-2011
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-025-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-025-tr.html)
Procedure Title	EGR Connection Tubes
Update Reason	Updated procedure with information related to the EGR hoses from replacing to inspecting the hoses.

Date	21-Oct-2011
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t108-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t108-tr.html)
Procedure Title	Lubricating or Transmission Oil in the Coolant
Update Reason	Removed Cause: Lubricating oil filter head is cracked or porous.

Date	25-Oct-2011
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t108-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t108-tr.html)
Procedure Title	Lubricating or Transmission Oil in the Coolant
Update Reason	Revised turbocharger bearing housing is cracked or porous step

Date	11-Nov-2011
Section	Section 20 - Vehicle Braking - Group 20
Procedure Number	35-020-007 (/qs3/pubsys2/xml/en/procedures/35/35-020-007.html)
Procedure Title	Engine Brake Housing Spacer
Update Reason	Revised Preparatory Steps/Finishing Steps by adding, Refer to Procedure 020-024.

Date	14-Mar-2012
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t149-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t149-tr.html)
Procedure Title	Stationary Regeneration - Will Not Complete
Update Reason	Updated, added technical content, and reorganized steps.

Date	03-Apr-2012
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-056 (/qs3/pubsys2/xml/en/procedures/35/35-011-056.html)
Procedure Title	Exhaust System Diagnostics
Update Reason	Revise DEF specification and add diagnostic information regarding high resistance in the aftertreatment sensor harness signal wires.

Date	20-Apr-2012
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-022-001_11 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_11.html)
Procedure Title	Service Tools
Update Reason	Added service tool Aftertreatment Fuel Injector Test Kit, Part Number 4918517.

Date	30-Apr-2012
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-019-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-019-tr.html)
Procedure Title	EGR Cooler
Update Reason	Updated procedure to match warranty progressive damage limits.

Date	01-May-12
Section	Section 14 - Engine Testing - Group 14
Procedure Number	101-014-013-tr (/qs3/pubsys2/xml/en/procedures/101/101-014-013-tr.html)
Procedure Title	Aftertreatment Testing
Update Reason	Updated procedure by removing information from Preparatory Steps, moving a test step and adding a test step.

Date	16-July-2012
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-018-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-018-tr.html)
Procedure Title	Cooling System
Update Reason	Added new step (Coolant Replacer Tool Method) to perform cooling system service using the Coolant Replacer Tool, Part Number 2892459.

Date	28-Jul-2012
Section	Section TT - Troubleshooting Symptoms (New Format)- Group TT
Procedure Number	105-t02-1001 (/qs3/pubsys2/xml/en/procedures/105/105-t02-1001.html)
Procedure Title	Engine Performance Troubleshooting Tree - Signature™ and ISX CM870
Update Reason	Changed wastegate controller resistance test values to 6 to 10 ohms, 12-VDC and 24 to 40 ohms for 24-VDC.

Date	15-Aug-2012
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t021-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t021-tr.html)
Procedure Title	Coolant Loss - Internal
Update Reason	Revised "Air compressor cylinder head is cracked or porous, or has a leaking gasket" node.

Date	22-Aug-2012
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	35-002-004-tr (/qs3/pubsys2/xml/en/procedures/35/35-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Added Notes to Finishing Steps.

Date	28-Sep-2012
Section	Section 16 - Mounting Adaptations - Group 16
Procedure Number	00-016-026-tr (/qs3/pubsys2/xml/en/procedures/00/00-016-026-tr.html)
Procedure Title	Marine Vibration Isolator
Update Reason	Procedure was revised to include information specific to the new isolator design introduced with the marine engine and to align with the most recent installation angularity requirements in the Marine Installation Directions.
Date	03-Oct-2012
Section	Section 11 - Exhaust System - Group 11
Procedure Number	101-011-041-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-041-tr.html)
Procedure Title	Aftertreatment Diesel Particulate Filter
Update Reason	Procedure updated to include statement regarding the proper match of ECM calibrations and DPF part numbers.
Date	30-Nov-2012
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t006-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t006-tr.html)
Procedure Title	Air Compressor Noise is Excessive
Update Reason	Added: Air compressor is excessively worn or internally damaged.
Date	22-Jan-2013
Section	Section 13 - Electrical Equipment - Group 13
Procedure Number	35-013-003-tr (/qs3/pubsys2/xml/en/procedures/35/35-013-003-tr.html)
Procedure Title	Alternator Bracket
Update Reason	Modified procedure to provide the field with the proper torque value for these alternator mounting options.

Date	05-Feb-2013
Section	TF - Troubleshooting Symptoms (New Format) - Group TF
Procedure Number	105-t02-1005 (/qs3/pubsys2/xml/en/procedures/105/105-t02-1005.html)
Procedure Title	Vibration Excessive
Update Reason	Revised Guided Step 1E, YES, to: Refer to the Engine Runs Rough troubleshooting symptom tree in Section TS or the Engine Performance Troubleshooting Tree in Section TT.
Date	28-Feb-2013
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t004-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t004-tr.html)
Procedure Title	Air Compressor Air Pressure Rises Slowly
Update Reason	Improved and identified troubleshooting steps implemented in air complaint system trees.
Date	28-Feb-2013
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t005-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t005-tr.html)
Procedure Title	Air Compressor Cycles Frequently
Update Reason	Improved and identified troubleshooting steps implemented in air complaint system trees.
Date	28-Feb-2013
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t006-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t006-tr.html)
Procedure Title	Air Compressor Noise is Excessive
Update Reason	Improved and identified troubleshooting steps implemented in air complaint system trees.

Date	28-Feb-2013
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t008-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t008-tr.html)
Procedure Title	Air Compressor Will Not Maintain Adequate Air Pressure (Not Pumping Continuously)
Update Reason	Improved and identified troubleshooting steps implemented in air complaint system trees.

Date	28-Feb-2013
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t009-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t009-tr.html)
Procedure Title	Air Compressor Will Not Pump Air
Update Reason	Improved and identified troubleshooting steps implemented in air complaint system trees.

Date	28-Feb-2013
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t010-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t010-tr.html)
Procedure Title	Air Compressor Will Not Stop Pumping
Update Reason	Improved and identified troubleshooting steps implemented in air complaint system trees.

Date	28-Feb-2013
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-013-tr (/qs3/pubsys2/xml/en/procedures/35/35-012-013-tr.html)
Procedure Title	Air Compressor Unloader and Valve Assembly
Update Reason	Improved direction on cleaning the air compressor cylinder head.

Date	28-Feb-2013
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-014-tr (/qs3/pubsys2/xml/en/procedures/35/35-012-014-tr.html)
Procedure Title	Air Compressor
Update Reason	Improved direction on cleaning the air compressor cylinder head.

Date	28-Feb-2013
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-017-tr (/qs3/pubsys2/xml/en/procedures/35/35-012-017-tr.html)
Procedure Title	Air Governor (Air Compressor Will Not Pump)
Update Reason	Improved direction on cleaning the air compressor cylinder head.

Date	28-Feb-2013
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-018-tr (/qs3/pubsys2/xml/en/procedures/35/35-012-018-tr.html)
Procedure Title	Air Governor (Air Compressor Pumps Continuously))
Update Reason	Improved direction on cleaning the air compressor cylinder head.

Date	28-Feb-2013
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-019-tr (/qs3/pubsys2/xml/en/procedures/35/35-012-019-tr.html)
Procedure Title	Air Leaks, Compressed Air System
Update Reason	Improved direction on cleaning the air compressor cylinder head.

Date	28-Feb-2013
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	101-012-003-tr (/qs3/pubsys2/xml/en/procedures/101/101-012-003-tr.html)
Procedure Title	Air Compressor Carbon Buildup
Update Reason	Improved direction on cleaning the air compressor cylinder head.

Date	28-Feb-2013
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	101-012-007-tr (/qs3/pubsys2/xml/en/procedures/101/101-012-007-tr.html)
Procedure Title	Air Compressor Cylinder Head, Single Cylinder
Update Reason	Improved direction on cleaning the air compressor cylinder head.

Date	15-Apr-2013
Section	Sectopm TT - Troubleshooting Symptoms - Group TT
Procedure Number	16-t02-1001b (/qs3/pubsys2/xml/en/procedures/16/16-t02-1001b.html)
Procedure Title	Engine Performance Troubleshooting Tree - ISM with CM876
Update Reason	Added a note to Step 6E: Inspect the turbocharger shaft movement.

Date	01-May-2013
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-041-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-041-tr.html)
Procedure Title	Turbocharger Coolant Hoses
Update Reason	Remove Step, removed statement: Remove and discard all banjo sealing washers.

Date	01-May-2013
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-046-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-046-tr.html)
Procedure Title	Turbocharger Coolant Hoses
Update Reason	Install Step, removed, with new o-rings from, Install the turbocharger oil supply line with new o-rings.

Date	28-Jun-2013
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-003-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-003-tr.html)
Procedure Title	Lubricating Oil Cooler
Update Reason	Clean and Inspect for Reuse Step, added Caution in reference to oil passages contaminated with debris or dirt causes damage.

Date	03-Jul-2013
Section	Section TF - Troubleshooting Fault Codes - Group TF
Procedure Number	3666322-t087-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t087-tr.html)
Procedure Title	Fuel Consumption Excessive
Update Reason	Removed Cause: VE/VMS® analysis uses incorrect data.

Date	14-Aug-2013
Section	Section 11 - Exhaust System Group 11
Procedure Number	101-011-047-tr (/qs3/pubsys2/xml/en/procedures/101/101-011-047-tr.html)
Procedure Title	Aftertreatment Diesel Particulate Filter Differential Pressure Sensor Tubes
Update Reason	Revise Install statement: The aftertreatment diesel particulate filter differential pressure sensor is marked with "HI" on one side of the sensor (1). This indicates the high-side differential pressure sensor tube connects to this port. The high-side differential pressure sensor tube connects to the aftertreatment system before the inlet to the diesel particulate filter.

Date	22-Aug-2013
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-019-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-019-tr.html)
Procedure Title	Cooling System - Air or Combustion Gas Test
Update Reason	EGR cooler added to the list of possible causes for a positive result from the combustion gas leak tester in the Leak Test step.

Date	22-Sep-2013
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	35-003-013-tr (/qs3/pubsys2/xml/en/procedures/35/35-003-013-tr.html)
Procedure Title	Rocker Lever Housing
Update Reason	Added new Note to Install step: Oil resistant, medium strength thread locker, such as Loctite 243 or equivalent, should be used when assembling the six short capscrews located on both sides of the three intake ports.

Date	25-Oct-2013
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	101-012-008-tr (/qs3/pubsys2/xml/en/procedures/101/101-012-008-tr.html)
Procedure Title	Air Compressor Cylinder Head, Two Cylinder
Update Reason	Added Procedure 012-008 to Section 12.
Date	09-Nov-2013
Section	Section V - Specifications - Group 18
Procedure Number	99-018-028 (/qs3/pubsys2/xml/en/procedures/99/99-018-028.html)
Procedure Title	Barometric Pressure at Altitude
Update Reason	Added to outline.
Date	27-Jan-2014
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-033-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Updated Axial and Radial endplay specifications.
Date	30-Jan-2014
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-028-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	Updated Install Step to be consistent with the Initial Check Step.

Date	14-Apr-2014
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-033-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Updated note in Finishing Steps.
Date	25-Apr-2014
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	101-012-007-tr (/qs3/pubsys2/xml/en/procedures/101/101-012-007-tr.html)
Procedure Title	Air Compressor Cylinder Head, Single Cylinder
Update Reason	This revised head with changes that need to be addressed in the manual to avoid confusion. The revised head has only one spring pin the old head had two.
Date	28-Apr-2014
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	35-006-025-tr (/qs3/pubsys2/xml/en/procedures/35/35-006-025-tr.html)
Procedure Title	Static Injection Timing
Update Reason	Measure Step: Added, injection timing code location and Static Timing Codes chart for CPL information.
Date	06-May-2014
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	101-001-006-tr (/qs3/pubsys2/xml/en/procedures/101/101-001-006-tr.html)
Procedure Title	Bearings, Main
Update Reason	Updated the procedure to make it consistent with the New Engine Build Standard (NEBS) torque specifications.

Date	25-Jun-2014
Section	Section 12 Compressed Air System - Group 12
Procedure Number	101-012-024-tr (/qs3/pubsys2/xml/en/procedures/101/101-012-024-tr.html)
Procedure Title	Air Pressure Relief Valve
Update Reason	Added steps for testing the operation of the air compressor relief valve.
Date	23-Jun-2014
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	101-001-054-tr (/qs3/pubsys2/xml/en/procedures/101/101-001-054-tr.html)
Procedure Title	Piston and Connecting Rod Assembly
Update Reason	Added Piston and Connecting Rod Assembly orientation instructions.
Date	23-Jul-2014
Section	Section 10 Air Intake System - Group 10
Procedure Number	35-010-033-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Added the clocking procedure.
Date	1-Oct-2014
Section	Section 3 - Rocker Levers - Group 03
Procedure Number	35-003-011-tr (/qs3/pubsys2/xml/en/procedures/35/35-003-011-tr.html)
Procedure Title	Rocker Lever Cover
Update Reason	Updated procedure to include a step to inspect the isolators and bolts for the valve cover and replace, if necessary.

Date	17-Nov-2014
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	35-002-004-tr (/qs3/pubsys2/xml/en/procedures/35/35-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Moved a note from the "Without EGR" section into the "With EGR" section in the Finishing Steps.

Date	09-Mar-2015
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	101-001-006-tr (/qs3/pubsys2/xml/en/procedures/101/101-001-006-tr.html)
Procedure Title	Bearings, Main
Update Reason	Revised a statement in the Install step as follows: "To rotate 180 degrees, use a socket that has been etched with two axial lines 180 degrees apart".

Date	09-Mar-2015
Section	Section V - Specifications Group 01
Procedure Number	101-001-006-shopas (/qs3/pubsys2/xml/en/procedures/101/101-001-006-shopas.html)
Procedure Title	Bearings, Main
Update Reason	Revised a statement in the Assemble step as follows: "To rotate 180 degrees, use a socket that has been etched with two axial lines 180 degrees apart".

Date	08-Apr-2015
Section	Section 8 - Cooling System - Group 08
Procedure Number	35-008-018-tr (/qs3/pubsys2/xml/en/procedures/35/35-008-018-tr.html)
Procedure Title	Cooling System
Update Reason	Added directions to allow the engine to cool before draining coolant.

Date	25-Jun-2015
Section	Section 20 - Vehicle Braking - Group 20
Procedure Number	35-020-007 (/qs3/pubsys2/xml/en/procedures/35/35-020-007.html)
Procedure Title	Engine Brake Housing Spacer
Update Reason	Updated to identify either a gasket or sealant may be used during installation of the engine brake housing spacer.
Date	06-Jul-2015
Section	Section 14 - Engine Testing - Group 14
Procedure Number	99-014-024 (/qs3/pubsys2/xml/en/procedures/99/99-014-024.html)
Procedure Title	Fluorescent Tracer Dye Test
Update Reason	Added to outline.
Date	28-Aug-2015
Section	Section 14 - Engine Testing - Group 14
Procedure Number	101-014-013-tr (/qs3/pubsys2/xml/en/procedures/101/101-014-013-tr.html)
Procedure Title	Aftertreatment Testing
Update Reason	Removed Preparatory Step section. Added regeneration information to Test section.
Date	13-Nov-2015
Section	Section 0 - Product - Group 00
Procedure Number	35-000-017 (/qs3/pubsys2/xml/en/procedures/35/35-000-017.html)
Procedure Title	Engine Barring
Update Reason	Added to outline.

Date	26-Feb-2016
Section	Section DS - Engine Disassembly Group 00
Procedure Number	35-001-028-shopds (/qs3/pubsys2/xml/en/procedures/35/35-001-028-shopds.html)
Procedure Title	Cylinder Liner
Update Reason	Missing part of the liner protrusion specification is being added in Clean and Inspect and Install steps: : Maximum allowable variation in liner protrusion for each 180 degrees is 0.03mm [0.001 inch].

Date	26-Feb-2016
Section	Section AS - Engine Assembly Group 00
Procedure Number	35-001-028-shopas (/qs3/pubsys2/xml/en/procedures/35/35-001-028-shopas.html)
Procedure Title	Cylinder Liner
Update Reason	Missing part of the liner protrusion specification is being added in Clean and Inspect and Install steps: : Maximum allowable variation in liner protrusion for each 180 degrees is 0.03mm [0.001 inch].

Date	26-Feb-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-028-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-028-tr.html)
Procedure Title	Cylinder Liner
Update Reason	Missing part of the liner protrusion specification is being added in Clean and Inspect and Install steps: : Maximum allowable variation in liner protrusion for each 180 degrees is 0.03mm [0.001 inch].

Date	12-Apr-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-003-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-003-tr.html)
Procedure Title	Accessory Drive Seal
Update Reason	Corrected the location of the seal in the graphic.

Date	14-Jul-2016
Section	TF - Troubleshooting Symptoms (New Format) - Group TF
Procedure Number	105-t02-1005 (/qs3/pubsys2/xml/en/procedures/105/105-t02-1005.html)
Procedure Title	Vibration Excessive
Update Reason	Revised troubleshooting for brake adjustment, engine mounts, front end belt drive accessories, and vibration damper.

Date	30-Aug-2016
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	101-007-025-tr (/qs3/pubsys2/xml/en/procedures/101/101-007-025-tr.html)
Procedure Title	Lubricating Oil Pan
Update Reason	Added installation information for a new 4 piece lubricating oil pan gasket.

Date	17-Oct-2016
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-022-001_01 (/qs3/pubsys2/xml/en/procedures/35/35-022-001_01.html)
Procedure Title	Service Tools
Update Reason	Added tool numbers 3376637 and 3376636 to page.

Date	15-Mar-17
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-013 (/qs3/pubsys2/xml/en/procedures/35/35-001-013.html)
Procedure Title	Camshaft Gear (Camshaft Removed)
Update Reason	Updated procedure to avoid confusion with removal and install.
Date	19-Jun-2017
Section	Section TS - Troubleshooting Symptoms - Group TS
Procedure Number	3666322-t105-tr (/qs3/pubsys2/xml/en/manual/3666322/3666322-t105-tr.html)
Procedure Title	Lubricating Oil Pressure Low
Update Reason	Modified symptom tree.
Date	07-Dec-2017
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-007-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-007-tr.html)
Procedure Title	Exhaust Manifold
Update Reason	Organized marine engine content.
Date	07-Dec-2017
Section	Section 6 - Injectors and Fuel Lines -Group 06
Procedure Number	35-006-024-tr (/qs3/pubsys2/xml/en/procedures/35/35-006-024-tr.html)
Procedure Title	Fuel Supply Line
Update Reason	Updated procedure to avoid kinking during installation of fuel supply line and updated torque spec.

Date	14-Dec-2017
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-095 (/qs3/pubsys2/xml/en/procedures/35/35-007-095.html)
Procedure Title	Lubricating Oil Filter Differential Pressure Measurement Test
Update Reason	Added to manual.
Date	19-Jan-2018
Section	Section 10 - Exhaust System - Group 10
Procedure Number	35-010-033-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Removed task titles and automotive references. Modified Marine application for slip joint exhaust manifold.
Date	29-Jan-2018
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-008-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-008-tr.html)
Procedure Title	Exhaust Manifold, Wet
Update Reason	Added to outline.
Date	18-May-2018
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-013-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-013-tr.html)
Procedure Title	Lubricating Oil Filter (Spin-On)
Update Reason	Updated General Information section for the combination NanoNet® lubricating oil filter.

Date	11-May-2018
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-999-tr (/qs3/pubsys2/xml/en/procedures/35/35-007-999-tr.html)
Procedure Title	Lubricating Oil System - Overview
Update Reason	Updated Lubricating Oil Filters of the General Information with the combination NanoNet® lubricating oil filter.
Date	14-May-2018
Section	Section V - Specifications
Procedure Number	35-018-017-tr (/qs3/pubsys2/xml/en/procedures/35/35-018-017-tr.html)
Procedure Title	Lubricating Oil System
Update Reason	Updated oil filter capacity of standard engine.
Date	05-Feb-2019
Section	Section 11 - Exhaust System
Procedure Number	35-011-073 (/qs3/pubsys2/xml/en/procedures/35/35-011-073.html)
Procedure Title	Exhaust Manifold Turbocharger Mounting Stud Replacement
Update Reason	Added to outline.
Date	03-Jun-2019
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-007-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-007-tr.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	Added information that the QSM11 engine does not have an exhaust manifold seal.

Date	03-Jun-2019
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-008-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-008-tr.html)
Procedure Title	Exhaust Manifold, Wet
Update Reason	Added information that the QSM11 engine does not have an exhaust manifold seal.
Date	08-Nov-2019
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	35-002-004-tr (/qs3/pubsys2/xml/en/procedures/35/35-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Part Number 3822476 in the Install Steps was replaced with Part Number 3822479.
Date	13-Nov-2019
Section	Section 1 - Cylinder Block - Group 01
Procedure Number	35-001-022-tr (/qs3/pubsys2/xml/en/procedures/35/35-001-022-tr.html)
Procedure Title	Crankshaft Pulley
Update Reason	Added note to the Preparatory Steps to note that the procedure is applicable for both single and dual damper configurations. Revised Torque Value listed within the second stepblock of the Install Steps.
Date	15-Jan-2020
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-007-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-007-tr.html)
Procedure Title	Exhaust Manifold, Dry
Update Reason	Removed step to use a light coat of grease or clean engine oil to lubricate the exhaust seal during assembly.

Date	29-Jan-2020
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-033-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Added service bulletin resources for damaged turbocharger compressor impellers and turbine wheels.

Date	04-Feb-2020
Section	Section 6 - Injectors and Fuel Lines - Group 06
Procedure Number	35-006-025-tr (/qs3/pubsys2/xml/en/procedures/35/35-006-025-tr.html)
Procedure Title	Static Injection Timing
Update Reason	Corrected the listed part number for the alignment tool.

Date	27-Feb-2020
Section	Section V - Specifications
Procedure Number	35-018-023 (/qs3/pubsys2/xml/en/procedures/35/35-018-023.html)
Procedure Title	Engine Testing
Update Reason	Corrected the format of the listed specifications to ensure they were readable.

Date	18-Jun-2020
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	35-002-004-tr (/qs3/pubsys2/xml/en/procedures/35/35-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Made minor corrections to procedure.

Date	22-Jun-2020
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	101-007-025-tr (/qs3/pubsys2/xml/en/procedures/101/101-007-025-tr.html)
Procedure Title	Lubricating Oil Pan
Update Reason	Added caution indicating not to use the capscrew to pull the transfer tube into place during installation.

Date	16-Sep-2020
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-050-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-050-tr.html)
Procedure Title	Turbocharger Wastegate Actuator
Update Reason	Corrected specification listed for QSM wastegate acutator.

Date	17-Nov-2020
Section	Section 7 - Lubricating Oil System - Group 07
Procedure Number	35-007-095 (/qs3/pubsys2/xml/en/procedures/35/35-007-095.html)
Procedure Title	Lubricating Oil Filter Differential Pressure Measurement Test
Update Reason	Corrected graphics to show the proper pressure differential measurement locations.

Date	19-Jan-2021
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-056 (/qs3/pubsys2/xml/en/procedures/35/35-011-056.html)
Procedure Title	Exhaust System Diagnostics
Update Reason	Added the typical values for a healthy system during a stationary (parked) regeneration.

Date	15-Feb-2022
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	82-019-363 (/qs3/pubsys2/xml/en/procedures/82/82-019-363.html)
Procedure Title	Camshaft Position Sensor
Update Reason	Added procedure to manual.

Date	15-Feb-2022
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	82-019-376 (/qs3/pubsys2/xml/en/procedures/82/82-019-376.html)
Procedure Title	Exhaust Gas Pressure Sensor
Update Reason	Added procedure to manual.

Date	15-Feb-2022
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	82-019-159 (/qs3/pubsys2/xml/en/procedures/82/82-019-159.html)
Procedure Title	Intake Manifold Pressure/Temperature Sensor
Update Reason	Added procedure to manual.

Date	15-Feb-2022
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	82-019-066 (/qs3/pubsys2/xml/en/procedures/82/82-019-066.html)
Procedure Title	Engine Oil Pressure Sensor/Switch
Update Reason	Added procedure to manual.

Date	26-Apr-2022
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	35-019-378 (/qs3/pubsys2/xml/en/procedures/35/35-019-378.html)
Procedure Title	EGR Temperature Sensor
Update Reason	Added procedure to manual.

Date	26-Apr-2022
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	35-019-443 (/qs3/pubsys2/xml/en/procedures/35/35-019-443.html)
Procedure Title	Aftertreatment Diesel Particulate Filter Differential Pressure Sensor
Update Reason	Added procedure to manual.
Date	29-Aug-2022
Section	Section 5 - Fuel System - Group 05
Procedure Number	35-005-043-tr (/qs3/pubsys2/xml/en/procedures/35/35-005-043-tr.html)
Procedure Title	Fuel Shutoff Valve
Update Reason	Consolidated and improved Fuel Shutoff Valve procedure.
Date	07-Sep-2022
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-022-tr (/qs3/pubsys2/xml/en/procedures/35/35-011-022-tr.html)
Procedure Title	EGR Valve
Update Reason	Removed reference to Troubleshooting and Repair Manual ISX CM871 and ISM CM876 Electronic Control System, Bulletin 4021560.
Date	14-Nov-2022
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	35-019-443 (/qs3/pubsys2/xml/en/procedures/35/35-019-443.html)
Procedure Title	Aftertreatment Diesel Particulate Filter Differential/Outlet Pressure Sensor
Update Reason	Added Aftertreatment Diesel Particulate Filter Outlet Pressure Sensor Voltage (VDC) minimum and maximum specifications to procedure.

Date	30-Nov-2022
Section	Section 2 - Cylinder Head - Group 02
Procedure Number	35-002-004-tr (/qs3/pubsys2/xml/en/procedures/35/35-002-004-tr.html)
Procedure Title	Cylinder Head
Update Reason	Corrected part number listed for one of the plug drivers from 3823372 to 3822372.
Date	14-Dec-2022
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-103 (/qs3/pubsys2/xml/en/procedures/35/35-012-103.html)
Procedure Title	Air Compressor Cylinder Head (Holset® SS and E-Type Models)
Update Reason	Added procedure to manual.
Date	14-Dec-2022
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-104 (/qs3/pubsys2/xml/en/procedures/35/35-012-104.html)
Procedure Title	Air Compressor Cylinder Head (Holset® QE Models)
Update Reason	Added procedure to manual.
Date	14-Dec-2022
Section	Section 12 - Compressed Air System - Group 12
Procedure Number	35-012-106 (/qs3/pubsys2/xml/en/procedures/35/35-012-106.html)
Procedure Title	Air Compressor Cylinder Head (Holset® ST Models)
Update Reason	Added procedure to manual.

Date	02-Mar-2023
Section	Section 11 - Exhaust System - Group 11
Procedure Number	35-011-056 (/qs3/pubsys2/xml/en/procedures/35/35-011-056.html)
Procedure Title	Exhaust System Diagnostics
Update Reason	Corrected exhaust gas pressure and intake manifold pressure specifications for a stationary (parked) regeneration.
Date	16-May-2023
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	82-019-395 (/qs3/pubsys2/xml/en/procedures/82/82-019-395.html)
Procedure Title	Turbocharger Compressor Intake Air Temperature Sensor
Update Reason	Added procedure to manual.
Date	07-Jun-2023
Section	Section 10 - Air Intake System - Group 10
Procedure Number	35-010-033-tr (/qs3/pubsys2/xml/en/procedures/35/35-010-033-tr.html)
Procedure Title	Turbocharger
Update Reason	Revised first Install stepblock of procedure, added note.
Date	27-Oct-2023
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	35-019-388 (/qs3/pubsys2/xml/en/procedures/35/35-019-388.html)
Procedure Title	Turbocharger Control Valve
Update Reason	Added procedure to manual.

Date	24-Sep-2024
Section	Section 19 - Electronic Controls - Group 19
Procedure Number	82-019-031 (/qs3/pubsys2/xml/en/procedures/82/82-019-031.html)
Procedure Title	Engine Control Module
Update Reason	No changes made to procedure, needed to update procedure title to align to proper assigned title.

Last Modified: 10-Dec-2024
