

Manual Change History (5659765) 15N CM2380 M104B Fault Code Troubleshooting Manual Change History

Date	31-Jul-2026
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001335
Solution Title	Lubricating oil cooler is leaking
Update Reason	Solution Removed
Date	12-Jul-2026
Fault Code / Symptom	Engine Crankcase Ventilation Hose Disconnected - Condition Exists
Solution Number	S00009883
Solution Title	Crankcase ventilation hoses loose or damaged
Update Reason	Solution Added
Date	04-Jul-2026
Fault Code / Symptom	Electronic Throttle Control Actuator - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	01-May-2026
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00001983
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Reordered
Date	01-May-2026
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00001983
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Modified

Date	12-Apr-2026
Fault Code / Symptom	Engine Auxiliary Shutdown Switch - Abnormal Update Rate
Solution Number	S00012527
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	29-Mar-2026
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001299
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Reordered
Date	29-Mar-2026
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001299
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Modified
Date	29-Mar-2026
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001299
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Reordered
Date	29-Mar-2026
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001299
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Modified
Date	15-Mar-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004290
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	15-Mar-2026
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004290
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	01-Feb-2026
Fault Code / Symptom	Engine Turbocharger Compressor Bypass Actuator Control Command Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011739
Solution Title	Compressor recirculation valve circuit response
Update Reason	Solution Removed
Date	01-Feb-2026
Fault Code / Symptom	Engine Turbocharger Compressor Bypass Actuator Control Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011737
Solution Title	Compressor recirculation valve circuit response
Update Reason	Solution Removed
Date	26-Jan-2026
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012663
Solution Title	Lubricating oil pressure sensor stuck in-range
Update Reason	Solution Added
Date	26-Jan-2026
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000342
Solution Title	Lubricating oil pressure sensor stuck in-range
Update Reason	Solution Removed

Date	18-Jan-2026
Fault Code / Symptom	Engine Fan 1 Requested Percent Speed - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	18-Jan-2026
Fault Code / Symptom	Engine Fan 1 Requested Percent Speed - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	18-Jan-2026
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Removed
Date	11-Jan-2026
Fault Code / Symptom	Transmission Engine Crank Enable - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	11-Jan-2026
Fault Code / Symptom	Engine Fuel Shutoff 1 Control - Condition Exists
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	11-Jan-2026
Fault Code / Symptom	Low Power
Solution Number	S00011805
Solution Title	Compressor recirculation valve is malfunctioning
Update Reason	Solution Added
Date	11-Jan-2026
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00011805
Solution Title	Compressor recirculation valve is malfunctioning
Update Reason	Solution Added
Date	11-Jan-2026
Fault Code / Symptom	Engine Turbocharger Compressor Bypass Actuator Control Command Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Jan-2026
Fault Code / Symptom	Engine Turbocharger Compressor Bypass Actuator Control Command Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011739
Solution Title	Compressor recirculation valve circuit response
Update Reason	Solution Added
Date	11-Jan-2026
Fault Code / Symptom	Engine Turbocharger Compressor Bypass Actuator Control Command Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011744
Solution Title	Compressor recirculation valve resistance check
Update Reason	Solution Added

Date	11-Jan-2026
Fault Code / Symptom	Engine Turbocharger Compressor Bypass Actuator Control Command Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011741
Solution Title	Compressor recirculation valve circuit response at the engine control module
Update Reason	Solution Added
Date	11-Jan-2026
Fault Code / Symptom	Engine Turbocharger Compressor Bypass Actuator Control Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	11-Jan-2026
Fault Code / Symptom	Engine Turbocharger Compressor Bypass Actuator Control Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011737
Solution Title	Compressor recirculation valve circuit response
Update Reason	Solution Added
Date	11-Jan-2026
Fault Code / Symptom	Engine Turbocharger Compressor Bypass Actuator Control Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011744
Solution Title	Compressor recirculation valve resistance check
Update Reason	Solution Added

Date	11-Jan-2026
Fault Code / Symptom	Engine Turbocharger Compressor Bypass Actuator Control Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011742
Solution Title	Compressor recirculation valve circuit response at the engine control module
Update Reason	Solution Added
Date	04-Jan-2026
Fault Code / Symptom	Engine Turbocharger Compressor Bypass Actuator Control Command Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	04-Jan-2026
Fault Code / Symptom	Engine Turbocharger Compressor Bypass Actuator Control Command Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	04-Jan-2026
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Dec-2025
Fault Code / Symptom	Engine Cylinder 1 Ignition Coil Secondary Output - Current Above Normal or Grounded Circuit
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	21-Dec-2025
Fault Code / Symptom	Engine Cylinder 2 Ignition Coil Secondary Output - Current Above Normal or Grounded Circuit
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	21-Dec-2025
Fault Code / Symptom	Engine Cylinder 3 Ignition Coil Secondary Output - Current Above Normal or Grounded Circuit
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	21-Dec-2025
Fault Code / Symptom	Engine Cylinder 4 Ignition Coil Secondary Output - Current Above Normal or Grounded Circuit
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	21-Dec-2025
Fault Code / Symptom	Engine Cylinder 5 Ignition Coil Secondary Output - Current Above Normal or Grounded Circuit
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	21-Dec-2025
Fault Code / Symptom	Engine Cylinder 6 Ignition Coil Secondary Output - Current Above Normal or Grounded Circuit
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	23-Nov-2025
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00012640
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Added

Date	23-Nov-2025
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00000532
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Removed

Date	23-Nov-2025
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012640
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Added

Date	23-Nov-2025
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000532
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Removed

Date	23-Nov-2025
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012640
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Added

Date	23-Nov-2025
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000532
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Removed
Date	23-Nov-2025
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012640
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Added
Date	23-Nov-2025
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000532
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Removed
Date	23-Nov-2025
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012640
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Added
Date	23-Nov-2025
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000532
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Removed

Date	23-Nov-2025
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00012640
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Added

Date	23-Nov-2025
Fault Code / Symptom	Charging System Potential (Voltage) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012640
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Added

Date	23-Nov-2025
Fault Code / Symptom	Charging System Potential (Voltage) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000532
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Removed

Date	23-Nov-2025
Fault Code / Symptom	Charging System Potential (Voltage) - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012640
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Added

Date	23-Nov-2025
Fault Code / Symptom	Charging System Potential (Voltage) - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000532
Solution Title	Charging system alternator is malfunctioning
Update Reason	Solution Removed

Date	02-Nov-2025
Fault Code / Symptom	EGR Mass Flow - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003480
Solution Title	EGR differential pressure sensor is malfunctioning
Update Reason	Solution Added
Date	26-Oct-2025
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00000553
Solution Title	Verify performance complaint
Update Reason	Solution Removed
Date	05-Oct-2025
Fault Code / Symptom	Accelerator Interlock Switch - Out of Calibration
Solution Number	S00012595
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	05-Oct-2025
Fault Code / Symptom	Clutch Switch - Out of Calibration
Solution Number	S00012598
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	05-Oct-2025
Fault Code / Symptom	Engine Shutdown Override Switch - Out of Calibration
Solution Number	S00012592
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	05-Oct-2025
Fault Code / Symptom	Engine Idle Decrement Switch - Out of Calibration
Solution Number	S00012594
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added

Date	05-Oct-2025
Fault Code / Symptom	Engine Idle Increment Switch - Out of Calibration
Solution Number	S00012593
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	05-Oct-2025
Fault Code / Symptom	Engine Remote PTO Governor Preprogrammed Speed Control Switch - Out of Calibration
Solution Number	S00012601
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	05-Oct-2025
Fault Code / Symptom	Engine PTO Governor Enable Switch - Out of Calibration
Solution Number	S00012600
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	05-Oct-2025
Fault Code / Symptom	Two Speed Axle Switch - Out of Calibration
Solution Number	S00012599
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	05-Oct-2025
Fault Code / Symptom	Remote Accelerator Pedal Position - Out of Calibration
Solution Number	S00012597
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	05-Oct-2025
Fault Code / Symptom	Remote Accelerator Enable Switch - Out of Calibration
Solution Number	S00012596
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added

Date	28-Sep-2025
Fault Code / Symptom	Brake Switch Circuit - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Cruise Control Enable Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Accelerator Pedal Position 1 - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	A/C High Pressure Fan Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	A/C High Pressure Fan Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Accelerator Interlock Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	28-Sep-2025
Fault Code / Symptom	Accelerator Interlock Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine Auxiliary Shutdown Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine Auxiliary Shutdown Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Cruise Control Enable Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Cruise Control Pause Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	28-Sep-2025
Fault Code / Symptom	Cruise Control Resume Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Cruise Control Resume Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Cruise Control Set Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Cruise Control Set Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Clutch Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Clutch Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	28-Sep-2025
Fault Code / Symptom	Engine Shutdown Override Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine Shutdown Override Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine Idle Decrement Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine Idle Decrement Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine Idle Increment Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	28-Sep-2025
Fault Code / Symptom	Engine Idle Increment Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine Remote PTO Governor Preprogrammed Speed Control Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine Remote PTO Governor Preprogrammed Speed Control Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine PTO Governor Resume Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine PTO Governor Resume Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	28-Sep-2025
Fault Code / Symptom	Engine PTO Governor Set Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine PTO Governor Set Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine PTO Governor Enable Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine PTO Governor Enable Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Two Speed Axle Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Two Speed Axle Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	28-Sep-2025
Fault Code / Symptom	Remote Accelerator Pedal Position - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Remote Accelerator Enable Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Remote Accelerator Enable Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Remote Accelerator Pedal Position - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine Retarder Selection - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine Retarder Selection - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	28-Sep-2025
Fault Code / Symptom	Brake Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine Diagnostic Test Mode Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Engine Diagnostic Test Mode Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Performance Bias Selection - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	28-Sep-2025
Fault Code / Symptom	Parking Brake Switch - Abnormal Update Rate
Solution Number	S00012521
Solution Title	Engine wiring harness open circuit check
Update Reason	Solution Added
Date	28-Sep-2025
Fault Code / Symptom	Parking Brake Switch - Abnormal Update Rate
Solution Number	S00012522
Solution Title	Engine wiring harness has a short to ground
Update Reason	Solution Added

Date	28-Sep-2025
Fault Code / Symptom	Parking Brake Switch - Abnormal Update Rate
Solution Number	S00012524
Solution Title	J1939 data link harness pin to pin short circuit
Update Reason	Solution Added
Date	21-Sep-2025
Fault Code / Symptom	SAE J1939 Multiplexing PGN Timeout Error - Abnormal Update Rate
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed
Date	21-Sep-2025
Fault Code / Symptom	J1939 Network #1 - Out of Calibration
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed
Date	21-Sep-2025
Fault Code / Symptom	Parking Brake Switch - Out of Calibration
Solution Number	S00000519
Solution Title	Incorrectly programmed OEM multiplexing unit
Update Reason	Solution Removed
Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00012513
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added
Date	18-Aug-2025
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed

Date	18-Aug-2025
Fault Code / Symptom	Parking Brake Switch - Abnormal Update Rate
Solution Number	S00007932
Solution Title	Incorrect terminating resistor in the J1939 data link
Update Reason	Solution Added
Date	10-Aug-2025
Fault Code / Symptom	Charging System Potential (Voltage) - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	10-Aug-2025
Fault Code / Symptom	Charging System Potential (Voltage) - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	10-Aug-2025
Fault Code / Symptom	Engine Cylinder 4 (B2) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001925
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	03-Aug-2025
Fault Code / Symptom	Parking Brake Switch - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	03-Aug-2025
Fault Code / Symptom	Parking Brake Switch - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	27-Jul-2025
Fault Code / Symptom	Closed Crankcase Ventilation System Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	27-Jul-2025
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Jul-2025
Fault Code / Symptom	External Lubricating Oil Leak
Solution Number	S00012455
Solution Title	Fluorescent Dye Tracer Test (lubricating oil)
Update Reason	Solution Added
Date	21-Jul-2025
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00012455
Solution Title	Fluorescent Dye Tracer Test (lubricating oil)
Update Reason	Solution Added
Date	21-Jul-2025
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00012455
Solution Title	Fluorescent Dye Tracer Test (lubricating oil)
Update Reason	Solution Added

Date	21-Jul-2025
Fault Code / Symptom	EGR Mass Flow - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00004357
Solution Title	EGR differential pressure sensor circuit response
Update Reason	Solution Removed
Date	13-Jul-2025
Fault Code / Symptom	Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001230
Solution Title	Engine control module malfunction
Update Reason	Solution Removed
Date	06-Jul-2025
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	29-Jun-2025
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00012427
Solution Title	Fuel leak check
Update Reason	Solution Added
Date	22-Jun-2025
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012426
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Added

Date	22-Jun-2025
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006385
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Removed
Date	22-Jun-2025
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00012426
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Added
Date	22-Jun-2025
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006385
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Removed
Date	22-Jun-2025
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012426
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Added
Date	22-Jun-2025
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006385
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Removed

Date	22-Jun-2025
Fault Code / Symptom	Engine Crankcase Ventilation Hose Disconnected - Condition Exists
Solution Number	S00012426
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Added
Date	22-Jun-2025
Fault Code / Symptom	Engine Crankcase Ventilation Hose Disconnected - Condition Exists
Solution Number	S00006385
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Removed
Date	22-Jun-2025
Fault Code / Symptom	Closed Crankcase Ventilation System Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012426
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Added
Date	22-Jun-2025
Fault Code / Symptom	Closed Crankcase Ventilation System Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006385
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Removed
Date	22-Jun-2025
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00012426
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Added

Date	22-Jun-2025
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006385
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Removed
Date	22-Jun-2025
Fault Code / Symptom	Engine Crankcase Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00012426
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Added
Date	22-Jun-2025
Fault Code / Symptom	Engine Crankcase Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006385
Solution Title	Crankcase ventilation system plugged
Update Reason	Solution Removed
Date	01-Jun-2025
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012405
Solution Title	EGR differential pressure sensor circuit response
Update Reason	Solution Added
Date	01-Jun-2025
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012410
Solution Title	EGR differential pressure sensor voltage supply check
Update Reason	Solution Added

Date	26-May-2025
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00012412
Solution Title	EGR differential pressure sensor voltage supply check
Update Reason	Solution Added
Date	26-May-2025
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00012413
Solution Title	EGR differential pressure sensor circuit response
Update Reason	Solution Added
Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Reordered
Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Modified
Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000400
Solution Title	Exhaust gas pressure sensor circuit response
Update Reason	Solution Reordered

Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000400
Solution Title	Exhaust gas pressure sensor circuit response
Update Reason	Solution Modified
Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Reordered
Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Modified
Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Reordered
Date	18-May-2025
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Modified

Date	18-May-2025
Fault Code / Symptom	Engine Exhaust Gas Bank 2 Pressure Sensor 1 - Voltage Above Normal or Shorted to High Source
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Reordered

Date	18-May-2025
Fault Code / Symptom	Engine Exhaust Gas Bank 2 Pressure Sensor 1 - Voltage Above Normal or Shorted to High Source
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Modified

Date	18-May-2025
Fault Code / Symptom	Engine Exhaust Gas Bank 2 Pressure Sensor 1 - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Reordered

Date	18-May-2025
Fault Code / Symptom	Engine Exhaust Gas Bank 2 Pressure Sensor 1 - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Modified

Date	18-May-2025
Fault Code / Symptom	Engine Exhaust Gas Pressure 2 Sensor - Condition Exists
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Reordered

Date	18-May-2025
Fault Code / Symptom	Engine Exhaust Gas Pressure 2 Sensor - Condition Exists
Solution Number	S00000776
Solution Title	Exhaust gas pressure sensor voltage check
Update Reason	Solution Modified
Date	27-Apr-2025
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L1 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008604
Solution Title	Ignition Coil Test
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L1 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008605
Solution Title	Ignition control module circuit check
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L1 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008606
Solution Title	Ignition control module circuit pin to ground short
Update Reason	Solution Added

Date	27-Apr-2025
Fault Code / Symptom	Cylinder L1 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008607
Solution Title	Ignition control module circuit pin to pin short
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L2 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008604
Solution Title	Ignition Coil Test
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L2 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008605
Solution Title	Ignition control module circuit check
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L2 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008606
Solution Title	Ignition control module circuit pin to ground short
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L2 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008607
Solution Title	Ignition control module circuit pin to pin short
Update Reason	Solution Added

Date	27-Apr-2025
Fault Code / Symptom	Cylinder L3 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008604
Solution Title	Ignition Coil Test
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L3 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008605
Solution Title	Ignition control module circuit check
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L3 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008606
Solution Title	Ignition control module circuit pin to ground short
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L3 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008607
Solution Title	Ignition control module circuit pin to pin short
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L4 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008604
Solution Title	Ignition Coil Test
Update Reason	Solution Added

Date	27-Apr-2025
Fault Code / Symptom	Cylinder L4 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008605
Solution Title	Ignition control module circuit check
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L4 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008606
Solution Title	Ignition control module circuit pin to ground short
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L4 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008607
Solution Title	Ignition control module circuit pin to pin short
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L5 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008604
Solution Title	Ignition Coil Test
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L5 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008605
Solution Title	Ignition control module circuit check
Update Reason	Solution Added

Date	27-Apr-2025
Fault Code / Symptom	Cylinder L5 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008606
Solution Title	Ignition control module circuit pin to ground short
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L5 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008607
Solution Title	Ignition control module circuit pin to pin short
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L6 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008604
Solution Title	Ignition Coil Test
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L6 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008605
Solution Title	Ignition control module circuit check
Update Reason	Solution Added
Date	27-Apr-2025
Fault Code / Symptom	Cylinder L6 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008606
Solution Title	Ignition control module circuit pin to ground short
Update Reason	Solution Added

Date	27-Apr-2025
Fault Code / Symptom	Cylinder L6 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00008607
Solution Title	Ignition control module circuit pin to pin short
Update Reason	Solution Added
Date	24-Feb-2025
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Outlet Pressure - Voltage Above Normal or Shorted to High Source
Solution Number	S00012319
Solution Title	Closed crankcase ventilation system pressure sensor circuit response
Update Reason	Solution Added
Date	24-Feb-2025
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Outlet Pressure - Voltage Above Normal or Shorted to High Source
Solution Number	S00012320
Solution Title	Closed crankcase ventilation system pressure sensor circuit response at the engine control module
Update Reason	Solution Added
Date	24-Feb-2025
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Outlet Pressure - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012321
Solution Title	Closed crankcase ventilation system pressure sensor circuit response
Update Reason	Solution Added

Date	24-Feb-2025
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Outlet Pressure - Voltage Below Normal or Shorted to Low Source
Solution Number	S00012322
Solution Title	Closed crankcase ventilation system pressure sensor circuit response at the engine control module
Update Reason	Solution Added
Date	16-Feb-2025
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Outlet Pressure - Voltage Above Normal or Shorted to High Source
Solution Number	S00009059
Solution Title	Closed crankcase ventilation system pressure sensor circuit response
Update Reason	Solution Removed
Date	16-Feb-2025
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Outlet Pressure - Voltage Above Normal or Shorted to High Source
Solution Number	S00009060
Solution Title	Closed crankcase ventilation system pressure sensor circuit response at the ECM
Update Reason	Solution Removed
Date	16-Feb-2025
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Outlet Pressure - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009061
Solution Title	Closed crankcase ventilation system pressure sensor circuit response
Update Reason	Solution Removed

Date	16-Feb-2025
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Outlet Pressure - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009062
Solution Title	Closed crankcase ventilation system pressure sensor circuit response at the ECM
Update Reason	Solution Removed
Date	09-Feb-2025
Fault Code / Symptom	Engine Crankcase Pressure 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	27-Jan-2025
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	05-Jan-2025
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00001983
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Added
Date	05-Jan-2025
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00000019
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed

Date	01-Dec-2024
Fault Code / Symptom	Antitheft Password Valid Indicator - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	01-Dec-2024
Fault Code / Symptom	Proprietary Datalink Error (OEM/Vehicle Datalink) - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	01-Dec-2024
Fault Code / Symptom	Anti-theft Encryption Seed - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	01-Dec-2024
Fault Code / Symptom	Engine Starter Motor Relay Control Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	01-Dec-2024
Fault Code / Symptom	Engine Starter Motor Relay Control Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	01-Dec-2024
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	25-Nov-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 Position - Data Not Rational - Drifted High
Solution Number	S00012281
Solution Title	Leaking compressed air system
Update Reason	Solution Added
Date	18-Nov-2024
Fault Code / Symptom	Turbocharger 1 Wastegate Control Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Nov-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 Position Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Nov-2024
Fault Code / Symptom	Engine Turbocharger 1 Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	18-Nov-2024
Fault Code / Symptom	Engine Turbocharger 1 Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00012025
Solution Title	Turbocharger control valve voltage check
Update Reason	Solution Added
Date	18-Nov-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Bad Intelligent Device or Component
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Nov-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	18-Nov-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00012025
Solution Title	Turbocharger control valve voltage check
Update Reason	Solution Added
Date	18-Nov-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 Position - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	06-Oct-2024
Fault Code / Symptom	Lubricating Oil Consumption
Solution Number	S00011059
Solution Title	Service Bulletin is available
Update Reason	Solution Added

Date	06-Oct-2024
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00011059
Solution Title	Service Bulletin is available
Update Reason	Solution Added
Date	23-Sep-2024
Fault Code / Symptom	Electronic Throttle Control Actuator - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	23-Sep-2024
Fault Code / Symptom	Engine Speed Surges/Speed Erratic
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	23-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Removed

Date	23-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Removed
Date	23-Sep-2024
Fault Code / Symptom	Engine Valve Lash Setting- Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	23-Sep-2024
Fault Code / Symptom	Engine Valve Lash Setting - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	09-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011522
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed

Date	09-Sep-2024
Fault Code / Symptom	Engine Cylinder 1 (A1) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011522
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Sep-2024
Fault Code / Symptom	Engine Cylinder 1 (A1) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	09-Sep-2024
Fault Code / Symptom	Engine Cylinder 2 (B1) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011522
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Sep-2024
Fault Code / Symptom	Engine Cylinder 2 (B1) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed

Date	09-Sep-2024
Fault Code / Symptom	Engine Cylinder 3 (A2) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011522
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Sep-2024
Fault Code / Symptom	Engine Cylinder 3 (A2) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	09-Sep-2024
Fault Code / Symptom	Engine Cylinder 4 (B2) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011522
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Sep-2024
Fault Code / Symptom	Engine Cylinder 4 (B2) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed

Date	09-Sep-2024
Fault Code / Symptom	Engine Cylinder 5 (A3) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011522
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Sep-2024
Fault Code / Symptom	Engine Cylinder 5 (A3) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	09-Sep-2024
Fault Code / Symptom	Engine Cylinder 6 (B3) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011522
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Sep-2024
Fault Code / Symptom	Engine Cylinder 6 (B3) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed

Date	09-Sep-2024
Fault Code / Symptom	Engine Turbocharger 1 Boost Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011522
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Sep-2024
Fault Code / Symptom	Engine Turbocharger 1 Boost Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	09-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011522
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Sep-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed

Date	09-Sep-2024
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011522
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Sep-2024
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	09-Sep-2024
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011522
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Sep-2024
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed

Date	26-Aug-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	26-Aug-2024
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001203
Solution Title	Turbocharger leaking air into crankcase
Update Reason	Solution Removed
Date	29-Jul-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00001217
Solution Title	Cranking State malfunction
Update Reason	Solution Added
Date	29-Jul-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00005820
Solution Title	Cranking State malfunction
Update Reason	Solution Removed
Date	29-Jul-2024
Fault Code / Symptom	EGR Mass Flow - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004158
Solution Title	Air/fuel mixer is malfunctioning
Update Reason	Solution Added
Date	22-Jul-2024
Fault Code / Symptom	Engine Speed Surges
Solution Number	
Solution Title	
Update Reason	Solution Set Removed

Date	22-Jul-2024
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000689
Solution Title	Incorrect base engine timing
Update Reason	Solution Reordered
Date	22-Jul-2024
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000689
Solution Title	Incorrect base engine timing
Update Reason	Solution Modified
Date	22-Jul-2024
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00000689
Solution Title	Incorrect base engine timing
Update Reason	Solution Added
Date	22-Jul-2024
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000689
Solution Title	Incorrect base engine timing
Update Reason	Solution Added
Date	07-Jul-2024
Fault Code / Symptom	Engine Speed Surges
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	07-Jul-2024
Fault Code / Symptom	Erratic Idle Speed
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	26-May-2024
Fault Code / Symptom	Engine Turbocharger 1 Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	26-May-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	26-May-2024
Fault Code / Symptom	Turbocharger 1 Wastegate Control Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	26-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 Position Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	26-May-2024
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted High
Solution Number	S00004677
Solution Title	Aftertreatment intake oxygen sensor is contaminated
Update Reason	Solution Removed
Date	26-May-2024
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted Low
Solution Number	S00004677
Solution Title	Aftertreatment intake oxygen sensor is contaminated
Update Reason	Solution Removed
Date	26-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Bad Intelligent Device or Component
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	26-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	26-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Removed

Date	26-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Removed
Date	26-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Removed
Date	26-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 Position - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	19-May-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009686
Solution Title	Turbocharger wastegate control valve is malfunctioning
Update Reason	Solution Added
Date	19-May-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009686
Solution Title	Turbocharger wastegate control valve is malfunctioning
Update Reason	Solution Added

Date	19-May-2024
Fault Code / Symptom	Turbocharger 1 Wastegate Control Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00006343
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	19-May-2024
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	19-May-2024
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	19-May-2024
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	19-May-2024
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	19-May-2024
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	19-May-2024
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	19-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Bad Intelligent Device or Component
Solution Number	S00009686
Solution Title	Turbocharger wastegate control valve is malfunctioning
Update Reason	Solution Added
Date	19-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Bad Intelligent Device or Component
Solution Number	S00006343
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	19-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00009686
Solution Title	Turbocharger wastegate control valve is malfunctioning
Update Reason	Solution Added

Date	19-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00006343
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	19-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 Position - Data Not Rational - Drifted High
Solution Number	S00006343
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	12-May-2024
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007920
Solution Title	Coolant level sensor open circuit check
Update Reason	Solution Removed
Date	12-May-2024
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007921
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Removed
Date	12-May-2024
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007922
Solution Title	Coolant level sensor circuit pin to pin short
Update Reason	Solution Removed

Date	12-May-2024
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor Circuit - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	12-May-2024
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor Circuit - Abnormal Update Rate
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added
Date	12-May-2024
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor Circuit - Abnormal Update Rate
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added
Date	12-May-2024
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009784
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	12-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00001110
Solution Title	Low battery voltage
Update Reason	Solution Added

Date	12-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added
Date	12-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added
Date	12-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00008545
Solution Title	J1939 data link engine wiring harness voltage check 3 pin service connector
Update Reason	Solution Added
Date	12-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00008546
Solution Title	J1939 data link component isolation
Update Reason	Solution Added
Date	12-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00008536
Solution Title	J1939 data link terminating resistance is incorrect
Update Reason	Solution Added

Date	12-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00005758
Solution Title	Engine data link terminating resistor resistance check
Update Reason	Solution Added

Date	12-May-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	S00005759
Solution Title	J1939 data link harness open circuit check
Update Reason	Solution Added

Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Reordered

Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Level Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Modified

Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Reordered

Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Modified

Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Temperature High
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Reordered
Date	05-May-2024
Fault Code / Symptom	Lubricating Oil Temperature High
Solution Number	S00001358
Solution Title	Basic oil system checks
Update Reason	Solution Modified
Date	05-May-2024
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004301
Solution Title	EGR differential pressure sensor stuck in-range
Update Reason	Solution Removed
Date	30-Apr-2024
Fault Code / Symptom	Crankcase Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000623
Solution Title	Crankcase pressure sensor stuck in-range
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00011966
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00011966
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	14-Apr-2024
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00004892
Solution Title	Gear train backlash is out of adjustment
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Air Compressor Noise
Solution Number	S00003076
Solution Title	Gear train backlash is out of adjustment
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00011966
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00011966
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00011966
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Reordered

Date	14-Apr-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00011966
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00004892
Solution Title	Gear train backlash is out of adjustment
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00003076
Solution Title	Gear train backlash is out of adjustment
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Exhaust Noise
Solution Number	S00011966
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00011966
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	14-Apr-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Reordered
Date	14-Apr-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Low Power
Solution Number	S00011966
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00011966
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00001267
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00011763
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Reordered

Date	14-Apr-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00011763
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Reordered
Date	14-Apr-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00001190
Solution Title	Incorrect base engine timing
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00011966
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00011966
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00001267
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	14-Apr-2024
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00011966
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	14-Apr-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00005091
Solution Title	Spark plug is contaminated with oil
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00004925
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00005091
Solution Title	Spark plug is contaminated with oil
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00004925
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00005091
Solution Title	Spark plug is contaminated with oil
Update Reason	Solution Removed

Date	14-Apr-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00004925
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	White Smoke
Solution Number	S00005091
Solution Title	Spark plug is contaminated with oil
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	White Smoke
Solution Number	S00004925
Solution Title	Worn or damaged power cylinder components
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009783
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009784
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	14-Apr-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009784
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	14-Apr-2024
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003168
Solution Title	Loose or damaged engine brake wiring harness connector
Update Reason	Solution Reordered

Date	14-Apr-2024
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003168
Solution Title	Loose or damaged engine brake wiring harness connector
Update Reason	Solution Modified

Date	14-Apr-2024
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003168
Solution Title	Loose or damaged engine brake wiring harness connector
Update Reason	Solution Reordered

Date	14-Apr-2024
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003168
Solution Title	Loose or damaged engine brake wiring harness connector
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003168
Solution Title	Loose or damaged engine brake wiring harness connector
Update Reason	Solution Reordered
Date	14-Apr-2024
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003168
Solution Title	Loose or damaged engine brake wiring harness connector
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003168
Solution Title	Loose or damaged engine brake wiring harness connector
Update Reason	Solution Reordered

Date	14-Apr-2024
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003168
Solution Title	Loose or damaged engine brake wiring harness connector
Update Reason	Solution Modified
Date	14-Apr-2024
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009783
Solution Title	Leaks in the exhaust system
Update Reason	Solution Removed
Date	14-Apr-2024
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009784
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	07-Apr-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Bad Intelligent Device or Component
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	07-Apr-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	07-Apr-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 Position - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	07-Apr-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00003075
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Reordered
Date	07-Apr-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00003075
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Modified
Date	07-Apr-2024
Fault Code / Symptom	Turbocharger 1 Wastegate Control Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	07-Apr-2024
Fault Code / Symptom	Engine Turbocharger Wastegate Actuator 1 Position Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	07-Apr-2024
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00011985
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added
Date	07-Apr-2024
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00011987
Solution Title	Engine Compression Test
Update Reason	Solution Added
Date	07-Apr-2024
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011985
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added
Date	07-Apr-2024
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011987
Solution Title	Engine Compression Test
Update Reason	Solution Added
Date	31-Mar-2024
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00004028
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	31-Mar-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered

Date	31-Mar-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified

Date	31-Mar-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00011971
Solution Title	Spark plug is damaged
Update Reason	Solution Added

Date	31-Mar-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00004028
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed

Date	31-Mar-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered

Date	31-Mar-2024
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified

Date	31-Mar-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00011971
Solution Title	Spark plug is damaged
Update Reason	Solution Added
Date	31-Mar-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00001350
Solution Title	Air intake or exhaust system leaks
Update Reason	Solution Removed
Date	31-Mar-2024
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Exhaust Noise
Solution Number	S00001350
Solution Title	Air intake or exhaust system leaks
Update Reason	Solution Removed
Date	31-Mar-2024
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered

Date	31-Mar-2024
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00004028
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	31-Mar-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified

Date	31-Mar-2024
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Low Power
Solution Number	S00004028
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	31-Mar-2024
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00011971
Solution Title	Spark plug is damaged
Update Reason	Solution Added

Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00004028
Solution Title	Leaks in the intake air system
Update Reason	Solution Removed
Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Reordered

Date	31-Mar-2024
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Air intake system restricted
Update Reason	Solution Modified
Date	31-Mar-2024
Fault Code / Symptom	White Smoke
Solution Number	S00011971
Solution Title	Spark plug is damaged
Update Reason	Solution Added
Date	24-Mar-2024
Fault Code / Symptom	Engine Valve Lash Setting- Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	24-Mar-2024
Fault Code / Symptom	Engine Valve Lash Setting - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	17-Mar-2024
Fault Code / Symptom	Engine Protection Torque Derate - Condition Exists
Solution Number	S00003080
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Added

Date	04-Feb-2024
Fault Code / Symptom	Lubricating Oil in the Coolant
Solution Number	S00001324
Solution Title	Transmission lubricating oil cooler is malfunctioning
Update Reason	Solution Removed
Date	04-Feb-2024
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011049
Solution Title	Circuit Load Test
Update Reason	Solution Removed
Date	04-Feb-2024
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011049
Solution Title	Circuit Load Test
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Air Conditioning Will Not Cool
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	14-Jan-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00011764
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	Black Smoke
Solution Number	S00004980
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Engine Knock
Solution Number	S00011764
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Engine Knock
Solution Number	S00004980
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00011764
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Engine Noise
Solution Number	S00004980
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Exhaust Noise
Solution Number	S00009910
Solution Title	Exhaust catalyst is malfunctioning
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	Exhaust Noise
Solution Number	S00004951
Solution Title	Exhaust catalyst is malfunctioning
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00011764
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00004980
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Low Power
Solution Number	S00011764
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Low Power
Solution Number	S00009910
Solution Title	Exhaust catalyst is malfunctioning
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Low Power
Solution Number	S00004980
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed

Date	14-Jan-2024
Fault Code / Symptom	Low Power
Solution Number	S00004951
Solution Title	Exhaust catalyst is malfunctioning
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00003583
Solution Title	Lubricating oil filter plugged
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Overhead Noise
Solution Number	S00011764
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Overhead Noise
Solution Number	S00004980
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00009910
Solution Title	Exhaust catalyst is malfunctioning
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00011729
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00011763
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00004980
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00004951
Solution Title	Exhaust catalyst is malfunctioning
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Turbocharger 1 Wastegate Control Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00011524
Solution Title	Wastegate control valve circuit response
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	Turbocharger 1 Wastegate Control Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00004313
Solution Title	Wastegate control valve circuit response
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00003853
Solution Title	Camshaft position sensor is malfunctioning
Update Reason	Solution Removed
Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00011730
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00011730
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00011730
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00011730
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00011730
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00011730
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011730
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added
Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder 2 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011730
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder 3 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011730
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder 4 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011730
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder 5 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011730
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added

Date	14-Jan-2024
Fault Code / Symptom	Engine Misfire Cylinder 6 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011730
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added

Date	17-Dec-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00011273
Solution Title	Check for primary fault codes
Update Reason	Solution Removed

Date	17-Dec-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00001983
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Removed
Date	03-Dec-2023
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Outlet Pressure - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	03-Dec-2023
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Outlet Pressure - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	03-Dec-2023
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	03-Dec-2023
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 2 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009833
Solution Title	Aftertreatment exhaust gas temperature sensor resistance check
Update Reason	Solution Removed

Date	03-Dec-2023
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003168
Solution Title	Loose or damaged engine brake wiring harness connector
Update Reason	Solution Added
Date	03-Dec-2023
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 2 - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	03-Dec-2023
Fault Code / Symptom	EGR Valve Control Circuit - Mechanical System Not Responding or Out of Adjustment
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	26-Nov-2023
Fault Code / Symptom	EGR Valve Control Circuit - Current Below Normal or Open Circuit
Solution Number	S00000773
Solution Title	EGR valve motor resistance check
Update Reason	Solution Removed
Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011546
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added

Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011546
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	22-Oct-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00011546
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	22-Oct-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed

Date	22-Oct-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011546
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	22-Oct-2023
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00011546
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	22-Oct-2023
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed

Date	22-Oct-2023
Fault Code / Symptom	Engine Cooling System Monitor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011546
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	22-Oct-2023
Fault Code / Symptom	Engine Cooling System Monitor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	22-Oct-2023
Fault Code / Symptom	Ambient Air Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	22-Oct-2023
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	22-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	22-Oct-2023
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	22-Oct-2023
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	22-Oct-2023
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	22-Oct-2023
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	22-Oct-2023
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	08-Oct-2023
Fault Code / Symptom	Engine Valve Lash Setting - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	08-Oct-2023
Fault Code / Symptom	Engine Valve Lash Setting - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	06-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010114
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	06-Aug-2023
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010114
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	06-Aug-2023
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010114
Solution Title	Restricted intake air filter
Update Reason	Solution Added

Date	06-Aug-2023
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010114
Solution Title	Restricted intake air filter
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Lubricating Oil Pressure High
Solution Number	S00006036
Solution Title	Main lubricating oil pressure regulator is malfunctioning
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Lubricating Oil Pressure High
Solution Number	S00000331
Solution Title	Main lubricating oil pressure regulator is malfunctioning
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00006036
Solution Title	Main lubricating oil pressure regulator is malfunctioning
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00000331
Solution Title	Main lubricating oil pressure regulator is malfunctioning
Update Reason	Solution Removed

Date	30-Jul-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001453
Solution Title	Main lubricating oil pressure regulator is malfunctioning
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000469
Solution Title	Main lubricating oil pressure regulator is malfunctioning
Update Reason	Solution Removed
Date	30-Jul-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00001453
Solution Title	Main lubricating oil pressure regulator is malfunctioning
Update Reason	Solution Added
Date	30-Jul-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00000469
Solution Title	Main lubricating oil pressure regulator is malfunctioning
Update Reason	Solution Removed

Date	30-Jul-2023
Fault Code / Symptom	Engine Oil Rifle Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000469
Solution Title	Main lubricating oil pressure regulator is malfunctioning
Update Reason	Solution Removed
Date	16-Jul-2023
Fault Code / Symptom	Long-term Fuel Trim - Bank 1 - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	16-Jul-2023
Fault Code / Symptom	Long-term Fuel Trim - Bank 1 - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Does Not Activate
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Reordered
Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Does Not Activate
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Modified

Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Slow Activation
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Reordered
Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Slow Activation
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Modified
Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Stuck On
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Reordered
Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Stuck On
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Modified
Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Weak
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Reordered
Date	25-Jun-2023
Fault Code / Symptom	Engine Brake Weak
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Modified

Date	25-Jun-2023
Fault Code / Symptom	Vibration
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Reordered
Date	25-Jun-2023
Fault Code / Symptom	Vibration
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Modified
Date	25-Jun-2023
Fault Code / Symptom	Engine Fuel Shutoff Valve Feedback Position Does Not Match Desired - Root Cause Not Known
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	25-Jun-2023
Fault Code / Symptom	Engine Fuel Shutoff Valve Feedback Position Does Not Match Desired - Root Cause Not Known
Solution Number	S00005504
Solution Title	Intake manifold pressure sensor stuck in-range
Update Reason	Solution Removed
Date	25-Jun-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011305
Solution Title	EGR mass measurement flow assembly is leaking
Update Reason	Solution Added

Date	18-Jun-2023
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Reordered
Date	18-Jun-2023
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Modified
Date	11-Jun-2023
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	11-Jun-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation 1 Valve 1 Control 1 - Condition Exists
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	28-May-2023
Fault Code / Symptom	Engine Fuel Shutoff Valve Feedback Position Does Not Match Desired - Root Cause Not Known
Solution Number	S00009753
Solution Title	Fuel pressure check
Update Reason	Solution Added

Date	14-May-2023
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	14-May-2023
Fault Code / Symptom	EGR Mass Flow - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	14-May-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	14-May-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000778
Solution Title	Exhaust gas pressure sensor open circuit check
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008970
Solution Title	Exhaust gas pressure sensor circuit pin to pin short
Update Reason	Solution Removed

Date	14-May-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation Outlet Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	14-May-2023
Fault Code / Symptom	Engine Exhaust Gas Pressure 2 Sensor - Condition Exists
Solution Number	S00000778
Solution Title	Exhaust gas pressure sensor open circuit check
Update Reason	Solution Removed
Date	14-May-2023
Fault Code / Symptom	Engine Exhaust Gas Pressure 2 Sensor - Condition Exists
Solution Number	S00008970
Solution Title	Exhaust gas pressure sensor circuit pin to pin short
Update Reason	Solution Removed
Date	07-May-2023
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	07-May-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed

Date	07-May-2023
Fault Code / Symptom	Engine Exhaust Gas Recirculation 1 Valve 1 Control 1 - Condition Exists
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	07-May-2023
Fault Code / Symptom	Engine Exhaust Gas Pressure 2 Sensor - Condition Exists
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Critical Internal Failure - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Modified
Date	23-Apr-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00001983
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Reordered
Date	23-Apr-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00001983
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Modified

Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Calibration Memory - Bad Intelligent Device or Component
Solution Number	S00008831
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	23-Apr-2023
Fault Code / Symptom	Engine Control Module Calibration Memory - Bad Intelligent Device or Component
Solution Number	S00008078
Solution Title	Internal ECM Error
Update Reason	Solution Removed
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Outlet Gas Sensor Heater - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008452
Solution Title	Aftertreatment outlet oxygen sensor is malfunctioning
Update Reason	Solution Added
Date	09-Apr-2023
Fault Code / Symptom	Aftertreatment 1 Outlet Gas Sensor Heater - Data Erratic, Intermittent, or Incorrect
Solution Number	S00004151
Solution Title	Aftertreatment intake oxygen sensor is malfunctioning
Update Reason	Solution Removed
Date	02-Apr-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00011273
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	02-Apr-2023
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00001983
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Added
Date	02-Apr-2023
Fault Code / Symptom	Engine Cylinder 3 (A2) Knock - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005891
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added
Date	26-Mar-2023
Fault Code / Symptom	Engine Knock
Solution Number	S00001332
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Reordered
Date	26-Mar-2023
Fault Code / Symptom	Engine Knock
Solution Number	S00001332
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Modified
Date	26-Mar-2023
Fault Code / Symptom	Exhaust Noise
Solution Number	S00001332
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Reordered

Date	26-Mar-2023
Fault Code / Symptom	Exhaust Noise
Solution Number	S00001332
Solution Title	Cylinder head gasket or cylinder head is malfunctioning
Update Reason	Solution Modified
Date	26-Mar-2023
Fault Code / Symptom	High Blowby
Solution Number	S00011059
Solution Title	Service Bulletin is available
Update Reason	Solution Added
Date	26-Mar-2023
Fault Code / Symptom	Engine Fuel Valve 1 Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009753
Solution Title	Fuel pressure check
Update Reason	Solution Added
Date	19-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011115
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Added
Date	19-Mar-2023
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000352
Solution Title	Intake manifold pressure sensor circuit response
Update Reason	Solution Removed

Date	05-Mar-2023
Fault Code / Symptom	Engine Turbocharger 1 Boost Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	05-Mar-2023
Fault Code / Symptom	TSC1 Control Purpose - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	26-Feb-2023
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000362
Solution Title	Lubricating oil temperature sensor resistance check
Update Reason	Solution Removed
Date	26-Feb-2023
Fault Code / Symptom	Engine Oil Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000362
Solution Title	Lubricating oil temperature sensor resistance check
Update Reason	Solution Removed
Date	29-Jan-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011102
Solution Title	Exhaust gas pressure sensor is malfunctioning
Update Reason	Solution Added

Date	29-Jan-2023
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00003039
Solution Title	Exhaust gas pressure sensor is malfunctioning
Update Reason	Solution Removed
Date	22-Jan-2023
Fault Code / Symptom	Specific Humidity Sensor - Abnormal Update Rate
Solution Number	S00010346
Solution Title	Humidity sensor voltage check
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Specific Humidity Sensor - Abnormal Update Rate
Solution Number	S00010347
Solution Title	Humidity sensor relay voltage check
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Specific Humidity Sensor - Abnormal Update Rate
Solution Number	S00010348
Solution Title	Humidity sensor relay resistance check
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Specific Humidity Sensor - Abnormal Update Rate
Solution Number	S00010349
Solution Title	Humidity sensor circuit check
Update Reason	Solution Added

Date	22-Jan-2023
Fault Code / Symptom	Specific Humidity Sensor - Abnormal Update Rate
Solution Number	S00010370
Solution Title	Humidity sensor relay open circuit check
Update Reason	Solution Added
Date	22-Jan-2023
Fault Code / Symptom	Specific Humidity Sensor - Abnormal Update Rate
Solution Number	S00005834
Solution Title	Humidity sensor voltage check
Update Reason	Solution Removed
Date	22-Jan-2023
Fault Code / Symptom	Specific Humidity Sensor - Abnormal Update Rate
Solution Number	S00005840
Solution Title	Humidity sensor open circuit check
Update Reason	Solution Removed
Date	22-Jan-2023
Fault Code / Symptom	Specific Humidity Sensor - Abnormal Update Rate
Solution Number	S00007918
Solution Title	Humidity sensor relay open circuit check
Update Reason	Solution Removed
Date	15-Jan-2023
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00001200
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Removed
Date	01-Jan-2023
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added

Date	01-Jan-2023
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Fan Not Running/Erratic Running
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Fan Runs Continuously/Excessive Operation
Solution Number	S00011070
Solution Title	Fan control solenoid air line is malfunctioning
Update Reason	Solution Added
Date	01-Jan-2023
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Removed
Date	01-Jan-2023
Fault Code / Symptom	Engine Coolant Temperature 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000127
Solution Title	Coolant temperature sensor resistance check
Update Reason	Solution Removed
Date	20-Nov-2022
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011048
Solution Title	EGR valve circuit check
Update Reason	Solution Added

Date	20-Nov-2022
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	20-Nov-2022
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000720
Solution Title	EGR valve position sensor voltage check at the ECM
Update Reason	Solution Removed
Date	20-Nov-2022
Fault Code / Symptom	EGR Valve Position Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011048
Solution Title	EGR valve circuit check
Update Reason	Solution Added
Date	20-Nov-2022
Fault Code / Symptom	EGR Valve Position Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	20-Nov-2022
Fault Code / Symptom	EGR Valve Position Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000720
Solution Title	EGR valve position sensor voltage check at the ECM
Update Reason	Solution Removed

Date	20-Nov-2022
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	20-Nov-2022
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Speed - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	20-Nov-2022
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00011049
Solution Title	Wiring harness load test
Update Reason	Solution Added
Date	20-Nov-2022
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000877
Solution Title	Wiring harness load test
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00011047
Solution Title	Air intake system restricted
Update Reason	Solution Added

Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00011047
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00011047
Solution Title	Air intake system restricted
Update Reason	Solution Added
Date	13-Nov-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	13-Nov-2022
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed

Date	06-Nov-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00011032
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Added
Date	06-Nov-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Removed
Date	06-Nov-2022
Fault Code / Symptom	Overhead Noise
Solution Number	S00011032
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Added
Date	06-Nov-2022
Fault Code / Symptom	Overhead Noise
Solution Number	S00001315
Solution Title	Engine brake adjustment is incorrect
Update Reason	Solution Removed
Date	06-Nov-2022
Fault Code / Symptom	Engine Starter Motor Relay Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	06-Nov-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00004485
Solution Title	EGR valve is malfunctioning
Update Reason	Solution Added

Date	30-Oct-2022
Fault Code / Symptom	Tachograph Output Shaft Speed - Out of Calibration
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	16-Oct-2022
Fault Code / Symptom	Engine Knock
Solution Number	S00001344
Solution Title	Air compressor timing incorrect
Update Reason	Solution Removed
Date	16-Oct-2022
Fault Code / Symptom	Coolant Level Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00007921
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00010993
Solution Title	Low battery voltage
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Added
Date	09-Oct-2022
Fault Code / Symptom	No Communication with the Cummins Electronic Service Tool or Equivalent to ECM
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Added

Date	09-Oct-2022
Fault Code / Symptom	Network Transceiver Status 1 - Condition Exists
Solution Number	S00008075
Solution Title	Incorrect adjustable parameter setting
Update Reason	Solution Added
Date	02-Oct-2022
Fault Code / Symptom	Coolant Overflow
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Coolant Overflow
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered

Date	02-Oct-2022
Fault Code / Symptom	Coolant Temperature Low
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Fan Runs Continuously/Excessive Operation
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Fan Runs Continuously/Excessive Operation
Solution Number	S00001303
Solution Title	Coolant temperature sensor stuck in-range
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00000898
Solution Title	Starter magnetic switch is malfunctioning
Update Reason	Solution Reordered
Date	02-Oct-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00000898
Solution Title	Starter magnetic switch is malfunctioning
Update Reason	Solution Modified
Date	02-Oct-2022
Fault Code / Symptom	Cylinder L1 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00010838
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	02-Oct-2022
Fault Code / Symptom	Cylinder L2 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00010838
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	02-Oct-2022
Fault Code / Symptom	Cylinder L3 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00010838
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	02-Oct-2022
Fault Code / Symptom	Cylinder L4 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00010838
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	02-Oct-2022
Fault Code / Symptom	Cylinder L5 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00010838
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	02-Oct-2022
Fault Code / Symptom	Cylinder L6 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	S00010838
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	30-Aug-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00003976
Solution Title	Camshaft gear is damaged
Update Reason	Solution Removed
Date	30-Aug-2022
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00003976
Solution Title	Camshaft gear is damaged
Update Reason	Solution Removed
Date	21-Aug-2022
Fault Code / Symptom	Engine Fuel Shutoff Valve 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	21-Aug-2022
Fault Code / Symptom	Engine Fuel Shutoff Valve Driver 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	21-Aug-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	21-Aug-2022
Fault Code / Symptom	Ambient Air Temperature Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Ambient Air Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Ignition Timing Signal Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Ignition Timing Signal Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Ignition Control Signal Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	21-Aug-2022
Fault Code / Symptom	Ignition Control Signal Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 1 - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Engine Fuel Shutoff Valve Feedback Position Does Not Match Desired - Root Cause Not Known
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Outlet Oxygen Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Outlet Oxygen Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 3 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 3 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 3 - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 2 - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 3 - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Ambient Air Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor Circuit - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Outlet Oxygen Sensor Heater - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Outlet Oxygen Sensor Heater - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Ambient Air Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 2 - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Specific Humidity Sensor - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Specific Humidity Sensor - Received Network Data in Error
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted High
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Engine Cylinder #1 Ignition Timing - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Engine Cylinder #2 Ignition Timing - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Engine Cylinder #3 Ignition Timing - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Engine Cylinder #4 Ignition Timing - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	21-Aug-2022
Fault Code / Symptom	Engine Cylinder #5 Ignition Timing - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Engine Cylinder #6 Ignition Timing - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Three Way Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Engine Ignition Control Module #1 - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Outlet Gas Sensor Heater - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Abnormal Rate of Change
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor Heater Control - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Bad Intelligent Device or Component
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Engine Cylinder 1 Ignition Timing - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	21-Aug-2022
Fault Code / Symptom	Engine Cylinder 2 Ignition Timing - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Engine Cylinder 3 Ignition Timing - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Engine Cylinder 4 Ignition Timing - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Engine Cylinder 5 Ignition Timing - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Engine Cylinder 6 Ignition Timing - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	21-Aug-2022
Fault Code / Symptom	Cylinder L1 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Cylinder L2 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Cylinder L3 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Cylinder L4 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Cylinder L5 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	21-Aug-2022
Fault Code / Symptom	Cylinder L6 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	21-Aug-2022
Fault Code / Symptom	Aftertreatment 1 Three Way Catalyst Missing - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	07-Aug-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005891
Solution Title	Cylinder Leak Down Test
Update Reason	Solution Added
Date	24-Jul-2022
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00004028
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	24-Jul-2022
Fault Code / Symptom	Low Power
Solution Number	S00004028
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	10-Jul-2022
Fault Code / Symptom	Cylinder L1 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	10-Jul-2022
Fault Code / Symptom	Cylinder L2 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	10-Jul-2022
Fault Code / Symptom	Cylinder L3 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	10-Jul-2022
Fault Code / Symptom	Cylinder L4 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	10-Jul-2022
Fault Code / Symptom	Cylinder L5 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	10-Jul-2022
Fault Code / Symptom	Cylinder L6 Ignition Coil Secondary - Current Below Normal or Open Circuit
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	04-Jul-2022
Fault Code / Symptom	Transmission Engine Crank Enable - Abnormal Update Rate
Solution Number	S00003428
Solution Title	ECM data link malfunction
Update Reason	Solution Removed
Date	28-Jun-2022
Fault Code / Symptom	Engine Protection Torque Derate - Condition Exists
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Removed
Date	12-Jun-2022
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	12-Jun-2022
Fault Code / Symptom	Remote Accelerator Pedal or Lever Position Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	05-Jun-2022
Fault Code / Symptom	Network Transceiver Status 1 - Condition Exists
Solution Number	
Solution Title	
Update Reason	Solution Set Added

Date	15-May-2022
Fault Code / Symptom	EGR Mass Flow - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008242
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	EGR Mass Flow - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00008242
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008242
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008242
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00008242
Solution Title	Technical Service Bulletin is available
Update Reason	Solution Removed

Date	15-May-2022
Fault Code / Symptom	Exhaust Gas Bank 1 Pressure Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00008513
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009775
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Added
Date	15-May-2022
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008971
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000733
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Exhaust Gas Pressure 1 - Data Erratic, Intermittent, or Incorrect
Solution Number	S00008513
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed

Date	15-May-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000733
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001370
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000734
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00008513
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008513
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed

Date	15-May-2022
Fault Code / Symptom	Engine Exhaust Gas Pressure 2 Sensor - Condition Exists
Solution Number	S00009775
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Added
Date	15-May-2022
Fault Code / Symptom	Engine Exhaust Gas Pressure 2 Sensor - Condition Exists
Solution Number	S00008971
Solution Title	Plugged or damaged exhaust gas pressure sensor tube
Update Reason	Solution Removed
Date	15-May-2022
Fault Code / Symptom	Engine Exhaust Gas Pressure 2 Sensor - Condition Exists
Solution Number	S00000733
Solution Title	Exhaust gas pressure sensor stuck in-range
Update Reason	Solution Removed
Date	08-May-2022
Fault Code / Symptom	Coolant Level Low
Solution Number	S00010674
Solution Title	Verify coolant loss complaint
Update Reason	Solution Added
Date	08-May-2022
Fault Code / Symptom	Coolant Level Low
Solution Number	S00002251
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Removed
Date	08-May-2022
Fault Code / Symptom	Coolant Level Low
Solution Number	S00000747
Solution Title	Coolant level sensor open circuit check
Update Reason	Solution Removed

Date	08-May-2022
Fault Code / Symptom	Coolant Level Low
Solution Number	S00000748
Solution Title	Coolant level sensor circuit pin to ground short
Update Reason	Solution Removed
Date	08-May-2022
Fault Code / Symptom	Coolant Level Low
Solution Number	S00000749
Solution Title	Coolant level sensor circuit pin to pin short
Update Reason	Solution Removed
Date	08-May-2022
Fault Code / Symptom	Lubricating Oil in the Coolant
Solution Number	S00000975
Solution Title	Internally leaking turbocharger bearing housing
Update Reason	Solution Removed
Date	08-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Reordered
Date	08-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Modified

Date	08-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Reordered

Date	08-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Modified

Date	08-May-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Reordered

Date	08-May-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Modified

Date	08-May-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Reordered

Date	08-May-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Modified
Date	08-May-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001379
Solution Title	Battery load test
Update Reason	Solution Removed
Date	08-May-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001852
Solution Title	Fuse check
Update Reason	Solution Removed
Date	08-May-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000754
Solution Title	Ground inspection
Update Reason	Solution Removed
Date	08-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Reordered

Date	08-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Modified
Date	02-May-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000684
Solution Title	Engine crankshaft speed/position sensor check
Update Reason	Solution Added
Date	02-May-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009205
Solution Title	Crankshaft position sensor is damaged
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00003764
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00003764
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Removed

Date	02-May-2022
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00000684
Solution Title	Engine crankshaft speed/position sensor check
Update Reason	Solution Added
Date	02-May-2022
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00009205
Solution Title	Crankshaft position sensor is damaged
Update Reason	Solution Removed
Date	02-May-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00003764
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Removed
Date	17-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010538
Solution Title	Coolant level check
Update Reason	Solution Added
Date	17-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00010538
Solution Title	Coolant level check
Update Reason	Solution Added

Date	17-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010538
Solution Title	Coolant level check
Update Reason	Solution Added

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007852
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003764
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00010538
Solution Title	Coolant level check
Update Reason	Solution Added

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00007852
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00003764
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Engine Oil Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008424
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	17-Apr-2022
Fault Code / Symptom	Engine Oil Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005682
Solution Title	Lubricating oil cooler is leaking
Update Reason	Solution Added
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00010538
Solution Title	Coolant level check
Update Reason	Solution Added
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00007852
Solution Title	Missing or damaged coolant level sensor
Update Reason	Solution Removed
Date	17-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed

Date	17-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010538
Solution Title	Coolant level check
Update Reason	Solution Added
Date	17-Apr-2022
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	10-Apr-2022
Fault Code / Symptom	Coolant Level Low
Solution Number	S00006123
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	10-Apr-2022
Fault Code / Symptom	Coolant Level Low
Solution Number	S00004665
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Removed
Date	10-Apr-2022
Fault Code / Symptom	Aftertreatment 1 Three Way Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00007279
Solution Title	Fault Code 5111 requires that ALL solutions be performed
Update Reason	Solution Removed

Date	03-Apr-2022
Fault Code / Symptom	Coolant Level Low
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	03-Apr-2022
Fault Code / Symptom	Engine Brake Stuck On
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	03-Apr-2022
Fault Code / Symptom	Engine Decelerates Slowly
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	03-Apr-2022
Fault Code / Symptom	Fuel Knock
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	03-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00010587
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	03-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00010587
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	03-Apr-2022
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00010587
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	27-Mar-2022
Fault Code / Symptom	Charging System Alternator Not Charging or Insufficient Charging
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	27-Mar-2022
Fault Code / Symptom	Charging System Alternator Overcharging
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	27-Mar-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Ignition Timing Signal Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Ignition Timing Signal Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Ignition Timing Signal Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Ignition Timing Signal Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Ignition Control Signal Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Ignition Control Signal Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Ignition Control Signal Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Ignition Control Signal Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Electrical Charging System Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000706
Solution Title	Battery power removed by battery disconnect switch
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000706
Solution Title	Battery power removed by battery disconnect switch
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Modified

Date	27-Mar-2022
Fault Code / Symptom	Specific Humidity Sensor - Abnormal Update Rate
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Specific Humidity Sensor - Abnormal Update Rate
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation 1 Valve 1 Control 1 - Condition Exists
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered
Date	27-Mar-2022
Fault Code / Symptom	Engine Exhaust Gas Recirculation 1 Valve 1 Control 1 - Condition Exists
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	27-Mar-2022
Fault Code / Symptom	Engine Ignition Control Module #1 - Abnormal Update Rate
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Reordered

Date	27-Mar-2022
Fault Code / Symptom	Engine Ignition Control Module #1 - Abnormal Update Rate
Solution Number	S00000451
Solution Title	Battery or battery cables are malfunctioning
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	20-Mar-2022
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Black Smoke
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Crank No Start
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	20-Mar-2022
Fault Code / Symptom	Engine Stalls/Shutdown
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Exhaust Temperature High
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	20-Mar-2022
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Low Power
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Lubricating Oil in the Air Intake
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered

Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Compressor Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Reordered
Date	20-Mar-2022
Fault Code / Symptom	Turbocharger Turbine Seal Leaking Oil
Solution Number	S00000554
Solution Title	Restricted intake air filter
Update Reason	Solution Modified
Date	06-Mar-2022
Fault Code / Symptom	Belt Fraying/Belt Wear
Solution Number	S00009892
Solution Title	Cooling fan belt loose
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	Belt Fraying/Belt Wear
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Belt Noise/Whining
Solution Number	S00009892
Solution Title	Cooling fan belt loose
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Belt Noise/Whining
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Coolant Temperature High
Solution Number	S00006123
Solution Title	Cooling system component is leaking
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Brake Does Not Activate
Solution Number	S00006007
Solution Title	Engine brake assembly check
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Brake Slow Activation
Solution Number	S00006007
Solution Title	Engine brake assembly check
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	Engine Brake Weak
Solution Number	S00006007
Solution Title	Engine brake assembly check
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Decelerates Slowly
Solution Number	S00001317
Solution Title	Engine brake solenoid valve assembly is leaking
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Decelerates Slowly
Solution Number	S00001321
Solution Title	Engine brake solenoid valve is stuck open
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00009891
Solution Title	Front end belt driven accessories
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	External Coolant Leak
Solution Number	S00006123
Solution Title	Cooling system component is leaking
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	External Coolant Leak
Solution Number	S00001211
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Fan Not Running/Erratic Running
Solution Number	S00009892
Solution Title	Cooling fan belt loose
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Internal Coolant Leak
Solution Number	S00006123
Solution Title	Cooling system component is leaking
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Internal Coolant Leak
Solution Number	S00001211
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00009693
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Vibration
Solution Number	S00009891
Solution Title	Front end belt driven accessories
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	Vibration
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009784
Solution Title	Charge air cooler system leak
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009783
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006382
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	06-Mar-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006382
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	06-Mar-2022
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006382
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	06-Mar-2022
Fault Code / Symptom	Aftertreatment Exhaust Gas Temperature 1 - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006382
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	06-Mar-2022
Fault Code / Symptom	EGR Mass Flow - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009783
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	EGR Mass Flow - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009783
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006382
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	EGR Valve Controller - Out of Calibration
Solution Number	S00006382
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006382
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009784
Solution Title	Charge air cooler system leak
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009783
Solution Title	Leaks in the exhaust system
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006382
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006382
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006382
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00009823
Solution Title	Charge air cooler drain valve plugged or damaged
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00009823
Solution Title	Charge air cooler drain valve plugged or damaged
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00009823
Solution Title	Charge air cooler drain valve plugged or damaged
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00009823
Solution Title	Charge air cooler drain valve plugged or damaged
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00009823
Solution Title	Charge air cooler drain valve plugged or damaged
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00009823
Solution Title	Charge air cooler drain valve plugged or damaged
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00009823
Solution Title	Charge air cooler drain valve plugged or damaged
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009823
Solution Title	Charge air cooler drain valve plugged or damaged
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009823
Solution Title	Charge air cooler drain valve plugged or damaged
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder 2 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009823
Solution Title	Charge air cooler drain valve plugged or damaged
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder 2 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder 3 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009823
Solution Title	Charge air cooler drain valve plugged or damaged
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder 3 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder 4 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009823
Solution Title	Charge air cooler drain valve plugged or damaged
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder 4 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added

Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder 5 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009823
Solution Title	Charge air cooler drain valve plugged or damaged
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder 5 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder 6 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009823
Solution Title	Charge air cooler drain valve plugged or damaged
Update Reason	Solution Added
Date	06-Mar-2022
Fault Code / Symptom	Engine Misfire Cylinder 6 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009077
Solution Title	Leaks in the intake air system
Update Reason	Solution Added
Date	20-Feb-2022
Fault Code / Symptom	Vibration
Solution Number	S00001949
Solution Title	Engine mounts are damaged
Update Reason	Solution Reordered

Date	20-Feb-2022
Fault Code / Symptom	Vibration
Solution Number	S00001949
Solution Title	Engine mounts are damaged
Update Reason	Solution Modified
Date	13-Feb-2022
Fault Code / Symptom	Belt Fraying/Belt Wear
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Reordered
Date	13-Feb-2022
Fault Code / Symptom	Belt Fraying/Belt Wear
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Modified
Date	13-Feb-2022
Fault Code / Symptom	Belt Noise/Whining
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Reordered
Date	13-Feb-2022
Fault Code / Symptom	Belt Noise/Whining
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Modified
Date	13-Feb-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Reordered

Date	13-Feb-2022
Fault Code / Symptom	Engine Noise
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Modified
Date	13-Feb-2022
Fault Code / Symptom	Vibration
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Reordered
Date	13-Feb-2022
Fault Code / Symptom	Vibration
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Modified
Date	13-Feb-2022
Fault Code / Symptom	Engine Brake Actuator Driver 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00001622
Solution Title	ECM Malfunction
Update Reason	Solution Removed
Date	13-Feb-2022
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00003168
Solution Title	Loose or damaged engine brake wiring harness connector
Update Reason	Solution Added

Date	13-Feb-2022
Fault Code / Symptom	Engine Brake Actuator Driver Output 2 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00003168
Solution Title	Loose or damaged engine brake wiring harness connector
Update Reason	Solution Added
Date	30-Jan-2022
Fault Code / Symptom	Cranks Slowly
Solution Number	S00005058
Solution Title	Engine Compression Test
Update Reason	Solution Removed
Date	30-Jan-2022
Fault Code / Symptom	Will Not Crank
Solution Number	S00005058
Solution Title	Engine Compression Test
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Coolant Overflow
Solution Number	S00002071
Solution Title	Cooling system pressure cap is malfunctioning
Update Reason	Solution Reordered
Date	09-Jan-2022
Fault Code / Symptom	Coolant Overflow
Solution Number	S00002071
Solution Title	Cooling system pressure cap is malfunctioning
Update Reason	Solution Modified
Date	09-Jan-2022
Fault Code / Symptom	Crank No Start
Solution Number	S00001852
Solution Title	Fuse check
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Crank No Start
Solution Number	S00008710
Solution Title	Blown or incorrect OEM fuse installation
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00001852
Solution Title	Fuse check
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Hard Start/Long Crank Time
Solution Number	S00008710
Solution Title	Blown or incorrect OEM fuse installation
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006413
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Cylinder 1 (A1) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Cylinder 1 (A1) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006413
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Cylinder 2 (B1) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Cylinder 2 (B1) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006413
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Cylinder 3 (A2) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Cylinder 3 (A2) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006413
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Cylinder 4 (B2) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Cylinder 4 (B2) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006413
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Engine Cylinder 5 (A3) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Cylinder 5 (A3) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006413
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Cylinder 6 (B3) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Cylinder 6 (B3) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006413
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed

Date	09-Jan-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001852
Solution Title	Fuse check
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000753
Solution Title	Fuse/distribution panel check
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006413
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added

Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006413
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002135
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Added
Date	09-Jan-2022
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00006413
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	12-Dec-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	S00010126
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Added
Date	12-Dec-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00010126
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Added

Date	12-Dec-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000341
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Removed
Date	12-Dec-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00010126
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Added
Date	12-Dec-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000341
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Removed
Date	05-Dec-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00008484
Solution Title	Overhead component damaged or out of adjustment
Update Reason	Solution Added
Date	05-Dec-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added

Date	05-Dec-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006382
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Added
Date	05-Dec-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00004561
Solution Title	Intake manifold temperature sensor stuck in-range
Update Reason	Solution Added
Date	05-Dec-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added
Date	29-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Added
Date	29-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000484
Solution Title	Radiator shutters malfunctioning (if equipped)
Update Reason	Solution Added

Date	29-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00003764
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Vibration
Solution Number	S00004003
Solution Title	Flywheel or flexplate is damaged or loose
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00002207
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added

Date	14-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00003142
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000476
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed

Date	14-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000476
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Added

Date	14-Nov-2021
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00003142
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00003142
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Turbocharger 1 Compressor Intake Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	14-Nov-2021
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Coolant Level - Data Valid But Below Normal Operating Range - Least Severe Level
Solution Number	S00003142
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002207
Solution Title	Check for primary fault codes
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00002155
Solution Title	Cooling system component is leaking
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added

Date	14-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00003142
Solution Title	Cooling system component is leaking
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000476
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed
Date	14-Nov-2021
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000025
Solution Title	Restricted intake air filter
Update Reason	Solution Removed

Date	14-Nov-2021
Fault Code / Symptom	Engine Cooling System Monitor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005206
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Added
Date	14-Nov-2021
Fault Code / Symptom	Engine Cooling System Monitor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000476
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00007493
Solution Title	Keyswitch open circuit check
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	Engine Control Module Warning Internal Hardware Failure - Bad Intelligent Device or Component
Solution Number	S00000530
Solution Title	Keyswitch open circuit check
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000530
Solution Title	Keyswitch open circuit check
Update Reason	Solution Removed

Date	31-Oct-2021
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006422
Solution Title	Ice buildup in the air system components
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007344
Solution Title	EGR valve plugged or restricted with ice
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001254
Solution Title	Incorrect air compressor discharge line routing
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001255
Solution Title	Air compressor discharge line plugged or restricted with ice
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009334
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Added

Date	31-Oct-2021
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009332
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00007820
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed

Date	31-Oct-2021
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009334
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009332
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed

Date	31-Oct-2021
Fault Code / Symptom	Intake Manifold 1 Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00007820
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000457
Solution Title	Intake manifold pressure sensor voltage check
Update Reason	Solution Removed

Date	31-Oct-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000758
Solution Title	Intake manifold pressure sensor voltage check at the ECM
Update Reason	Solution Removed
Date	31-Oct-2021
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00006422
Solution Title	Ice buildup in the air system components
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00007344
Solution Title	EGR valve plugged or restricted with ice
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001254
Solution Title	Incorrect air compressor discharge line routing
Update Reason	Solution Added
Date	31-Oct-2021
Fault Code / Symptom	EGR Valve Position - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001255
Solution Title	Air compressor discharge line plugged or restricted with ice
Update Reason	Solution Added

Date	31-Oct-2021
Fault Code / Symptom	Engine Crankcase Breather Oil Separator Speed - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	24-Oct-2021
Fault Code / Symptom	Engine Oil Change Interval - Condition Exists
Solution Number	S00000671
Solution Title	Oil change interval maintenance warning
Update Reason	Solution Reordered
Date	24-Oct-2021
Fault Code / Symptom	Engine Oil Change Interval - Condition Exists
Solution Number	S00000671
Solution Title	Oil change interval maintenance warning
Update Reason	Solution Modified
Date	10-Oct-2021
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	10-Oct-2021
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	10-Oct-2021
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	10-Oct-2021
Fault Code / Symptom	Crankcase Pressure Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	10-Oct-2021
Fault Code / Symptom	Engine Crankcase Ventilation Hose Disconnected - Condition Exists
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	10-Oct-2021
Fault Code / Symptom	Closed Crankcase Ventilation System Pressure Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	10-Oct-2021
Fault Code / Symptom	Closed Crankcase Ventilation System Pressure Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	10-Oct-2021
Fault Code / Symptom	Closed Crankcase Ventilation System Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Air Leak Noise
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Continuous Operation/Frequent Cycling
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Pumping Lubricating Oil
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Air Compressor Will Not Pump Air
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Black Smoke
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed

Date	19-Sep-2021
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Low Power
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	19-Sep-2021
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00002738
Solution Title	Charge air cooler or exhaust system leak
Update Reason	Solution Removed
Date	12-Sep-2021
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00003013
Solution Title	Loose or broken lubricating oil suction tube
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001642
Solution Title	Loose or broken lubricating oil suction tube
Update Reason	Solution Removed
Date	12-Sep-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Added

Date	12-Sep-2021
Fault Code / Symptom	Battery 1 Voltage - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001686
Solution Title	Cooling fan component inspection
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	EGR Valve Control Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00000773
Solution Title	EGR valve motor resistance check
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	EGR Valve Control Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00009037
Solution Title	EGR valve motor resistance check
Update Reason	Solution Removed
Date	12-Sep-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006419
Solution Title	EGR cooler is contaminated
Update Reason	Solution Removed

Date	12-Sep-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006419
Solution Title	EGR cooler is contaminated
Update Reason	Solution Removed

Date	12-Sep-2021
Fault Code / Symptom	Engine Control Module Calibration Memory - Bad Intelligent Device or Component
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	12-Sep-2021
Fault Code / Symptom	Engine Starter Mode Overcrank Protection - Condition Exists
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	12-Sep-2021
Fault Code / Symptom	Security Device - Abnormal Update Rate
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	12-Sep-2021
Fault Code / Symptom	Security Device - Data Erratic, Intermittent, or Incorrect
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added

Date	12-Sep-2021
Fault Code / Symptom	Transmission Engine Crank Enable - Received Network Data in Error
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	Transmission Engine Crank Enable - Abnormal Update Rate
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	12-Sep-2021
Fault Code / Symptom	Engine/Transmission Match - Out of Calibration
Solution Number	S00000443
Solution Title	ECM calibration revision history check
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Belt Fraying/Belt Wear
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Belt Fraying/Belt Wear
Solution Number	S00002948
Solution Title	Cooling fan belt loose
Update Reason	Solution Removed
Date	25-Aug-2021
Fault Code / Symptom	Belt Noise/Whining
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Added

Date	25-Aug-2021
Fault Code / Symptom	Belt Noise/Whining
Solution Number	S00002948
Solution Title	Cooling fan belt loose
Update Reason	Solution Removed
Date	25-Aug-2021
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Reordered
Date	25-Aug-2021
Fault Code / Symptom	Crank No Start
Solution Number	S00001276
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Modified
Date	25-Aug-2021
Fault Code / Symptom	Engine Noise
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Fan Not Running/Erratic Running
Solution Number	S00008162
Solution Title	Cooling fan belt loose
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Fan Not Running/Erratic Running
Solution Number	S00002948
Solution Title	Cooling fan belt loose
Update Reason	Solution Removed

Date	25-Aug-2021
Fault Code / Symptom	Lubricating Oil Filter Plugging
Solution Number	S00001886
Solution Title	Incorrect lubricating oil filter
Update Reason	Solution Added
Date	25-Aug-2021
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001886
Solution Title	Incorrect lubricating oil filter
Update Reason	Solution Reordered
Date	25-Aug-2021
Fault Code / Symptom	Lubricating Oil Pressure Low
Solution Number	S00001886
Solution Title	Incorrect lubricating oil filter
Update Reason	Solution Modified
Date	25-Aug-2021
Fault Code / Symptom	Vibration
Solution Number	S00004458
Solution Title	Front end belt driven accessories
Update Reason	Solution Added
Date	15-Aug-2021
Fault Code / Symptom	Air Compressor Pumping Coolant
Solution Number	S00001213
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (single cylinder)
Update Reason	Solution Removed
Date	15-Aug-2021
Fault Code / Symptom	Coolant Overflow
Solution Number	S00001213
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (single cylinder)
Update Reason	Solution Removed

Date	15-Aug-2021
Fault Code / Symptom	Coolant in the Lubricating Oil
Solution Number	S00001213
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (single cylinder)
Update Reason	Solution Removed
Date	15-Aug-2021
Fault Code / Symptom	Internal Coolant Leak
Solution Number	S00001213
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (single cylinder)
Update Reason	Solution Removed
Date	08-Aug-2021
Fault Code / Symptom	Accelerator Pedal Position 1 - Abnormal Update Rate
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	08-Aug-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000485
Solution Title	Radiator is externally obstructed
Update Reason	Solution Added
Date	08-Aug-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Added

Date	08-Aug-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Added
Date	02-Aug-2021
Fault Code / Symptom	Black Smoke
Solution Number	S00003589
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	02-Aug-2021
Fault Code / Symptom	Blue Smoke
Solution Number	S00003589
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	02-Aug-2021
Fault Code / Symptom	Engine Noise
Solution Number	S00003589
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	02-Aug-2021
Fault Code / Symptom	Fuel Consumption Excessive
Solution Number	S00003589
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed

Date	02-Aug-2021
Fault Code / Symptom	Low Power
Solution Number	S00003589
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	02-Aug-2021
Fault Code / Symptom	Turbocharger Noise
Solution Number	S00003589
Solution Title	Turbocharger wastegate actuator is malfunctioning
Update Reason	Solution Removed
Date	25-Jul-2021
Fault Code / Symptom	Runs Rough or Misfires
Solution Number	S00009693
Solution Title	Exhaust leak visual check
Update Reason	Solution Added
Date	12-Jul-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000785
Solution Title	Thermostat is malfunctioning
Update Reason	Solution Removed
Date	12-Jul-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00001359
Solution Title	Out-of-chassis opening temperature test
Update Reason	Solution Removed

Date	12-Jul-2021
Fault Code / Symptom	Ambient Air Temperature Sensor 1 Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	12-Jul-2021
Fault Code / Symptom	Ambient Air Temperature Sensor 1 Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	12-Jul-2021
Fault Code / Symptom	Engine Cylinder 2 (B1) Knock - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	12-Jul-2021
Fault Code / Symptom	Engine Cylinder 5 (A3) Knock - Voltage Below Normal or Shorted to Low Source
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	12-Jul-2021
Fault Code / Symptom	Ambient Air Temperature - Data Erratic, Intermittent, or Incorrect
Solution Number	
Solution Title	
Update Reason	Overview Modified

Date	12-Jul-2021
Fault Code / Symptom	Ambient Air Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	05-Jul-2021
Fault Code / Symptom	Air Compressor Pumping Coolant
Solution Number	S00009574
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (two cylinder)
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Coolant Overflow
Solution Number	S00009574
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (two cylinder)
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Coolant in the Lubricating Oil
Solution Number	S00009574
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (two cylinder)
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Internal Coolant Leak
Solution Number	S00009574
Solution Title	Air compressor cylinder head gasket or cylinder head is malfunctioning (two cylinder)
Update Reason	Solution Added

Date	05-Jul-2021
Fault Code / Symptom	EGR Mass Flow - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009577
Solution Title	Exhaust leak visual check
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	EGR Mass Flow - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001143
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009577
Solution Title	Exhaust leak visual check
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00001143
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009577
Solution Title	Exhaust leak visual check
Update Reason	Solution Added

Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment Intake Oxygen Sensor - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001143
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted High
Solution Number	S00009577
Solution Title	Exhaust leak visual check
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted High
Solution Number	S00001143
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted Low
Solution Number	S00009577
Solution Title	Exhaust leak visual check
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Intake Oxygen Sensor - Data Not Rational - Drifted Low
Solution Number	S00001143
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed

Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted High
Solution Number	S00009577
Solution Title	Exhaust leak visual check
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted High
Solution Number	S00001143
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	S00009577
Solution Title	Exhaust leak visual check
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Outlet Oxygen - Data Not Rational - Drifted Low
Solution Number	S00001143
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Three Way Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009576
Solution Title	EGR cooler is internally leaking
Update Reason	Solution Added

Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Three Way Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00001143
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Three Way Catalyst Missing - Condition Exists
Solution Number	S00009577
Solution Title	Exhaust leak visual check
Update Reason	Solution Added
Date	05-Jul-2021
Fault Code / Symptom	Aftertreatment 1 Three Way Catalyst Missing - Condition Exists
Solution Number	S00001143
Solution Title	Exhaust leak visual check
Update Reason	Solution Removed
Date	21-Jun-2021
Fault Code / Symptom	Closed Crankcase Ventilation System Pressure Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009062
Solution Title	Closed crankcase ventilation system pressure sensor circuit response at the ECM
Update Reason	Solution Added
Date	14-Jun-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000476
Solution Title	Fan clutch operates incorrectly
Update Reason	Solution Removed

Date	09-Jun-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	09-Jun-2021
Fault Code / Symptom	Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000490
Solution Title	Malfunctioning cooling fan drive or cooling fan controls
Update Reason	Solution Added
Date	09-Jun-2021
Fault Code / Symptom	EGR Mass Flow - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009275
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	30-May-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added
Date	30-May-2021
Fault Code / Symptom	Intake Manifold 1 Temperature - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed

Date	30-May-2021
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	30-May-2021
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed

Date	30-May-2021
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	30-May-2021
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 1 (A1) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 1 (A1) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 2 (B1) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 2 (B1) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 3 (A2) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 3 (A2) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 4 (B2) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 4 (B2) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 5 (A3) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 5 (A3) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 6 (B3) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 6 (B3) Knock - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 1 (A1) Knock - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 1 (A1) Knock - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 2 (B1) Knock - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 2 (B1) Knock - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 3 (A2) Knock - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 3 (A2) Knock - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 4 (B2) Knock - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 4 (B2) Knock - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 5 (A3) Knock - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 5 (A3) Knock - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed
Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 6 (B3) Knock - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added
Date	30-May-2021
Fault Code / Symptom	Engine Cylinder 6 (B3) Knock - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00006439
Solution Title	Engine Compression Test
Update Reason	Solution Removed
Date	23-May-2021
Fault Code / Symptom	Aftertreatment 1 Three Way Catalyst Missing - Condition Exists
Solution Number	
Solution Title	
Update Reason	Solution Set Added
Date	23-May-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002446
Solution Title	Check for primary fault codes
Update Reason	Solution Added

Date	23-May-2021
Fault Code / Symptom	Intake Manifold 1 Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00002000
Solution Title	Check for primary fault codes
Update Reason	Solution Removed
Date	23-May-2021
Fault Code / Symptom	Aftertreatment 1 Three Way Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	23-May-2021
Fault Code / Symptom	Aftertreatment 1 Three Way Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009259
Solution Title	Primary three way catalyst is malfunctioning
Update Reason	Solution Added
Date	23-May-2021
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00008632
Solution Title	Ignition/injector control module is malfunctioning
Update Reason	Solution Added
Date	23-May-2021
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00008632
Solution Title	Ignition/injector control module is malfunctioning
Update Reason	Solution Added

Date	23-May-2021
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00008632
Solution Title	Ignition/injector control module is malfunctioning
Update Reason	Solution Added

Date	23-May-2021
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00008632
Solution Title	Ignition/injector control module is malfunctioning
Update Reason	Solution Added

Date	23-May-2021
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00008632
Solution Title	Ignition/injector control module is malfunctioning
Update Reason	Solution Added

Date	23-May-2021
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00008632
Solution Title	Ignition/injector control module is malfunctioning
Update Reason	Solution Added

Date	23-May-2021
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00008632
Solution Title	Ignition/injector control module is malfunctioning
Update Reason	Solution Added

Date	23-May-2021
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008632
Solution Title	Ignition/injector control module is malfunctioning
Update Reason	Solution Added
Date	23-May-2021
Fault Code / Symptom	Engine Misfire Cylinder 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008632
Solution Title	Ignition/injector control module is malfunctioning
Update Reason	Solution Added
Date	23-May-2021
Fault Code / Symptom	Engine Misfire Cylinder 2 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008632
Solution Title	Ignition/injector control module is malfunctioning
Update Reason	Solution Added
Date	23-May-2021
Fault Code / Symptom	Engine Misfire Cylinder 3 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008632
Solution Title	Ignition/injector control module is malfunctioning
Update Reason	Solution Added

Date	23-May-2021
Fault Code / Symptom	Engine Misfire Cylinder 4 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008632
Solution Title	Ignition/injector control module is malfunctioning
Update Reason	Solution Added
Date	23-May-2021
Fault Code / Symptom	Engine Misfire Cylinder 5 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008632
Solution Title	Ignition/injector control module is malfunctioning
Update Reason	Solution Added
Date	23-May-2021
Fault Code / Symptom	Engine Misfire Cylinder 6 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00008632
Solution Title	Ignition/injector control module is malfunctioning
Update Reason	Solution Added
Date	16-May-2021
Fault Code / Symptom	EGR Mass Flow - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009275
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added

Date	16-May-2021
Fault Code / Symptom	Exhaust Gas Recirculation Differential Pressure - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009275
Solution Title	Plugged EGR differential pressure sensor supply ports
Update Reason	Solution Added
Date	16-May-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000341
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	16-May-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Least Severe Level
Solution Number	S00000341
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Modified
Date	16-May-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000341
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Reordered
Date	16-May-2021
Fault Code / Symptom	Exhaust Gas Recirculation Temperature - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000341
Solution Title	EGR temperature sensor stuck in-range
Update Reason	Solution Modified

Date	16-May-2021
Fault Code / Symptom	Aftertreatment 1 Three Way Catalyst Conversion Efficiency - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00004334
Solution Title	Exhaust catalyst is malfunctioning
Update Reason	Solution Removed
Date	09-May-2021
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00009205
Solution Title	Crankshaft position sensor is damaged
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002938
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Removed
Date	09-May-2021
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00009205
Solution Title	Crankshaft position sensor is damaged
Update Reason	Solution Added

Date	09-May-2021
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Engine Speed/Position Camshaft and Crankshaft Misalignment - Mechanical System Not Responding or Out of Adjustment
Solution Number	S00002938
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Removed
Date	09-May-2021
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002938
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Removed
Date	09-May-2021
Fault Code / Symptom	Engine Fuel Shutoff Valve Feedback Position Does Not Match Desired - Root Cause Not Known
Solution Number	S00009221
Solution Title	OEM fuel system component check
Update Reason	Solution Added

Date	09-May-2021
Fault Code / Symptom	Engine Fuel Shutoff Valve Feedback Position Does Not Match Desired - Root Cause Not Known
Solution Number	S00005679
Solution Title	Fuel level check
Update Reason	Solution Removed
Date	09-May-2021
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00001226
Solution Title	Camshaft position sensor is damaged
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002938
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Removed
Date	09-May-2021
Fault Code / Symptom	EGR Valve Control Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00009037
Solution Title	EGR valve motor resistance check
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Engine Fuel Valve 1 Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00009221
Solution Title	OEM fuel system component check
Update Reason	Solution Added

Date	09-May-2021
Fault Code / Symptom	Engine Fuel Valve 1 Intake Pressure - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	S00005679
Solution Title	Fuel level check
Update Reason	Solution Removed
Date	09-May-2021
Fault Code / Symptom	Engine Fuel Valve 1 Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00009221
Solution Title	OEM fuel system component check
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Engine Fuel Valve 1 Intake Pressure - Data Valid But Below Normal Operating Range - Most Severe Level
Solution Number	S00005679
Solution Title	Fuel level check
Update Reason	Solution Removed
Date	09-May-2021
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00009221
Solution Title	OEM fuel system component check
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Root Cause Not Known
Solution Number	S00005679
Solution Title	Fuel level check
Update Reason	Solution Removed

Date	09-May-2021
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009221
Solution Title	OEM fuel system component check
Update Reason	Solution Added
Date	09-May-2021
Fault Code / Symptom	Engine Misfire for Multiple Cylinders - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00005679
Solution Title	Fuel level check
Update Reason	Solution Removed
Date	09-May-2021
Fault Code / Symptom	Engine Fuel Intake Pressure Sensor - Data Not Rational - Drifted High
Solution Number	S00005679
Solution Title	Fuel level check
Update Reason	Solution Removed
Date	09-May-2021
Fault Code / Symptom	Engine Fuel Intake Pressure Sensor - Data Not Rational - Drifted Low
Solution Number	S00005679
Solution Title	Fuel level check
Update Reason	Solution Removed
Date	02-May-2021
Fault Code / Symptom	Engine Speed Surges
Solution Number	
Solution Title	
Update Reason	Solution Set Removed

Date	02-May-2021
Fault Code / Symptom	Erratic Idle Speed
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-May-2021
Fault Code / Symptom	Fuel Smell
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-May-2021
Fault Code / Symptom	Gear Whine Noise
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	02-May-2021
Fault Code / Symptom	No Communication ECM to Component
Solution Number	
Solution Title	
Update Reason	Solution Set Removed
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified

Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered

Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified

Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 1 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 5 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered

Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 3 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 6 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 2 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified

Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 4 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 7 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 7 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 8 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered

Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 8 Circuit - Current Below Normal or Open Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 8 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 8 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 7 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Reordered
Date	27-Apr-2021
Fault Code / Symptom	Injector Solenoid Driver 7 Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00008689
Solution Title	Fuel injector solenoid resistance check
Update Reason	Solution Modified
Date	18-Apr-2021
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Reordered

Date	18-Apr-2021
Fault Code / Symptom	Cranks Slowly
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Modified
Date	18-Apr-2021
Fault Code / Symptom	Will Not Crank
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Reordered
Date	18-Apr-2021
Fault Code / Symptom	Will Not Crank
Solution Number	S00001223
Solution Title	Solenoid on starter motor is malfunctioning
Update Reason	Solution Modified
Date	18-Apr-2021
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00000626
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed
Date	18-Apr-2021
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00000626
Solution Title	Plugged external crankcase breather tube
Update Reason	Solution Removed
Date	20-Apr-2021
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009066
Solution Title	Lubricating oil level is incorrect
Update Reason	Solution Added

Date	20-Apr-2021
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00003234
Solution Title	Lubricating oil level is incorrect
Update Reason	Solution Removed

Date	20-Apr-2021
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00009066
Solution Title	Lubricating oil level is incorrect
Update Reason	Solution Added

Date	20-Apr-2021
Fault Code / Symptom	Crankcase Pressure - Data Valid But Above Normal Operating Range - Most Severe Level
Solution Number	S00003234
Solution Title	Lubricating oil level is incorrect
Update Reason	Solution Removed

Date	20-Apr-2021
Fault Code / Symptom	Closed Crankcase Ventilation System Pressure Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00009059
Solution Title	Closed crankcase ventilation system pressure sensor circuit response
Update Reason	Solution Added

Date	20-Apr-2021
Fault Code / Symptom	Closed Crankcase Ventilation System Pressure Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00009060
Solution Title	Closed crankcase ventilation system pressure sensor circuit response at the ECM
Update Reason	Solution Added

Date	20-Apr-2021
Fault Code / Symptom	Closed Crankcase Ventilation System Pressure Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00006467
Solution Title	Closed crankcase ventilation system pressure sensor circuit response
Update Reason	Solution Removed
Date	20-Apr-2021
Fault Code / Symptom	Closed Crankcase Ventilation System Pressure Sensor - Voltage Above Normal or Shorted to High Source
Solution Number	S00006427
Solution Title	Closed crankcase ventilation system pressure sensor circuit response at the ECM
Update Reason	Solution Removed
Date	20-Apr-2021
Fault Code / Symptom	Closed Crankcase Ventilation System Pressure Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009061
Solution Title	Closed crankcase ventilation system pressure sensor circuit response
Update Reason	Solution Added
Date	20-Apr-2021
Fault Code / Symptom	Closed Crankcase Ventilation System Pressure Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006466
Solution Title	Closed crankcase ventilation system pressure sensor circuit response
Update Reason	Solution Removed

Date	20-Apr-2021
Fault Code / Symptom	Closed Crankcase Ventilation System Pressure Sensor - Voltage Below Normal or Shorted to Low Source
Solution Number	S00006431
Solution Title	Closed crankcase ventilation system pressure sensor circuit response at the ECM
Update Reason	Solution Removed
Date	29-Mar-2021
Fault Code / Symptom	EGR Valve Control Circuit - Current Above Normal or Grounded Circuit
Solution Number	S00009022
Solution Title	ECM Malfunction
Update Reason	Solution Added
Date	23-Mar-2021
Fault Code / Symptom	Engine Noise
Solution Number	S00005058
Solution Title	Engine Compression Test
Update Reason	Solution Removed
Date	23-Mar-2021
Fault Code / Symptom	Engine Magnetic Speed/Position Lost Both of Two Signals - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002938
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Added
Date	23-Mar-2021
Fault Code / Symptom	Throttle Position 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009001
Solution Title	Throttle position sensor voltage check
Update Reason	Solution Added

Date	23-Mar-2021
Fault Code / Symptom	Throttle Position 1 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009002
Solution Title	Throttle position sensor voltage check at the ECM
Update Reason	Solution Added
Date	23-Mar-2021
Fault Code / Symptom	Throttle Position 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009001
Solution Title	Throttle position sensor voltage check
Update Reason	Solution Added
Date	23-Mar-2021
Fault Code / Symptom	Throttle Position 1 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009002
Solution Title	Throttle position sensor voltage check at the ECM
Update Reason	Solution Added
Date	23-Mar-2021
Fault Code / Symptom	Engine Camshaft Speed/Position Sensor - Data Erratic, Intermittent, or Incorrect
Solution Number	S00002938
Solution Title	Crankshaft/camshaft sensor
Update Reason	Solution Added
Date	23-Mar-2021
Fault Code / Symptom	Throttle Position 2 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009001
Solution Title	Throttle position sensor voltage check
Update Reason	Solution Added

Date	23-Mar-2021
Fault Code / Symptom	Throttle Position 2 Sensor Circuit - Voltage Above Normal or Shorted to High Source
Solution Number	S00009002
Solution Title	Throttle position sensor voltage check at the ECM
Update Reason	Solution Added
Date	23-Mar-2021
Fault Code / Symptom	Throttle Position 2 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009001
Solution Title	Throttle position sensor voltage check
Update Reason	Solution Added
Date	23-Mar-2021
Fault Code / Symptom	Throttle Position 2 Sensor Circuit - Voltage Below Normal or Shorted to Low Source
Solution Number	S00009002
Solution Title	Throttle position sensor voltage check at the ECM
Update Reason	Solution Added
Date	23-Mar-2021
Fault Code / Symptom	Engine Intake Air Mass Flow - Data Valid But Below Normal Operating Range - Moderately Severe Level
Solution Number	
Solution Title	
Update Reason	Overview Modified
Date	23-Mar-2021
Fault Code / Symptom	Engine Misfire Cylinder #1 - Root Cause Not Known
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	23-Mar-2021
Fault Code / Symptom	Engine Misfire Cylinder #2 - Root Cause Not Known
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	23-Mar-2021
Fault Code / Symptom	Engine Misfire Cylinder #3 - Root Cause Not Known
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	23-Mar-2021
Fault Code / Symptom	Engine Misfire Cylinder #4 - Root Cause Not Known
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	23-Mar-2021
Fault Code / Symptom	Engine Misfire Cylinder #5 - Root Cause Not Known
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	23-Mar-2021
Fault Code / Symptom	Engine Misfire Cylinder #6 - Root Cause Not Known
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	23-Mar-2021
Fault Code / Symptom	Engine Misfire Cylinder 1 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	23-Mar-2021
Fault Code / Symptom	Engine Misfire Cylinder 2 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	23-Mar-2021
Fault Code / Symptom	Engine Misfire Cylinder 3 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	23-Mar-2021
Fault Code / Symptom	Engine Misfire Cylinder 4 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	23-Mar-2021
Fault Code / Symptom	Engine Misfire Cylinder 5 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added

Date	23-Mar-2021
Fault Code / Symptom	Engine Misfire Cylinder 6 - Data Valid But Above Normal Operating Range - Moderately Severe Level
Solution Number	S00009019
Solution Title	Engine Compression Test
Update Reason	Solution Added
Date	20-Mar-2021
Fault Code / Symptom	
Solution Number	
Solution Title	
Update Reason	15N CM2380 M104B New manual released for use.

Last Modified: 23-Aug-2026
