

Fault Code: 292


OEM Temperature - Engine Protection

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 292 PID(P): P223 SPN: 1083 FMI: 14 Lamp: Engine Protection SRT:	OEM temperature out-of-range has been detected. Voltage signal at OEM temperature signal pin 27 indicates OEM temperature beyond the OEM-specified threshold.	Calibration-dependent progressive power and speed derate and engine shutdown with increasing time after alert.

©Cummins Inc



19400893

OEM Temperature Circuit

Circuit Description

The OEM resistive signal is used by the ECM to monitor an OEM temperature. The OEM temperature is used by the ECM for the engine protection system.

Component Location

The location varies with the OEM. Refer to the OEM manual.

Shoptalk

The resistance of all temperature sensors varies with the ambient temperature.

Refer to Troubleshooting Fault Code t05-292 (</qs3/pubsys2/xml/en/procedures/19/19-t05-292.html>)

Last Modified: 01-Mar-2011
