

Fault Code: 384


Ether Injection Circuit

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 384 PID(P): S237 SPN: 626 FMI: 11 Lamp: Yellow SRT: 00-365	The ether injection solenoid circuit is open or shorted at pin 2 of the engine harness.	Ether injection feature is disabled.

©Cummins Inc



19400679

Ether Injection Solenoid Circuit

Circuit Description

The ether injection solenoid is a device used by the ECM to control the ether injection system during cold starts.

Component Location

The ether injection solenoid location is dependent on the OEM. Refer to the OEM manual.

Refer to Troubleshooting Fault Code t05-384 (/qs3/pubsys2/xml/en/procedures/19/19-t05-384.html)

Last Modified: 01-Mar-2011
