

Fault Code: 487

Ether System Empty

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 487 PID(P): SPN: FMI: Lamp: White SRT:	The ether bottle for the ether injection system is empty.	The ether injection system is disabled.

©Cummins Inc

Circuit Description

nonapplicable for this fault code

Component Location

nonapplicable for this fault code

(/qs3/pubsys2/xml/en/procedures/--.html)

Last Modified: 01-Mar-2011
