



# Technical Service Bulletin

Technical Service Bulletin: tsb100720

Released Date: 04-Aug-2008

New Fuel Return Bracket

## New Fuel Return Bracket

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

This Technical Service Bulletin introduces a redesigned ISM fuel return line mounting bracket. Previous ISM fuel return brackets utilized a rectangular staked brass fitting to secure the fuel return line and fitting to the engine block. The redesigned ISM fuel return bracket includes a round, staked, and brazed steel fitting to secure the fuel return line to the engine block. This new fuel return bracket is being released for all ISM, ISMe, and QSM engines as a new part and replaces all previous parts. The new ISM fuel return bracket, Part Number 4985465, supersedes Part Number 3401236. Reference Figure 1 and Figure 2 for the differences between the old ISM fuel return bracket and the new ISM fuel return bracket.

The release date for the new ISM fuel return bracket for production is June 2008.

The release date for the new ISM fuel return bracket for service is July 2008.

The engine serial number (ESN) first is 35233686.

#### Parts Status Table

| Old Part Number | Part Name           | Quantity | New Part Number |
|-----------------|---------------------|----------|-----------------|
| 3401236         | Fuel return bracket | 1        | 4985465         |




Figure 1: Old fuel return bracket, Part Number 3401236.

- 1. Bracket
- 2. Fitting




Figure 2: New fuel return bracket, Part Number 4985465.