



Technical Service Bulletin

Technical Service Bulletin: tsb100728

Released Date: 12-Aug-2008

New Water Pump O-Ring

New Water Pump O-Ring

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin introduces a new water pump o-ring which obsoletes and supersedes the old part number as shown in the table below. The o-ring seals the joint between the water pump and the gear housing. The new o-ring was released as part of a product improvement project to eliminate the degradation of the o-ring material when exposed to oil.

The new o-ring has a diameter of 101.3 mm [3.987 inch] and has a Teflon™ coating that is pink, for identification purposes **only**. The color change is intended to aid technicians in distinguishing the new o-ring from the old o-ring, which was light blue in color.

The engine serial number (ESN) first is 35229696 implemented on May 28, 2008.

New Part Number	Teflon™ Coating Color	Description	Old Part Number	Teflon™ Coating Color
2863701	Pink	Seal, O-Ring	3882774	Light Blue

Last Modified: 12-Aug-2008