



# Technical Service Bulletin

Technical Service Bulletin: tsb100730

Released Date: 12-Aug-2008

New Hydraulic Pump Adapter O-Ring

## New Hydraulic Pump Adapter O-Ring

### Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

### Contents

This Technical Service Bulletin introduces a new ISM hydraulic pump adapter o-ring which obsoletes and supersedes the old o-ring, as indicated in the table below. The o-ring seals the joint between the hydraulic pump adapter and the gear housing. The new o-ring is being released as part of a product improvement project to eliminate the degradation of the o-ring material, when exposed to oil.

The new o-ring has a diameter of 127.7 mm [4.987 inch] and is Teflon™ coated light blue in color, for identification purposes **only**. The color change is intended to aid technicians in distinguishing between the new o-ring and the previous o-ring, which is pink in color.

The engine serial number (ESN) first is 35229759 implemented on May 28, 2008.

| New Part Number | Teflon™ Coating Color | Description  | Old Part Number | Teflon™ Coating Color |
|-----------------|-----------------------|--------------|-----------------|-----------------------|
| 2863702         | Light Blue            | Seal, O-Ring | 3883042         | Pink                  |

Last Modified: 12-Aug-2008