



Technical Service Bulletin

Technical Service Bulletin: tsb100783

Released Date: 12-Dec-2008

New Bushed Gear Lubricating Oil Pumps

New Bushed Gear Lubricating Oil Pumps

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin announces a product improvement to the ISX family lube pump. This change is backwards compatible with all ISX engines. There are several internal dimensional and part changes, resulting in an obsolete and supersede process for old part numbers, as shown in Table 1.

Table 1

Part Description	Old Part Number	New Part Number	ESN First
Pump, Lubricating Oil (Aluminum Body)	4026691	2864072	79311644 on May 11 2008
Pump, Lubricating Oil (Cast Iron Body)	3100445	2864073	79321671 on June 27 2008
Kit, Lube Pump (Aluminum Body)	4024814	4955954	N/A
Kit, Lube Pump (Cast Iron Body)	4024935	4955955	N/A

Contents of Lube Pump Kits

Description

Shims

Pump, Lubricating Oil

These changes were implemented into production on May 11, 2008, with ESN first 79311644. The new service kits were made available July 2008, and obsolete and supersede other lubricating oil pump kits.

