



Technical Service Bulletin

Technical Service Bulletin: tsb100812

Released Date: 15-Apr-2009

New Turbochargers and Related Service Kits

New Turbochargers and Related Service Kits

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Technical Service Bulletin announces new turbochargers and related service kits for use on QSK19, QSK38, QSK45, QSK50 series diesel engines due to the change in turbocharger part numbers.

The new service kits contain turbochargers with new impeller designs in order to further improve product durability.

The installation procedure remains unchanged.

Turbochargers and related kit part numbers

Part Name	Old Part Number	New Part Number	Part Name	Old Part Number	New Part Number
Turbocharger	3593168	2837521	Kit, Turbocharger	4025239	4956140
Turbocharger	4044771	2837524	Kit, Turbocharger	4955472	4956141
Turbocharger	4044827	2837525	Kit, Turbocharger	4955461	4956142
Turbocharger	4043252	2837531	Kit, Turbocharger	4955514	4956143
Turbocharger	4043254	2837532	Kit, Turbocharger	4955513	4956144
Turbocharger	4043624	2837533	Kit, Turbocharger	4955430	4956145

Turbochargers and related kit part numbers					
Part Name	Old Part Number	New Part Number	Part Name	Old Part Number	New Part Number
Turbocharger	4044190	2837534	Kit, Turbocharger	4955515	4956146
Turbocharger	4044192	2837535	Kit, Turbocharger	4955516	4956147
Turbocharger	4044772	2837536	Kit, Turbocharger	4955504	4956148
Turbocharger	4044773	2837537	Kit, Turbocharger	4955473	4956149
Turbocharger	4047882	2838541	Kit, Turbocharger	4955933	4956137

Last Modified: 15-Apr-2009
