



Technical Service Bulletin

Technical Service Bulletin: tsb101308

Released Date: 29-Sep-2003

Revised Oil Pan Capscrew Torque Sequence and Torque Value

Revised Oil Pan Capscrew Torque Sequence and Torque Value

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This service/parts topic revises the torquing sequence and torque values of the oil pan capscrews.

Related Procedures

10-007-025
(/qs3/pubsys2/xml/en/procedures/10/10-007-025.html)

Lubricating Oil Pan
(/qs3/pubsys2/xml/en/procedures/10/10-007-025.html)

Last Modified: 29-Sep-2003