



Technical Service Bulletin

Technical Service Bulletin: tsb101940

Released Date: 14-Aug-2006

Air Compressor Procedures, Carbon Removal Information

Air Compressor Procedures, Carbon Removal Information

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds the following procedures to the ISM Service Manual and converts the procedures from engine specific to common procedures to be used for both the ISX and ISM series engines.

- Procedure 012-003, Air Compressor Carbon Buildup
- Procedure 012-007, Air Compressor Cylinder Head, Single Cylinder
- Procedure 012-024, Air Pressure Relief Valve.

Related Procedures

101-012-003 (/qs3/pubsys2/xml/en/procedures/101/101-012-003.html)	Air Compressor Carbon Buildup (/qs3/pubsys2/xml/en/procedures/101/101-012-003.html)
101-012-007 (/qs3/pubsys2/xml/en/procedures/101/101-012-007.html)	Air Compressor Cylinder Head, Single Cylinder (/qs3/pubsys2/xml/en/procedures/101/101-012-007.html)
101-012-024 (/qs3/pubsys2/xml/en/procedures/101/101-012-024.html)	Air Pressure Relief Valve (/qs3/pubsys2/xml/en/procedures/101/101-012-024.html)

Last Modified: 14-Aug-2006

