



Technical Service Bulletin

Technical Service Bulletin: tsb102071

Released Date: 01-Dec-2006

Revision, 12-VDC Specification Changes, Engine Brake Solenoid Valve Procedure

Revision, 12-VDC Specification Changes, Engine Brake Solenoid Valve Procedure

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the solenoid resistance specifications of each 12-VDC engine brake solenoid (wiring harness disconnected), as measured from the terminal to the body of the solenoid in procedure, Engine Brake Solenoid Valve, 020-012.

Related Procedures

10-020-012
(/qs3/pubsys2/xml/en/procedures/10/10-020-012.html)

Engine Brake Solenoid Valve
(/qs3/pubsys2/xml/en/procedures/10/10-020-012.html)

Last Modified: 01-Dec-2006