



Technical Service Bulletin

Technical Service Bulletin: tsb102584	Released Date: 10-Dec-2007
Revision, Symptom Tree, Coolant in the Lubricating Oil	

Revision, Symptom Tree, Coolant in the Lubricating Oil

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises symptom tree t025 (Coolant in the Lubricating Oil) in Section TS, to check for coolant leaks in the EGR cooler.
--

Coolant in the Lubricating Oil

Last Modified: 10-Dec-2007
