



Technical Service Bulletin

Technical Service Bulletin: tsb103101

Released Date: 09-Oct-2008

Cylinder Head Procedure, Assemble Section Revision

Cylinder Head Procedure, Assemble Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds the injector protrusion gauge, Part Number 4919196, to the Assemble section of Procedure 002-004 (Cylinder Head) in the K19 Service Manual, Bulletin 4021499.

Related Procedures

18-002-004-tr
(/qs3/pubsys2/xml/en/procedures/18/18-002-004-tr.html)

Cylinder Head
(/qs3/pubsys2/xml/en/procedures/18/18-002-004-tr.html)

Last Modified: 09-Oct-2008