



Technical Service Bulletin

Technical Service Bulletin: tsb103332

Released Date: 20-Jan-2009

STC Oil Manifold Procedure, Install Section Revision

STC Oil Manifold Procedure, Install Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises the Install section in Procedure 006-038 (STC Oil Manifold) for the K19 engine. Loctite™ 271 is be applied to the capscrews before installation, to prevent loosening.

Note : This is a product improvement and is not subject to campaign.

Related Procedures

18-006-038
(/qs3/pubsys2/xml/en/procedures/18/18-006-038.html)

STC Oil Manifold
(/qs3/pubsys2/xml/en/procedures/18/18-006-038.html)

Last Modified: 20-Jan-2009