



Technical Service Bulletin

Technical Service Bulletin: tsb103344

Released Date: 03-Mar-2009

Multiple Group 02 Procedure Revisions

Multiple Group 02 Procedure Revisions

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic revises Procedures 002-004 (Cylinder Head) and 002-016 (Valve Guide Seal, Cylinder Head) in the Signature™, ISX and QSX15 Service Manual, Bulletin 3666239. The revision includes the addition of detailed steps for the new four valve spring compressor tool, Part Number 4919358.

Related Procedures

10-002-004-tr (/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html)	Cylinder Head (/qs3/pubsys2/xml/en/procedures/10/10-002-004-tr.html)
10-002-016 (/qs3/pubsys2/xml/en/procedures/10/10-002-016.html)	Valve Guide Seal, Cylinder Head (/qs3/pubsys2/xml/en/procedures/10/10-002-016.html)

Last Modified: 03-Mar-2009