



Technical Service Bulletin

Technical Service Bulletin: tsb103373

Released Date: 14-Oct-2014

Service Tool Addition, Lubricating Oil System

Service Tool Addition, Lubricating Oil System

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document adds the Oil Cooler Leak Test Kit, Part Number 4918200, to Service Tools in Section 7.

The oil cooler leak test kit is used to pressurize the oil cooler assembly in order to check for leaks. It is used with air pressure regulator, Part Number 3164231 or equivalent. Use the following procedure in the Signature™, ISX, and QSX15 Service Manual, Bulletin 3666239. Refer to Procedure 007-003 in Section 7. (</qs3/pubsys2/xml/en/procedures/10/10-007-003-tr.html>)

Document History

Date	Details
2014-10-10	QSOL Work Oder 64767

Last Modified: 14-Oct-2014