



Technical Service Bulletin

Technical Service Bulletin: tsb104068

Released Date: 24-Mar-2010

Cylinder Block Service Tool Addition

Cylinder Block Service Tool Addition

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds a new cylinder block service tool. This new service tool is used with Guide Kit, Part Number 4918339, to inspect the connecting rods for bends, twists, and length.

Related Procedures

10-022-001_01
(/qs3/pubsys2/xml/en/procedures/10/10-022-001_01.html)

Cylinder Block Service Tool
(/qs3/pubsys2/xml/en/procedures/10/10-022-001_01.html)

Last Modified: 24-Mar-2010