



Technical Service Bulletin

Technical Service Bulletin: tsb104103

Released Date: 18-Feb-2010

Fuel Drain Line Restriction Procedure, Measure Section Revision

Fuel Drain Line Restriction Procedure, Measure Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service/Parts Topic adds maximum fuel drain line restriction specifications for applications equipped with a system check valve to Procedure 006-012 (Fuel Drain Line Restriction) in Section 6 of the Signature™, ISX, and QSX15 Service Manual, Bulletin 3666239.

Related Procedures

10-006-012
(/qs3/pubsys2/xml/en/procedures/10/10-006-012.html)

Fuel Drain Line Restriction
(/qs3/pubsys2/xml/en/procedures/10/10-006-012.html)

Last Modified: 18-Feb-2010