



Technical Service Bulletin

Technical Service Bulletin: tsb104200

Released Date: 13-May-2010

(Bearings, Connecting Rod) Procedure, Clean and Inspect for Reuse Section Revision

(Bearings, Connecting Rod) Procedure, Clean and Inspect for Reuse Section Revision

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This Service /Parts Topic revises Procedure 001-005 (Bearings, Connecting Rod) in the K19 Service Manual, Bulletin 4021499. The Clean and Inspect for Reuse Section has been revised to include reuse guidelines for the connecting rod bearings.

Related Procedures

18-001-005
(/qs3/pubsys2/xml/en/procedures/18/18-001-005.html)

Bearing, Connecting Rod
(/qs3/pubsys2/xml/en/procedures/18/18-001-005.html)

Last Modified: 13-May-2010