



Technical Service Bulletin

Technical Service Bulletin: TSB110195

Released Date: 25-Jul-2011

New Accessory Drive Belt Tensioner

New Accessory Drive Belt Tensioner

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

This document announces the release of a new accessory drive belt tensioner, Part Number 2891940, for all ISX and QSX platforms. This new belt tensioner has a dual ball bearing pulley and improved grease to improve overall reliability.

The new belt tensioner, Part Number 2891940, will have a slightly different arm and pulley, but is a direct replacement for the old belt tensioner, Part Number 3104149. The present mounting hardware will continue to be used.

The new accessory drive belt tensioner, Part Number 2891940, obsoletes and supersedes the previous tensioner, Part Number 3104149. See Table 1 for the engine serial number (ESN) first.

Engine Model	ESN	Build Date
ISX15	79493464	7 July 2011
ISX11.9	75004331	7 July 2011

See Table 2 for the new and old part numbers.

Table 2: New and Old Belt Tensioner Part Numbers

Quantity	Description	New Part Number	Old Part Number
1	Belt Tensioner	2891940	3104149

Document History

Date	Details
2011-6-27	Module Created

