



Technical Service Bulletin

Technical Service Bulletin: TSB120066

Released Date: 03-Sep-2021

New Oil Cooler Element for ISX15

New Oil Cooler Element for ISX15

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

A new stainless steel oil cooler element was released as a service **only** part. The new oil cooler element obsoletes and supersedes the previous 63 mm [2.5 in] aluminum oil cooler element, and is used in all engine ratings for ISX15 engines built before 1 November 2007.

The stainless steel oil cooler element requires two o-ring seals instead of two gaskets. Two o-ring seals, Part Number 4966084, should be ordered with every new oil cooler. The mounting bolts are unchanged.

Reference the part replacement table below:

Noun Name	New Part Number	Obsolete Part Number
COOLER, OIL	2892304*	4965870
		4952494
		4920187

* Two o-ring seals required (ordered separately)

Parts became available at MDC on 2 March 2012.

The sealing o-ring exposes the mounting holes, that were previously protected with a gasket, to the coolant. Apply red, chemical resistant, anaerobic thread locker, such as Loctite™ 2760, to seal the threads of the oil cooler element mounting capscrews when using the new part.

Document History

Date	Details
2012-3-6	Module Created
2012-5-29	Add statement instructing use of Loctite® 2760
2021-8-25	Added two obsolete part numbers.

