



Technical Service Bulletin

Technical Service Bulletin: TSB170115

Released Date: 27-Nov-2017

New Turbocharger Oil Drain Tube

New Turbocharger Oil Drain Tube

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSB6.7 CM2150 B109

Description of Change

A new turbocharger oil drain tube part number is available.

Reason for Change

Path of turbocharger oil drain tube was changed to correct interference issues.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts

Part Description	Existing Part Number	Obsoleted	Superseded	New Part Number
Turbocharger Oil Drain Tube	3975076	No	No	5368665

Part Identification




Figure 1: Existing Turbocharger Oil Drain Tube, Part Number 3975076.



Figure 2: New Turbocharger Oil Drain Tube, Part Number 5368665.

Production Status

Table 2, Production Information		
ESN First	Build Date*	Engine Plant
26647504	17-February-2016	Komatsu Cummins® Engine CO.
*Engine build date can be found on engine data plate.		

Document History

Date	Details
2017-11-3	Module Created

Last Modified: 27-Nov-2017
