


Fault Code: 147

Frequency Accelerator Circuit

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 147 PID(P): P91 SPN: 091 FMI: 8 Lamp: Red SRT:	A frequency of less than 100 Hz has been detected at frequency accelerator signal pin 17 of the OEM interface harness.	Calibration-dependent power and speed derate.



Frequency Accelerator Circuit

Circuit Description

The frequency accelerator provides the driver's accelerator command to the ECM through the OEM harness and the OEM interface harness. The ECM uses this signal to determine the fueling command.

Component Location

Accelerator location varies with each OEM. Refer to the OEM manual.

Shoptalk

The frequency accelerator can either be used in conjunction with a voltage accelerator or by itself.

Refer to Troubleshooting Fault Code t05-147 (</qs3/pubsys2/xml/en/procedures/19/19-t05-147.html>)

Last Modified: 19-Aug-2010
