

Fault Code: 426

J1939 Datalink No Communication

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 426 PID(P): SPN: FMI: Lamp: Yellow SRT:	ECM can not transmit on J1939 datalink.	No action is taken by ECM.

©Cummins Inc

Circuit Description

nonapplicable for this fault code

Component Location

nonapplicable for this fault code

(/qs3/pubsys2/xml/en/procedures/--.html)

Last Modified: 01-Mar-2011
