



Technical Service Bulletin: TSB200080

Released Date: 15-Feb-2023

New Aftertreatment Diesel Particulate Filter Differential Pressure Sensor

New Aftertreatment Diesel Particulate Filter Differential Pressure Sensor

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- X15 CM2350 X114B
- X15 CM2350 X116B
- X15 CM2350 X123B

Description of Change

Due to the implementation of the new Aftertreatment Diesel Particulate Filter Differential Pressure Sensor, new service kits are required to service the components. The new sensor has larger connection ports and larger diameter tubes.

Service Instructions

Any service event that requires DPF differential pressure sensor replacement, will require the new DPF differential pressure sensor and new DPF differential pressure tubes, provided in a service kit. Service kit part numbers are shown below.

Service Parts Availability

Different service kits are available for different aftertreatment configurations.

Reference Table 1 for applicable aftertreatment configuration part numbers, located on the aftertreatment decomposition reactor tube.

Once the aftertreatment configuration is identified, use Table 2 to find the correct service kit.

Table 1, Aftertreatment Configuration Part Numbers	
Horizontal Outside Rail– Side In Side Out (SISO), End In Side Out (EISO), Side In End Out (SIEO), End In End Out (EIEO)	4387634
	4387635
	4387636
	4387637
	4387638
	4387639
	4387640
	4387641
	4394899
	4394917
	4394920
	4394925
	4394927
	4394986
	4394987
	4394988
	4394989
	4394990
	4394991
	4395043
	4395044
	4395045
	4395046
	5417544
	5417562
	5417696
	5417977
	5417978
	5417985
	5418132
	5418403
	5505890
	5505891
	5505892
	5505894
	5505895

Table 1, Aftertreatment Configuration Part Numbers					
			5505896		
			5505898		
			5506191		
			5506405		
			5506406		
Horizontal Between Rail End In End Out (EIEO)			4394830		
			4394831		
Vertical – End In End Out (EIEO)			4387855		
			4395079		
			5418148		
			5418149		
			5505889		
			5505893		
			5505897		
Table 2, New Available Service Parts					
Configuration	New Kit Part Number (Emission Solutions Part Number / Cummins Part Number)	Item	Quantity	New Emission Solutions Part Number	New Cummins Part Number
Horizontal Outside Rail – SISO, EISO, SIEO, EIEO	A060X956 / 5507314	Sensor	1	A061B903	5492073
		High Pressure Tube	1	A059E903	5418414
		Low Pressure Tube	1	A059E905	5418425
		Cap Screw	2	A054S710	4394382
Horizontal Between Rail EIEO	A060X957 / 5507309	Sensor	1	A061B903	5492073
		High Pressure Tube	1	A059E911	5418427
		Low Pressure Tube	1	A059E913	5418428
		Cap Screw	2	A054S710	4394382

Table 2, New Available Service Parts					
Configuration	New Kit Part Number (Emission Solutions Part Number / Cummins Part Number)	Item	Quantity	New Emission Solutions Part Number	New Cummins Part Number
Vertical - EIEO	A060X958 / 5507315	Sensor	1	A061B903	5492073
		High Pressure Tube	1	A059E907	5418415
		Low Pressure Tube	1	A059E909	5418430
		Cap Screw	2	A054S710	4394382

Document History

Date	Details
2020-4-1	Module Created
2023-2-14	Added X15 CM2350 X123B.