

Fault Code: 1335


Non-Critical Scalar Out-of-Range

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 1335 PID(P): SPN: FMI: Lamp: Warning SRT:	One or more trims have been set so that a non-critical scalar is out-of-range.	No alternator protection. Possible loss of performance.

©Cummins Inc



19802494

Engine Control Module

Circuit Description

Component Location

Refer to Troubleshooting Fault Code t05-1335. (</qs3/pubsys2/xml/en/procedures/01/01-t05-1335.html>)

