

Fault Code: 1337


LonWorks Wink Command Event

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 1337 PCODE(P): SPN: FMI: Lamp: None SRT:	LonWorks wink event has been commanded.	No corrective action taken with this fault code.

©Cummins Inc



ECM

Circuit Description

Component Location

Refer to Troubleshooting Fault Code t05-1337 (/qs3/pubsys2/xml/en/procedures/01/01-t05-1337.html)

