

Fault Code: 1341


LonWorks Network Commanded Shutdown

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 1341 PCODE(P): SPN: FMI: Lamp: None SRT:	The paralleling controller has requested a generator shutdown.	The generator will shutdown.

©Cummins Inc



19802649

Generator Set ECM Card Cage

Circuit Description

Component Location

Refer to Troubleshooting Fault Code t05-1341 (/qs3/pubsys2/xml/en/procedures/01/01-t05-1341.html)

Last Modified: 29-Jul-2010
