

Fault Code: 1343


Base Board - Incorrect Installation

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 1343 PID(P): SPN: FMI: Lamp: Shutdown SRT:	The base board (slot 1) is missing or has not been installed correctly.	Engine will not start.

©Cummins Inc



19802789

Generator Set ECM Base Board

Circuit Description

Once the software has been loaded into the ECM, the software will do a hardware check to make sure that all necessary cards are installed for the application.

This fault code is used by the ECM to tell the operator that the base board (slot 1) is missing or has been installed incorrectly.

Component Location

Refer to Section E for location of the ECM card cage and the base board (slot 1).

Shoptalk

The possible failure modes are incorrect installation of the base board and loading an incorrect software calibration into the ECM.

Refer to Troubleshooting Fault Code t05-1343 (</qs3/pubsys2/xml/en/procedures/01/01-t05-1343.html>)

Last Modified: 29-Jul-2010
