

Fault Code: 1424

Relay High Side Driver Diagnostic

 Printable Version

Overview

Codes	Reason	Effect
Fault Code: 1424 PID(P): SPN: FMI: Lamp: Warning SRT:	Relay high side driver diagnostic has detected an error.	The user interface relay drivers will not function correctly. No action is taken by the ECM. No loss of performance.

©Cummins Inc



19802500

Relay High Side Driver Circuit

Circuit Description

The relay driver supply pin supplies power for all of the user interface relay drivers. The ECM monitors the voltage, no voltage/low voltage will trip Fault Code 1424, and can be caused by shorts, opens, or a failed driver in the ECM.

Component Location

Refer to the OEM manual for location of the ECM. Refer to the OEM manual for location of the user interface panel.

Shoptalk

The possible failure modes are open circuit, short to ground, and loss of supply voltage inside the ECM.

Refer to Troubleshooting Fault Code t05-1424 (</qs3/pubsys2/xml/en/procedures/01/01-t05-1424.html>)

Last Modified: 29-Jul-2010
